07-12 2:42:37 PM



MONTGOMERY SISAM ARCHITECTS INC. ARCHITECTURAL

21508.F03 **ISSUED FOR TENDER** MAY 2022

HANDRAIL REPLACEMENT

LAKESHORE LODGE LONG-TERM CARE HOMES AND SERVICES 3197 LAKESHORE BLVD. W., ETOBICOKE



Long-Term Care Homes and Services Division

GENERAL NOTES

- 1 REPAIR. PATCH & MAKE GOOD ALL EXISTING STRUCTURE AND FINISHES AFFECTED BY CONSTRUCTION.
- ALL REQUIRED CUTTING & FITTING INCLUDING ELECTRICAL & MECHANICAL TO CONNECT THE 2. EXISTING WORK WITH THE NEW WORK SHALL BE PERFORMED AS PART OF THIS CONTRACT AS AN ENTIRE OR COMPLETE WORK IN A PROFESSIONAL AND WHOLE MANNER.
- ALL NEW WORK TO MAKE GOOD EXISTING; SHALL MATCH EXISTING IN MATERIAL, 3 CONSTRUCTION AND FINISH UNLESS OTHERWISE SPECIFIED.
- CONTRACTOR SHALL PERFORM ALL NECESSARY DEMOLITION. ALTERATIONS AND NEW 4 CONSTRUCTIONS AS REQUIRED TO MAKE THE WORK A COMPLETE JOB, INCLUDING BUT NOT LIMITED TO WORK SHOWN ON DRAWINGS AND SPECIFICATIONS.
- ANY OPENINGS IN FIRE RATED WALLS. CEILINGS AND FLOORS TO BE RETURNED TO 5 EQUIVALENT CONDITION PRIOR TO THE OPENING. ALL ELECTRICAL & MECHANICAL PENETRATIONS TO BE SEALED WITH FIRE STOP MATERIAL AS PER SPECIFICATION. ALL ELECTRICAL & MECHANICAL PENETRATIONS TO BE SEALED WITH FIRE STOP MATERIAL AS REQUIRED BY O.B.C.
- AII ITEMS INDICATED IN THE CONTRACT DOCUMENTS AS 'COORDINATION ITEMS' OR ITEMS 6 IDENTIFIED AS N.I.C., INCLUDING BUT NOT LIMITED TO EQUIPMENT AND OTHER SPECIALTY ITEMS IDENTIFIED AS TO BE SUPPLIED AND INSTALLED BY OTHER PARTIES OR ALLOWANCES WILL REQUIRE THE COMMON ACTION OR EFFORT OF THE GENERAL CONTRACTOR IN RELATION TO THE OVERALL PROJECT. WITH RESPECT TO ALL COORDINATION ITEMS IDENTIFIED. THE GENERAL CONTRACTOR IS EXPECTED TO:

a. REVIEW ALL ITEMS IDENTIFIED AS 'COORDINATION ITEMS' IN THE DRAWINGS AND COMMUNICATE WITH THE REQUIRED RESPONSIBLE PARTIES OF THE DEVICES THE DETAILED REQUIREMENTS OF EACH ITEM AS IT IMPACTS THE WORK OF GENERAL CONTRACTOR AND AS IT RELATES TO THE OVERALL COMPLETION OF THE PROJECT. b. VERIFY THE EXISTING CONDITION AND ANY LIMITATIONS OF THE DEVICE AS INSTALLED IN THE PROPOSED LOCATION.

c. PROVIDE ALL REQUIRED ROUGH-INS, RELATED CONSTRUCTIONS AND CONNECTIONS REQUIRED BY THE DEVICES OF OTHERS TO SUIT THE COORDINATION ITEM AND AS INDICATED IN THE CONTRACT DOCUMENTS.

d. SCHEDULE AND COORDINATE THE WORK OF OTHERS INTO THE OVERALL CONSTRUCTION SEQUENCE TO AVOID UNNECESSARY DELAY TO THE COMPLETION OF THE OVERALL PROJECT.

e. ENSURE THAT THE PROPOSED ITEM IS INSTALLED AS INTENDED AND IS MADE FULLY OPERATIONAL AT THE COMPLETION OF THE WORK.

7 THE EXISTING PORTIONS OF THESE PLANS ARE TAKEN FROM ARCHIVE DRAWINGS AND LIMITED SITE SURVEY INFORMATION. CONTRACTOR TO SITE VERIFY ALL DIMENSIONS. CONDITIONS AND LEVELS ON SITE PRIOR TO FABRICATIONS/ INSTALLATIONS. ALL DIMENSIONS ARE PER SITE REVIEW AND EXIST. ARCH. DWGS. ALL DISCREPANCIES BETWEEN CONDITIONS SHOWN AND SITE CONDITIONS ARE TO BE REPORTED TO THE ARCHITECT. PRIOR TO SUBMITTING A BID, THE CONTRACTOR SHALL VISIT THE SITE AND EXAMINE THE FOLLOWING: I: VERIFY EXISTING AREAS WITHIN THE SCOPE OF WORK WITH RESPECT TO THE PROPOSED FOR PROBLEMS AND ANY LIMITATIONS. ii: VERIFY EXISTING ARCHITECTURE, STRUCTURE AND ALL ADJACENT FINISHES IMPACTED BY THE WORK UPON EXAMINING ALL OF THE ABOVE AGAINST THE DRAWINGS AND SPECIFICATIONS AND TERMS OF THE CONTRACT, THE CONTRACTOR MUST SATISFY HIMSELF THAT THE PROPOSED WORK CAN BE CARRIED OUT AS INTENDED, TO THE SATISFACTION OF THE

OWNER, AT NO ADDITIONAL COST TO THE CONTRACT.

- PROTECT ALL FINISHES TO REMAIN PART OF THE FINAL PRODUCT. ALL FINISHES DAMAGED AS A RESULT OF CONSTRUCTION SHALL BE MADE GOOD BY THE GC.
- COORDINATE ALL WORK WITH THE HOME AND FOLLOW ALL HOME PROTOCOLS. 9
- 10 HOARDING SHALL BE CONSTRUCTED TO THE SATISFACTION OF THE HOME.
- 11. COORDINATE ALL WORK WITH ARCHITECTURAL / MECHANICAL / ELECTRICAL DRAWINGS AND SPECIFICATIONS. WHERE A DISCREPANCY IS DISCOVERED BETWEEN THE DOCUMENTS NOTIFY THE ARCHITECT.
- ALL REMOVED AND DEMOLISHED MATERIAL TO BE REMOVED FROM THE SITE. LOCATION OF 12 REMOVAL RECEPTACLE TO BE CO-ORDINATED WITH BUILDING MAINTENANCE DEPARTMENT.
- 13. MAINTAIN EXISTING FIRE RATING AT ALL TIMES DURING THE WORK AND AFTER.

DRAWING LIST	ſ
--------------	---

A0 00

A0.00	COVER
A0.01	GENERAL INFORMATION
A0.02	GENERAL INFORMATION
A0.03	CONSTRUCTION CONTROL PLAN
A0.04	AREA OF WORK PLAN - LEVEL 2
A0.05	AREA OF WORK PLAN - LEVEL 1 - ALTERNATIVE PRICE #1
A0.06	AREA OF WORK PLAN - LEVEL 1 - ALTERNATIVE PRICE #2
A0.08	EXISTING CONDITIONS PHOTOS (ECP) - LEVEL 1
A0.09	EXISTING CONDITIONS PHOTOS (ECP) - LEVEL 2
A1.01	DEMO. PLAN_LEVEL 1 (SOUTH WING)
A1.02	DEMO. PLAN_LEVEL 1 (CENTRE AREA)
A1.03	DEMO. PLAN_LEVEL 2 (SOUTH WING)
A1.04	DEMO. PLAN_LEVEL 2 (CENTRE AREA)
A1.05	DEMO. PLAN_LEVEL 2 (NORTH WING)
A2.01	TYP. EXISTING WOOD HANDRAIL DEMO. SECTIONS
A2.02	TYP. EXISTING WOOD HANDRAIL DEMO. SECTIONS
A2.03	TYP. EXISTING WOOD HANDRAIL DEMO. SECTIONS
A2.04	TYP. EXISTING WOOD HANDRAIL DEMO. SECTIONS
A2.05	TYP. EXISTING CRASH RAIL DEMO. DETAILS
A3.01	PROPOSED PLAN_LEVEL 1 (SOUTH WING)
A3.02	PROPOSED PLAN_LEVEL 1 (CENTRE AREA)
A3.03	PROPOSED PLAN_LEVEL 2 (SOUTH WING)
A3.04	PROPOSED PLAN_LEVEL 2 (CENTRE AREA)
A3.05	PROPOSED PLAN_LEVEL 2 (NORTH WING)
A4.01	TYPICAL PROPOSED HANDRAIL DETAILS
A4.02	TYPICAL PROPOSED HANDRAIL DETAILS
A4.03	TYP. NEW HANDRAIL DETAILS
A4.04	NEW HANDRAIL AT BANKING WINDOW DETAILS
A4.05	NEW HANDTAIL OVER GLASS BLOCK WALL DETAILS
A4.06	TYP. NEW CRASH RAIL DETAILS
A4.07	NEW CRASH RAIL UNDER GLASS CABINET DETAILS
A4.08	TYP. NEW WALL PROTECTION DETAILS_LEVEL 1
A4.09	TYP. NEW WALL PROTECTION DETAILS_LEVEL 2
A4.10	TYP. NEW WALL PROTECTION DETAILS_LEVEL 2
A4.11	TYP. CORNER GUARD PLAN DETAILS
A4.12	TYP. CORNER GUARD PLAN DETAILS
A5.01	NEW HANDRAIL LAYOUT DIAGRAM

PHASING & CONSTRUCTION NOTES

- ALL WORK WITHIN THIS PROJECT WILL BE COMPREHENSIVELY SCHEDULED WITH THE HOME PRIOR TO START-UP ON SITE. CONTRACTORS WILL BE REQUIRED TO ADHERE TO THIS SCHEDULE FOR THE DURATION OF THE WORK.
- NO WORK SHALL BE LEFT IN AN UNFINISHED STATE AT DAYS 2 END. ALL AREAS OF WORK SHOULD BE MADE SAFE AND COMPLETELY OPERATIONAL AT THE END OF EACH DAYS WORK.

3

- THE REQUIRED MOVING AND REINSTALLATION OF ANY FURNITURE IS TO BE INCLUDED IN THE BASE BID PRICE. IT IS EXPECTED THAT ALL AREAS WILL BE HANDED BACK TO THE HOME IN A RESTORED AND FULLY FUNCTIONAL ORDER BY THE CONTRACTOR. TEMPORARY STORAGE FOR ALL REMOVED FURNITURE AND EQUIPMENT WILL BE PROVIDED BY AND COORDINATED WITH THE HOME.
- 4 THE CONTRACTOR SHALL PROVIDE THE FOLLOWING MOCK-UPS:

CONSTRUCT ONE (1) STANDARD HANDRAIL (HR1) / CRASH RAIL (CR1) ASSEMBLY W/ WALL PROTECTION (WP1 /WP2) WHERE IT APPLIES - INCLUDING STANDARD END CAP, INSIDE CORNER AND OUTSIDE CORNER, IN EACH CORRIDOR - CORRIDOR G79, CORRIDOR G48 AND CORRIDOR 202, THREE (3) TOTAL. INCLUDING BUT NOT LIMITED TO HANDRAIL, CRASH RAIL, MOUNTING BRACKET, WALL PROTECTION, CORNER GUARD, PATCH / REPAIR WORK AND ALL OTHER WORK AS PER THE CONTRACT DOCUMENTS.

ARRANGE FOR THE CONSULTANTS REVIEW AND ACCEPTANCE. ALLOW 48HRS AFTER ACCEPTANCE BEFORE PROCEEDING WITH WORK.

MOCK-UP MAY REMAIN AS PART OF THE WORK IF ACCEPTED BY THE CONSULTANT. REMOVE AND DISPOSE OF MOCK-UPS THAT DO NOT CONFORM TO THE WORK. UPON ACCEPTANCE, MOCK-UP SHALL SERVE AS A MINIMUM STANDARD OF QUALITY FOR THE BALANCE OF THE RELATED WORK. THE LOCATION OF THE MOCK-UPS SHALL BE DETERMINED BY THE HOME.

FINISH / MATERIAL / PRODUCT SCHEDULE

REFERENCE	PRODUCT	MANUFACTURER	TYPE	COLOUR	COMMENTS
CG1	CORNER GUARD	CONSTRUCTION SPECIALTIES - ACROVYN	MODEL: SM-20N	FULL COLOUR RANGE ACROVYN	COLOUR TO BE VERIFIED BY ARCHIT
ET1	EDGE TRIM FOR WALL PROTECTION	ALTRO	G833	FULL COLOUR RANGE PVCU	COLOUR TO BE VERIFIED BY ARCHIT
WP1	WALL PROTECTION	ALTRO	WHITEROCK SATINS	FULL COLOUR RANGE	COLOUR TO BE VERIFIED BY ARCHIT
WP2	WALL PROTECTION	CONSTRUCTION SPECIALTIES - ACROVYN	0.06"(1.52MM) THICK ACROVYN WALL COVERING	FULL COLOUR RANGE	COLOUR TO BE VERIFIED BY ARCHIT
HR1	HANDRAIL	CONSTRUCTION SPECIALTIES - ACROVYN	MODEL: P-RAN WITH INTERNATIONAL OFFSET HANDRAIL	FULL COLOUR RANGE CHAMELEON SIMULATED WOOD HANDRAIL + S/S MOUNTING BRACKET	COLOUR TO BE VERIFIED BY ARCHIT MOUNT HEIGHT TO MATCH EXISTING COMPLETE WITH PREFABRICATED C PREDRILL FOR MOUNTING HARDWA
CR1	CRASHRAIL	CONSTRUCTION SPECIALTIES - STAINLESS STEEL	MODEL: ECR-32S	STAINLESS STEEL	-UPPER S/S CRASH RAIL MOUNT ±13 -LOWER S/S CRASH RAIL MOUNT AB COMPLETE WITH PREFABRICATED C PREDRILL FOR MOUNTING HARDWA

ITECT.
ITECT.
ITECT.

ITECT

ITECT. NG WOOD HANDRAIL CORNERS AND END RETURNS, ARE BY C/S GROUP.

1321 MM ABOVE FINISHED FLOOR. BOVE TOP OF PROPOSED COVE BASE. CORNERS AND END RETURNS, ARE BY C/S GROUP.

Montgomery Sisam Architects Inc.

197 Spadina Avenue, Toronto, Ontario M5T 2C8 montgomerysisam.com Tel 416.364.8079 Fax 416.364 7723

MontgomerySisam

4	2022-05-19	ISSUED FOR TENDER	MSA
1	2019-12-19	ISSUED FOR CONSTRUCTION	MSA
#	Date:	Revision:	By
revi	sions		

All drawing and specifications are the property of the architect. The contractor shall verify all dimensions and information on site and report any discrepancy to architect before proceeding.

INTERIOR HANDRAIL REPLACEMENT


3197 LAKESHORE BLVD. W., ETOBICOKE

GENERAL INFORMATION

scale:	As indicated
drawn by:	MY
reviewed by:	AR
job number:	21508.F03
plot date:	2019-12-19

A0.01


SYMBOL LEGEND




ABBREVIATION SCHEDULE

AD3 B.S.M. CG CH CJ CMU CONC CO CT CR COVE C/W DEMO. DU DIA. ELEV EPTW EA FA FEC FD FIX FIN FLR FRA GALV GB GIF GL GWB HC H.D. HIM HIM HIM HIM	COAT HOOK CONTROL JOINT CONCRETE MASONRY UNIT CONCRETE CLEAN OUT CERAMIC TILE CLOSET RAIL COVE/INTEGRAL BASE COMPLETED WITH DEMOLISHED DUPLEX RECEPTACLE PLATE DIAMETER ELEVATION EPOXY PAINT EXISTING WALL BOARD FIRE ALARM DEVICE FIRE EXTINGUISHER CABINET FIRE ALARM DEVICE FIRE EXTINGUISHER CABINET FIRE DAMPER FIXED FINISH FLOOR FIRE RESISTANT RATING GAUGE GALVANIZED GRAB BAR GROUND FAULT INTERRUPTER GLASS GYPSUM WALL BOARD HOLLOW CORE HANDRAIL DIMENSION HOLLOW INSULATED METAL	MG MTL N/A NC N.I.C. NTS O.C. O.F. O/H PWD.C. PLAM ± PLY PS PT PTD QU RB RCP R.O. RSF SF SIM S.M. S/S STL STN SV TEMP T TBC TERR T.O. TYP U/S U.N.O. VB	NOT TO SCALE ON CENTRE OUTSIDE FACE OVER HEAD POWDER COATED PLASTIC LAMINATE PLUS/MINUS PLYWOOD PULL STATION PAINT PAPER TOWEL DISPENSER QUAD RECEPTACLE PLATE RESILIENT BASE REFLECTED CEILING PLAN ROUGH OPENING RESILIENT SHEET FLOORING SAFETY FLOORING SIMILAR SITE MEASUREMENT STAINLESS STEEL STEEL STONE SHEET VINYL TEMPORARY THERMOSTAT TO BE CONFIRMED TERRAZZO TOP OF TYPICAL UNDERSIDE OF UNLESS NOTED OTHERWISE VAPOUR BARRIER
HM HIM HT	HOLLOW METAL HOLLOW INSULATED METAL HEIGHT	U/S U.N.O. VB	UNDERSIDE OF UNLESS NOTED OTHERWISE VAPOUR BARRIER
INT L.L. MAT'L	INTERIOR LOOSE LINTEL	VCT V.I.F.	VINYL COMPOSITION TILE VERIFY IN FIELD VAPOUR RETARDER WOOD
MAX MIN M.I.		WF	WOOD WINDOW FILM WALL PROTECTION
MIR	MIRROR	W/	WITH


								197 Spadina Avenu	y Sisam Architects Inc. ^a , Toronto, Ontario M5T 2C8
IL REFERENCE	A	GRID LINE	Room name	ROOM NAME & NUMBER TAG	3	0	EMERGENCY EYE WASH STATION	- ·	om Tel 416.364.8079 Fox 416.364.7723 SomerySisam
TING AREA TO NIN AS-IS		KEYNOTES	FHC	FIRE HOSE CAE	BINET	F	FIRE ALARM MANUAL PULL STATION		
). CRASH RAIL LL PROTECTION	1200	DEMO. WALL PROTECTION	1200	DIMENSION (TA AND DOOR OP	KEN FROM WALL ENING)	GFCI	DUPLEX RECEPTACLE GFCI OUTLET, WALL MOUNTED		
CRASH RAIL LL PROTECTION	1200	NEW WALL PROTECTION	1200 H.D.	DIMENSION OF	HANDRAIL	\oplus	DUPLEX RECEPTACLE OUTLET, WALL MOUNTED		
ORNER ANDRAIL/CRASH RAIL		90° CORNER OF HANDRAIL/CRASH RAIL	1200 S.M.	DIMENSION OF	SITE MEASUREMEN	NT			
	DEMOLITIO	N NOTES			CONSTR		NOTES		
DO1	REMOVE EXISTING CF	RASH RAIL ASSEMBLY - REMOVE FRO	DM SITE.	01	INSTALL NEW C	RASH RAIL ASSEM	BLY.		ISSUED FOR TENDER MSA ISSUED FOR CONSTRUCTION MSA
D02	REMOVE EXISTING CO OR REMOVAL.	DRNER GUARDS & COORDINATE W/ E	3.S.M. FOR STORAGE	02	(MODIFY & MAK	E GOOD IF REQUIR	R RE-INSTATE EXISTING CORNER GUARDS	# Date: revisions	Revision: E
D03	DEMOLISH AND REMC	OVE EXISTING RUBBER BASE & REMO	OVE FROM SITE.		RESERVED.	ED WITH TOP OF W	ALL BASE.		
D04	TEMPORARY REMOVE COORDINATE W/ B.S.M	E EXISTING EMERGENCY EYE WASH M. FOR STORAGE.	STATION &	03 04		STING EMERGENC	Y EYE WASH STATION.		
D05	TEMPORARY REMOVE COORDINATE W/ B.S.M	E EXISTING DUPLEX WALL-MOUNTED M. FOR STORAGE.	OUTLET PANEL &	05	REINSTATE EXI	STING DUPLEX WA	LL-MOUNTED OUTLET PANEL.		
DOG		E EXISTING PUSH BUTTON & CARD RI ORPORATION SECURITY. COORDINA		06	REINSTATE EXI	STING PUSH BUTT	ON & CARD READER.		
(D07)	MANUAL PULL STATIC	NECT FIRE ALARM, REMOVE EXISTIN NN & PROGRAM PANEL TO ENSURE N RDINATE W/ B.S.M. FOR STORAGE.		07			AS REQUIRED TO ENSURE NO TROUBLE IN 3 FIRE ALARM MANUAL PULL STATION.		
DO8	TEMPORARY REMOVE FOR STORAGE.	E EXISTING MAP ON THE WALL. COOP	RDINATE W/ B.S.M.	08	REINSTATE EXIS	STING MAP ON THE	E WALL AFTER NEW WALL PROTECTION	of the archite dimensions of	and specifications are the property ct. The contractor shall verify all and information on site and report ncy to architect before proceeding.
D09	TEMPORARY REMOVE W/ B.S.M. FOR STORA	E EXISTING ELEVATOR CONTROL PAN GE.	NEL. COORDINATE	09	REINSTATE EXIS PROTECTION IN		CONTROL PANEL AFTER NEW WALL		
D10	DEMOLISH AND REMC	VE EXISTING WALL PROTECTION - R	EMOVE FROM SITE.	10	INSTALL NEW W	ALL PROTECTION		HANDRAI	L REPLACEMENT
	CUT & REMOVE EXIST CONSTRUCTION.	ING GWB. AS REQUIRED TO FACILIT	ATE PROPOSED				ORATED GWB. TO MATCH EXISTING AS SED CONSTRUCTION.		RE BLVD. W., ETOBICOKE
D12		CE EXISTING 25 X100 CONTINUOUS W	OOD BLOCKING IF		RESERVED.				
D13		HELF & FASTENERS OF THE BANKING	WINDOW, PATCH &		PLAM FINISHED	PLY BOARD OF TH PORT U/S - MATCH	IE BANKING WINDOW, SECURELY FASTENED NEW HANDRAIL .	scale:	1 : 100
D14		OOD HANDRAIL ASSEMBLY - REMOVE	E FROM SITE.			ANDRAIL ASSEMBI		drawn by: reviewed by:	MY AR
D15		E EXISTING MAILBOX. COORDINATE V	V/ B.S.M. FOR		REINSTATE EXI	STING MAILBOX AF	TER HANDRAIL REPLACEMENT.	job number:	21508.F03
D16	STORAGE. TEMPORARY REMOVE STORAGE.	E EXISTING PUSH BUTTON. COORDIN	ATE W/ B.S.M. FOR		REINSTATE EXI REPLACEMENT.		ON AFTER WALL PROTECTION	plot date: 	A0.02






drawing number:

A0.04






AREA OF WORK PLAN - LEVEL 1 - ALTERNATIVE PRICE #1 A0.05 1 : 250







revi	sions		
#	Date:	Revision:	By
2	2019-08-28	ISSUED FOR TENDER	MSA
4	2022-05-19	ISSUED FOR TENDER	MSA



INTERIOR HANDRAIL REPLACEMENT

3197 LAKESHORE BLVD. W., ETOBICOKE

AREA OF WORK PLAN -LEVEL 1 - ALTERNATIVE PRICE #1

scale:	1 : 250
drawn by:	MY
reviewed by:	AR
job number:	21508.F03
plot date:	2019-12-19

A0.05


drawing number:

INFANTS PLAYROOM G19 W.R. G18 MJ REST ROOM G20 CORRIDOR G24 W.R. G41 П PRESCHOOL PLAYROOM G40

Δ-


W.R.

G17









revis	ions		
#	Date:	Revision:	Ву
2	2019-08-28	ISSUED FOR TENDER	MSA
4	2022-05-19	ISSUED FOR TENDER	MSA



INTERIOR HANDRAIL REPLACEMENT

3197 LAKESHORE BLVD. W., ETOBICOKE

AREA OF WORK PLAN -LEVEL 1 - ALTERNATIVE PRICE #2

scale:	1 : 250
drawn by:	MY
reviewed by:	AR
job number:	21508.F03
plot date:	2019-12-19

A0.06

drawing number:

W.R. G17 INFANTS PLAYROOM G19 W.R. G18 M REST ROOM G20 CELECT TEL C22 C23 CORRIDOR G24 W.R. G41 PRESCHOOL PLAYROOM G40

















EXISTING CONDITION PHOTO - ECP03





EXISTING CONDITION PHOTO - ECP08



EXISTING CONDITION PHOTO - ECP02

EXISTING CONDITION PHOTO - ECP07



EXISTING CONDITION PHOTO - ECP01



EXISTING CONDITION PHOTO - ECP06



EXISTING CONDITION PHOTO - ECP17



EXISTING CONDITION PHOTO - ECP20



EXISTING CONDITION PHOTO - ECP16

EXISTING CONDITION PHOTO - ECP19



EXISTING CONDITION PHOTO - ECP15





EXISTING CONDITION PHOTO - ECP14



EXISTING CONDITION PHOTO - ECP13



EXISTING CONDITION PHOTO - ECP05

EXISTING CONDITION PHOTO - ECP12



EXISTING CONDITION PHOTO - ECP18



EXISTING CONDITION PHOTO - ECP21

Montgomery Sisam Architects Inc.

197 Spadina Avenue, Toronto, Ontario M5T 2C8 montgomerysisam.com Tel 416.364.8079 Fax 416.364.7723

MontgomerySisam

2 2019-08-28 ISSUED FOR TENDER # Date: Revision: MSA By revisions

> All drawing and specifications are the property of the architect. The contractor shall verify all dimensions and information on site and report any discrepancy to architect before proceeding.

INTERIOR HANDRAIL REPLACEMENT

3197 LAKESHORE BLVD. W., ETOBICOKE

EXISTING CONDITIONS PHOTOS (ECP) - LEVEL 1

cale:	
lrawn by:	MY
eviewed by:	AR
ob number:	21508.F
lot date:	2019-12

drawing number


.F03 12-19

A0.08











EXISTING CONDITION PHOTO - ECP02



EXISTING CONDITION PHOTO - ECP01









EXISTING CONDITION PHOTO - ECP12



EXISTING CONDITION PHOTO - ECP07




EXISTING CONDITION PHOTO - ECP06



EXISTING CONDITION PHOTO - ECP05



PHOTO - ECP11



EXISTING CONDITION PHOTO - ECP10

EXISTING CONDITION PHOTO - ECP04



EXISTING CONDITION PHOTO - ECP09

EXISTING CONDITION PHOTO - ECP13

Montgomery Sisam Architects Inc.

. 197 Spadina Avenue, Toronto, Ontario M5T 2C8 montgomerysisam.com Tel 416.364.8079 Fax 416.364.7723

MontgomerySisam

 4
 2022-05-19
 ISSUED FOR TENDER
 MSA

 1
 2019-12-19
 ISSUED FOR CONSTRUCTION
 MSA
 # Date: By Revis revisions

All drawing and specifications are the property of the architect. The contractor shall verify all dimensions and information on site and report any discrepancy to architect before proceeding.

INTERIOR HANDRAIL REPLACEMENT

3197 LAKESHORE BLVD. W., ETOBICOKE


EXISTING CONDITIONS PHOTOS (ECP) - LEVEL 2


scale:
drawn by:
reviewed by:
job number:
plot date:

MY AR 21508.F03 2019-12-19

drawing number:

A0.09








DEMO. PLAN -LEVEL 1 (CENTRE AREA) A1.02 1:100

DEMOLITION NOTES INCLUSIVE










2022-07-12 2:43:18 PM



3 WOOD HANDRAIL AT BRICK@BRICK-DEMO. SECTION A2.01 1:10

2 WOOD HANDRAIL AT BRICK@CONC.-DEMO. SECTION A2.01 1 : 10



Montgomery Sisam Architects Inc.

197 Spadina Avenue, Toronto, Ontario M5T 2C8 montgomerysisam.com Tel 416.364.8079 Fax 416.364.7723

MontgomerySisam

4	2022-05-19	ISSUED FOR TENDER	MSA
2	2019-08-28	ISSUED FOR TENDER	MSA
#	Date:	Revision:	By
revi	sions		

All drawing and specifications are the property of the architect. The contractor shall verify all dimensions and information on site and report any discrepancy to architect before proceeding.


INTERIOR HANDRAIL REPLACEMENT

3197 LAKESHORE BLVD. W., ETOBICOKE

TYP. EXISTING WOOD HANDRAIL DEMO. SECTIONS

scale:	1 : 10	
drawn by:	MY	
reviewed by:	AR	
job number:	21508.F03	
plot date:	2019-12-19	

A2.01




A2.02 1:10

A2.02 1:10


2022-07-12 2:43:19 PM

A2.02 1:10

	Montgomery Sisam Architects Inc. 197 Spadina Avenue, Toronto, Ontario M5T 2C8 montgomerysisam.com Tel 416.364.8079 Fax 416.364.7723
	MontgomerySisam
EXISTING GWB. EXISTING MOUNTING BRACKETS ON GWB. TO BE REMOVED EXISTING WOOD HANDRAIL TO BE REMOVED	
CUT & REPLACE EXISTING GWB. AS REQUIRED TO FACILITATE PROPOSED CONSTRUCTION PAINTED TO MATCH EXISTING COLOUR	4 2022-05-19 ISSUED FOR TENDER MSA 1 2019-12-19 ISSUED FOR CONSTRUCTION MSA # Date: Revision: By revisions
EXISTING RUBBER BASE TO BE REMOVED	
	All drawing and specifications are the property of the architect. The contractor shall verify all dimensions and information on site and report any discrepancy to architect before proceeding.
ECTION	INTERIOR HANDRAIL REPLACEMENT 3197 LAKESHORE BLVD. W., ETOBICOKE TYP. EXISTING WOOD HANDRAIL DEMO. SECTIONS scale: 1:10 drawn by: MY reviewed by: AR job number: 21508.F03 plot date: 2019-12-19 drawing number: A2.02



WOOD HANDRAIL AT GWB. LAMIN. ON CONC. - DEMO. SECTION 2 A2.03 1 : 10



Montgomery Sisam Architects Inc.

197 Spadina Avenue, Toronto, Ontario M5T 2C8 montgomerysisam.com Tel 416.364.8079 Fax 416.364.7723

MontgomerySisam

4 2022-05-19 ISSUED FOR TENDER MSA 1 2019-12-19 ISSUED FOR CONSTRUCTION MSA # Date: Revisio By revisions

All drawing and specifications are the property of the architect. The contractor shall verify all dimensions and information on site and report any discrepancy to architect before proceeding.


INTERIOR HANDRAIL REPLACEMENT

3197 LAKESHORE BLVD. W., ETOBICOKE

TYP. EXISTING WOOD HANDRAIL DEMO. SECTIONS

scale:	1 : 10
drawn by:	MY
reviewed by:	AR
job number:	21508.F03
plot date:	2019-12-19

A2.03







Montgomery Sisam Architects Inc.

197 Spadina Avenue, Toronto, Ontario M5T 2C8 montgomerysisam.com Tel 416.364.8079 Fax 416.364.7723

MontgomerySisam

 4
 2022-05-19
 ISSUED FOR TENDER
 MSA

 1
 2019-12-19
 ISSUED FOR CONSTRUCTION
 MSA

 #
 Date:
 Revision:
 By

 revisions

All drawing and specifications are the property of the architect. The contractor shall verify all dimensions and information on site and report any discrepancy to architect before proceeding.

INTERIOR HANDRAIL REPLACEMENT


3197 LAKESHORE BLVD. W., ETOBICOKE

TYP. EXISTING WOOD HANDRAIL DEMO. SECTIONS

scale:	1 : 10
drawn by:	MY
reviewed by:	AR
job number:	21508.F03
plot date:	2019-12-19

drawing number:

A2.04






1 CRASH RAIL AT DRYWALL ON CONCRETE A2.05 1 : 10

CRASH RAIL AT DRYWALL

3

A2.05/1:10



Montgomery Sisam Architects Inc.

197 Spadina Avenue, Toronto, Ontario M5T 2C8 montgomerysisam.com Tel 416.364.8079 Fax 416.364.7723

MontgomerySisam

 2
 2019-08-28
 ISSUED FOR TENDER
 MSA

 #
 Date:
 Revision:
 By

All drawing and specifications are the property of the architect. The contractor shall verify all dimensions and information on site and report any discrepancy to architect before proceeding.


INTERIOR HANDRAIL REPLACEMENT


3197 LAKESHORE BLVD. W., ETOBICOKE


TYP. EXISTING CRASH RAIL DEMO. DETAILS


scale:	1 : 10
drawn by:	MY
reviewed by:	AR
job number:	21508.F03
plot date:	2019-12-19












Montgomery Sisam Architects Inc.

197 Spadina Avenue, Toronto, Ontario M5T 2C8 montgomerysisam.com Tel 416.364.8079 Fax 416.364.7723

MontgomerySisam



4	2022-05-19	ISSUED FOR TENDER	MSA
1	2019-12-19	ISSUED FOR CONSTRUCTION	MSA
#	Date:	Revision:	By

All drawing and specifications are the property of the architect. The contractor shall verify all dimensions and information on site and report any discrepancy to architect before proceedir

INTERIOR HANDRAIL REPLACEMENT


3197 LAKESHORE BLVD. W., ETOBICOKE


PROPOSED PLAN_LEVEL 2 (CENTRE AREA)

scale:	1 : 100	
drawn by:	MY	
reviewed by:	AR	
job number:	21508.F03	
plot date:	2019-12-19	

drawing number:

A3.04






 $\widehat{2}$ PROPOSED HANDRAIL AT DRYWALL DETAIL A4.01 1:2



Montgomery Sisam Architects Inc.

197 Spadina Avenue, Toronto, Ontario M5T 2C8 montgomerysisam.com Tel 416.364.8079 Fax 416.364.7723

MontgomerySisam



MSA

By

All drawing and specifications are the property of the architect. The contractor shall verify all dimensions and information on site and report any discrepancy to architect before proceeding.


HANDRAIL REPLACEMENT

3197 LAKESHORE BLVD. W., ETOBICOKE

TYPICAL PROPOSED HANDRAIL DETAILS

scale:	1:2
drawn by:	MY
reviewed by:	AR
job number:	21508.F03
plot date:	2019-12-19

A4.01



Montgomery Sisam Architects Inc.

197 Spadina Avenue, Toronto, Ontario M5T 2C8 montgomerysisam.com Tel 416.364.8079 Fax 416.364.7723

MontgomerySisam



EXISTING BRICK VENEER
 4
 2022-05-19
 ISSUED FOR TENDER
 MSA

 #
 Date:
 Revision:
 By

 revisions
 Provision
 Provision
 Provision

All drawing and specifications are the property of the architect. The contractor shall verify all dimensions and information on site and report any discrepancy to architect before proceeding.

INTERIOR HANDRAIL REPLACEMENT

3197 LAKESHORE BLVD. W., ETOBICOKE


TYPICAL PROPOSED HANDRAIL DETAILS


scale:	1:2
drawn by:	SK
reviewed by:	AR
job number:	21508.F03
plot date:	2019-12-19


A4.02












197 Spadina Avenue, Toronto, Ontario M5T 2C8 montgomerysisam.com Tel 416.364.8079 Fax 416.364.7723

MontgomerySisam



1	2019-12-19	ISSUED FOR CONSTRUCTION	MSA
#	Date:	Revision:	By
evi	sions		

All drawing and specifications are the property of the architect. The contractor shall verify all dimensions and information on site and report any discrepancy to architect before proceeding.


INTERIOR HANDRAIL REPLACEMENT

3197 LAKESHORE BLVD. W., ETOBICOKE


TYP. NEW HANDRAIL DETAILS

scale:	As indicated
drawn by:	MY
reviewed by:	AR
job number:	21508.F03
plot date:	2019-12-19










Montgomery Sisam Architects Inc.



Montgomery Sisam Architects Inc.

197 Spadina Avenue, Toronto, Ontario M5T 2C8 montgomerysisam.com Tel 416.364.8079 Fax 416.364.7723

MontgomerySisam

revisions				
#	Date:	Revision:	By	
2	2019-08-28	ISSUED FOR TENDER	MSA	
4	2022-05-19	ISSUED FOR TENDER	MSA	

All drawing and specifications are the property of the architect. The contractor shall verify all dimensions and information on site and report any discrepancy to architect before proceeding.


INTERIOR HANDRAIL REPLACEMENT

3197 LAKESHORE BLVD. W., ETOBICOKE

NEW HANDTAIL OVER GLASS BLOCK WALL DETAILS

scale:	1:2
drawn by:	MY
reviewed by:	AR
job number:	21508.F03
plot date:	2019-12-19

A4.05




A4.06 1:2

2022-07-12 2:43:26 PM


	197 Spadina Avenue	y Sisam Architects Ind a, Toronto, Ontario M5T 2C8 om Tel 416.364.8079 Fax 416.364	
	Montg	gomerySisa	am
(ISTING GWB. WALL SSEMBLY TO REMAIN		, ,	
TRO SEALANT A802 DLOUR TO MATCH FIELD OF ALL PVC TRIM			
/CU EDGE TRIM DLOUR TO BE SELECTED FULL NGE & VERIFIED BY RCHITECT			
DOUBLE SIDED PE			
ROVIDE MIN. 20 GA. DRIZONTAL STEEL TUD AND TRAPPING & REQUIRED			
KISTING GWB. WALL SEMBLY - CUT & EPLACE EXISTING WB. WITH NEW GWB. S REQUIRED TO CILITATE PROPOSED DNSTRUCTION, NINTED TO MATCH	4 2022-05-19 2 2019-08-28 # Date: revisions		MSA MSA By
(ISTING COLOUR			
DOUBLE SIDED PE			
ROVIDE MIN. 20 GA. DRIZONTAL STEEL 'UD AND RAPPING & REQUIRED	of the archite dimensions a	nd specifications are the property ct. The contractor shall verify all nd information on site and report roy to architect before proceeding.	
	INTERIOR HANDRAII	REPLACEMENT	
	3197 LAKESHOF	RE BLVD. W., ETOBICOKE	
	TYP. NEW DETAILS	CRASH RAIL	
	scale:	As indicated	
	drawn by: reviewed by:	MY AR	
	job number:	21508.F03	
	plot date:	2019-12-19	





2 NEW CRASH RAIL AT GWB. UNDER GLASS CABINET CALL A4.07 1:2

		197 Spadina Avenue,	Sisam Architects Inc. Toronto, Ontario M5T 2C8 n Tel 416.364.8079 Fax 416.364.7723	3
	EXISTING GWB. WALL ASSEMBLY TO REMAIN	Montg	omerySisan	n
	ALTRO SEALANT A802 COLOUR TO MATCH FIELD OF WALL PROTECTION			
	1" DOUBLE SIDED TAPE PROVIDE MIN. 20 GA. HORIZONTAL STEEL STUD AND STRAPPING AS REQUIRED			
	EXISTING GWB. WALL ASSEMBLY - CUT & REPLACE EXISTING GWB. WITH NEW GWB. AS REQUIRED TO FACILITATE PROPOSED CONSTRUCTION, PAINTED TO MATCH EXISTING COLOUR	4 2022-05-19 2 2019-08-28 # Date: revisions		ISA ISA By
	AltroFix ADHESIVE 1" DOUBLE SIDED TAPE			
	PROVIDE MIN. 20 GA. HORIZONTAL STEEL STUD AND STRAPPING AS REQUIRED	of the architect dimensions an	d specifications are the property . The contractor shall verify all d information on site and report y to architect before proceeding.	
		3197 LAKESHORE	REPLACEMENT E BLVD. W., ETOBICOKE SH RAIL UNDER BINET DETAILS	
OUT		scale: drawn by: reviewed by: job number: plot date: drawing number:	As indicated MY AR 21508.F03 2019-12-19	
			A4.07	



2 NEW WALL PROTECTION - BACK OF HOUSE - LEVEL 1 CALLOUT A4.08/1:2

Montgomery Sisam Architects Inc. 197 Spadina Avenue, Toronto, Ontario M5T 2C8 montgomerysisam.com Tel 416.364.8079 Fax 416.364.7723 EXISTING GWB. WALL ASSEMBLY TO REMAIN MontgomerySisam ALTRO SEALANT A802 COLOUR TO MATCH FIELD OF PVCU EDGE TRIM COLOUR TO BE SELECTED FULL RANGE & VERIFIED BY ARCHITECT 1" DOUBLE SIDED PROVIDE MIN. 20 GA. HORIZONTAL STEEL STUD AND STRAPPING AS REQUIRED EXISTING GWB. WALL ASSEMBLY - CUT & REPLACE EXISTING GWB. WITH NEW GWB. AS REQUIRED TO FACILITATE PROPOSED CONSTRUCTION, PAINTED TO MATCH 4 2022-05-19 ISSUED FOR TENDER EXISTING COLOUR MSA 2 2019-08-28 ISSUED FOR TENDER MSA # Date: By Revisi revisions AltroFix ADHESIVE 1" DOUBLE SIDED PROVIDE MIN. 20 GA. HORIZONTAL STEEL STUD AND STRAPPING All drawing and specifications are the property AS REQUIRED of the architect. The contractor shall verify all dimensions and information on site and report any discrepancy to architect before proceeding. INTERIOR HANDRAIL REPLACEMENT 3197 LAKESHORE BLVD. W., ETOBICOKE TYP. NEW WALL PROTECTION

scale:	As indicated
drawn by:	MY
reviewed by:	AR
job number:	21508.F03
plot date:	2019-12-19

DETAILS LEVEL 1

drawing number:

A4.08



EXISTING CONDITION PHOTO - ECP01

EXISTING CONDITION PHOTO - ECP02



FLOOR

TO FINISH F

900 100

EXISTING CONDITION PHOTO - ECP03

NEW WALL PROTCTION (WP2) ON SECOND FLOOR CORRIDOR CONSTRUCTION NOTE:

ECP01: TYPICAL NEW WALL PROTECTION AS PER DRAWING 1/A4.09.

ECP02: TYPICAL NEW WALL PROTECTION WITH WALL-MOUNTED OUTLET PANEL:

- TEMPORARY REMOVE EXISTING DUPLEX WALL-MOUNTED OUTLET PANEL & COORDINATE W/ B.S.M. FOR STORAGE. - INSTALL NEW WALL PROTECTION (WP2) AS PER DRAWING 1/A4.09.
- INSTALL NEW CRASH RAIL (CR2);
- REINSTATE EXISTING DUPLEX WALL-MOUNTED OUTLET PANEL.

ECP03: TYPICAL NEW WALL PROTECTION @ EXISTING FHC:

- CUT & FIT NEW WALL PROTECTION (WP2) TO THE EXISTING FHC; - INSTALL NEW WALL PROTECTION (WP2) AS PER DRAWING 1/A4.09.

ECP04: NO NEW WALL PROTECTION (WP2) ON EXISTING WALL PAPER:

ECP05: NO NEW WALL PROTECTION (WP2) ON EXISTING MILLWORKS.

ECP06: NO NEW WALL PROTECTION (WP2) ON EXISTING GLASS GLAZING & METAL FRAMES.



EXISTING CONDITION PHOTO - ECP04



PHOTO - ECP05









EXISTING CONDITION

PHOTO - ECP06






EXISTING GWB.	Montgomery Sisam Architects Inc. 197 Spadina Avenue, Toronto, Ontario M5T 2C8 montgomerysisam.com Tel 416.364.8079 Fax 416.364.7723
SEALANT COLOUR TO MATCH FIELD OF WAINSCOT TRIM	MontgomerySisam
KEEP EXISTING 100 WIDE CONT. 20 GA. GALV. STEEL BRACING FOR HANDRAIL SUPPORT PROVIDE ADDITIONAL BLOCKING IF REQUIRED V.I.F.	
1" DOUBLE SIDED TAPE	4 2022-05-19 ISSUED FOR TENDER MSA
CUT & REPLACE EXISTING GWB. AS REQUIRED TO FACILITATE PROPOSED CONSTRUCTION PAINTED TO MATCH EXISTING COLOUR	1 2019-12-19 ISSUED FOR TENDER MSA # Date: Revision: By revisions
	All drawing and specifications are the property of the architect. The contractor shall verify all dimensions and information on site and report any discrepancy to architect before proceeding.
	HANDRAIL REPLACEMENT 3197 LAKESHORE BLVD. W., ETOBICOKE
	TYP. NEW WALL PROTECTION DETAILS_LEVEL 2
	scale:1 : 2drawn by:MYreviewed by:ARjob number:21508.F03plot date:2019-12-19
<u>N</u>	drawing number: A4.09




EXISTING CONDITION PHOTO - ECP01


NEW WALL PROTCTION (WP2) ON KNEE WALL @ TV LOUNGE_SECOND FLOOR CONSTRUCTION NOTE:

- TEMPORARY REMOVE EXISTING DUPLEX WALL-MOUNTED OUTLET PANEL & COORDINATE W/ B.S.M. FOR STORAGE;
 REMOVE EXISITNG CORNER GUARDS;
 INSTALL NEW WALL PROTECTION (WP2) AS PER DRAWING 1/A4.10;
 INSTALL NEW CRASH RAIL (CR2);
 REINSTATE EXISTING DUPLEX WALL-MOUNTED OUTLET PANEL;
 INSTALL NEW CORNER GUARDS (CG1) AT ORIGINAL LOCATION.





	Montgomery Sisam Architects Inc.
	197 Spadina Avenue, Toronto, Ontario M5T 2C8 montgomerysisam.com Tel 416.364.8079 Fax 416.364.7723
TOP SURFACE OF EXISTING KNEE WALL	
EXISTING GWB.	
1" DOUBLE SIDED TAPE	
SEALANT COLOUR TO MATCH EXISTING CRASH RAIL	4 2022-05-19 ISSUED FOR TENDER MSA 1 2019-12-19 ISSUED FOR CONSTRUCTION MSA # Date: Revision: By revisions
	All drawing and specifications are the property of the architect. The contractor shall verify all dimensions and information on site and report any discrepancy to architect before proceeding. INTERIOR HANDRAIL REPLACEMENT
	3197 LAKESHORE BLVD. W., ETOBICOKE TYP. NEW WALL PROTECTION DETAILS_LEVEL 2
-	scale: 1 : 2 drawn by: MY reviewed by: AR job number: 21508.F03 plot date: 2019-12-19
	drawing number: A4.10



2 TYP. 02 S/S CORNER GUARD AT BACK OF HOUSE CORRIDOR - G48 - LEVEL 1 A4.11 1:2

TYP. 01 S/S CORNER GUARD AT BACK OF HOUSE CORRIDOR - G48 - LEVEL 1 1 A4.11 1:2

Montgomery Sisam Architects Inc.

197 Spadina Avenue, Toronto, Ontario M5T 2C8 montgomerysisam.com Tel 416.364.8079 Fax 416.364.7723

MontgomerySisam

REINSTATE EXISTING OR NEW 48"X2"X2" - 90° STAINLESS STEEL CORNER GUARD

COUNTERSINK S/S FASTENER TBC BY MISC. METALS 05 50 00

INTERIOR SEALANT, COLOUR TO BE CONFIRMED BY ARCHITECT

- NEW WALL PROTECTION(WP1)

CUT & REPLACE EXISTING GWB. AS REQUIRED PAINTED TO MATCH EXISTING COLOUR

REPLACE EXISTING WOOD **BLOCKING IF DETERIORATED** V.I.F.

EXISTING CONC. OR CONC. BLOCK WALL TO REMAIN

4	2022-05-19	ISSUED FOR TENDER	MSA	
2	2019-08-28	ISSUED FOR TENDER	MSA	
#	Date:	Revision:	By	
revisions				

All drawing and specifications are the property of the architect. The contractor shall verify all dimensions and information on site and report any discrepancy to architect before proceeding.

INTERIOR HANDRAIL REPLACEMENT

3197 LAKESHORE BLVD. W., ETOBICOKE

TYP. CORNER GUARD PLAN DETAILS

scale:	1:2	
drawn by:	MY	
reviewed by:	AR	
job number:	21508.F03	
plot date:	2019-12-19	

A4.11




EXISTING CONDITION PHOTO - ECP 01

210 -


EXISTING CONDITION PHOTO - ECP 02

NOTE:

- 1. ALL CORNER GUARDS ON THE SECOND FLOOR -LOBBY 201, CORRIDOR 202 / 264 AND TV LOUNGE 241 / 280 SHOULD BE REPLACE WITH NEW.
- 2. ALL NEW CORNER GUARDS SHOULD BE BOTTOM ALIGNED WITH THE TOP OF NEW COVE BASE. 3. NEW CORNER GUARD SHOULD BE INSTALLED AS PER ORIGINAL LOCATION CUT, MODIFIED CORNER GUARDS AND SUBSTRATE AS REQUIRED.







07-12 2:43:34 PM

Montgomery Sisam Architects Inc.

197 Spadina Avenue, Toronto, Ontario M5T 2C8 montgomerysisam.com Tel 416.364.8079 Fax 416.364.7723

MontgomerySisam

4	2022-05-19	ISSUED FOR TENDER	MSA
2	2019-08-28	ISSUED FOR TENDER	MSA
#	Date:	Revision:	By
revi	sions		

All drawing and specifications are the property of the architect. The contractor shall verify all dimensions and information on site and report any discrepancy to architect before proceeding.

INTERIOR HANDRAIL REPLACEMENT

3197 LAKESHORE BLVD. W., ETOBICOKE

NEW HANDRAIL LAYOUT DIAGRAM

scale:	1:3
drawn by:	MY
reviewed by:	AR
job number:	21508.F03
plot date:	2019-12-19

A5.01