

**DESIGNATED SUBSTANCES and HAZARDOUS
MATERIALS SURVEY**



**LONG TERM CARE HOMES & SERVICES
Bendale Acres
2920 Lawrence Avenue East
Toronto, Ontario**

Presented to:

Sara Reid

City of Toronto
Corporate Real Estate Management

Project Number: FE 23-12800

SEPTEMBER 1, 2023

EXECUTIVE SUMMARY

Fisher Engineering Limited was retained by the City of Toronto, Corporate Real Estate Management to conduct a reassessment survey for designated substances and hazardous materials in the Toronto Long Term Care Homes & Services building named Bendale Acres, located at 2920 Lawrence Avenue East in Toronto, Ontario.

The objective of the survey was to determine the condition of previously identified asbestos-containing materials (ACM), identify and assess the condition of designated substances and other hazardous materials, and, if necessary, provide recommendations to assist the City of Toronto in fulfilling requirements to achieve regulatory compliance, as set forth under the Ontario Occupational Health and Safety Act, and enforced by the Ontario Ministry of Labour regulations for designated substances; O. Reg. 490/09 – Designated Substances and O. Reg. 278/05 – Asbestos on Construction Projects and in Buildings and Repair Operations.

This document should be filed as an addendum to the original survey report, which was issued by Fisher Environmental Ltd. on April 14, 2015.

These Designated Substances and Hazardous Materials survey report is intended for management purposes only. It is not to be used to establish the presence of designated substances or hazardous materials in building materials prior to renovation or demolition activities. A pre-renovation/pre-demolition audit of the work area for designated substances and hazardous materials should be conducted prior to any work activities that may disturb building materials potentially containing designated materials or hazardous substances.

Renata Stec of Fisher Engineering Limited performed the fieldwork on May 18, 2023.

FINDINGS

The following presents a brief outline of findings within the facility. Refer to the main body and appendices of the report for specific details, quantities, conditions and locations of Designated Substances and Hazardous Materials within the facility.

Material	Findings
Asbestos	<p>Confirmed ACM were identified in the facility as follows:</p> <ul style="list-style-type: none">• Caulking – 0.5-5% Anthophyllite,• Exterior Panels – 25-50% Chrysotile & Crocidolite, and• Transite Panels (Penthouse) – 6-8% Chrysotile. <p>Assumed ACM were identified in the facility as follows:</p> <ul style="list-style-type: none">• Roofing Materials,• Caulking,• Ceiling Tile – one (1) variety;• Vinyl Floor Tile – one (1) variety; and

Material	Findings
	<ul style="list-style-type: none"> Vinyl Sheet Flooring – thirteen (13) varieties. All confirmed or assumed ACM were observed in GOOD condition.
Lead	Paint finishes were generally noted to be in GOOD condition throughout the Site. During the disturbance of any painted surfaces that contain lead, it is recommended that appropriate procedures and use of respirators be followed to protect workers.
Mercury	Mercury can be found in fluorescent light bulbs and building thermostats.
Silica	As the building is constructed of concrete block and brick, with concrete floors, silica is expected to be found within these components of the building.
Other Designated Substances	No evidence of Acrylonitrile, Arsenic, Benzene, Coke Oven Emissions, Ethylene Oxide, Isocyanates, and Vinyl Chloride was found during the building survey.
PCB	No PCB containing equipment with the potential exception of fluorescent lighting ballasts was observed.
UFFI	No UFFI containing insulation was observed on site.
Mould	During the visual inspection of the surveyed areas, visible mould growth and water staining on non-ACM fibreglass insulation were observed.

RECOMMENDATIONS

Fisher Engineering Limited would report any deficiencies and recommendations to the City of Toronto using a 2023 Reassessment Program Corrective Actions Reporting Form. On completion of the recommended actions, an Addendum is made to confirm completion of all corrective actions.

TABLE OF CONTENTS

EXECUTIVE SUMMARY	I
1. INTRODUCTION AND REGULATORY REQUIREMENTS	1
1.1 INTRODUCTION AND SCOPE	1
2. SURVEY METHODOLOGY.....	1
2.1 GENERAL APPROACH.....	1
2.2 SURVEY METHODOLOGY	1
3. FINDINGS AND RECOMMENDATIONS.....	2
3.1 ASBESTOS.....	2
3.1.1 Findings.....	2
3.1.2 Recommendations.....	3
3.2 LEAD.....	4
3.2.1 Findings.....	4
3.2.2 Recommendations.....	4
3.3 ACRYLONITRILE.....	5
3.3.1 Findings.....	5
3.3.2 Recommendations.....	5
3.4 ARSENIC.....	5
3.4.1 Findings.....	5
3.4.2 Recommendations.....	5
3.5 BENZENE.....	6
3.5.1 Findings.....	6
3.5.2 Recommendations.....	6
3.6 COKE OVEN EMISSIONS.....	6
3.6.1 Findings.....	6
3.6.2 Recommendations.....	6
3.7 ETHYLENE OXIDES	6
3.7.1 Findings.....	7
3.7.2 Recommendations.....	7
3.8 ISOCYANATES	7
3.8.1 Findings.....	7
3.8.2 Recommendations.....	7
3.9 MERCURY.....	7
3.9.1 Findings.....	7
3.9.2 Recommendations.....	8
3.10 SILICA.....	8
3.10.1 Findings.....	8
3.10.2 Recommendations.....	8
3.11 VINYL CHLORIDE.....	8
3.11.1 Findings.....	8
3.11.2 Recommendations.....	9
3.12 POLYCHLORINATED BIPHENYLS (PCBS).....	9
3.12.1 Findings.....	9
3.12.2 Recommendations.....	9
3.13 UREA FORMALDEHYDE FOAM INSULATION (UFFI).....	9
3.13.1 Findings.....	10

TABLE OF CONTENTS

3.13.2 Recommendations.....	10
3.14 MOULD.....	10
3.14.1 Findings.....	10
3.14.2 Recommendations.....	11
4. CORRECTIVE ACTIONS	11
5. STATEMENT OF LIMITATIONS	11
SIGN-OFF.....	12
APPENDIX I – DESIGNATED SUBSTANCES AND HAZARDOUS MATERIALS INVENTORY SHEET	
APPENDIX II – RESULTS OF BULK SAMPLE ANALYSIS	
APPENDIX III – SITE DRAWINGS	
APPENDIX IV – SITE PHOTOGRAPHS	
APPENDIX V – CORRECTIVE ACTIONS INSPECTION REPORT	

1. INTRODUCTION AND REGULATORY REQUIREMENTS

1.1 Introduction and Scope

Fisher Engineering Limited was retained by the City of Toronto, Corporate Real Estate Management to conduct a reassessment survey for designated substances and hazardous materials in the Toronto Long Term Care Homes & Services building named Bendale Acres, located at 2920 Lawrence Avenue East in Toronto, Ontario.

The objective of the survey was to determine the condition of previously identified asbestos-containing materials (ACM), identify and assess the condition of designated substances and other hazardous materials, and, if necessary, provide recommendations to assist the City of Toronto in fulfilling requirements to achieve regulatory compliance, as set forth under the Ontario Occupational Health and Safety Act, and enforced by the Ontario Ministry of Labour regulations for designated substances; O. Reg. 490/09 – Designated Substances and O. Reg. 278/05 – Asbestos on Construction Projects and in Buildings and Repair Operations.

This document should be filed as an addendum to the original survey, which was completed by Fisher Environmental Ltd. on April 14, 2015.

The Designated Substances and Hazardous Materials survey report is intended for management purposes only. It is not to be used to establish the presence of designated substances or hazardous materials in building materials prior to renovation or demolition activities. A pre-renovation/pre-demolition audit of the work area for designated substances and hazardous materials should be conducted prior to any work activities that may disturb building materials potentially containing designated materials or hazardous substances.

Renata Stec of Fisher Engineering Limited performed the fieldwork on May 18, 2023.

2. SURVEY METHODOLOGY

2.1 General Approach

To ensure familiarity with the building, the Surveyor made reference to the previous assessment and reassessment reports provided by the City of Toronto prior to commencing the survey. The Surveyor also referred to facility floor plans included in the previous assessment reports, or provided independently by the City of Toronto. Site drawings identifying locations of asbestos-containing materials, if present, are included in Appendix III. Site photographs are included in Appendix IV.

2.2 Survey Methodology

The City of Toronto provided the consultant with the previous Designated Substances and Hazardous Materials Survey report and / or other survey reports identified for the facility, if available. Prior to conducting the current survey, previous reports were reviewed by Fisher

Engineering Limited and the current report is updated with all available information regarding ACM, including that from past assessments and reassessments.

The survey was conducted in compliance with the Ontario Ministry of Labour (MOL) regulations for designated substances; O. Reg. 490/09 - *Designated Substances* and O. Reg. 278/05 - *Asbestos on Construction Projects and in Buildings and Repair Operations* made under the Occupational Health and Safety Act (OHSA), R.S.O. 1990.

The Surveyor conducted a visual reassessment of all known and assumed asbestos-containing materials in all accessible areas of the building, as detailed in past survey reports, and recorded the condition (GOOD, FAIR or POOR) of each known or assumed ACM on the Designated Substances and Hazardous Materials Inventory Sheet. The Surveyor also recorded detailed descriptions of previously-unidentified potential ACM, if observed. Please refer to Appendix I for the updated Designated Substances and Hazardous Materials Inventory Sheet.

Materials confirmed to be asbestos-containing during previous assessments were not sampled for this reassessment survey. Additionally, samples were not collected of materials that were previously confirmed to be non-asbestos by the requirements of O. Reg. 278/05.

Any other potential asbestos-containing materials noted during the reassessment survey that had not been identified in a previous survey, or were not sampled in accordance with the requirements of O. Reg. 278/05, were noted as part of the reassessment.

The Designated Substances and Hazardous Materials Survey is based on a walk-through assessment of the facility and shall be conducted room by room to establish locations, conditions, and types of designated substances. The survey shall also include an examination for the presence of polychlorinated biphenyls (PCBs), urea-formaldehyde foam insulation (UFFI), and visible mould growth.

3. FINDINGS AND RECOMMENDATIONS

3.1 Asbestos

Asbestos fibres may be released into the air by the disturbance of ACM during product use, demolition work, building or home maintenance, repair, and remodelling. In general, exposure may occur only when the ACM is disturbed in some way to release particles and fibres into the air.

3.1.1 Findings

Previously identified confirmed or assumed ACM include the following:

- Roofing Material;
- Caulking;

- Exterior Panels;
- Asbestos Cement (Transite) Panels;
- Ceiling Tiles – one (1) variety;
- Vinyl Floor Tile – one (1) variety; and
- Vinyl Sheet Flooring – twelve (12) varieties.

Vinyl Sheet Flooring 26 (Beige with Brown Lines) not identified during previous assessment surveys, was observed in Corridors 2-016 and 2-020, and Washroom 2-034.

Vinyl Sheet Flooring 19 (Hardwood Design) identified during previous assessment surveys, was observed in locations: 6-041 Lounge, 6-071 Lounge, 5-071 Rehab Room, and 2-040 Lounge Room.

Vinyl Sheet Flooring 12 (Beige with Black Dots) identified during previous assessment surveys, was not observed in the following Washrooms: 6-005, 4-053, 3-053, and 2-053.

Vinyl Sheet Flooring 24 (Grey with White Dots) identified during previous assessment surveys, was not observed in the following Shower & Tub Rooms: 3-011, 3-3-073, 4-011, 5-011, 5-067, 6-011 and 6-067.

Vinyl Sheet Flooring 16 (Grey with Black Dots) identified during previous assessment surveys, was not observed in the following Shower & Tub Rooms: 2-011, 1-073, 3-073, 4-011, 4-073, 5-011, 5-067, 6-011 and 6-067.

Vinyl Floor Tile 2 (12" x 12" Rose with Multicoloured Dots) identified during previous assessment surveys was not observed in Auditorium 1-124.

No samples were collected for analysis during the current survey.

Unless previously determined to be non-asbestos, plaster, drywall joint compound, vinyl floor tiles, mastics and window caulking in other areas of the facility should continue to be assumed to be asbestos-containing, and should be sampled prior to renovation and/or demolition activities.

3.1.2 Recommendations

All confirmed and assumed ACM were observed in GOOD condition at the time of the reassessment. Therefore, no recommended corrective actions are made currently.

Any other building materials suspected to contain asbestos which are not outlined in this report should be assumed to be asbestos-containing until sample analysis determines asbestos content.

O. Reg. 278/05 requires that an Asbestos Management Program (AMP) be implemented as long as ACM are present in a building. The AMP, original survey report and subsequent

reassessment reports must be available at the work place, and must identify the type of asbestos, and where asbestos can be found on a room-by-room basis.

NOTE: Interpretation of all sources of asbestos-related information, including but not limited to the original asbestos survey report, asbestos reassessment reports, room-by-room survey data, survey drawings and reports from previous asbestos abatement projects, should be completed by a competent person trained in the historical application of asbestos in building materials, building design and preferably by a person with site-specific knowledge and/or experience.

Information contained within any of the above-noted sources may not relieve the Regulatory responsibility of building Owners, or project Employers/Constructors, to complete a detailed site inspection prior to commencement of a project.

This report should not be used as a substitute for a detailed site inspection to identify asbestos-containing building materials, which must be specifically tailored to the scope and nature of any given project, and completed prior to any maintenance, renovation or demolition work that may cause disturbance to building materials.

3.2 **Lead**

Most lead in the environment comes from human activities such as burning fossil fuels, mining, and manufacturing. Lead is used in the production of batteries, ammunition, metal products such as solder and pipes, and x-ray devices. Exposure happens when eating food or drinking water that contains lead. Deteriorated lead paint can contribute to lead dust. The main target for lead toxicity is the nervous system.

The regulation for lead applies to every employer and worker at a workplace where lead is present, produced, processed, used, handled, or stored and at which a worker is likely to be exposed to lead.

Additionally, in 2004 the MOL issued *Guideline: Lead on Construction Projects* outlining practices that should be followed during construction projects to protect workers from exposure to lead. This includes the methods and equipment employed in the removal of lead containing coatings that reduce the creation of dust, providing appropriate facilities for workers to wash after each shift, and providing protective clothing and respirators where necessary.

3.2.1 **Findings**

Paint finishes were generally noted to be in GOOD condition throughout the Site. Based on the age of the building, it is possible that lead-based paint and lead plumbing are present within the building. During the current investigation, no lead samples were collected for analysis.

No other indication of lead containing materials was observed during the building survey, with the exception of that which may be contained within batteries.

3.2.2 Recommendations

During the disturbance of any painted surfaces that contain lead, it would be recommended that appropriate procedures and use of respirators be followed to protect workers.

No immediate corrective actions were recommended with regard to lead.

3.3 *Acrylonitrile*

Acrylonitrile is used to make other chemicals such as plastics, synthetic rubber, and acrylic fibres. Breathing high concentrations of acrylonitrile will cause nose and throat irritation, tightness in chest, difficulty breathing, nausea, dizziness, weakness, headache, impaired judgment, and convulsions. These symptoms usually disappear when exposure has stopped. If spilled on the skin, acrylonitrile will burn the skin and cause blisters and redness. Acrylonitrile is believed to be carcinogenic.

3.3.1 Findings

Acrylonitrile based polymers may have been utilized in the production of some of the building construction materials (e.g., paints, sealants, and adhesives). Although these polymers are generally volatile, they are expected to produce significant acrylonitrile exposure only during or shortly after application of the subject material. If present on site, acrylonitrile would not be expected to be a concern during future renovation or demolition works. Acrylonitrile was not evident in its pure form anywhere within the subject areas of the building.

3.3.2 Recommendations

No immediate corrective actions were recommended about acrylonitrile.

3.4 *Arsenic*

Inorganic arsenic compounds are mainly used to preserve wood. Organic arsenic compounds are used as pesticides. Arsenic occurs naturally in soil and minerals and therefore may enter air and water. Breathing high levels of arsenic may cause sore throat and irritated lungs. Ingesting high levels of arsenic can result in death. Arsenic is a suspected carcinogenic substance.

3.4.1 Findings

Low levels of arsenic may be contained within paints or coatings utilized on building construction materials, however exposure levels resulting from personal contact are not expected to be significant. Arsenic or arsenic containing compounds were not encountered during the building survey works.

3.4.2 Recommendations

No immediate corrective actions were recommended about arsenic.

3.5 ***Benzene***

Benzene is colourless liquid with a sweet odour. Benzene utilization has historically been associated with solvents, paints, stains, adhesives, and in the manufacturing of various rubber products. While its current use in building materials has greatly decreased due to an increased awareness of associated health concerns, it may still be present in trace quantities in various industrial solvents. Gasoline sold in Canada contains approximately 4% benzene.

Breathing very high levels of benzene can result in death, while high levels may cause drowsiness, dizziness, rapid heart rate, headaches, and unconsciousness.

3.5.1 **Findings**

While it may be expected, given the age of the building, that the original construction materials utilized did contain some trace levels of benzene, it is likely that any has since volatilized and would not exceed the permissible exposure values. During future renovation or demolition works, it would not be expected to be a concern. No evidence of benzene was noted during the building survey, except for that which may be contained in regular gasoline fuel burning equipment.

It was noted during the site visit – a diesel fuel tank is located outside of the emergency generator room (location B-21) and various oils are stored in a basement pump room (location B-053) and electrical storage room (location B-055).

3.5.2 **Recommendations**

No immediate corrective actions were recommended about benzene.

3.6 ***Coke Oven Emissions***

Coke oven emissions are released during the carbonization of bituminous coal to produce coke. Exposure routes include inhalation, skin and / or eye contact. Coke oven emissions are potential occupational carcinogens.

3.6.1 **Findings**

This substance would not be expected to be found in the building. No evidence of the burning of coke was found during the building survey.

3.6.2 **Recommendations**

No immediate corrective actions were recommended about coke oven emissions.

3.7 ***Ethylene Oxides***

Ethylene oxide is a man-made chemical used primarily to make ethylene glycol (antifreeze and polyester). Breathing low levels of ethylene oxides for a prolonged period causes eye,

skin, and respiratory irritations, and can affect nervous system. Higher levels of exposure for shorter time produce symptoms that are similar but more severe.

3.7.1 Findings

This substance would not be expected to be found in the building. No evidence of ethylene oxides was found during the building survey.

3.7.2 Recommendations

No immediate corrective actions were recommended about ethylene oxides.

3.8 *Isocyanates*

Isocyanates are a family of highly reactive, low molecular weight chemicals. They are widely used in the manufacture of flexible and rigid foams, fibres, and coatings such as paints and varnishes, and elastomers and various building materials (e.g., spray on polyurethane products). Isocyanates are powerful irritants to the eyes, skin, and respiratory and gastrointestinal tracts.

3.8.1 Findings

Use of isocyanates or isocyanate compounds would not be expected in the building. No evidence of isocyanates was found during the building survey.

3.8.2 Recommendations

No immediate corrective actions were recommended about isocyanates.

3.9 *Mercury*

Mercury is a naturally occurring metal. It is a shiny, silver-white, and odourless liquid. It combines with other elements to form inorganic compounds or salts. Metallic mercury is used to produce chlorine gas and caustic soda, and is used in thermostats and thermometers, fluorescent light bulbs, dental fillings, and batteries. Exposure occurs when breathing vapours from spills, incinerators, etc.

The nervous system is very sensitive to all forms of mercury. Exposure to high levels of metallic inorganic or organic mercury can permanently damage the brain, kidneys and developing fetus. Short-term exposure may cause lung damage, nausea, vomiting and diarrhea as well as skin and eye irritation.

3.9.1 Findings

Mercury can be found in fluorescent light bulbs and building thermostats. Prior to future renovation or demolition works, it would be recommended that these products be safely removed. The disposal of mercury containing items are regulated under the Environmental Protection Act, and it would be recommended that for disposal purposes any mercury

containing thermostats and fluorescent light bulbs be disposed of at an MOE licensed receiver. Except for fluorescent light bulbs and building thermostats, no other evidence of mercury was noted during the building survey.

3.9.2 Recommendations

No immediate corrective actions were recommended about mercury.

3.10 Silica

Silica is a crystalline compound occurring abundantly as quartz, sand, and many other minerals, and used to manufacture a variety of materials, especially glass and concrete. When mining this substance, silica can be deadly when it becomes airborne. If inhaled, silica dust can cause silicosis which can be fatal.

Additionally, in 2004 the MOL issued *Guideline: Silica on Construction Projects* outlining practices that should be followed during construction projects to protect workers from exposure to silica. This includes the methods and equipment employed in the removal of silica containing materials that reduce the creation of dust, providing appropriate facilities for workers to wash after each shift, and providing protective clothing and respirators where necessary.

3.10.1 Findings

As the building is constructed of concrete block and brick, with concrete floors, silica is expected to be found within these components of the building. During any significant renovation or demolition works where concrete dust is generated, dust suppression techniques should be utilized to control worker exposure to silica. Silica is expected to be present in concrete and masonry products in the building.

3.10.2 Recommendations

No immediate corrective actions were recommended about silica.

3.11 Vinyl Chloride

Vinyl chloride is used to make polyvinyl chloride (PVC) which is found in a variety of plastic products, including pipes, wires, cable coatings and packaging materials. Breathing high levels of vinyl chloride can cause dizziness, unconsciousness, and death. Prolonged exposure causes changes in liver, nerve damage, immune reactions, and changes in blood flow.

3.11.1 Findings

PVC pipe is generally stable and does not allow for the liberation of vinyl chloride, under normal conditions. During future renovation or demolition works, this substance would not

be expected to be a concern. Vinyl chloride was not evident in its pure form, anywhere in the subject dwellings.

3.11.2 Recommendations

No immediate corrective actions were recommended about vinyl chloride.

3.12 *Polychlorinated Biphenyls (PCBs)*

PCBs are mixtures of synthetic organic chemicals with the same basic chemical structure and similar physical properties ranging from oily liquids to waxy solids. Due to their non-flammability, chemical stability, high boiling point and electrical insulating properties, PCBs were used in hundreds of industrial and commercial applications including electrical, heat transfer, and hydraulic equipment; as plasticizers in paints, plastics, and rubber products; in pigments, dyes and carbonless copy paper and many other applications.

PCBs have been demonstrated to cause a variety of adverse health effects. PCBs have been shown to cause cancer.

3.12.1 Findings

No PCB containing equipment with the potential exception of fluorescent lighting ballasts was observed on site. The disposal of PCB containing equipment is regulated under MOE Reg. 558, and it would be recommended that during any ballast replacement works the generated ballasts be evaluated for PCB content, with any PCB ballasts being consolidated and sent for disposal to an MOE licensed PCB receiver under waste class 243D.

3.12.2 Recommendations

It would be recommended that during any ballast replacement works the generated ballasts be evaluated for PCB content. Any PCB ballasts identified should be consolidated and sent for disposal to an MOE licensed PCB receiver under waste class 243D.

3.13 *Urea Formaldehyde Foam Insulation (UFFI)*

UFFI was developed in Europe in the 1950s as an improved means of insulating difficult-to-reach cavities in house walls. UFFI is composed of a mixture of urea-formaldehyde resin, a foaming agent, and compressed air. It was commonly injected into exterior wood frame walls in order to insulate difficult to reach cavities, until its ban in Canada in December 1980. When the mixture is injected into the wall, urea and formaldehyde unite and "cure" into an insulating foam plastic. In the insulating process, a slight excess of formaldehyde was often added to ensure complete "curing" with the urea to produce the urea-formaldehyde foam. That excess was given off during the curing, almost entirely within a day or two of injection. Properly installed, UFFI might not have resulted in any problem. Unfortunately, however, UFFI was sometimes improperly installed or used in locations where it should not have been.

While small amounts of formaldehyde are harmless, it is an irritating and toxic gas in significant concentrations. Symptoms of overexposure to formaldehyde include irritation to eyes, nose, and throat; persistent cough and respiratory distress; skin irritation; nausea; headache; and dizziness.

3.13.1 Findings

No UFFI containing insulation was observed on site.

3.13.2 Recommendations

No immediate corrective action is recommended with regard to UFFI.

3.14 Mould

Mould contamination inside buildings has become a concern to both building owners and occupants. Exposure to moulds is known to cause a variety of health effects in some people. Many fungal spores are allergenic to susceptible persons, though individual susceptibility varies greatly.

Elevated levels of indoor mould are usually attributed to the chronic moist conditions due to water leaks, floods, or elevated humidity. Under these conditions, already low levels of fungal spores in air from plants and other sources may multiply on cellulose containing materials such as carpets, wallboards, and wood, and result in mould contamination and, if left untreated, can be destructive to certain building materials.

Currently, no Canadian regulations govern the presence of mould and/or water-damaged materials in the workplace environment. However, the Health Canada document "Fungal Contamination in Public Buildings: Health Effects and Investigation Methodology" (2004) concludes that current knowledge supports the need to prevent damp conditions and mould growth and remediate any fungal growth and/or contamination in buildings.

Therefore, the presence of mould growth, mould-contaminated materials and/or water-damaged materials in the occupied environment is interpreted as a failure of Health Canada guidelines for microbial contamination in indoor environments, and as such, requires remedial action.

The MOL issued a document titled "Alert: Mould in Workplace Buildings." This document explains the MOL's position with respect to the presence of mould in workplace buildings.

The Environmental Abatement Council of Canada (EACC) has provided guidelines regarding investigation and remediation works Mould Abatement Guidelines Edition 3 (2015). Mould Guidelines for the EACC to protect the health of workers who may be exposed to mould during building renovations.

3.14.1 Findings

During the visual inspection of the surveyed areas, visible mould growth was observed on (non-ACM) insulation on five pipes in the Valve Room B-051.

3.14.2 Recommendations

Removal of the mould-impacted building materials should be conducted as a Level 1 Mould Remediation Operations, based on EACC guidelines. Following abatement, the source of water ingress should be determined and addressed to prevent potential future fungal amplification.

4. CORRECTIVE ACTIONS

Fisher Engineering Limited communicated the reported deficiencies and recommendations for corrective actions to the City of Toronto. These activities have been completed and an Addendum was made to this report to confirm completion of the corrective actions. Details of the abatement work can be found in the Corrective Actions Inspection Report (Project No. FE 23-13254), which are provided in Appendix V.

Fisher Engineering Limited believes that all recommendations made as a result of the findings of the reassessment survey have been addressed.

5. STATEMENT OF LIMITATIONS

Fisher Engineering Limited accepts responsibility for the competent performance of its duties in executing this assignment within the normal standards of the profession, but disclaims responsibility for consequential damages, if any.

The extent of the building survey of designated substances and hazardous materials is based on prior agreement of the scope of work with the client, and the rationale given in this report. The building survey findings rely on professional interpretation of selective sampling and analysis. Sample analysis results have been applied to homogenous materials in unsampled locations; it was not within the scope of work to carry out an exhaustive sampling and analysis program. For non-accessible building spaces, the likelihood of the presence or absence of asbestos and other designated substances has been described, but such assessment is not a definitive statement of presence or absence.

This report was prepared for the City of Toronto, Corporate Real Estate Management. The scope of services performed may not be appropriate for the purposes of other users, and any use or reuse of this document or its findings or recommendations represented herein is at the sole risk of any other user.

We trust that the information provided in the report meets your current requirements. If you have any questions or concerns, please do not hesitate to contact the undersigned.


6. SIGN-OFF

We trust that this report meets with City of Toronto requirements and we thank you for the opportunity to be of service. Should you have any questions, please do not hesitate to contact us.


Fisher Engineering Limited

Prepared By:

Reviewed By:



Renata Stec, M.Sc.
Project Manager



David Fisher, P. Eng., C. Chem.
Principal



APPENDIX I

DESIGNATED SUBSTANCES AND HAZARDOUS MATERIALS INVENTORY SHEET

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Building Address	2920 Lawrence Avenue East	Date(s) of Current Reassessment:	May 18, 2023
Building Name	Bendale Acres	Organization Completing Reassessment:	Fisher Engineering Limited / Project FE 23-12800
Original Survey Conducted By:	Fisher Environmental Ltd.	Name of Surveyor:	Renata Stec
Date(s) of Original Survey:	April 14, 2015	Signature of Surveyor:	

Summary of Findings
All Hazardous materials were found in GOOD condition.

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
0-00	Exterior	Roof	Roofing Material	Asbestos	Not Sampled	ACM Assumed	32000 SF	Good	
0-00	Exterior	Roof	Caulking	Asbestos	20-5449-1 to 3*	None Detected	N/A	N/A	Brown, Skylight roof, around the glass frame. *From Fisher Project No. 20-10691, dated Oct. 2020
0-00	Exterior	Roof	Caulking	Asbestos	20-5449-4 to 6*	None Detected	N/A	N/A	Green, Skylight roof, around the glass frame. *From Fisher Project No. 20-10691, dated Oct. 2020
0-00	Exterior	Window	Caulking	Asbestos	18-8899-01 to 03*	None Detected	N/A	N/A	White *From Fisher Project No. 18-8834, dated May 2018
0-00	Exterior	Window	Caulking	Asbestos	18-8899-07 to 09*	None Detected	N/A	N/A	Green *From Fisher Project No. 18-8834, dated May 2018
0-00	Exterior	Window	Putty	Asbestos	18-8899-10 to 12*	None Detected	N/A	N/A	Black *From Fisher Project No. 18-8834, dated May 2018
0-00	Exterior	Window	Putty	Asbestos	18-8899-04 to 06*	None Detected	N/A	N/A	Grey *From Fisher Project No. 18-8834, dated May 2018
0-00	Exterior	Door	Caulking	Asbestos	18-9046-07 to 09*	None Detected	N/A	N/A	Red & Grey *From Fisher Project No. 18-8867, dated June 2018
0-00	Exterior	Door	Caulking	Asbestos	20-5449-10 to 12*	None Detected	N/A	N/A	Grey, Loading Dock around overhead door frame *From Fisher Project No.20-10691, dated Oct. 2020
0-00	Exterior	Door	Caulking	Asbestos	20-5449-13 to 15*	None Detected	N/A	N/A	White & Tan, Around the double door frame *From Fisher Project No.20-10691, dated Oct. 2020
0-00	Exterior	Door	Caulking	Asbestos	20-5449-16 to 18*	None Detected	N/A	N/A	Tan, Compactor room around overhead door frame *From Fisher Project No.20-10691, dated Oct. 2020
0-00	Exterior	Walls	Brick	N/A	N/A	N/A	N/A	N/A	
0-00	Exterior	Walls	Mortar	Asbestos	18-8899-13 to 15*	None Detected	N/A	N/A	*From Fisher Project No. 18-8834, dated May 2018
0-00	Exterior	Walls	Caulking	Asbestos	18-9046-13 to 15*	None Detected	N/A	N/A	Black from Exterior Pads *From Fisher Project No. 18-8867, dated June 2018
0-00	Exterior	Walls	Exterior Panels	Asbestos	19-1721-01 to 03*	25-50% Chrysotile & Crocidolite	All	Good	*From Fisher Project No. 19-9245, dated Jan. 2019
0-00	Exterior	Walls	Transite Panels	Asbestos	060907-01 to 03*	6-8% Chrysotile	All	Good	Exterior Walls of Lower Penthouse *From Building Asbestos Survey, dated 2007
0-00	Exterior	Other	Paint	Lead	20-5449-20*	199 ppm	N/A	N/A	Black, Loading Dock Area, guardrail for ramp *From Fisher Project No.20-10691, dated Oct. 2020
0-00	Exterior	Other	Paint	Lead	20-5449-21*	809 ppm	N/A	N/A	Yellow, Markings on the curb *From Fisher Project No.20-10691, dated Oct. 2020
0-00	Exterior	Other	Paint	Lead	20-5449-22*	194 ppm	N/A	N/A	Green, Loading Dock Area, post for the shade *From Fisher Project No.20-10691, dated Oct. 2020
CB-001	Corridor	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
CB-001	Corridor	Walls	Drywall (DJC)	Asbestos	18-9046-01 to 03*	None Detected	N/A	N/A	*From Fisher Project No. 18-8867, dated June 2018
CB-001	Corridor	Walls	Caulking	Asbestos	18-9046-04 to 06*	None Detected	N/A	N/A	Off-White, from wall expansion *From Fisher Project No. 18-8867, dated June 2018

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
CB-001	Corridor	Walls	Block	N/A	N/A	N/A	N/A	N/A	
CB-001	Corridor	Door	Caulking	Asbestos	18-9046-10 to 12*	None Detected	N/A	N/A	Grey, Door Frames *From Fisher Project No. 18-8867, dated June 2018
CB-001	Corridor	Door	Caulking	Asbestos	18-9046-16 to 18*	None Detected	N/A	N/A	Cream, Door Frames *From Fisher Project No. 18-8867, dated June 2020
CB-001	Corridor	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
CB-002	Mechanical Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
CB-002	Mechanical Room	Walls	Block	N/A	N/A	N/A	N/A	N/A	
CB-002	Mechanical Room	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
CB-003	Storage	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
CB-003	Storage	Walls	Block	N/A	N/A	N/A	N/A	N/A	
CB-003	Storage	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
SB-001	Lower Boiler Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
SB-001	Lower Boiler Room	Walls	Concrete	N/A	N/A	N/A	N/A	N/A	
SB-001	Lower Boiler Room	Walls	Paint	Lead	16-3754-4*	1212 ppm	All	Good	Grey *From Fisher Project No. 16-7701, dated April 2016
SB-001	Lower Boiler Room	Walls	Paint	Lead	16-3754-5*	356 ppm	N/A	N/A	Beige *From Fisher Project No. 16-7701, dated April 2016
SB-001	Lower Boiler Room	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
SB-001	Lower Boiler Room	Other	Boiler Vents	Asbestos	060907-10 to 12*	70% Chrysotile	N/A	N/A	*From Building Asbestos Survey, dated 2007 Abatement completed in August 2016 (From Fisher Project No. 16-7809, dated Aug. 2016) NOT OBSERVED
SB-001	Lower Boiler Room	Other	Exhaust Vests Parging Cement	Asbestos	16-4166-01 to 03*	25-50% Chrysotile	N/A	N/A	*From Fisher Project No. 16-7809, dated Aug. 2016 Abatement completed in August 2016 (From Fisher Project No. 16-7809, dated Aug. 2016) NOT OBSERVED
SB-001	Lower Boiler Room	Pipe	Parging Cement	Asbestos	16-4166-04 to 06*	25-50% Chrysotile	N/A	N/A	*From Fisher Project No. 16-7809, dated Aug. 2016 Abatement completed in August 2016 (From Fisher Project No. 16-7809, dated Aug. 2016) NOT OBSERVED
SB-002	Electrical Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
SB-002	Electrical Room	Walls	Concrete	N/A	N/A	N/A	N/A	N/A	
SB-002	Electrical Room	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
SB-003	Tunnel	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
SB-003	Tunnel	Walls	Concrete	N/A	N/A	N/A	N/A	N/A	
SB-003	Tunnel	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
B-001	Lobby	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 17-7565-04 to 06	None Detected	N/A	N/A	Green with Grey and White Streaks
B-001	Lobby	Walls	Block	N/A	N/A	N/A	N/A	N/A	
B-001	Lobby	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-002	Corridor	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 17-7565-04 to 06	None Detected	N/A	N/A	Green with Grey and White Streaks
B-002	Corridor	Walls	Block	N/A	N/A	N/A	N/A	N/A	
B-002	Corridor	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7565-01 to 03 & 18-8899-50 to 52	None Detected	N/A	N/A	
B-002	Corridor	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-003	Electrical Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
B-003	Electrical Room	Walls	Block	N/A	N/A	N/A	N/A	N/A	
B-003	Electrical Room	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-004	Soiled Linen	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
B-004	Soiled Linen	Walls	Block	N/A	N/A	N/A	N/A	N/A	
B-004	Soiled Linen	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-005	Main Kitchen	Floor	Vinyl Sheet Flooring 2	Asbestos	Not Sampled	ACM Assumed	1500 SF	Good	Blue
B-005	Main Kitchen	Walls	Block	N/A	N/A	N/A	N/A	N/A	
B-005	Main Kitchen	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7565-01 to 03 & 18-8899-50 to 52	None Detected	N/A	N/A	
B-006	Potwash	Floor	Vinyl Sheet Flooring 2	Asbestos	Not Sampled	ACM Assumed	100 SF	Good	Blue
B-006	Potwash	Walls	Block	N/A	N/A	N/A	N/A	N/A	
B-006	Potwash	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7565-01 to 03 & 18-8899-50 to 52	None Detected	N/A	N/A	
B-007	Janitor's Closet	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
B-007	Janitor's Closet	Walls	Block	N/A	N/A	N/A	N/A	N/A	
B-007	Janitor's Closet	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-008	Corridor	Floor	Vinyl Sheet Flooring 2	Asbestos	Not Sampled	ACM Assumed	260 SF	Good	Blue
B-008	Corridor	Door	Putty	Asbestos	17-5667-01 to 03*	None Detected	N/A	N/A	*From Fisher Project No. 17-8078, dated Feb. 2017
B-008	Corridor	Door	Paint	Lead	17-5667-08*	<10 ppm	N/A	N/A	Blue, Door Frame *From Fisher Project No. 17-8078, dated Feb. 2017
B-008	Corridor	Walls	Block	N/A	N/A	N/A	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
B-008	Corridor	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7565-01 to 03 & 18-8899-50 to 52	None Detected	N/A	N/A	
B-009	Electrical Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
B-009	Electrical Room	Walls	Block	N/A	N/A	N/A	N/A	N/A	
B-009	Electrical Room	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-010	Office	Floor	Vinyl Sheet Flooring 2	Asbestos	Not Sampled	ACM Assumed	100 SF	Good	Blue
B-010	Office	Walls	Block	N/A	N/A	N/A	N/A	N/A	
B-010	Office	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
B-011	Preparation Room	Floor	Vinyl Sheet Flooring 2	Asbestos	Not Sampled	ACM Assumed	125 SF	Good	Blue
B-011	Preparation Room	Walls	Block	N/A	N/A	N/A	N/A	N/A	
B-011	Preparation Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7565-01 to 03 & 18-8899-50 to 52	None Detected	N/A	N/A	
B-012	Storage	Floor	Vinyl Sheet Flooring 2	Asbestos	Not Sampled	ACM Assumed	120 SF	Good	Blue
B-012	Storage	Walls	Block	N/A	N/A	N/A	N/A	N/A	
B-012	Storage	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7565-01 to 03 & 18-8899-50 to 52	None Detected	N/A	N/A	
B-013	Dry Storage	Floor	Vinyl Sheet Flooring 2	Asbestos	Not Sampled	ACM Assumed	360 SF	Good	Blue
B-013	Dry Storage	Walls	Block	N/A	N/A	N/A	N/A	N/A	
B-013	Dry Storage	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7565-01 to 03 & 18-8899-50 to 52	None Detected	N/A	N/A	
B-014	Receiving	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
B-014	Receiving	Walls	Block	N/A	N/A	N/A	N/A	N/A	
B-014	Receiving	Door	Paint	Lead	20-5449-19*	3051 ppm	30 LF	Good	Light Pink, Loading Dock overhead door frame. *From Fisher Project No. 20-10691, dated Oct. 2020
B-014	Receiving	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-015	Storage	Floor	Vinyl Sheet Flooring 2	Asbestos	Not Sampled	ACM Assumed	100 SF	Good	Blue
B-015	Storage	Walls	Block	N/A	N/A	N/A	N/A	N/A	
B-015	Storage	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
B-016	Storage	Floor	Vinyl Sheet Flooring 2	Asbestos	Not Sampled	ACM Assumed	120 SF	Good	Blue
B-016	Storage	Walls	Block	N/A	N/A	N/A	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
B-016	Storage	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
B-017	Meals on Wheels	Floor	Vinyl Sheet Flooring 2	Asbestos	Not Sampled	ACM Assumed	300 SF	Good	Blue
B-017	Meals on Wheels	Walls	Block	N/A	N/A	N/A	N/A	N/A	
B-017	Meals on Wheels	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
B-018	Compressor Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
B-018	Compressor Room	Walls	Block	N/A	N/A	N/A	N/A	N/A	
B-018	Compressor Room	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-019	Morgue	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	NO ACCESS
B-019	Morgue	Walls	Block	N/A	N/A	N/A	N/A	N/A	
B-019	Morgue	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-020	Compactor	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
B-020	Compactor	Walls	Block	N/A	N/A	N/A	N/A	N/A	
B-020	Compactor	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-021	Generator Room	Roof	Roofing Material	Asbestos	19-3554-16 to 18*	None Detected	N/A	N/A	*From Fisher Project No. 19-9873, dated Nov. 2019
B-021	Generator Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
B-021	Generator Room	Walls	Drywall (DJC)	Asbestos	19-3554-07 to 09*	None Detected	N/A	N/A	Interior wall *From Fisher Project No. 19-9873, dated Nov. 2019
B-021	Generator Room	Walls	Firestop-Grey	Asbestos	19-3554-10 to 12*	None Detected	N/A	N/A	*From Fisher Project No. 19-9873, dated Nov. 2019
B-021	Generator Room	Walls	Expansion Joint	Asbestos	19-3554-13 to 15*	None Detected	N/A	N/A	Black, along the joint of the concrete curb *From Fisher Project No. 19-9873, dated Nov. 2019
B-021	Generator Room	Walls	Sealant	Asbestos	19-3554-19 to 21*	None Detected	N/A	N/A	Black, around the conduit penetration *From Fisher Project No. 19-9873, dated Nov. 2019
B-021	Generator Room	Walls	Sealant	Asbestos	19-3554-22 to 24*	None Detected	N/A	N/A	Brown, around the footing of the cooling unit *From Fisher Project No. 19-9873, dated Nov. 2019
B-021	Generator Room	Walls	Sealant	Asbestos	19-3554-25 to 27*	None Detected	N/A	N/A	White, around the footing of the cooling unit *From Fisher Project No. 19-9873, dated Nov. 2019
B-021	Generator Room	Walls	Caulking	Asbestos	19-3554-01 to 03*	None Detected	N/A	N/A	Light Grey, along the joint of door frame and brick wall *From Fisher Project No. 19-9873, dated Nov. 2019
B-021	Generator Room	Walls	Putty	Asbestos	19-3554-04 to 06*	None Detected	N/A	N/A	Light Grey, along the joint of the louver frame *From Fisher Project No. 19-9873, dated Nov. 2019
B-021	Generator Room	Walls	Block	N/A	N/A	N/A	N/A	N/A	
B-021	Generator Room	Door	Paint	Lead	19-3554-28*	3741 ppm	All	Good	Blue *From Fisher Project No. 19-9873, dated Nov. 2019
B-021	Generator Room	Walls	Paint	Lead	19-3554-29*	31 ppm	N/A	N/A	Cream *From Fisher Project No. 19-9873, dated Nov. 2019
B-021	Generator Room	Other	Paint	Lead	19-3554-30*	136 ppm	N/A	N/A	Yellow, base frame of generator *From Fisher Project No. 19-9873, dated Nov. 2019

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
B-021	Generator Room	Other	Paint	Lead	19-3554-31*	37200 ppm	All	Good	Orange, pipe *From Fisher Project No. 19-9873, dated Nov. 2019
B-021	Generator Room	Other	Paint	Lead	19-3554-32*	2065 ppm	All	Good	Red, metal column *From Fisher Project No. 19-9873, dated Nov. 2019
B-021	Generator Room	Door	Paint	Lead	19-3554-33*	8969 ppm	All	Good	White *From Fisher Project No. 19-9873, dated Nov. 2019
B-021	Generator Room	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-022	Upper Boiler Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
B-022	Upper Boiler Room	Walls	Concrete	N/A	N/A	N/A	N/A	N/A	
B-022	Upper Boiler Room	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-023	Office	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
B-023	Office	Walls	Block	N/A	N/A	N/A	N/A	N/A	
B-023	Office	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-024	Workshop	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
B-024	Workshop	Walls	Block	N/A	N/A	N/A	N/A	N/A	
B-024	Workshop	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-025	Storage	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
B-025	Storage	Walls	Block	N/A	N/A	N/A	N/A	N/A	
B-025	Storage	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-026	Storage	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
B-026	Storage	Walls	Block	N/A	N/A	N/A	N/A	N/A	
B-026	Storage	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-027	Storage	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
B-027	Storage	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7565-01 to 03 & 18-8899-50 to 52	None Detected	N/A	N/A	
B-027	Storage	Walls	Block/Concrete	N/A	N/A	N/A	N/A	N/A	
B-027	Storage	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-028	Women's Locker Room	Floor	Vinyl Sheet Flooring 4	Asbestos	Homogeneous w/ 18-8899-32 to 34	None Detected	N/A	N/A	Beige Mosaic
B-028	Women's Locker Room	Floor	Vinyl Sheet Flooring 25	Asbestos	Not Sampled	ACM Assumed	100 SF	Good	Grey with Blue and Beige Specks
B-028	Women's Locker Room	Floor	Terrazzo	N/A	N/A	N/A	N/A	N/A	
B-028	Women's Locker Room	Walls	Block	N/A	N/A	N/A	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
B-028	Women's Locker Room	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-029	Janitor's Closet	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
B-029	Janitor's Closet	Walls	Block	N/A	N/A	N/A	N/A	N/A	
B-029	Janitor's Closet	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-030	Men's Locker Room	Floor	Terrazzo	N/A	N/A	N/A	N/A	N/A	
B-030	Men's Locker Room	Floor	Vinyl Sheet Flooring 4	Asbestos	Homogeneous w/ 18-8899-32 to 34	None Detected	N/A	N/A	Beige Mosaic
B-030	Men's Locker Room	Walls	Block	N/A	N/A	N/A	N/A	N/A	
B-030	Men's Locker Room	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-031	Foyer	Floor	Vinyl Sheet Flooring 25	Asbestos	Not Sampled	ACM Assumed	400 SF	Good	Grey with Blue and Beige Specks
B-031	Foyer	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 17-7565-04 to 06	None Detected	N/A	N/A	Green with Grey and White Streaks NOT OBSERVED
B-031	Foyer	Walls	Block	N/A	N/A	N/A	N/A	N/A	
B-031	Foyer	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
B-032	Office	Floor	Vinyl Sheet Flooring 25	Asbestos	Not Sampled	ACM Assumed	220 SF	Good	Grey with Blue and Beige Specks
B-032	Office	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 17-7565-04 to 06	None Detected	N/A	N/A	Green with Grey and White Streaks NOT OBSERVED
B-032	Office	Walls	Block	N/A	N/A	N/A	N/A	N/A	
B-032	Office	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
B-033	Office	Floor	Vinyl Sheet Flooring 25	Asbestos	Not Sampled	ACM Assumed	220 SF	Good	Grey with Blue and Beige Specks
B-033	Office	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 17-7565-04 to 06	None Detected	N/A	N/A	Green with Grey and White Streaks NOT OBSERVED
B-033	Office	Walls	Block	N/A	N/A	N/A	N/A	N/A	
B-033	Office	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
B-034	Cart Wash	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
B-034	Cart Wash	Walls	Block	N/A	N/A	N/A	N/A	N/A	
B-034	Cart Wash	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-035	Corridor	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	ACM Assumed	160 SF	Good	Light Green with Dark Green Specks
B-035	Corridor	Walls	Block	N/A	N/A	N/A	N/A	N/A	
B-035	Corridor	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-036	Paint Shop	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
B-036	Paint Shop	Walls	Block	N/A	N/A	N/A	N/A	N/A	
B-036	Paint Shop	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-037	Stairs # 5	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
B-037	Stairs # 5	Walls	Block	N/A	N/A	N/A	N/A	N/A	
B-037	Stairs # 5	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-038	Women's Locker Room	Floor	Terrazzo	N/A	N/A	N/A	N/A	N/A	
B-038	Women's Locker Room	Walls	Block	N/A	N/A	N/A	N/A	N/A	
B-038	Women's Locker Room	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-039	Corridor	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 17-7565-04 to 06	None Detected	N/A	N/A	Green with Grey and White Streaks
B-039	Corridor	Walls	Block	N/A	N/A	N/A	N/A	N/A	
B-039	Corridor	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-040	Maintenance Shop	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
B-040	Maintenance Shop	Walls	Block/Concrete	N/A	N/A	N/A	N/A	N/A	
B-040	Maintenance Shop	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-041	Paint Storage	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
B-041	Paint Storage	Walls	Block	N/A	N/A	N/A	N/A	N/A	
B-041	Paint Storage	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-042	Office	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 17-7565-04 to 06	None Detected	N/A	N/A	Green with Grey and White Streaks
B-042	Office	Walls	Block	N/A	N/A	N/A	N/A	N/A	
B-042	Office	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-043	Storage	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
B-043	Storage	Walls	Block/Concrete	N/A	N/A	N/A	N/A	N/A	
B-043	Storage	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-044	Linen Room	Floor	Vinyl Floor Tile 1	Asbestos	15-1632-01 to 03*	None Detected	N/A	N/A	12" x 12" Beige with Grey and Brown Smears *From Fisher Project No.15-7261, dated July 2015
B-044	Linen Room	Floor	Vinyl Floor Tile 3	Asbestos	Not Sampled	ACM Assumed	220 SF	Good	12" x 12" Light Grey with Black and Grey Specks
B-044	Linen Room	Walls	Block	N/A	N/A	N/A	N/A	N/A	
B-044	Linen Room	Walls	Drywall (DJC)	Asbestos	17-7565-01 to 03*	None Detected	N/A	N/A	*From Fisher Project No. 17-8527, dated Nov. 2017

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
B-044	Linen Room	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-045	Office	Floor	Vinyl Sheet Flooring 25	Asbestos	Not Sampled	ACM Assumed	220 SF	Good	Grey with Blue and Beige Specks
B-045	Office	Floor	Vinyl Sheet Flooring 1	Asbestos	17-7565-04 to 06*	None Detected	N/A	N/A	Green with Grey and White Streaks *From Fisher Project No. 17-8527, dated Nov. 2017 NOT OBSERVED
B-045	Office	Door	Insulation	Asbestos	18-8899-47 to 49*	None Detected	N/A	N/A	*From Fisher Project No. 18-8834, dated May 2018
B-045	Office	Walls	Drywall (DJC)	Asbestos	18-8899-50 to 52*	None Detected	N/A	N/A	*From Fisher Project No. 18-8834, dated May 2018
B-045	Office	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
B-046	Storage	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
B-046	Storage	Walls	Block/Concrete	N/A	N/A	N/A	N/A	N/A	
B-046	Storage	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-047	Storage	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 17-7565-04 to 06	None Detected	N/A	N/A	NO ACCESS Green with Grey and White Streaks
B-047	Storage	Walls	Block	N/A	N/A	N/A	N/A	N/A	
B-047	Storage	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-048	Storage	Floor	Vinyl Sheet Flooring 25	Asbestos	Not Sampled	ACM Assumed	220 SF	Good	Grey with Blue and Beige Specks
B-048	Storage	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 17-7565-04 to 06	None Detected	N/A	N/A	Green with Grey and White Streaks NOT OBSERVED
B-048	Storage	Walls	Block	N/A	N/A	N/A	N/A	N/A	
B-048	Storage	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-049	Corridor	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 17-7565-04 to 06	None Detected	N/A	N/A	Green with Grey and White Streaks
B-049	Corridor	Walls	Block	N/A	N/A	N/A	N/A	N/A	
B-049	Corridor	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-050	Nurses Supplies	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 17-7565-04 to 06	None Detected	N/A	N/A	NO ACCESS Green with Grey and White Streaks
B-050	Nurses Supplies	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7565-01 to 03 & 18-8899-50 to 52	None Detected	N/A	N/A	
B-050	Nurses Supplies	Walls	Block	N/A	N/A	N/A	N/A	N/A	
B-050	Nurses Supplies	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-051	Valve Room	Floor	Vinyl Sheet Flooring 25	Asbestos	Not Sampled	ACM Assumed	220 SF	Good	Grey with Blue and Beige Specks
B-051	Valve Room	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 17-7565-04 to 06	None Detected	N/A	N/A	Green with Grey and White Streaks NOT OBSERVED
B-051	Valve Room	Walls	Block	N/A	N/A	N/A	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
B-051	Valve Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7565-01 to 03 & 18-8899-50 to 52	None Detected	N/A	N/A	
B-051	Valve Room	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-052	Nurses Supplies	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
B-052	Nurses Supplies	Walls	Block	N/A	N/A	N/A	N/A	N/A	
B-052	Nurses Supplies	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-053	Pump Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
B-053	Pump Room	Walls	Block/Concrete	N/A	N/A	N/A	N/A	N/A	
B-053	Pump Room	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-054	Mechanical Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
B-054	Mechanical Room	Walls	Block/Concrete	N/A	N/A	N/A	N/A	N/A	
B-054	Mechanical Room	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-055	Elevator Machine Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
B-055	Elevator Machine Room	Walls	Block	N/A	N/A	N/A	N/A	N/A	
B-055	Elevator Machine Room	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-056	Electrical Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
B-056	Electrical Room	Walls	Block	N/A	N/A	N/A	N/A	N/A	
B-056	Electrical Room	Duct	Sprayed Fireproofing	Asbestos	22-7881-8, 9*	None Detected	N/A	N/A	*From Fisher Project No. 22-11869, dated Feb. 2022
B-056	Electrical Room	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-057	Women's Locker Room	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 17-7565-04 to 06	None Detected	N/A	N/A	Green with Grey and White Streaks
B-057	Women's Locker Room	Walls	Block	N/A	N/A	N/A	N/A	N/A	
B-057	Women's Locker Room	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-058	Admin Records	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	NO ACCESS
B-058	Admin Records	Walls	Block	N/A	N/A	N/A	N/A	N/A	
B-058	Admin Records	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-059	Residents Records	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	NO ACCESS
B-059	Residents Records	Walls	Block	N/A	N/A	N/A	N/A	N/A	
B-059	Residents Records	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
1-001	Vestibule	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A	
1-001	Vestibule	Walls	Glass	N/A	N/A	N/A	N/A	N/A	
1-001	Vestibule	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-001	Vestibule	Ceiling	Glass	N/A	N/A	N/A	N/A	N/A	
1-002	Lobby	Floor	Carpet/Ceramic	N/A	N/A	N/A	N/A	N/A	
1-002	Lobby	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-002	Lobby	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
1-002	Lobby	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-002	Lobby	Ceiling	Drywall (DJC)	Asbestos	20-5449-7 to 9*	None Detected	N/A	N/A	Interior wall, skylight *From Fisher Project No. 20-10691, dated Oct. 2020
1-002	Lobby	Ceiling	Glass	N/A	N/A	N/A	N/A	N/A	
1-003	Waiting Area	Floor	Carpet/Ceramic	N/A	N/A	N/A	N/A	N/A	
1-003	Waiting Area	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-003	Waiting Area	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
1-004	Chapel	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
1-004	Chapel	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-004	Chapel	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-004	Chapel	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
1-005	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
1-005	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-005	Office	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
1-006	Reception	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A	
1-006	Reception	Walls	Drywall (DJC)	Asbestos	18-8216-04, 05*	None Detected	N/A	N/A	*From Fisher Project No. 18-8687, dated March 2018
1-006	Reception	Walls	Paint	Lead	18-8216-06*	<10 ppm	N/A	N/A	Beige *From Fisher Project No. 18-8687, dated March 2018
1-006	Reception	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
1-007	Photocopy Room	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A	
1-007	Photocopy Room	Walls	Drywall (DJC)	Asbestos	18-8216-01*	None Detected	N/A	N/A	*From Fisher Project No. 18-8687, dated March 2018
1-007	Photocopy Room	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
1-008	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
1-008	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-008	Office	Walls	Paint	Lead	18-8899-74*	<10 ppm	N/A	N/A	Grey *From Fisher Project No. 18-8834, dated May 2018
1-008	Office	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-008	Office	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
1-009	Meeting Room	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
1-009	Meeting Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-009	Meeting Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-009	Meeting Room	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
1-010	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
1-010	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-010	Office	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
1-011	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
1-011	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-011	Office	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
1-012	Meeting Room	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
1-012	Meeting Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-012	Meeting Room	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
1-013	Telecommunication Room	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
1-013	Telecommunication Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-013	Telecommunication Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-014	Electrical Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
1-014	Electrical Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-014	Electrical Room	Ceiling	Not Found	N/A	N/A	N/A	N/A	N/A	Open to above
1-015	Storage	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
1-015	Storage	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-015	Storage	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
1-016	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
1-016	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-016	Office	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
1-017	Men's Washroom	Floor	Vinyl Sheet Flooring 16	Asbestos	Not Sampled	ACM Assumed	40 SF	Good	Grey with Black Dots
1-017	Men's Washroom	Floor	Vinyl Sheet Flooring 8	Asbestos	Homogeneous w/ 15-2988-07 to 09	None Detected	N/A	N/A	Rust with Black and Beige Dots NOT OBSERVED
1-017	Men's Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-017	Men's Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-018	Women's Washroom	Floor	Vinyl Sheet Flooring 16	Asbestos	Not Sampled	ACM Assumed	40 SF	Good	Grey with Black Dots
1-018	Women's Washroom	Floor	Vinyl Sheet Flooring 8	Asbestos	Homogeneous w/ 15-2988-07 to 09	None Detected	N/A	N/A	Rust with Black and Beige Dots NOT OBSERVED
1-018	Women's Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-018	Women's Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-019	Corridor	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
1-019	Corridor	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-019	Corridor	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
1-020	Rotunda	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A	
1-020	Rotunda	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-020	Rotunda	Ceiling	Glass	N/A	N/A	N/A	N/A	N/A	
1-021	Corridor	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
1-021	Corridor	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-021	Corridor	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
1-022	Library	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
1-022	Library	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-022	Library	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
1-023	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
1-023	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-023	Office	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
1-024	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
1-024	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-024	Office	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
1-025	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
1-025	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-025	Office	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
1-026	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
1-026	Office	Walls	Drywall (DJC)	Asbestos	18-8899-26*	None Detected	N/A	N/A	*From Fisher Project No. 18-8834, dated May 2018
1-026	Office	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
1-027	Multi Purpose Room	Floor	Vinyl Sheet Flooring 9	Asbestos	Homogeneous w/ 18-8899-44 to 46	None Detected	N/A	N/A	Beige
1-027	Multi Purpose Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-027	Multi Purpose Room	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
1-028	Beauty Salon	Floor	Vinyl Sheet Flooring 25	Asbestos	Not Sampled	ACM Assumed	220 SF	Good	Grey with Blue and Beige Specks
1-028	Beauty Salon	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-028	Beauty Salon	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-028	Beauty Salon	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
1-029	Bistro	Floor	Vinyl Sheet Flooring 9	Asbestos	Homogeneous w/ 18-8899-44 to 46	None Detected	N/A	N/A	NO ACCESS Beige
1-029	Bistro	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-029	Bistro	Walls	Glass	N/A	N/A	N/A	N/A	N/A	
1-029	Bistro	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
1-030	Gift Shop	Floor	Laminate	N/A	N/A	N/A	N/A	N/A	
1-030	Gift Shop	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-030	Gift Shop	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
1-031	Elevator Lobby	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A	
1-031	Elevator Lobby	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-031	Elevator Lobby	Walls	Paint	Lead	18-8899-72*	<10 ppm	N/A	N/A	Yellow *From Fisher Project No. 18-8834, dated May 2018
1-031	Elevator Lobby	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
1-032	Electrical Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
1-032	Electrical Room	Walls	Block	N/A	N/A	N/A	N/A	N/A	
1-032	Electrical Room	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
1-033	Fire Control	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 15-1632-01 to 03	None Detected	N/A	N/A	12" x 12" Beige with Grey and Brown Smears
1-033	Fire Control	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-033	Fire Control	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
1-034	Corridor	Floor	Vinyl Sheet Flooring 20	Asbestos	Not Sampled	ACM Assumed	600 SF	Good	Dark Grey
1-034	Corridor	Floor	Vinyl Sheet Flooring 11	Asbestos	Homogeneous w/ 15-2988-34 to 38	None Detected	N/A	N/A	Pink with Black Dots NOT OBSERVED
1-034	Corridor	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-034	Corridor	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-035	Stairs # 2	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
1-035	Stairs # 2	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-035	Stairs # 2	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A	
1-036	Corridor	Floor	Vinyl Sheet Flooring 20	Asbestos	Not Sampled	ACM Assumed	900 SF	Good	Dark Grey
1-036	Corridor	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-036	Corridor	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-037	Laundry Room	Floor	Vinyl Sheet Flooring 21	Asbestos	Not Sampled	ACM Assumed	100 SF	Good	Grey with Dark Grey Specks
1-037	Laundry Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-037	Laundry Room	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
1-038	Kitchen and Pantry	Floor	Vinyl Sheet Flooring 21	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	Grey with Dark Grey Specks
1-038	Kitchen and Pantry	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
1-038	Kitchen and Pantry	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-038	Kitchen and Pantry	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
1-039	Staff Washroom	Floor	Vinyl Sheet Flooring 20	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Dark Grey
1-039	Staff Washroom	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
1-039	Staff Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-039	Staff Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
1-040	Staff Lounge	Floor	Vinyl Sheet Flooring 20	Asbestos	Not Sampled	ACM Assumed	260 SF	Good	Dark Grey

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
1-040	Staff Lounge	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-040	Staff Lounge	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
1-041	Office	Floor	Vinyl Sheet Flooring 20	Asbestos	Not Sampled	ACM Assumed	180 SF	Good	Dark Grey
1-041	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-041	Office	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
1-042	Sleep Room	Floor	Vinyl Sheet Flooring 20	Asbestos	Not Sampled	ACM Assumed	240 SF	Good	Dark Grey
1-042	Sleep Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-042	Sleep Room	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
1-043	Infants Room	Floor	Vinyl Sheet Flooring 20	Asbestos	Not Sampled	ACM Assumed	550 SF	Good	Dark Grey
1-043	Infants Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-043	Infants Room	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
1-044	Infant Mud Room	Floor	Vinyl Sheet Flooring 20	Asbestos	Not Sampled	ACM Assumed	110 SF	Good	Dark Grey
1-044	Infant Mud Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-044	Infant Mud Room	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
1-045	Infant Washroom	Floor	Vinyl Sheet Flooring 20	Asbestos	Not Sampled	ACM Assumed	35 SF	Good	Dark Grey
1-045	Infant Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-045	Infant Washroom	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
1-045	Infant Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
1-046	Toddler Mud Room	Floor	Vinyl Sheet Flooring 20	Asbestos	Not Sampled	ACM Assumed	100 SF	Good	Dark Grey
1-046	Toddler Mud Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-046	Toddler Mud Room	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
1-047	Toddler Room	Floor	Vinyl Sheet Flooring 20	Asbestos	Not Sampled	ACM Assumed	565 SF	Good	Dark Grey
1-047	Toddler Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-047	Toddler Room	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
1-048	Toddler Washroom	Floor	Vinyl Sheet Flooring 20	Asbestos	Not Sampled	ACM Assumed	95 SF	Good	Dark Grey
1-048	Toddler Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-048	Toddler Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
1-049	Pre-School Washroom	Floor	Vinyl Sheet Flooring 20	Asbestos	Not Sampled	ACM Assumed	95 SF	Good	Dark Grey
1-049	Pre-School Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-049	Pre-School Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
1-050	Pre-School Mud Room	Floor	Vinyl Sheet Flooring 20	Asbestos	Not Sampled	ACM Assumed	100 SF	Good	Dark Grey
1-050	Pre-School Mud Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-050	Pre-School Mud Room	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
1-051	Pre-School Room	Floor	Vinyl Sheet Flooring 20	Asbestos	Not Sampled	ACM Assumed	885 SF	Good	Dark Grey
1-051	Pre-School Room	Walls	Drywall (DJC)	Asbestos	18-8899-24 and 25*	None Detected	N/A	N/A	*From Fisher Project No. 18-8834, dated May 2018
1-051	Pre-School Room	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
1-052	Storage	Floor	Vinyl Sheet Flooring 20	Asbestos	Not Sampled	ACM Assumed	210 SF	Good	Dark Grey
1-052	Storage	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-052	Storage	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
1-053	Storage	Floor	Vinyl Sheet Flooring 20	Asbestos	Not Sampled	ACM Assumed	90 SF	Good	Dark Grey
1-053	Storage	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-053	Storage	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
1-054	Electrical Room	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A	
1-054	Electrical Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-054	Electrical Room	Ceiling	Not Found	N/A	N/A	N/A	N/A	N/A	Open to above
1-055	Electrical Room	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A	
1-055	Electrical Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-055	Electrical Room	Ceiling	Not Found	N/A	N/A	N/A	N/A	N/A	Open to above
1-056	Washroom	Floor	Vinyl Sheet Flooring 21	Asbestos	Not Sampled	ACM Assumed	180 SF	Good	Grey with Dark Grey Specks
1-056	Washroom	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
1-056	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-056	Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
1-057	Washroom	Floor	Vinyl Sheet Flooring 21	Asbestos	Not Sampled	ACM Assumed	100 SF	Good	Grey with Dark Grey Specks
1-057	Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
1-057	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-057	Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
1-058	Washroom	Floor	Vinyl Sheet Flooring 21	Asbestos	Not Sampled	ACM Assumed	100 SF	Good	Grey with Dark Grey Specks
1-058	Washroom	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
1-058	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-058	Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
1-059	Washroom	Floor	Vinyl Sheet Flooring 21	Asbestos	Not Sampled	ACM Assumed	100 SF	Good	Grey with Dark Grey Specks
1-059	Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-059	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-059	Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
1-060	Washroom	Floor	Vinyl Sheet Flooring 21	Asbestos	Not Sampled	ACM Assumed	100 SF	Good	Grey with Dark Grey Specks
1-060	Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-060	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-060	Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
1-061	Office	Floor	Vinyl Sheet Flooring 20	Asbestos	Not Sampled	ACM Assumed	150 SF	Good	Dark Grey
1-061	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-061	Office	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
1-062	Day Program	Floor	Vinyl Sheet Flooring 4	Asbestos	18-8899-32 to 34*	None Detected	N/A	N/A	Beige Mosaic *From Fisher Project No. 18-8834, dated May 2018
1-062	Day Program	Floor	Vinyl Sheet Flooring 6	Asbestos	18-8899-38 to 40*	None Detected	N/A	N/A	Pink with Brown and Beige Smears *From Fisher Project No. 18-8834, dated May 2018
1-062	Day Program	Floor	Vinyl Sheet Flooring 9	Asbestos	18-8899-44 to 46*	None Detected	N/A	N/A	Beige *From Fisher Project No. 18-8834, dated May 2018
1-062	Day Program	Floor	Vinyl Sheet Flooring 22	Asbestos	18-8899-35 to 37*	None Detected	N/A	N/A	Teal *From Fisher Project No. 18-8834, dated May 2018
1-062	Day Program	Walls	Drywall (DJC)	Asbestos	18-8899-22*	None Detected	N/A	N/A	*From Fisher Project No. 18-8834, dated May 2018
1-062	Day Program	Walls	Paint	Lead	18-9046-19*	<10 ppm	N/A	N/A	Beige *From Fisher Project No. 18-8867, dated June 2018
1-062	Day Program	Walls	Paint	Lead	18-8899-71*	<10 ppm	N/A	N/A	Brown *From Fisher Project No. 18-8834, dated May 2018
1-062	Day Program	Window	Caulking	Asbestos	18-8899-16 to 18*	None Detected	N/A	N/A	Brown from Interior Window *From Fisher Project No. 18-8834, dated May 2018
1-062	Day Program	Ceiling	Drywall (DJC)	Asbestos	18-8899-27, 28*	None Detected	N/A	N/A	*From Fisher Project No. 18-8834, dated May 2018
1-062	Day Program	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
1-062	Day Program	Ceiling	Ceiling Tile 2	Asbestos	18-8899-19 to 21*	None Detected	N/A	N/A	2' x 4' Pinhole Long Fissure *From Fisher Project No. 18-8834, dated May 2018
1-062	Day Program	Ceiling	Ceiling Tile 3	Asbestos	18-8899-29 to 31*	None Detected	N/A	N/A	2' x 4' Pinhole Short Fissure *From Fisher Project No. 18-8834, dated May 2018
1-062	Day Program	Ceiling	Ceiling Tile 4	Asbestos	Homogeneous w/ 15-2988-31 to 33	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
1-063	Servery	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 18-8899-38 to 40	None Detected	N/A	N/A	Pink with Brown and Beige Smears
1-063	Servery	Walls	Block	N/A	N/A	N/A	N/A	N/A	
1-063	Servery	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
1-063	Servery	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 18-8899-19 to 21	None Detected	N/A	N/A	2' x 4' Pinhole Long Fissure
1-064	Dish Washing	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
1-064	Dish Washing	Walls	Block	N/A	N/A	N/A	N/A	N/A	
1-064	Dish Washing	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-065	Corridor	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A	
1-065	Corridor	Walls	Block	N/A	N/A	N/A	N/A	N/A	
1-065	Corridor	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
1-065	Corridor	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 18-8899-19 to 21	None Detected	N/A	N/A	2' x 4' Pinhole Long Fissure
1-066	Telephone Room	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
1-066	Telephone Room	Walls	Block	N/A	N/A	N/A	N/A	N/A	
1-066	Telephone Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-067	Washroom	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
1-067	Washroom	Floor	Vinyl Sheet Flooring 8	Asbestos	Homogeneous w/ 15-2988-07 to 09	None Detected	N/A	N/A	Rust with Black and Beige Dots NOT OBSERVED
1-067	Washroom	Walls	Block	N/A	N/A	N/A	N/A	N/A	
1-067	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-068	Washroom	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
1-068	Washroom	Floor	Vinyl Sheet Flooring 8	Asbestos	Homogeneous w/ 15-2988-07 to 09	None Detected	N/A	N/A	Rust with Black and Beige Dots NOT OBSERVED
1-068	Washroom	Walls	Block	N/A	N/A	N/A	N/A	N/A	
1-068	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-069	Janitor's Closet	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
1-069	Janitor's Closet	Floor	Vinyl Sheet Flooring 8	Asbestos	Homogeneous w/ 15-2988-07 to 09	None Detected	N/A	N/A	Rust with Black and Beige Dots NOT OBSERVED

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
1-069	Janitor's Closet	Walls	Block	N/A	N/A	N/A	N/A	N/A	
1-069	Janitor's Closet	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-070	Washroom	Floor	Vinyl Sheet Flooring 16	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Grey with Black Dots
1-070	Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-070	Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
1-070	Washroom	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 18-8899-19 to 21	None Detected	N/A	N/A	2' x 4' Pinhole Long Fissure
1-070	Washroom	Ceiling	Ceiling Tile 3	Asbestos	Homogeneous w/ 18-8899-29 to 31	None Detected	N/A	N/A	2' x 4' Pinhole Short Fissure
1-071	Dining Room	Floor	Vinyl Sheet Flooring 9	Asbestos	Homogeneous w/ 18-8899-44 to 46	None Detected	N/A	N/A	Beige
1-071	Dining Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-071	Dining Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-071	Dining Room	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
1-072	Servery	Floor	Vinyl Sheet Flooring 8	Asbestos	15-2988-07 to 09*	None Detected	N/A	N/A	Rust with Black and Beige Dots *From Fisher Project No. 15-7543, dated Dec. 2015
1-072	Servery	Walls	Drywall (DJC)	Asbestos	15-2988-01 to 03*	None Detected	N/A	N/A	*From Fisher Project No. 15-7543, dated Dec. 2015
1-072	Servery	Ceiling	Ceiling Tile 1	Asbestos	15-2988-04 to 06*	None Detected	N/A	N/A	2' x 4' Random Pinhole *From Fisher Project No. 15-7543, dated Dec. 2015
1-073	Corridor	Floor	Vinyl Sheet Flooring 9	Asbestos	Homogeneous w/ 18-8899-44 to 46	None Detected	N/A	N/A	Beige
1-073	Corridor	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-073	Corridor	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-073	Corridor	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
1-074	Janitor's Closet	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
1-074	Janitor's Closet	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-074	Janitor's Closet	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-075	Family Lounge	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
1-075	Family Lounge	Floor	Vinyl Sheet Flooring 19	Asbestos	Not Sampled	ACM Assumed	400 SF	Good	Hardwood Design
1-075	Family Lounge	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-075	Family Lounge	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
1-076	Conference Room	Floor	Vinyl Sheet Flooring 9	Asbestos	Homogeneous w/ 18-8899-44 to 46	None Detected	N/A	N/A	Beige
1-076	Conference Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
1-076	Conference Room	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
1-076	Conference Room	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 18-8899-19 to 21	None Detected	N/A	N/A	2' x 4' Pinhole Long Fissure
1-076	Conference Room	Ceiling	Ceiling Tile 3	Asbestos	Homogeneous w/ 18-8899-29 to 31	None Detected	N/A	N/A	2' x 4' Pinhole Short Fissure
1-076	Conference Room	Ceiling	Ceiling Tile 4	Asbestos	Homogeneous w/ 15-2988-31 to 33	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
1-077	Shower & Tub Room	Floor	Vinyl Sheet Flooring 16	Asbestos	Not Sampled	ACM Assumed	240 SF	Good	Grey with Black Dots
1-077	Shower & Tub Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-077	Shower & Tub Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-078	Janitor's Closet	Floor	Vinyl Sheet Flooring 12	Asbestos	Not Sampled	ACM Assumed	160 SF	Good	Beige with Black Dots
1-078	Janitor's Closet	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-078	Janitor's Closet	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-079	Room 120 & WR	Floor	Vinyl Sheet Flooring 12	Asbestos	Not Sampled	ACM Assumed	400 SF	Good	Beige with Black Dots
1-079	Room 120 & WR	Floor	Vinyl Sheet Flooring 11	Asbestos	Homogeneous w/ 15-2988-34 to 38	None Detected	N/A	N/A	Pink with Black Dots NOT OBSERVED
1-079	Room 120 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-079	Room 120 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-079	Room 120 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
1-080	Room 122 & WR	Floor	Vinyl Sheet Flooring 9	Asbestos	Homogeneous w/ 18-8899-44 to 46	None Detected	N/A	N/A	Beige
1-080	Room 122 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-080	Room 122 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-080	Room 122 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
1-081	Stairs # 3	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
1-081	Stairs # 3	Walls	Block	N/A	N/A	N/A	N/A	N/A	
1-081	Stairs # 3	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
1-082	Corridor	Floor	Vinyl Sheet Flooring 9	Asbestos	Homogeneous w/ 18-8899-44 to 46	None Detected	N/A	N/A	Beige
1-082	Corridor	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-082	Corridor	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
1-083	Kitchen	Floor	Vinyl Sheet Flooring 16	Asbestos	Not Sampled	ACM Assumed	150 SF	Good	Grey with Black Dots
1-083	Kitchen	Floor	Vinyl Sheet Flooring 11	Asbestos	15-2988-34*	None Detected	N/A	N/A	Pink with Black Dots *From Fisher Project No. 15-7543, dated Dec. 2015 NOT OBSERVED

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
1-083	Kitchen	Walls	Drywall (DJC)	Asbestos	15-2988-10 to 12*	None Detected	N/A	N/A	*From Fisher Project No. 15-7543, dated Dec. 2015
1-083	Kitchen	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
1-083	Kitchen	Ceiling	Ceiling Tile 7	Asbestos	15-2988-13 to 15*	None Detected	N/A	N/A	2' x 4' Textured Pinhole *From Fisher Project No. 15-7543, dated Dec. 2015
1-084	Dining Room	Floor	Vinyl Sheet Flooring 9	Asbestos	Homogeneous w/ 18-8899-44 to 46	None Detected	N/A	N/A	Beige
1-084	Dining Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-084	Dining Room	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
1-085	Vestibule	Floor	Vinyl Sheet Flooring 9	Asbestos	Homogeneous w/ 18-8899-44 to 46	None Detected	N/A	N/A	Beige
1-085	Vestibule	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-085	Vestibule	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-086	Room 139 & WR	Floor	Vinyl Sheet Flooring 12	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	Beige with Black Dots
1-086	Room 139 & WR	Floor	Vinyl Sheet Flooring 11	Asbestos	Homogeneous w/ 15-2988-34 to 38	None Detected	N/A	N/A	Pink with Black Dots NOT OBSERVED
1-086	Room 139 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-086	Room 139 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-086	Room 139 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
1-087	Room 138 & WR	Floor	Vinyl Sheet Flooring 12	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	Beige with Black Dots
1-087	Room 138 & WR	Floor	Vinyl Sheet Flooring 11	Asbestos	Homogeneous w/ 15-2988-34 to 38	None Detected	N/A	N/A	Pink with Black Dots NOT OBSERVED
1-087	Room 138 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-087	Room 138 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-087	Room 138 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
1-088	Room 137 & WR	Floor	Vinyl Sheet Flooring 12	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	Beige with Black Dots
1-088	Room 137 & WR	Floor	Vinyl Sheet Flooring 11	Asbestos	Homogeneous w/ 15-2988-34 to 38	None Detected	N/A	N/A	Pink with Black Dots NOT OBSERVED
1-088	Room 137 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-088	Room 137 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-088	Room 137 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
1-089	Room 136 & WR	Floor	Vinyl Sheet Flooring 12	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	Beige with Black Dots
1-089	Room 136 & WR	Floor	Vinyl Sheet Flooring 11	Asbestos	Homogeneous w/ 15-2988-34 to 38	None Detected	N/A	N/A	Pink with Black Dots NOT OBSERVED
1-089	Room 136 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
1-089	Room 136 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-089	Room 136 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
1-090	Room 135 & WR	Floor	Vinyl Sheet Flooring 12	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	Beige with Black Dots
1-090	Room 135 & WR	Floor	Vinyl Sheet Flooring 11	Asbestos	Homogeneous w/ 15-2988-34 to 38	None Detected	N/A	N/A	Pink with Black Dots NOT OBSERVED
1-090	Room 135 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-090	Room 135 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-090	Room 135 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
1-091	Room 134 & WR	Floor	Vinyl Sheet Flooring 12	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	Beige with Black Dots
1-091	Room 134 & WR	Floor	Vinyl Sheet Flooring 11	Asbestos	Homogeneous w/ 15-2988-34 to 38	None Detected	N/A	N/A	Pink with Black Dots NOT OBSERVED
1-091	Room 134 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-091	Room 134 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-091	Room 134 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
1-092	Room 133 & WR	Floor	Vinyl Sheet Flooring 12	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	Beige with Black Dots
1-092	Room 133 & WR	Floor	Vinyl Sheet Flooring 11	Asbestos	Homogeneous w/ 15-2988-34 to 38	None Detected	N/A	N/A	Pink with Black Dots NOT OBSERVED
1-092	Room 133 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-092	Room 133 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-092	Room 133 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
1-093	Room 132 & WR	Floor	Vinyl Sheet Flooring 12	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	Beige with Black Dots
1-093	Room 132 & WR	Floor	Vinyl Sheet Flooring 11	Asbestos	Homogeneous w/ 15-2988-34 to 38	None Detected	N/A	N/A	Pink with Black Dots NOT OBSERVED
1-093	Room 132 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-093	Room 132 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-093	Room 132 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
1-094	Room 131 & WR	Floor	Vinyl Sheet Flooring 12	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	Beige with Black Dots
1-094	Room 131 & WR	Floor	Vinyl Sheet Flooring 11	Asbestos	Homogeneous w/ 15-2988-34 to 38	None Detected	N/A	N/A	Pink with Black Dots NOT OBSERVED
1-094	Room 131 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-094	Room 131 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-094	Room 131 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
1-095	Room 130 & WR	Floor	Vinyl Sheet Flooring 12	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	Beige with Black Dots
1-095	Room 130 & WR	Floor	Vinyl Sheet Flooring 11	Asbestos	Homogeneous w/ 15-2988-34 to 38	None Detected	N/A	N/A	Pink with Black Dots NOT OBSERVED
1-095	Room 130 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-095	Room 130 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-095	Room 130 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
1-096	Room 129 & WR	Floor	Vinyl Sheet Flooring 12	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	Beige with Black Dots
1-096	Room 129 & WR	Floor	Vinyl Sheet Flooring 11	Asbestos	Homogeneous w/ 15-2988-34 to 38	None Detected	N/A	N/A	Pink with Black Dots NOT OBSERVED
1-096	Room 129 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-096	Room 129 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-096	Room 129 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
1-097	Room 128 & WR	Floor	Vinyl Sheet Flooring 12	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	Beige with Black Dots
1-097	Room 128 & WR	Floor	Vinyl Sheet Flooring 11	Asbestos	Homogeneous w/ 15-2988-34 to 38	None Detected	N/A	N/A	Pink with Black Dots NOT OBSERVED
1-097	Room 128 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-097	Room 128 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-097	Room 128 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
1-098	Room 127 & WR	Floor	Vinyl Sheet Flooring 12	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	Beige with Black Dots
1-098	Room 127 & WR	Floor	Vinyl Sheet Flooring 11	Asbestos	Homogeneous w/ 15-2988-34 to 38	None Detected	N/A	N/A	Pink with Black Dots NOT OBSERVED
1-098	Room 127 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-098	Room 127 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-098	Room 127 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
1-099	Room 126 & WR	Floor	Vinyl Sheet Flooring 12	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	Beige with Black Dots
1-099	Room 126 & WR	Floor	Vinyl Sheet Flooring 11	Asbestos	Homogeneous w/ 15-2988-34 to 38	None Detected	N/A	N/A	Pink with Black Dots NOT OBSERVED
1-099	Room 126 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-099	Room 126 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-099	Room 126 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
1-100	Vestibule	Floor	Vinyl Sheet Flooring 16	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Grey with Black Dots
1-100	Vestibule	Floor	Vinyl Sheet Flooring 11	Asbestos	Homogeneous w/ 15-2988-34 to 38	None Detected	N/A	N/A	Pink with Black Dots

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
1-100	Vestibule	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-100	Vestibule	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-101	Lounge	Floor	Vinyl Sheet Flooring 19	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	Hardwood Design
1-101	Lounge	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-101	Lounge	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
1-102	Nurses Station	Floor	Vinyl Sheet Flooring 9	Asbestos	Homogeneous w/ 18-8899-44 to 46	None Detected	N/A	N/A	Beige
1-102	Nurses Station	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-102	Nurses Station	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-102	Nurses Station	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
1-103	Washroom	Floor	Vinyl Sheet Flooring 13	Asbestos	Homogeneous w/ 21-5940-1 to 3	None Detected	N/A	N/A	Blue with Beige, Brown and Black Specks
1-103	Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-103	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-104	Storage	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 18-8899-38 to 40	None Detected	N/A	N/A	Pink with Brown and Beige Smears
1-104	Storage	Walls	Drywall (DJC)	N/A	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-104	Storage	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
1-105	Storage	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 18-8899-38 to 40	None Detected	N/A	N/A	Pink with Brown and Beige Smears
1-105	Storage	Walls	Drywall (DJC)	N/A	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-105	Storage	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
1-106	Nurses Supplies	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 18-8899-38 to 40	None Detected	N/A	N/A	NO ACCESS Pink with Brown and Beige Smears
1-106	Nurses Supplies	Walls	Drywall (DJC)	N/A	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-106	Nurses Supplies	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
1-107	Shower & Tub Room	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
1-107	Shower & Tub Room	Floor	Vinyl Sheet Flooring 13	Asbestos	21-5940-1 to 3*	None Detected	N/A	N/A	Blue with Beige, Brown and Black Specks *From Fisher Project No. 21-10932, dated Feb. 2021 NOT OBSERVED
1-107	Shower & Tub Room	Floor	Mastic	Asbestos	21-5940-4 to 6*	None Detected	N/A	N/A	Under Vinyl Sheet Flooring 13 *From Fisher Project No. 21-10932, dated Feb. 2021
1-107	Shower & Tub Room	Walls	Drywall (DJC)	Asbestos	21-5940-7 to 9*	None Detected	N/A	N/A	*From Fisher Project No. 21-10932, dated Feb. 2021
1-107	Shower & Tub Room	Walls	Paint	Lead	21-5940-10*	<10 ppm	N/A	N/A	Light Green *From Fisher Project No. 21-10932, dated Feb. 2021
1-107	Shower & Tub Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
1-108	Washroom	Floor	Vinyl Sheet Flooring 13	Asbestos	Homogeneous w/ 21-5940-1 to 3	None Detected	N/A	N/A	Blue with Beige, Brown and Black Specks
1-108	Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-108	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-109	Shower & Tub Room	Floor	Vinyl Sheet Flooring 13	Asbestos	Homogeneous w/ 21-5940-1 to 3	None Detected	N/A	N/A	Blue with Beige, Brown and Black Specks
1-109	Shower & Tub Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-109	Shower & Tub Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-110	Soiled Utility	Floor	Vinyl Sheet Flooring 8	Asbestos	Homogeneous w/ 15-2988-07 to 09	None Detected	N/A	N/A	Rust with Black and Beige Dots
1-110	Soiled Utility	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-110	Soiled Utility	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
1-111	Janitor's Closet	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
1-111	Janitor's Closet	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-111	Janitor's Closet	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-112	Stairs # 4	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
1-112	Stairs # 4	Walls	Concrete	N/A	N/A	N/A	N/A	N/A	
1-112	Stairs # 4	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A	
1-112	Stairs # 4	Walls	Sprayed Fireproofing	Asbestos	19-2282-1 to 4*	None Detected	N/A	N/A	Inside Pipe Chase *From Fisher Project No. 19-9402, Dated April 2019
1-113	Room 125 & WR	Floor	Vinyl Sheet Flooring 12	Asbestos	Not Sampled	ACM Assumed	160 SF	Good	Beige with Black Dots
1-113	Room 125 & WR	Floor	Vinyl Sheet Flooring 11	Asbestos	Homogeneous w/ 15-2988-34 to 38	None Detected	N/A	N/A	Pink with Black Dots
1-113	Room 125 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-113	Room 125 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-113	Room 125 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
1-114	Lounge	Floor	Vinyl Sheet Flooring 19	Asbestos	Not Sampled	ACM Assumed	400 SF	Good	Hardwood Design
1-114	Lounge	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-114	Lounge	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-114	Lounge	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
1-115	Room 121 & WR	Floor	Vinyl Sheet Flooring 12	Asbestos	Not Sampled	ACM Assumed	160 SF	Good	Beige with Black Dots
1-115	Room 121 & WR	Floor	Vinyl Sheet Flooring 11	Asbestos	Homogeneous w/ 15-2988-34 to 38	None Detected	N/A	N/A	Pink with Black Dots NOT OBSERVED

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
1-115	Room 121 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-115	Room 121 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-115	Room 121 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
1-116	Room 119 & WR	Floor	Vinyl Sheet Flooring 9	Asbestos	Homogeneous w/ 18-8899-44 to 46	None Detected	N/A	N/A	Beige
1-116	Room 119 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-116	Room 119 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-116	Room 119 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
1-117	Room 117 & WR	Floor	Vinyl Sheet Flooring 9	Asbestos	Homogeneous w/ 18-8899-44 to 46	None Detected	N/A	N/A	Beige
1-117	Room 117 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-117	Room 117 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-117	Room 117 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
1-118	Room 115 & WR	Floor	Vinyl Sheet Flooring 12	Asbestos	Not Sampled	ACM Assumed	160 SF	Good	Beige with Black Dots
1-118	Room 115 & WR	Floor	Vinyl Sheet Flooring 11	Asbestos	Homogeneous w/ 15-2988-34 to 38	None Detected	N/A	N/A	Pink with Black Dots NOT OBSERVED
1-118	Room 115 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-118	Room 115 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-118	Room 115 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
1-119	Room 113 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	160 SF	Good	Cream with Rust Swirls
1-119	Room 113 & WR	Floor	Vinyl Sheet Flooring 11	Asbestos	Homogeneous w/ 15-2988-34 to 38	None Detected	N/A	N/A	Pink with Black Dots NOT OBSERVED
1-119	Room 113 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-119	Room 113 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-119	Room 113 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
1-120	Vestibule	Floor	Vinyl Sheet Flooring 9	Asbestos	Homogeneous w/ 18-8899-44 to 46	None Detected	N/A	N/A	Beige
1-120	Vestibule	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-120	Vestibule	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
1-121	Electrical Room	Floor	Vinyl Sheet Flooring 9	Asbestos	Homogeneous w/ 18-8899-44 to 46	None Detected	N/A	N/A	Beige
1-121	Electrical Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-121	Electrical Room	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
1-122	Storage	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 18-8899-38 to 40	None Detected	N/A	N/A	Pink with Brown and Beige Smears
1-122	Storage	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-122	Storage	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
1-123	Servery	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 18-8899-38 to 40	None Detected	N/A	N/A	Pink with Brown and Beige Smears
1-123	Servery	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-123	Servery	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
1-124	Auditorium	Floor	Vinyl Sheet Flooring 4	Asbestos	Homogeneous w/ 18-8899-32 to 34	None Detected	N/A	N/A	Beige Mosaic
1-124	Auditorium	Floor	Vinyl Sheet Flooring 11	Asbestos	Homogeneous w/ 15-2988-34 to 38	None Detected	N/A	N/A	Pink with Black Dots
1-124	Auditorium	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-124	Auditorium	Walls	Block	N/A	N/A	N/A	N/A	N/A	
1-124	Auditorium	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
1-125	Storage	Floor	Vinyl Sheet Flooring 4	Asbestos	Homogeneous w/ 18-8899-32 to 34	None Detected	N/A	N/A	Beige Mosaic
1-125	Storage	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-125	Storage	Ceiling	Not Found	N/A	N/A	N/A	N/A	N/A	Open to above
1-126	Storage	Floor	Vinyl Sheet Flooring 21	Asbestos	Not Sampled	ACM Assumed	60 SF	Good	Grey with Dark Grey Specks
1-126	Storage	Floor	Vinyl Sheet Flooring 11	Asbestos	Homogeneous w/ 15-2988-34 to 38	None Detected	N/A	N/A	Pink with Black Dots NOT OBSERVED
1-126	Storage	Walls	Block	N/A	N/A	N/A	N/A	N/A	
1-126	Storage	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
1-127	Cafeteria	Floor	Vinyl Sheet Flooring 11	Asbestos	Homogeneous w/ 15-2988-34 to 38	None Detected	N/A	N/A	Pink with Black Dots
1-127	Cafeteria	Walls	Block	N/A	N/A	N/A	N/A	N/A	
1-127	Cafeteria	Walls	Drywall (DJC)	Asbestos	18-8899-23*	None Detected	N/A	N/A	*From Fisher Project No. 18-8834, dated May 2018
1-127	Cafeteria	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
1-128	Corridor	Floor	Vinyl Sheet Flooring 11	Asbestos	Homogeneous w/ 15-2988-34 to 38	None Detected	N/A	N/A	Pink with Black Dots
1-128	Corridor	Walls	Block	N/A	N/A	N/A	N/A	N/A	
1-128	Corridor	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
1-129	Washroom	Floor	Vinyl Sheet Flooring 11	Asbestos	Homogeneous w/ 15-2988-34 to 38	None Detected	N/A	N/A	Pink with Black Dots
1-129	Washroom	Walls	Block	N/A	N/A	N/A	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
1-129	Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
1-130	Washroom	Floor	Vinyl Sheet Flooring 11	Asbestos	Homogeneous w/ 15-2988-34 to 38	None Detected	N/A	N/A	Pink with Black Dots
1-130	Washroom	Walls	Block	N/A	N/A	N/A	N/A	N/A	
1-130	Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
1-131	Storage	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 15-1632-01 to 03	None Detected	N/A	N/A	NO ACCESS 12" x 12" Beige with Grey and Brown Smears
1-131	Storage	Floor	Vinyl Sheet Flooring 23	Asbestos	18-8899-41 to 43*	None Detected	N/A	N/A	Grey *From Fisher Project No. 18-8834, dated May 2018
1-131	Storage	Walls	Block	N/A	N/A	N/A	N/A	N/A	
1-131	Storage	Duct	Sprayed Fireproofing	Asbestos	22-7881-10*	None Detected	N/A	N/A	*From Fisher Project No. 22-11869, dated Feb. 2022
1-131	Storage	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
1-132	Vestibule	Floor	Vinyl Sheet Flooring 9	Asbestos	Homogeneous w/ 18-8899-44 to 46	None Detected	N/A	N/A	Beige
1-132	Vestibule	Walls	Block	N/A	N/A	N/A	N/A	N/A	
1-132	Vestibule	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-22 to 28	None Detected	N/A	N/A	
1-132	Vestibule	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
1-133	Solarium	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A	
1-133	Solarium	Walls	Block/Glass	N/A	N/A	N/A	N/A	N/A	
1-133	Solarium	Ceiling	Ceiling Tile 5	Asbestos	Not Sampled	ACM Assumed	290 SF	Good	2' x 4' Pinhole Thick Long Fissure
2-001	Elevator Lobby	Floor	Vinyl Sheet Flooring 9	Asbestos	Homogeneous w/ 18-8899-44 to 46	None Detected	N/A	N/A	Beige
2-001	Elevator Lobby	Walls	Drywall (DJC)	Asbestos	18-8899-69*	None Detected	N/A	N/A	*From Fisher Project No. 18-8834, dated May 2018
2-001	Elevator Lobby	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-001	Elevator Lobby	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
2-002	Nurses Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
2-002	Nurses Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-002	Nurses Office	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
2-003	Nurses Station	Floor	Vinyl Sheet Flooring 9	Asbestos	Homogeneous w/ 18-8899-44 to 46	None Detected	N/A	N/A	Beige
2-003	Nurses Station	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-003	Nurses Station	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
2-004	Medication Room	Floor	Vinyl Sheet Flooring 9	Asbestos	Homogeneous w/ 18-8899-44 to 46	None Detected	N/A	N/A	Beige
2-004	Medication Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-004	Medication Room	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
2-005	Washroom	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
2-005	Washroom	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 18-8899-38 to 40	None Detected	N/A	N/A	Pink with Brown and Beige Smears NOT OBSERVED
2-005	Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-005	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-006	Corridor	Floor	Vinyl Sheet Flooring 9	Asbestos	Homogeneous w/ 18-8899-44 to 46	None Detected	N/A	N/A	Beige
2-006	Corridor	Walls	Drywall (DJC)	Asbestos	18-8899-68*	None Detected	N/A	N/A	*From Fisher Project No. 18-8834, dated May 2018
2-006	Corridor	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
2-007	Room 212 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	160 SF	Good	Cream with Rust Swirls
2-007	Room 212 & WR	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED
2-007	Room 212 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-007	Room 212 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-007	Room 212 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
2-008	Room 214 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	160 SF	Good	Cream with Rust Swirls
2-008	Room 214 & WR	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED
2-008	Room 214 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-008	Room 214 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-008	Room 214 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
2-009	Janitor's Closet	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink
2-009	Janitor's Closet	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-009	Janitor's Closet	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
2-010	Room 216 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	160 SF	Good	Cream with Rust Swirls
2-010	Room 216 & WR	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED
2-010	Room 216 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-010	Room 216 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-010	Room 216 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
2-011	Shower & Tub Room	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
2-011	Shower & Tub Room	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
2-011	Shower & Tub Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-012	Room 218 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	160 SF	Good	Cream with Rust Swirls
2-012	Room 218 & WR	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED
2-012	Room 218 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-012	Room 218 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-012	Room 218 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
2-013	Soiled Utility	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 18-8899-38 to 40	None Detected	N/A	N/A	Pink with Brown and Beige Smears
2-013	Soiled Utility	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-013	Soiled Utility	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-014	Room 220 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	160 SF	Good	Cream with Rust Swirls
2-014	Room 220 & WR	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED
2-014	Room 220 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-014	Room 220 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-014	Room 220 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
2-015	Room 222 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	160 SF	Good	Cream with Rust Swirls
2-015	Room 222 & WR	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
2-015	Room 222 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-015	Room 222 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-015	Room 222 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
2-016	Corridor	Floor	Vinyl Sheet Flooring 26	Asbestos	Not Sampled	ACM Assumed	600 SF	Good	Beige with Brown Lines
2-016	Corridor	Floor	Vinyl Sheet Flooring 9	Asbestos	Homogeneous w/ 18-8899-44 to 46	None Detected	N/A	N/A	Beige NOT OBSERVED
2-016	Corridor	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-016	Corridor	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
2-017	Conference Room	Floor	Vinyl Sheet Flooring 9	Asbestos	Homogeneous w/ 18-8899-44 to 46	None Detected	N/A	N/A	Beige
2-017	Conference Room	Walls	Drywall (DJC)	Asbestos	18-8899-70*	None Detected	N/A	N/A	*From Fisher Project No. 18-8834, dated May 2018
2-017	Conference Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-017	Conference Room	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
2-018	Nurses Station	Floor	Vinyl Sheet Flooring 9	Asbestos	Homogeneous w/ 18-8899-44 to 46	None Detected	N/A	N/A	Beige
2-018	Nurses Station	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED
2-018	Nurses Station	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-018	Nurses Station	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
2-019	Electrical Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
2-019	Electrical Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-019	Electrical Room	Ceiling	Sprayed Fireproofing	Asbestos	Homogeneous w/ 18-8899-56 to 58 and 19-2282-1 to 4	None Detected	N/A	N/A	
2-020	Corridor	Floor	Vinyl Sheet Flooring 26	Asbestos	Not Sampled	ACM Assumed	500 SF	Good	Beige with Brown Lines
2-020	Corridor	Floor	Vinyl Sheet Flooring 9	Asbestos	Homogeneous w/ 18-8899-44 to 46	None Detected	N/A	N/A	Beige NOT OBSERVED
2-020	Corridor	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-020	Corridor	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
2-021	Room 238 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	160 SF	Good	Cream with Rust Swirls

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
2-021	Room 238 & WR	Floor	Vinyl Sheet Flooring 9	Asbestos	Homogeneous w/ 18-8899-44 to 46	None Detected	N/A	N/A	Beige NOT OBSERVED
2-021	Room 238 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-021	Room 238 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-021	Room 238 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
2-022	Room 237 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	160 SF	Good	Cream with Rust Swirls
2-022	Room 237 & WR	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED
2-022	Room 237 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-022	Room 237 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-022	Room 237 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
2-023	Room 236& WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	160 SF	Good	Cream with Rust Swirls
2-023	Room 236& WR	Floor	Vinyl Sheet Flooring 9	Asbestos	Homogeneous w/ 18-8899-44 to 46	None Detected	N/A	N/A	Beige NOT OBSERVED
2-023	Room 236 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-023	Room 236 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-023	Room 236 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
2-024	Room 235 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	160 SF	Good	Cream with Rust Swirls
2-024	Room 235 & WR	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED
2-024	Room 235 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-024	Room 235 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-024	Room 235 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
2-025	Room 234 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	160 SF	Good	Cream with Rust Swirls
2-025	Room 234 & WR	Floor	Vinyl Sheet Flooring 9	Asbestos	Homogeneous w/ 18-8899-44 to 46	None Detected	N/A	N/A	Beige NOT OBSERVED
2-025	Room 234 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-025	Room 234 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
2-025	Room 234 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
2-026	Room 233 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	160 SF	Good	Cream with Rust Swirls
2-026	Room 233 & WR	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED
2-026	Room 233 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-026	Room 233 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-026	Room 233 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
2-027	Room 232 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	160 SF	Good	Cream with Rust Swirls
2-027	Room 232 & WR	Floor	Vinyl Sheet Flooring 9	Asbestos	Homogeneous w/ 18-8899-44 to 46	None Detected	N/A	N/A	Beige NOT OBSERVED
2-027	Room 232 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-027	Room 232 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-027	Room 232 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
2-028	Room 231 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	160 SF	Good	Cream with Rust Swirls
2-028	Room 231 & WR	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED
2-028	Room 231 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-028	Room 231 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-028	Room 231 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
2-029	Room 230 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	160 SF	Good	Cream with Rust Swirls
2-029	Room 230 & WR	Floor	Vinyl Sheet Flooring 9	Asbestos	Homogeneous w/ 18-8899-44 to 46	None Detected	N/A	N/A	Beige NOT OBSERVED
2-029	Room 230 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-029	Room 230 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-029	Room 230 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
2-030	Room 229 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	160 SF	Good	Cream with Rust Swirls
2-030	Room 229 & WR	Floor	Vinyl Sheet Flooring 9	Asbestos	Homogeneous w/ 18-8899-44 to 46	None Detected	N/A	N/A	Beige NOT OBSERVED

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
2-030	Room 229 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-030	Room 229 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-030	Room 229 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
2-031	Room 228 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	160 SF	Good	Cream with Rust Swirls
2-031	Room 228 & WR	Floor	Vinyl Sheet Flooring 9	Asbestos	Homogeneous w/ 18-8899-44 to 46	None Detected	N/A	N/A	Beige NOT OBSERVED
2-031	Room 228 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-031	Room 228 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-031	Room 228 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
2-032	Room 227 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	160 SF	Good	Cream with Rust Swirls
2-032	Room 227 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-032	Room 227 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-032	Room 227 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
2-033	Room 226 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	160 SF	Good	Cream with Rust Swirls
2-033	Room 226 & WR	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED
2-033	Room 226 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-033	Room 226 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-033	Room 226 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
2-034	Washroom	Floor	Vinyl Sheet Flooring 26	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Beige with Brown Lines
2-034	Washroom	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED
2-034	Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-034	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-035	Shower & Tub Room	Floor	Vinyl Sheet Flooring 13	Asbestos	Homogeneous w/ 21-5940-1 to 3	None Detected	N/A	N/A	Blue with Beige, Brown and Black Specks
2-035	Shower & Tub Room	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
2-035	Shower & Tub Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-036	Washroom	Floor	Vinyl Sheet Flooring 13	Asbestos	Homogeneous w/ 21-5940-1 to 3	None Detected	N/A	N/A	Blue with Beige, Brown and Black Specks
2-036	Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-036	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-037	Shower & Tub Room	Floor	Vinyl Sheet Flooring 13	Asbestos	Homogeneous w/ 21-5940-1 to 3	None Detected	N/A	N/A	Blue with Beige, Brown and Black Specks
2-037	Shower & Tub Room	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
2-037	Shower & Tub Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-037	Shower & Tub Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-038	Clean Utility	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink
2-038	Clean Utility	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-038	Clean Utility	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-039	Soiled Utility	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink
2-039	Soiled Utility	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-039	Soiled Utility	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-040	Lounge	Floor	Vinyl Sheet Flooring 19	Asbestos	Not Sampled	ACM Assumed	400 SF	Good	Hardwood Design
2-040	Lounge	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-040	Lounge	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
2-041	Janitor's Closet	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink
2-041	Janitor's Closet	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-041	Janitor's Closet	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
2-042	Room 225 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	160 SF	Good	Cream with Rust Swirls
2-042	Room 225 & WR	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
2-042	Room 225 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-042	Room 225 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-042	Room 225 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
2-043	Room 223 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	160 SF	Good	Cream with Rust Swirls
2-043	Room 223 & WR	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED
2-043	Room 223 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-043	Room 223 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-043	Room 223 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
2-044	Room 221 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	160 SF	Good	Cream with Rust Swirls
2-044	Room 221 & WR	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED
2-044	Room 221 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-044	Room 221 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-044	Room 221 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
2-045	Room 219 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	160 SF	Good	Cream with Rust Swirls
2-045	Room 219 & WR	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED
2-045	Room 219 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-045	Room 219 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-045	Room 219 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
2-046	Room 217 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	160 SF	Good	Cream with Rust Swirls
2-046	Room 217 & WR	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED
2-046	Room 217 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-046	Room 217 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-046	Room 217 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
2-047	Room 215 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	160 SF	Good	Cream with Rust Swirls
2-047	Room 215 & WR	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED
2-047	Room 215 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-047	Room 215 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-047	Room 215 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
2-048	Room 213 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	160 SF	Good	Cream with Rust Swirls
2-048	Room 213 & WR	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED
2-048	Room 213 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-048	Room 213 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-048	Room 213 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
2-049	Laundry Room	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
2-049	Laundry Room	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED
2-049	Laundry Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-049	Laundry Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-050	Lounge	Floor	Parquet	N/A	N/A	N/A	N/A	N/A	
2-050	Lounge	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-050	Lounge	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
2-051	Dining Room	Floor	Vinyl Sheet Flooring 9	Asbestos	Homogeneous w/ 18-8899-44 to 46	None Detected	N/A	N/A	Beige
2-051	Dining Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-051	Dining Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-051	Dining Room	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
2-052	Kitchen	Floor	Vinyl Sheet Flooring 11	Asbestos	15-2988-35*	None Detected	N/A	N/A	Pink with Black Dots *From Fisher Project No. 15-7543, dated Dec. 2015
2-052	Kitchen	Floor	Vinyl Sheet Flooring 9	Asbestos	Homogeneous w/ 18-8899-44 to 46	None Detected	N/A	N/A	Beige NOT OBSERVED

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
2-052	Kitchen	Walls	Drywall (DJC)	Asbestos	15-2988-16 to 18*	None Detected	N/A	N/A	*From Fisher Project No. 15-7543, dated Dec. 2015
2-052	Kitchen	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-053	Washroom	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
2-053	Washroom	Walls	Block	N/A	N/A	N/A	N/A	N/A	
2-053	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-054	Nurses Supplies	Floor	Vinyl Sheet Flooring 18	Asbestos	Not Sampled	ACM Assumed	60 SF	Good	NO ACCESS Green with Black Dots
2-054	Nurses Supplies	Walls	Block	N/A	N/A	N/A	N/A	N/A	
2-054	Nurses Supplies	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-055	Office	Floor	Vinyl Sheet Flooring 4	Asbestos	Homogeneous w/ 18-8899-32 to 34	None Detected	N/A	N/A	Beige Mosaic
2-055	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-055	Office	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
2-056	Office	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 18-8899-38 to 40	None Detected	N/A	N/A	Pink with Brown and Beige Smears
2-056	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-056	Office	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
2-057	Electrical Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
2-057	Electrical Room	Walls	Block	N/A	N/A	N/A	N/A	N/A	
2-057	Electrical Room	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
2-058	Corridor	Floor	Vinyl Sheet Flooring 9	Asbestos	Homogeneous w/ 18-8899-44 to 46	None Detected	N/A	N/A	Beige
2-058	Corridor	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-058	Corridor	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
2-059	Lounge	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink
2-059	Lounge	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-059	Lounge	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
2-059	Lounge	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
2-060	Room 211 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	160 SF	Good	Cream with Rust Swirls
2-060	Room 211 & WR	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED
2-060	Room 211 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-060	Room 211 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-060	Room 211 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
2-061	Room 209 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	160 SF	Good	Cream with Rust Swirls
2-061	Room 209 & WR	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED
2-061	Room 209 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-061	Room 209 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-061	Room 209 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
2-062	Room 207 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	160 SF	Good	Cream with Rust Swirls
2-062	Room 207 & WR	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED
2-062	Room 207 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-062	Room 207 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-062	Room 207 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
2-063	Room 205 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	160 SF	Good	Cream with Rust Swirls
2-063	Room 205 & WR	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED
2-063	Room 205 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-063	Room 205 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-063	Room 205 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
2-064	Room 203 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	160 SF	Good	Cream with Rust Swirls
2-064	Room 203 & WR	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
2-064	Room 203 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-064	Room 203 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-064	Room 203 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
2-065	Room 201 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	160 SF	Good	Cream with Rust Swirls
2-065	Room 201 & WR	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED
2-065	Room 201 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-065	Room 201 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-065	Room 201 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
2-066	Clean Utility	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink
2-066	Clean Utility	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-066	Clean Utility	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-067	Soiled Utility	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink
2-067	Soiled Utility	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-067	Soiled Utility	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-068	Lounge	Floor	Vinyl Sheet Flooring 21	Asbestos	Not Sampled	ACM Assumed	100 SF	Good	Grey with Dark Grey Specks
2-068	Lounge	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-068	Lounge	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
2-069	Room 202 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	160 SF	Good	Cream with Rust Swirls
2-069	Room 202 & WR	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED
2-069	Room 202 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-069	Room 202 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-069	Room 202 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
2-070	Room 204 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	160 SF	Good	Cream with Rust Swirls
2-070	Room 204 & WR	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED
2-070	Room 204 & WR	Floor	Vinyl Sheet Flooring 9	Asbestos	Homogeneous w/ 18-8899-44 to 46	None Detected	N/A	N/A	Beige
2-070	Room 204 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-070	Room 204 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-070	Room 204 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
2-071	Washroom	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
2-071	Washroom	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 18-8899-38 to 40	None Detected	N/A	N/A	Pink with Brown and Beige Smears NOT OBSERVED
2-071	Washroom	Floor	Vinyl Sheet Flooring 9	Asbestos	Homogeneous w/ 18-8899-44 to 46	None Detected	N/A	N/A	Beige NOT OBSERVED
2-071	Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-071	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-072	Room 206 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	160 SF	Good	Cream with Rust Swirls
2-072	Room 206 & WR	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED
2-072	Room 206 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-072	Room 206 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-072	Room 206 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
2-073	Shower & Tub Room	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
2-073	Shower & Tub Room	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
2-073	Shower & Tub Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-074	Room 208 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	160 SF	Good	Cream with Rust Swirls
2-074	Room 208 & WR	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED
2-074	Room 208 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-074	Room 208 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
2-074	Room 208 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
2-075	Janitor's Closet	Floor	Vinyl Sheet Flooring 15	Asbestos	18-9720-01 to 03*	None Detected	N/A	N/A	Pink *Fisher Project No. 18-8787, September 2018
2-075	Janitor's Closet	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-075	Janitor's Closet	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-076	Room 210 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	160 SF	Good	Cream with Rust Swirls
2-076	Room 210 & WR	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED
2-076	Room 210 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-076	Room 210 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-076	Room 210 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
2-077	Lounge	Floor	Vinyl Sheet Flooring 21	Asbestos	Not Sampled	ACM Assumed	100 SF	Good	Grey with Dark Grey Specks
2-077	Lounge	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-077	Lounge	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-077	Lounge	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
2-078	Linen Chute	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 18-8899-38 to 40	None Detected	N/A	N/A	Pink with Brown and Beige Smears
2-078	Linen Chute	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-078	Linen Chute	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
2-079	Linen Room	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 18-8899-38 to 40	None Detected	N/A	N/A	Pink with Brown and Beige Smears
2-079	Linen Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-079	Linen Room	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
2-080	Electrical/Sprinkler	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 15-1632-01 to 03	None Detected	N/A	N/A	12" x 12" Beige with Grey and Brown Smears
2-080	Electrical/Sprinkler	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8899-68 to 70 & 15-2988-16 to 18	None Detected	N/A	N/A	
2-080	Electrical/Sprinkler	Ceiling	Not Found	N/A	N/A	N/A	N/A	N/A	Open to above

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
2-080	Electrical/Sprinkler	Ceiling	Sprayed Fireproofing	Asbestos	Homogeneous w/ 18-8899-56 to 58 and 19-2282-1 to 4	None Detected	N/A	N/A	NOT OBSERVED
3-001	Elevator Lobby	Floor	Vinyl Sheet Flooring 9	Asbestos	Homogeneous w/ 18-8899-44 to 46	None Detected	N/A	N/A	Beige
3-001	Elevator Lobby	Walls	Drywall (DJC)	Asbestos	18-8899-61*	None Detected	N/A	N/A	*From Fisher Project No. 18-8834, dated May 2018
3-001	Elevator Lobby	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-001	Elevator Lobby	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
3-002	Nurses Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
3-002	Nurses Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-002	Nurses Office	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
3-003	Nurses Station	Floor	Vinyl Sheet Flooring 9	Asbestos	Homogeneous w/ 18-8899-44 to 46	None Detected	N/A	N/A	Beige
3-003	Nurses Station	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-003	Nurses Station	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
3-004	Medication Room	Floor	Vinyl Sheet Flooring 9	Asbestos	Homogeneous w/ 18-8899-44 to 46	None Detected	N/A	N/A	Beige
3-004	Medication Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-004	Medication Room	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
3-005	Washroom	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
3-005	Washroom	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 18-8899-38 to 40	None Detected	N/A	N/A	Pink with Brown and Beige Smears NOT OBSERVED
3-005	Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-005	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-005	Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole NOT OBSERVED
3-006	Corridor	Floor	Vinyl Sheet Flooring 9	Asbestos	Homogeneous w/ 18-8899-44 to 46	None Detected	N/A	N/A	Beige
3-006	Corridor	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-006	Corridor	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
3-007	Room 312 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	160 SF	Good	Cream with Rust Swirls

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
3-007	Room 312 & WR	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED
3-007	Room 312 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-007	Room 312 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-007	Room 312 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
3-008	Room 314 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	160 SF	Good	Cream with Rust Swirls
3-008	Room 314 & WR	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED
3-008	Room 314 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-008	Room 314 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-008	Room 314 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
3-009	Janitor's Closet	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
3-009	Janitor's Closet	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED
3-009	Janitor's Closet	Walls	Drywall (DJC)	Asbestos	18-8899-60*	None Detected	N/A	N/A	*From Fisher Project No. 18-8834, dated May 2018
3-009	Janitor's Closet	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-010	Room 316 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	160 SF	Good	Cream with Rust Swirls
3-010	Room 316 & WR	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED
3-010	Room 316 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-010	Room 316 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-010	Room 316 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
3-011	Shower & Tub Room	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
3-011	Shower & Tub Room	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
3-011	Shower & Tub Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-012	Room 318 & WR	Floor	Vinyl Sheet Flooring 9	Asbestos	Homogeneous w/ 18-8899-44 to 46	None Detected	N/A	N/A	Beige
3-012	Room 318 & WR	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
3-012	Room 318 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-012	Room 318 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-012	Room 318 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
3-013	Soiled Utility	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 18-8899-38 to 40	None Detected	N/A	N/A	Pink with Brown and Beige Smears
3-013	Soiled Utility	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-013	Soiled Utility	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-014	Room 320 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	160 SF	Good	Cream with Rust Swirls
3-014	Room 320 & WR	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED
3-014	Room 320 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-014	Room 320 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-014	Room 320 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
3-015	Room 322 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	160 SF	Good	Cream with Rust Swirls
3-015	Room 322 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-015	Room 322 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-015	Room 322 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-015	Room 322 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
3-016	Corridor	Floor	Vinyl Sheet Flooring 9	Asbestos	Homogeneous w/ 18-8899-44 to 46	None Detected	N/A	N/A	Beige
3-016	Corridor	Walls	Drywall (DJC)	Asbestos	18-8899-59*	None Detected	N/A	N/A	*From Fisher Project No. 18-8834, dated May 2018
3-016	Corridor	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
3-017	Conference Room	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
3-017	Conference Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-017	Conference Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
3-017	Conference Room	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
3-018	Rehab Room	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 18-8899-38 to 40	None Detected	N/A	N/A	Pink with Brown and Beige Smears
3-018	Rehab Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-018	Rehab Room	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
3-019	Electrical Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
3-019	Electrical Room	Floor	Firestop-Red	Asbestos	22-7881-11, 12*	None Detected	N/A	N/A	*From Fisher Project No. 22-11869, dated Feb. 2022
3-019	Electrical Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-019	Electrical Room	Ceiling	Sprayed Fireproofing	Asbestos	Homogeneous w/ 18-8899-56 to 58 and 19-2282-1 to 4	None Detected	N/A	N/A	
3-020	Corridor	Floor	Vinyl Sheet Flooring 9	Asbestos	Homogeneous w/ 18-8899-44 to 46	None Detected	N/A	N/A	Beige
3-020	Corridor	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-020	Corridor	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
3-021	Room 338 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	160 SF	Good	Cream with Rust Swirls
3-021	Room 338 & WR	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED
3-021	Room 338 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-021	Room 338 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-021	Room 338 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
3-022	Room 337 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	160 SF	Good	Cream with Rust Swirls
3-022	Room 337 & WR	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED
3-022	Room 337 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-022	Room 337 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-022	Room 337 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
3-023	Room 336 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	160 SF	Good	Cream with Rust Swirls
3-023	Room 336 & WR	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
3-023	Room 336 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-023	Room 336 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-023	Room 336 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
3-024	Room 335 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	160 SF	Good	Cream with Rust Swirls
3-024	Room 335 & WR	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED
3-024	Room 335 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-024	Room 335 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-024	Room 335 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
3-025	Room 334 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	160 SF	Good	Cream with Rust Swirls
3-025	Room 334 & WR	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED
3-025	Room 334 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-025	Room 334 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-025	Room 334 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
3-026	Room 333 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	160 SF	Good	Cream with Rust Swirls
3-026	Room 333 & WR	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED
3-026	Room 333 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-026	Room 333 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-026	Room 333 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
3-027	Room 332 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	160 SF	Good	Cream with Rust Swirls
3-027	Room 332 & WR	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED
3-027	Room 332 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-027	Room 332 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-027	Room 332 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
3-028	Room 331 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	160 SF	Good	Cream with Rust Swirls
3-028	Room 331 & WR	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED
3-028	Room 331 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-028	Room 331 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-028	Room 331 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
3-029	Room 330 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	160 SF	Good	Cream with Rust Swirls
3-029	Room 330 & WR	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED
3-029	Room 330 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-029	Room 330 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-029	Room 330 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
3-030	Room 329 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	160 SF	Good	Cream with Rust Swirls
3-030	Room 329 & WR	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED
3-030	Room 329 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-030	Room 329 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-030	Room 329 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
3-031	Room 328 & WR	Floor	Vinyl Sheet Flooring 12	Asbestos	Not Sampled	ACM Assumed	160 SF	Good	Beige with Black Dots
3-031	Room 328 & WR	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED
3-031	Room 328 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-031	Room 328 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-031	Room 328 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
3-032	Room 327 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	160 SF	Good	Cream with Rust Swirls
3-032	Room 327 & WR	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED
3-032	Room 327 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
3-032	Room 327 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-032	Room 327 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
3-033	Room 326 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	160 SF	Good	Cream with Rust Swirls
3-033	Room 326 & WR	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED
3-033	Room 326 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-033	Room 326 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-033	Room 326 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
3-034	Washroom	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink
3-034	Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-034	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-035	Shower & Tub Room	Floor	Vinyl Sheet Flooring 13	Asbestos	Homogeneous w/ 21-5940-1 to 3	None Detected	N/A	N/A	Blue with Beige, Brown and Black Specks
3-035	Shower & Tub Room	Floor	Vinyl Sheet Flooring 24	Asbestos	Not Sampled	ACM Assumed	120 SF	Good	Grey with White Dots
3-035	Shower & Tub Room	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
3-035	Shower & Tub Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-036	Washroom	Floor	Vinyl Sheet Flooring 13	Asbestos	Homogeneous w/ 21-5940-1 to 3	None Detected	N/A	N/A	Blue with Beige, Brown and Black Specks
3-036	Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-036	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-037	Shower & Tub Room	Floor	Vinyl Sheet Flooring 13	Asbestos	Homogeneous w/ 21-5940-1 to 3	None Detected	N/A	N/A	Blue with Beige, Brown and Black Specks
3-037	Shower & Tub Room	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
3-037	Shower & Tub Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-037	Shower & Tub Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-038	Clean Utility	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
3-038	Clean Utility	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-038	Clean Utility	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-039	Soiled Utility	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink
3-039	Soiled Utility	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-039	Soiled Utility	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-040	Lounge	Floor	Vinyl Sheet Flooring 19	Asbestos	Not Sampled	ACM Assumed	350 SF	Good	Hardwood Design
3-040	Lounge	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-040	Lounge	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
3-041	Janitor's Closet	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 18-8899-38 to 40	None Detected	N/A	N/A	Pink with Brown and Beige Smears
3-041	Janitor's Closet	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-041	Janitor's Closet	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-042	Room 325 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	160 SF	Good	Cream with Rust Swirls
3-042	Room 325 & WR	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED
3-042	Room 325 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-042	Room 325 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-042	Room 325 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
3-043	Room 323 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	160 SF	Good	Cream with Rust Swirls
3-043	Room 323 & WR	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED
3-043	Room 323 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-043	Room 323 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-043	Room 323 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
3-044	Room 321 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	160 SF	Good	Cream with Rust Swirls

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
3-044	Room 321 & WR	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED
3-044	Room 321 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-044	Room 321 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-044	Room 321 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
3-045	Room 319 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	160 SF	Good	Cream with Rust Swirls
3-045	Room 319 & WR	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED
3-045	Room 319 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-045	Room 319 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-045	Room 319 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
3-046	Room 317 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	160 SF	Good	Cream with Rust Swirls
3-046	Room 317 & WR	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED
3-046	Room 317 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-046	Room 317 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-046	Room 317 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
3-047	Room 315 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	160 SF	Good	Cream with Rust Swirls
3-047	Room 315 & WR	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED
3-047	Room 315 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-047	Room 315 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-047	Room 315 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
3-048	Room 313 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	160 SF	Good	Cream with Rust Swirls
3-048	Room 313 & WR	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED
3-048	Room 313 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-048	Room 313 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
3-048	Room 313 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
3-049	Laundry Room	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
3-049	Laundry Room	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED
3-049	Laundry Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-049	Laundry Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-050	Lounge	Floor	Parquet	N/A	N/A	N/A	N/A	N/A	
3-050	Lounge	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-050	Lounge	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
3-051	Dining Room	Floor	Vinyl Sheet Flooring 9	Asbestos	Homogeneous w/ 18-8899-44 to 46	None Detected	N/A	N/A	Beige
3-051	Dining Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-051	Dining Room	Window	Putty	Asbestos	18-8899-53 to 55*	None Detected	N/A	N/A	Black *From Fisher Project No. 18-8834, dated May 2018
3-051	Dining Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-051	Dining Room	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
3-052	Kitchen	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 18-8899-38 to 40	None Detected	N/A	N/A	Pink with Brown and Beige Smears
3-052	Kitchen	Floor	Vinyl Sheet Flooring 9	Asbestos	Homogeneous w/ 18-8899-44 to 46	None Detected	N/A	N/A	Beige NOT OBSERVED
3-052	Kitchen	Walls	Drywall (DJC)	Asbestos	15-2988-19 to 21*	None Detected	N/A	N/A	*From Fisher Project No. 15-7543, dated Dec. 2015
3-052	Kitchen	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-053	Washroom	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
3-053	Washroom	Walls	Block	N/A	N/A	N/A	N/A	N/A	
3-053	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-054	Nurses Supplies	Floor	Vinyl Sheet Flooring 18	Asbestos	Not Sampled	ACM Assumed	60 SF	Good	Green with Black Dots
3-054	Nurses Supplies	Walls	Block	N/A	N/A	N/A	N/A	N/A	
3-054	Nurses Supplies	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
3-055	Office	Floor	Vinyl Sheet Flooring 4	Asbestos	Homogeneous w/ 18-8899-32 to 34	None Detected	N/A	N/A	Beige Mosaic
3-055	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-055	Office	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
3-056	Office	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink
3-056	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-056	Office	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
3-057	Electrical Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
3-057	Electrical Room	Walls	Block	N/A	N/A	N/A	N/A	N/A	
3-057	Electrical Room	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
3-058	Corridor	Floor	Vinyl Sheet Flooring 9	Asbestos	Homogeneous w/ 18-8899-44 to 46	None Detected	N/A	N/A	Beige
3-058	Corridor	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-058	Corridor	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
3-059	Lounge	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 18-8899-38 to 40	None Detected	N/A	N/A	Pink with Brown and Beige Smears
3-059	Lounge	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-059	Lounge	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-059	Lounge	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
3-060	Room 311 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	160 SF	Good	Cream with Rust Swirls
3-060	Room 311 & WR	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED
3-060	Room 311 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-060	Room 311 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-060	Room 311 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
3-061	Room 309 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	160 SF	Good	Cream with Rust Swirls
3-061	Room 309 & WR	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
3-061	Room 309 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-061	Room 309 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-061	Room 309 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
3-062	Room 307 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	160 SF	Good	Cream with Rust Swirls
3-062	Room 307 & WR	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED
3-062	Room 307 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-062	Room 307 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-062	Room 307 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
3-063	Room 305 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	160 SF	Good	Cream with Rust Swirls
3-063	Room 305 & WR	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED
3-063	Room 305 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-063	Room 305 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-063	Room 305 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
3-064	Room 303 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	160 SF	Good	Cream with Rust Swirls
3-064	Room 303 & WR	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED
3-064	Room 303 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-064	Room 303 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-064	Room 303 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
3-065	Room 301 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	160 SF	Good	Cream with Rust Swirls
3-065	Room 301 & WR	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED
3-065	Room 301 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-065	Room 301 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-065	Room 301 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
3-066	Clean Utility	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 18-8899-38 to 40	None Detected	N/A	N/A	Pink with Brown and Beige Smears
3-066	Clean Utility	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-066	Clean Utility	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-067	Soiled Utility	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink
3-067	Soiled Utility	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-067	Soiled Utility	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-068	Office	Floor	Vinyl Sheet Flooring 16	Asbestos	Not Sampled	ACM Assumed	240 SF	Good	Grey with Black Dots
3-068	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-068	Office	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
3-069	Room 302 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	160 SF	Good	Cream with Rust Swirls
3-069	Room 302 & WR	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED
3-069	Room 302 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-069	Room 302 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-069	Room 302 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
3-070	Room 304 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	160 SF	Good	Cream with Rust Swirls
3-070	Room 304 & WR	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED
3-070	Room 304 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-070	Room 304 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-070	Room 304 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
3-071	Washroom	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
3-071	Washroom	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 18-8899-38 to 40	None Detected	N/A	N/A	Pink with Brown and Beige Smears NOT OBSERVED
3-071	Washroom	Floor	Vinyl Sheet Flooring 9	Asbestos	Homogeneous w/ 18-8899-44 to 46	None Detected	N/A	N/A	Beige NOT OBSERVED
3-071	Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
3-071	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-072	Room 306 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	160 SF	Good	Cream with Rust Swirls
3-072	Room 306 & WR	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED
3-072	Room 306 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-072	Room 306 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-072	Room 306 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
3-073	Shower & Tub Room	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
3-073	Shower & Tub Room	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
3-073	Shower & Tub Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-074	Room 308 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	160 SF	Good	Cream with Rust Swirls
3-074	Room 308 & WR	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED
3-074	Room 308 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-074	Room 308 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-074	Room 308 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
3-075	Janitor's Closet	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
3-075	Janitor's Closet	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED
3-075	Janitor's Closet	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-075	Janitor's Closet	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-076	Room 310 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	160 SF	Good	Cream with Rust Swirls
3-076	Room 310 & WR	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED
3-076	Room 310 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-076	Room 310 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-076	Room 310 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
3-077	Lounge	Floor	Parquet	N/A	N/A	N/A	N/A	N/A	
3-077	Lounge	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-077	Lounge	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-077	Lounge	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
3-078	Linen Chute	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 18-8899-38 to 40	None Detected	N/A	N/A	Pink with Brown and Beige Smears
3-078	Linen Chute	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-078	Linen Chute	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
3-079	Linen Room	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 18-8899-38 to 40	None Detected	N/A	N/A	Pink with Brown and Beige Smears
3-079	Linen Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-079	Linen Room	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
3-080	Electrical/Sprinkler	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 15-1632-01 to 03	None Detected	N/A	N/A	12" x 12" Beige with Grey and Brown Smears
3-080	Electrical/Sprinkler	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-19 to 21 & 18-8899-59 to 61	None Detected	N/A	N/A	
3-080	Electrical/Sprinkler	Ceiling	Sprayed Fireproofing	Asbestos	Homogeneous w/ 18-8899-56 to 58 and 19-2282-1 to 4	None Detected	N/A	N/A	
4-001	Elevator Lobby	Floor	Vinyl Sheet Flooring 9	Asbestos	Homogeneous w/ 18-8899-44 to 46	None Detected	N/A	N/A	Beige
4-001	Elevator Lobby	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-001	Elevator Lobby	Ceiling	Drywall (DJC)	Asbestos	22-7881-1*	None Detected	N/A	N/A	*From Fisher Project No. 22-11869, dated Feb. 2022
4-001	Elevator Lobby	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
4-002	Nurses Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
4-002	Nurses Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-002	Nurses Office	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
4-003	Nurses Station	Floor	Vinyl Sheet Flooring 9	Asbestos	Homogeneous w/ 18-8899-44 to 46	None Detected	N/A	N/A	Beige
4-003	Nurses Station	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-003	Nurses Station	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
4-004	Medication Room	Floor	Vinyl Sheet Flooring 9	Asbestos	Homogeneous w/ 18-8899-44 to 46	None Detected	N/A	N/A	Beige

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
4-004	Medication Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-004	Medication Room	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
4-005	Washroom	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
4-005	Washroom	Floor	Vinyl Sheet Flooring 11	Asbestos	Homogeneous w/ 15-2988-34 to 38	None Detected	N/A	N/A	Pink with Black Dots NOT OBSERVED
4-005	Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-005	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-005	Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole NOT OBSERVED
4-006	Corridor	Floor	Vinyl Sheet Flooring 9	Asbestos	Homogeneous w/ 18-8899-44 to 46	None Detected	N/A	N/A	Beige
4-006	Corridor	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-006	Corridor	Ceiling	Drywall (DJC)	Asbestos	22-7881-2*	None Detected	N/A	N/A	*From Fisher Project No. 22-11869, dated Feb. 2022
4-006	Corridor	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
4-007	Room 412 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	Cream with Rust Swirls
4-007	Room 412 & WR	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED
4-007	Room 412 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-007	Room 412 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-007	Room 412 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
4-008	Room 414 & WR	Floor	Vinyl Sheet Flooring 9	Asbestos	Homogeneous w/ 18-8899-44 to 46	None Detected	N/A	N/A	Beige
4-008	Room 414 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-008	Room 414 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-008	Room 414 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
4-009	Janitor's Closet	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
4-009	Janitor's Closet	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED
4-009	Janitor's Closet	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-009	Janitor's Closet	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-010	Room 416 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	Cream with Rust Swirls
4-010	Room 416 & WR	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED
4-010	Room 416 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
4-010	Room 416 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-010	Room 416 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
4-011	Shower & Tub Room	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
4-011	Shower & Tub Room	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
4-011	Shower & Tub Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-012	Room 418 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	Cream with Rust Swirls
4-012	Room 418 & WR	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED
4-012	Room 418 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-012	Room 418 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-012	Room 418 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
4-013	Soiled Utility	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 18-8899-38 to 40	None Detected	N/A	N/A	Pink with Brown and Beige Smears
4-013	Soiled Utility	Walls	Drywall (DJC)	Asbestos	22-7881-5*	None Detected	N/A	N/A	*From Fisher Project No. 22-11869, dated Feb. 2022
4-013	Soiled Utility	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-014	Room 420 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	Cream with Rust Swirls
4-014	Room 420 & WR	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED
4-014	Room 420 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-014	Room 420 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-014	Room 420 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
4-015	Room 422 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	Cream with Rust Swirls
4-015	Room 422 & WR	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED
4-015	Room 422 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-015	Room 422 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-015	Room 422 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
4-016	Corridor	Floor	Vinyl Sheet Flooring 9	Asbestos	Homogeneous w/ 18-8899-44 to 46	None Detected	N/A	N/A	Beige
4-016	Corridor	Floor	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-016	Corridor	Ceiling	Drywall (DJC)	Asbestos	22-7881-3*	None Detected	N/A	N/A	*From Fisher Project No. 22-11869, dated Feb. 2022
4-016	Corridor	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
4-017	Conference Room	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
4-017	Conference Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-017	Conference Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-017	Conference Room	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
4-018	Rehab Room	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 18-8899-38 to 40	None Detected	N/A	N/A	Pink with Brown and Beige Smears
4-018	Rehab Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-018	Rehab Room	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
4-019	Electrical Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
4-019	Electrical Room	Walls	Drywall (DJC)	Asbestos	22-7881-4*	None Detected	N/A	N/A	*From Fisher Project No. 22-11869, dated Feb. 2022
4-019	Electrical Room	Ceiling	Sprayed Fireproofing	Asbestos	Homogeneous w/ 18-8899-56 to 58 and 19-2282-1 to 4	None Detected	N/A	N/A	
4-020	Corridor	Floor	Vinyl Sheet Flooring 9	Asbestos	Homogeneous w/ 18-8899-44 to 46	None Detected	N/A	N/A	Beige
4-020	Corridor	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-020	Corridor	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
4-021	Room 438 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	Cream with Rust Swirls
4-021	Room 438 & WR	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED
4-021	Room 438 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-021	Room 438 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-021	Room 438 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
4-022	Room 437 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	Cream with Rust Swirls
4-022	Room 437 & WR	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED
4-022	Room 437 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-022	Room 437 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-022	Room 437 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
4-023	Room 436 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	Cream with Rust Swirls
4-023	Room 436 & WR	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED
4-023	Room 436 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-023	Room 436 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
4-023	Room 436 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
4-024	Room 435 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	Cream with Rust Swirls
4-024	Room 435 & WR	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED
4-024	Room 435 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-024	Room 435 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-024	Room 435 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
4-025	Room 434 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	Cream with Rust Swirls
4-025	Room 434 & WR	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED
4-025	Room 434 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-025	Room 434 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-025	Room 434 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
4-026	Room 433 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	Cream with Rust Swirls
4-026	Room 433 & WR	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED
4-026	Room 433 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-026	Room 433 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-026	Room 433 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
4-027	Room 432 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	Cream with Rust Swirls
4-027	Room 432 & WR	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED
4-027	Room 432 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-027	Room 432 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-027	Room 432 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
4-028	Room 431 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	Cream with Rust Swirls
4-028	Room 431 & WR	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED
4-028	Room 431 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-028	Room 431 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-028	Room 431 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
4-029	Room 430 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	Cream with Rust Swirls

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
4-029	Room 430 & WR	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED
4-029	Room 430 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-029	Room 430 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-029	Room 430 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
4-030	Room 429 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	Cream with Rust Swirls
4-030	Room 429 & WR	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED
4-030	Room 429 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-030	Room 429 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-030	Room 429 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
4-031	Room 428 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	Cream with Rust Swirls
4-031	Room 428 & WR	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED
4-031	Room 428 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-031	Room 428 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-031	Room 428 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
4-032	Room 427 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	Cream with Rust Swirls
4-032	Room 427 & WR	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED
4-032	Room 427 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-032	Room 427 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-032	Room 427 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
4-033	Room 426 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	Cream with Rust Swirls
4-033	Room 426 & WR	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED
4-033	Room 426 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-033	Room 426 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-033	Room 426 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
4-034	Washroom	Floor	Vinyl Sheet Flooring 16	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Grey with Black Dots
4-034	Washroom	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED
4-034	Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
4-034	Washroom	Ceiling	Drywall (DJC)	Asbestos	22-7881-6*	None Detected	N/A	N/A	*From Fisher Project No. 22-11869, dated Feb. 2022
4-035	Shower & Tub Room	Floor	Vinyl Sheet Flooring 13	Asbestos	Homogeneous w/ 21-5940-1 to 3	None Detected	N/A	N/A	Blue with Beige, Brown and Black Specks
4-035	Shower & Tub Room	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
4-035	Shower & Tub Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-036	Washroom	Floor	Vinyl Sheet Flooring 13	Asbestos	Homogeneous w/ 21-5940-1 to 3	None Detected	N/A	N/A	Blue with Beige, Brown and Black Specks
4-036	Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-036	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-037	Shower & Tub Room	Floor	Vinyl Sheet Flooring 13	Asbestos	Homogeneous w/ 21-5940-1 to 3	None Detected	N/A	N/A	Blue with Beige, Brown and Black Specks
4-037	Shower & Tub Room	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
4-037	Shower & Tub Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-037	Shower & Tub Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-038	Clean Utility	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink
4-038	Clean Utility	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-038	Clean Utility	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-039	Soiled Utility	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink
4-039	Soiled Utility	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-039	Soiled Utility	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-040	Lounge	Floor	Vinyl Sheet Flooring 19	Asbestos	Not Sampled	ACM Assumed	350 SF	Good	Hardwood Design
4-040	Lounge	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-040	Lounge	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
4-041	Janitor's Closet	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 18-8899-38 to 40	None Detected	N/A	N/A	Pink with Brown and Beige Smears
4-041	Janitor's Closet	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
4-041	Janitor's Closet	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-041	Janitor's Closet	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
4-042	Room 425 & WR	Floor	Vinyl Sheet Flooring 12	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	Beige with Black Dots
4-042	Room 425 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-042	Room 425 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
4-042	Room 425 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
4-043	Room 423 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	Cream with Rust Swirls
4-043	Room 423 & WR	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED
4-043	Room 423 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-043	Room 423 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-043	Room 423 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
4-044	Room 421 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	Cream with Rust Swirls
4-044	Room 421 & WR	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED
4-044	Room 421 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-044	Room 421 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-044	Room 421 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
4-045	Room 419 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	Cream with Rust Swirls
4-045	Room 419 & WR	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED
4-045	Room 419 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-045	Room 419 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-045	Room 419 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
4-046	Room 417 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	Cream with Rust Swirls
4-046	Room 417 & WR	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED
4-046	Room 417 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-046	Room 417 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-046	Room 417 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
4-047	Room 415 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	Cream with Rust Swirls
4-047	Room 415 & WR	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED
4-047	Room 415 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-047	Room 415 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-047	Room 415 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
4-048	Room 413 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	Cream with Rust Swirls

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
4-048	Room 413 & WR	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED
4-048	Room 413 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-048	Room 413 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-048	Room 413 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
4-049	Laundry Room	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
4-049	Laundry Room	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED
4-049	Laundry Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-049	Laundry Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-050	Lounge	Floor	Parquet	N/A	N/A	N/A	N/A	N/A	
4-050	Lounge	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-050	Lounge	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
4-051	Dining Room	Floor	Vinyl Sheet Flooring 9	Asbestos	Homogeneous w/ 18-8899-44 to 46	None Detected	N/A	N/A	Beige
4-051	Dining Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-051	Dining Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-051	Dining Room	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
4-052	Kitchen	Floor	Vinyl Sheet Flooring 11	Asbestos	15-2988-36*	None Detected	N/A	N/A	Pink with Black Dots *From Fisher Project No. 15-7543, dated Dec. 2015
4-052	Kitchen	Floor	Vinyl Sheet Flooring 9	Asbestos	Homogeneous w/ 18-8899-44 to 46	None Detected	N/A	N/A	Beige NOT OBSERVED
4-052	Kitchen	Walls	Drywall (DJC)	Asbestos	15-2988-22 to 24*	None Detected	N/A	N/A	*From Fisher Project No. 15-7543, dated Dec. 2015
4-052	Kitchen	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-053	Washroom	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
4-053	Washroom	Walls	Block	N/A	N/A	N/A	N/A	N/A	
4-053	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-054	Nurses Supplies	Floor	Vinyl Sheet Flooring 9	Asbestos	Homogeneous w/ 18-8899-44 to 46	None Detected	N/A	N/A	Beige
4-054	Nurses Supplies	Walls	Block	N/A	N/A	N/A	N/A	N/A	
4-054	Nurses Supplies	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-055	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
4-055	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
4-055	Office	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
4-056	Office	Floor	Vinyl Sheet Flooring 9	Asbestos	Homogeneous w/ 18-8899-44 to 46	None Detected	N/A	N/A	Beige
4-056	Office	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED
4-056	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-056	Office	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
4-057	Electrical Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
4-057	Electrical Room	Walls	Block	N/A	N/A	N/A	N/A	N/A	
4-057	Electrical Room	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
4-058	Corridor	Floor	Vinyl Sheet Flooring 9	Asbestos	Homogeneous w/ 18-8899-44 to 46	None Detected	N/A	N/A	Beige
4-058	Corridor	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-058	Corridor	Ceiling	Drywall (DJC)	Asbestos	22-7881-7*	None Detected	N/A	N/A	*From Fisher Project No. 22-11869, dated Feb. 2022
4-058	Corridor	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
4-059	Lounge	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 18-8899-38 to 40	None Detected	N/A	N/A	Pink with Brown and Beige Smears
4-059	Lounge	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-059	Lounge	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-059	Lounge	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
4-060	Room 411 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	Cream with Rust Swirls
4-060	Room 411 & WR	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED
4-060	Room 411 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-060	Room 411 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-060	Room 411 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
4-061	Room 409 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	Cream with Rust Swirls
4-061	Room 409 & WR	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED
4-061	Room 409 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-061	Room 409 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-061	Room 409 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
4-062	Room 407 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	Cream with Rust Swirls

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
4-062	Room 407 & WR	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED
4-062	Room 407 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-062	Room 407 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-062	Room 407 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
4-063	Room 405 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	Cream with Rust Swirls
4-063	Room 405 & WR	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED
4-063	Room 405 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-063	Room 405 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-063	Room 405 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
4-064	Room 403 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	Cream with Rust Swirls
4-064	Room 403 & WR	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED
4-064	Room 403 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-064	Room 403 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-064	Room 403 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
4-065	Room 401 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	Cream with Rust Swirls
4-065	Room 401 & WR	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED
4-065	Room 401 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-065	Room 401 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-065	Room 401 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
4-066	Clean Utility	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink
4-066	Clean Utility	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-066	Clean Utility	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-067	Soiled Utility	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink
4-067	Soiled Utility	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-067	Soiled Utility	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-068	Lounge	Floor	Parquet	N/A	N/A	N/A	N/A	N/A	
4-068	Lounge	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
4-068	Lounge	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
4-069	Room 402 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	Cream with Rust Swirls
4-069	Room 402 & WR	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED
4-069	Room 402 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-069	Room 402 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-069	Room 402 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
4-070	Room 404 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	Cream with Rust Swirls
4-070	Room 404 & WR	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED
4-070	Room 404 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-070	Room 404 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-070	Room 404 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
4-071	Washroom	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
4-071	Washroom	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 18-8899-38 to 40	None Detected	N/A	N/A	Pink with Brown and Beige Smears NOT OBSERVED
4-071	Washroom	Floor	Vinyl Sheet Flooring 9	Asbestos	Homogeneous w/ 18-8899-44 to 46	None Detected	N/A	N/A	Beige NOT OBSERVED
4-071	Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-071	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-072	Room 406 & WR	Floor	Vinyl Sheet Flooring 9	Asbestos	Homogeneous w/ 18-8899-44 to 46	None Detected	N/A	N/A	Beige
4-072	Room 406 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-072	Room 406 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-072	Room 406 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
4-073	Shower & Tub Room	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
4-073	Shower & Tub Room	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
4-073	Shower & Tub Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-074	Room 408 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	Cream with Rust Swirls
4-074	Room 408 & WR	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED
4-074	Room 408 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-074	Room 408 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
4-074	Room 408 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
4-075	Janitor's Closet	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
4-075	Janitor's Closet	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED
4-075	Janitor's Closet	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-075	Janitor's Closet	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-076	Room 410 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	Cream with Rust Swirls
4-076	Room 410 & WR	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED
4-076	Room 410 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-076	Room 410 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-076	Room 410 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
4-077	Lounge	Floor	Parquet	N/A	N/A	N/A	N/A	N/A	
4-077	Lounge	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-077	Lounge	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-077	Lounge	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
4-078	Linen Chute	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 18-8899-38 to 40	None Detected	N/A	N/A	Pink with Brown and Beige Smears
4-078	Linen Chute	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-078	Linen Chute	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-079	Linen Room	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 18-8899-38 to 40	None Detected	N/A	N/A	Pink with Brown and Beige Smears
4-079	Linen Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-079	Linen Room	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
4-080	Electrical/Sprinkler	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
4-080	Electrical/Sprinkler	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 22-7881-1 to 7	None Detected	N/A	N/A	
4-080	Electrical/Sprinkler	Ceiling	Sprayed Fireproofing	Asbestos	Homogeneous w/ 18-8899-56 to 58 and 19-2282-1 to 4	None Detected	N/A	N/A	
5-001	Elevator Lobby	Floor	Vinyl Sheet Flooring 9	Asbestos	Homogeneous w/ 18-8899-44 to 46	None Detected	N/A	N/A	Beige
5-001	Elevator Lobby	Walls	Drywall (DJC)	Asbestos	18-8899-62*	None Detected	N/A	N/A	*From Fisher Project No. 18-8834, dated May 2018
5-001	Elevator Lobby	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
5-001	Elevator Lobby	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
5-002	Nurses Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
5-002	Nurses Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-002	Nurses Office	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
5-003	Nurses Station	Floor	Vinyl Sheet Flooring 9	Asbestos	Homogeneous w/ 18-8899-44 to 46	None Detected	N/A	N/A	Beige
5-003	Nurses Station	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-003	Nurses Station	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
5-004	Medication Room	Floor	Vinyl Sheet Flooring 9	Asbestos	Homogeneous w/ 18-8899-44 to 46	None Detected	N/A	N/A	Beige
5-004	Medication Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-004	Medication Room	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
5-005	Washroom	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
5-005	Washroom	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 18-8899-38 to 40	None Detected	N/A	N/A	Pink with Brown and Beige Smears NOT OBSERVED
5-005	Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-005	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-006	Office	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink
5-006	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-006	Office	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
5-007	Communication Room	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 18-8899-38 to 40	None Detected	N/A	N/A	Pink with Brown and Beige Smears
5-007	Communication Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-007	Communication Room	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
5-008	Lounge/Gathering Place	Floor	Parquet	N/A	N/A	N/A	N/A	N/A	
5-008	Lounge	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-008	Lounge	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
5-008	Lounge	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
5-009	Room 516 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	175 SF	Good	Cream with Rust Swirls
5-009	Room 516 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-009	Room 516 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-009	Room 516 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
5-010	Janitor's Closet	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
5-010	Janitor's Closet	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED
5-010	Janitor's Closet	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-010	Janitor's Closet	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-011	Shower & Tub Room	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
5-011	Shower & Tub Room	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
5-011	Shower & Tub Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-012	Room 518 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	175 SF	Good	Cream with Rust Swirls
5-012	Room 518 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-012	Room 518 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-012	Room 518 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
5-013	Soiled Utility	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 18-8899-38 to 40	None Detected	N/A	N/A	Pink with Brown and Beige Smears
5-013	Soiled Utility	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-013	Soiled Utility	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-014	Room 520 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	Cream with Rust Swirls
5-014	Room 520 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-014	Room 520 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
5-014	Room 520 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
5-015	Room 522 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	Cream with Rust Swirls
5-015	Room 522 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-015	Room 522 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-015	Room 522 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
5-016	Corridor	Floor	Vinyl Sheet Flooring 9	Asbestos	Homogeneous w/ 18-8899-44 to 46	None Detected	N/A	N/A	Beige
5-016	Corridor	Walls	Drywall (DJC)	Asbestos	18-8899-63*	None Detected	N/A	N/A	*From Fisher Project No. 18-8834, dated May 2018
5-016	Corridor	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
5-017	Corridor	Floor	Vinyl Sheet Flooring 9	Asbestos	Homogeneous w/ 18-8899-44 to 46	None Detected	N/A	N/A	Beige
5-017	Corridor	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-017	Corridor	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
5-018	Conference Room	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
5-018	Conference Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-018	Conference Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-018	Conference Room	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
5-019	Rehab Room	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 18-8899-38 to 40	None Detected	N/A	N/A	Pink with Brown and Beige Smears
5-019	Rehab Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-019	Rehab Room	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
5-020	Electrical Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
5-020	Electrical Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-020	Electrical Room	Ceiling	Sprayed Fireproofing	Asbestos	Homogeneous w/ 18-8899-56 to 58 and 19-2282-1 to 4	None Detected	N/A	N/A	
5-021	Corridor	Floor	Vinyl Sheet Flooring 9	Asbestos	Homogeneous w/ 18-8899-44 to 46	None Detected	N/A	N/A	Beige
5-021	Corridor	Walls	Drywall (DJC)	Asbestos	18-8899-64*	None Detected	N/A	N/A	*From Fisher Project No. 18-8834, dated May 2018

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
5-021	Corridor	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
5-022	Room 538 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	160 SF	Good	Cream with Rust Swirls
5-022	Room 538 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-022	Room 538 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-022	Room 538 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
5-023	Room 537 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	160 SF	Good	Cream with Rust Swirls
5-023	Room 537 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-023	Room 537 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-023	Room 537 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
5-024	Room 536 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	160 SF	Good	Cream with Rust Swirls
5-024	Room 536 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-024	Room 536 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-024	Room 536 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
5-025	Room 535 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	160 SF	Good	Cream with Rust Swirls
5-025	Room 535 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-025	Room 535 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-025	Room 535 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
5-026	Room 534 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	160 SF	Good	Cream with Rust Swirls
5-026	Room 534 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-026	Room 534 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-026	Room 534 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
5-027	Room 533 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	160 SF	Good	Cream with Rust Swirls
5-027	Room 533 & WR	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
5-027	Room 533 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-027	Room 533 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-027	Room 533 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
5-028	Room 532 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	160 SF	Good	Cream with Rust Swirls
5-028	Room 532 & WR	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED
5-028	Room 532 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-028	Room 532 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-028	Room 532 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
5-029	Room 531 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	160 SF	Good	Cream with Rust Swirls
5-029	Room 531 & WR	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED
5-029	Room 531 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-029	Room 531 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-029	Room 531 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
5-030	Room 530 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	160 SF	Good	Cream with Rust Swirls
5-030	Room 530 & WR	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED
5-030	Room 530 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-030	Room 530 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-030	Room 530 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
5-031	Room 529 & WR	Floor	Vinyl Sheet Flooring 9	Asbestos	Homogeneous w/ 18-8899-44 to 46	None Detected	N/A	N/A	Beige
5-031	Room 529 & WR	Floor	Vinyl Sheet Flooring 12	Asbestos	Not Sampled	ACM Assumed	20 SF	Good	Beige with Black Dots
5-031	Room 529 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-031	Room 529 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-031	Room 529 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
5-032	Room 528 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	160 SF	Good	Cream with Rust Swirls
5-032	Room 528 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-032	Room 528 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-032	Room 528 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
5-033	Room 527 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	160 SF	Good	Cream with Rust Swirls
5-033	Room 527 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-033	Room 527 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-033	Room 527 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
5-034	Room 526 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	160 SF	Good	Cream with Rust Swirls
5-034	Room 526 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-034	Room 526 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-034	Room 526 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
5-035	Washroom	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink
5-035	Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-035	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-036	Shower & Tub Room	Floor	Vinyl Sheet Flooring 13	Asbestos	Homogeneous w/ 21-5940-1 to 3	None Detected	N/A	N/A	Blue with Beige, Brown and Black Specks
5-036	Shower & Tub Room	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
5-036	Shower & Tub Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-037	Washroom	Floor	Vinyl Sheet Flooring 13	Asbestos	Homogeneous w/ 21-5940-1 to 3	None Detected	N/A	N/A	Blue with Beige, Brown and Black Specks
5-037	Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-037	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-038	Shower & Tub Room	Floor	Vinyl Sheet Flooring 13	Asbestos	Homogeneous w/ 21-5940-1 to 3	None Detected	N/A	N/A	Blue with Beige, Brown and Black Specks

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
5-038	Shower & Tub Room	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
5-038	Shower & Tub Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-038	Shower & Tub Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-039	Clean Utility	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink
5-039	Clean Utility	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-039	Clean Utility	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-040	Soiled Utility	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink
5-040	Soiled Utility	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-040	Soiled Utility	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-041	Lounge	Floor	Vinyl Sheet Flooring 19	Asbestos	Not Sampled	ACM Assumed	350 SF	Good	Hardwood Design
5-041	Lounge	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-041	Lounge	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
5-042	Janitor's Closet	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
5-042	Janitor's Closet	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
5-042	Janitor's Closet	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-042	Janitor's Closet	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-043	Room 525 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	175 SF	Good	Cream with Rust Swirls
5-043	Room 525 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-043	Room 525 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-043	Room 525 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
5-044	Room 523 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	Cream with Rust Swirls
5-044	Room 523 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
5-044	Room 523 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-044	Room 523 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
5-045	Room 521 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	175 SF	Good	Cream with Rust Swirls
5-045	Room 521 & WR	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED
5-045	Room 521 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-045	Room 521 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-045	Room 521 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
5-046	Room 519 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	175 SF	Good	Cream with Rust Swirls
5-046	Room 519 & WR	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED
5-046	Room 519 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-046	Room 519 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-046	Room 519 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
5-047	Room 517 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	175 SF	Good	Cream with Rust Swirls
5-047	Room 517 & WR	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED
5-047	Room 517 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-047	Room 517 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-047	Room 517 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
5-048	Room 515 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	175 SF	Good	Cream with Rust Swirls
5-048	Room 515 & WR	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED
5-048	Room 515 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-048	Room 515 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-048	Room 515 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
5-049	Kitchen/Servery	Floor	Vinyl Sheet Flooring 11	Asbestos	15-2988-37*	None Detected	N/A	N/A	Pink with Black Dots *From Fisher Project No. 15-7543, dated Dec. 2015

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
5-049	Kitchen/Servery	Walls	Drywall (DJC)	Asbestos	15-2988-25 to 27*	None Detected	N/A	N/A	*From Fisher Project No. 15-7543, dated Dec. 2015
5-049	Kitchen/Servery	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
5-049	Kitchen/Servery	Ceiling	Ceiling Tile 6	N/A	N/A	N/A	N/A	N/A	2' x 4' Fibreglass
5-050	Dining Room	Floor	Vinyl Sheet Flooring 9	Asbestos	Homogeneous w/ 18-8899-44 to 46	None Detected	N/A	N/A	Beige
5-050	Dining Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-050	Dining Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-050	Dining Room	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
5-051	Corridor	Floor	Vinyl Sheet Flooring 9	Asbestos	Homogeneous w/ 18-8899-44 to 46	None Detected	N/A	N/A	Beige
5-051	Corridor	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-051	Corridor	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
5-052	Electrical Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
5-052	Electrical Room	Walls	Block	N/A	N/A	N/A	N/A	N/A	
5-052	Electrical Room	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
5-053	Activity Room	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 18-8899-38 to 40	None Detected	N/A	N/A	Pink with Brown and Beige Smears
5-053	Activity Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-053	Activity Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-053	Activity Room	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
5-054	Room 511 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	Cream with Rust Swirls
5-054	Room 511 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-054	Room 511 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-054	Room 511 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
5-055	Room 509 & WR	Floor	Vinyl Sheet Flooring 9	Asbestos	Homogeneous w/ 18-8899-44 to 46	None Detected	N/A	N/A	Beige
5-055	Room 509 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
5-055	Room 509 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-055	Room 509 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
5-056	Room 507 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	Cream with Rust Swirls
5-056	Room 507 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-056	Room 507 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-056	Room 507 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
5-057	Room 505 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	Cream with Rust Swirls
5-057	Room 505 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-057	Room 505 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-057	Room 505 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
5-058	Room 503 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	Cream with Rust Swirls
5-058	Room 503 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-058	Room 503 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-058	Room 503 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
5-059	Room 501 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	175 SF	Good	Cream with Rust Swirls
5-059	Room 501 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-059	Room 501 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-059	Room 501 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
5-060	Clean Utility	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink
5-060	Clean Utility	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-060	Clean Utility	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-061	Soiled Utility	Floor	Vinyl Sheet Flooring 11	Asbestos	Homogeneous w/ 15-2988-34 to 38	None Detected	N/A	N/A	Pink with Black Dots

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
5-061	Soiled Utility	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-061	Soiled Utility	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-062	Lounge	Floor	Parquet	N/A	N/A	N/A	N/A	N/A	
5-062	Lounge	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-062	Lounge	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
5-063	Room 502 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	Cream with Rust Swirls
5-063	Room 502 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-063	Room 502 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-063	Room 502 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
5-064	Room 504 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	Cream with Rust Swirls
5-064	Room 504 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-064	Room 504 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-064	Room 504 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
5-065	Washroom	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
5-065	Washroom	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 18-8899-38 to 40	None Detected	N/A	N/A	Pink with Brown and Beige Smears NOT OBSERVED
5-065	Washroom	Floor	Vinyl Sheet Flooring 9	Asbestos	Homogeneous w/ 18-8899-44 to 46	None Detected	N/A	N/A	Beige NOT OBSERVED
5-065	Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-065	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-066	Room 506 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	175 SF	Good	Cream with Rust Swirls
5-066	Room 506 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-066	Room 506 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-066	Room 506 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
5-067	Shower & Tub Room	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
5-067	Shower & Tub Room	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
5-067	Shower & Tub Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-067	Shower & Tub Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-068	Room 508 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	175 SF	Good	Cream with Rust Swirls
5-068	Room 508 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-068	Room 508 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-068	Room 508 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
5-069	Janitor's Closet	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
5-069	Janitor's Closet	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED
5-069	Janitor's Closet	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
5-069	Janitor's Closet	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-069	Janitor's Closet	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-070	Room 510 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	Cream with Rust Swirls
5-070	Room 510 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-070	Room 510 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-070	Room 510 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
5-071	Rehab Room	Floor	Vinyl Sheet Flooring 19	Asbestos	Not Sampled	ACM Assumed	350 SF	Good	Hardwood Design
5-071	Rehab Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-071	Rehab Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-071	Rehab Room	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
5-072	Linen Chute	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 18-8899-38 to 40	None Detected	N/A	N/A	Pink with Brown and Beige Smears

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
5-072	Linen Chute	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-072	Linen Chute	Ceiling	Sprayed Fireproofing	Asbestos	Homogeneous w/ 18-8899-56 to 58 and 19-2282-1 to 4	None Detected	N/A	N/A	
5-072	Linen Chute	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-073	Linen Room	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 18-8899-38 to 40	None Detected	N/A	N/A	Pink with Brown and Beige Smears
5-073	Linen Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-073	Linen Room	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
5-074	Electrical/Sprinkler	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
5-074	Electrical/Sprinkler	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-25 to 27 & 18-8899-62 to 64	None Detected	N/A	N/A	
5-074	Electrical/Sprinkler	Ceiling	Sprayed Fireproofing	Asbestos	Homogeneous w/ 18-8899-56 to 58 and 19-2282-1 to 4	None Detected	N/A	N/A	
6-001	Elevator Lobby	Floor	Vinyl Sheet Flooring 9	Asbestos	Homogeneous w/ 18-8899-44 to 46	None Detected	N/A	N/A	Beige
6-001	Elevator Lobby	Walls	Drywall (DJC)	Asbestos	18-8899-66*	None Detected	N/A	N/A	*From Fisher Project No. 18-8834, dated May 2018
6-001	Elevator Lobby	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-001	Elevator Lobby	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
6-002	Nurses Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
6-002	Nurses Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-002	Nurses Office	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
6-003	Nurses Station	Floor	Vinyl Sheet Flooring 9	Asbestos	Homogeneous w/ 18-8899-44 to 46	None Detected	N/A	N/A	Beige
6-003	Nurses Station	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-003	Nurses Station	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
6-004	Medication Room	Floor	Vinyl Sheet Flooring 9	Asbestos	Homogeneous w/ 18-8899-44 to 46	None Detected	N/A	N/A	NO ACCESS Beige
6-004	Medication Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-004	Medication Room	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
6-005	Washroom	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
6-005	Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-005	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-006	Common Room	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 18-8899-38 to 40	None Detected	N/A	N/A	Pink with Brown and Beige Smears
6-006	Common Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-006	Common Room	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
6-007	Office	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 18-8899-38 to 40	None Detected	N/A	N/A	Pink with Brown and Beige Smears
6-007	Office	Floor	Vinyl Sheet Flooring 9	Asbestos	Homogeneous w/ 18-8899-44 to 46	None Detected	N/A	N/A	Beige NOT OBSERVED
6-007	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-007	Office	Ceiling	Sprayed Fireproofing	Asbestos	18-8899-56 to 58*	None Detected	N/A	N/A	*From Fisher Project No. 18-8834, dated May 2018
6-007	Office	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
6-008	Lounge	Floor	Parquet	N/A	N/A	N/A	N/A	N/A	
6-008	Lounge	Walls	Drywall (DJC)	Asbestos	18-8899-65*	None Detected	N/A	N/A	*From Fisher Project No. 18-8834, dated May 2018
6-008	Lounge	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-008	Lounge	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
6-009	Room 616 & WR	Floor	Vinyl Sheet Flooring 11	Asbestos	Homogeneous w/ 15-2988-34 to 38	None Detected	N/A	N/A	Pink with Black Dots
6-009	Room 616 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-009	Room 616 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-009	Room 616 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
6-010	Janitor's Closet	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink
6-010	Janitor's Closet	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-010	Janitor's Closet	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-011	Shower & Tub Room	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
6-011	Shower & Tub Room	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
6-011	Shower & Tub Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-012	Room 618 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	175 SF	Good	Cream with Rust Swirls
6-012	Room 618 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-012	Room 618 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-012	Room 618 & WR	Door	Caulking	Asbestos	17-5667-04 to 06*	0.5-5% Anthophyllite	20 LF	Good	Between door valance and wall *From Fisher Project No. 17-8078, dated Feb. 2017
6-012	Room 618 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
6-013	Soiled Utility	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 18-8899-38 to 40	None Detected	N/A	N/A	Pink with Brown and Beige Smears
6-013	Soiled Utility	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-013	Soiled Utility	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-014	Room 620 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	Cream with Rust Swirls
6-014	Room 620 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-014	Room 620 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-014	Room 620 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
6-015	Room 622 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	Cream with Rust Swirls
6-015	Room 622 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-015	Room 622 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-015	Room 622 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
6-016	Corridor	Floor	Vinyl Sheet Flooring 9	Asbestos	Homogeneous w/ 18-8899-44 to 46	None Detected	N/A	N/A	Beige
6-016	Corridor	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-016	Corridor	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
6-017	Corridor	Floor	Vinyl Sheet Flooring 9	Asbestos	Homogeneous w/ 18-8899-44 to 46	None Detected	N/A	N/A	Beige
6-017	Corridor	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
6-017	Corridor	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
6-018	Conference Room	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
6-018	Conference Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-018	Conference Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-018	Conference Room	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
6-019	Rehab Room	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 18-8899-38 to 40	None Detected	N/A	N/A	Pink with Brown and Beige Smears
6-019	Rehab Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-019	Rehab Room	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
6-020	Electrical Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
6-020	Electrical Room	Floor	Firestop-Red	Asbestos	22-7881-13*	None Detected	N/A	N/A	*From Fisher Project No. 22-11869, dated Feb. 2022
6-020	Electrical Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-020	Electrical Room	Ceiling	Sprayed Fireproofing	Asbestos	Homogeneous w/ 18-8899-56 to 58 and 19-2282-1 to 4	None Detected	N/A	N/A	
6-021	Corridor	Floor	Vinyl Sheet Flooring 9	Asbestos	Homogeneous w/ 18-8899-44 to 46	None Detected	N/A	N/A	Beige
6-021	Corridor	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-021	Corridor	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
6-022	Room 638 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	160 SF	Good	Cream with Rust Swirls
6-022	Room 638 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-022	Room 638 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-022	Room 638 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
6-023	Room 637 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	160 SF	Good	Cream with Rust Swirls
6-023	Room 637 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-023	Room 637 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-023	Room 637 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
6-024	Room 636 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	160 SF	Good	Cream with Rust Swirls
6-024	Room 636 & WR	Floor	Vinyl Sheet Flooring 11	Asbestos	Homogeneous w/ 15-2988-34 to 38	None Detected	N/A	N/A	Pink with Black Dots
6-024	Room 636 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-024	Room 636 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-024	Room 636 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
6-025	Room 635 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	160 SF	Good	Cream with Rust Swirls
6-025	Room 635 & WR	Floor	Vinyl Sheet Flooring 11	Asbestos	Homogeneous w/ 15-2988-34 to 38	None Detected	N/A	N/A	Pink with Black Dots
6-025	Room 635 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-025	Room 635 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-025	Room 635 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
6-026	Room 634 & WR	Floor	Vinyl Sheet Flooring 11	Asbestos	Homogeneous w/ 15-2988-34 to 38	None Detected	N/A	N/A	Pink with Black Dots
6-026	Room 634 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-026	Room 634 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-026	Room 634 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
6-027	Room 633 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	160 SF	Good	Cream with Rust Swirls
6-027	Room 633 & WR	Floor	Vinyl Sheet Flooring 11	Asbestos	Homogeneous w/ 15-2988-34 to 38	None Detected	N/A	N/A	Pink with Black Dots
6-027	Room 633 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-027	Room 633 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-027	Room 633 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
6-028	Room 632 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	300 SF	Good	Cream with Rust Swirls
6-028	Room 632 & WR	Floor	Vinyl Sheet Flooring 11	Asbestos	Homogeneous w/ 15-2988-34 to 38	None Detected	N/A	N/A	Pink with Black Dots
6-028	Room 632 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-028	Room 632 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
6-028	Room 632 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
6-029	Room 631 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	160 SF	Good	Cream with Rust Swirls
6-029	Room 631 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-029	Room 631 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-029	Room 631 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
6-030	Room 630 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	160 SF	Good	Cream with Rust Swirls
6-030	Room 630 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-030	Room 630 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-030	Room 630 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
6-031	Room 629 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	300 SF	Good	Cream with Rust Swirls
6-031	Room 629 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-031	Room 629 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-031	Room 629 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
6-032	Room 628 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	160 SF	Good	Cream with Rust Swirls
6-032	Room 628 & WR	Floor	Vinyl Sheet Flooring 11	Asbestos	Homogeneous w/ 15-2988-34 to 38	None Detected	N/A	N/A	Pink with Black Dots
6-032	Room 628 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-032	Room 628 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-032	Room 628 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
6-033	Room 627 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	160 SF	Good	Cream with Rust Swirls
6-033	Room 627 & WR	Floor	Vinyl Sheet Flooring 11	Asbestos	Homogeneous w/ 15-2988-34 to 38	None Detected	N/A	N/A	Pink with Black Dots
6-033	Room 627 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-033	Room 627 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-033	Room 627 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
6-034	Room 626 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	160 SF	Good	Cream with Rust Swirls
6-034	Room 626 & WR	Floor	Vinyl Sheet Flooring 11	Asbestos	Homogeneous w/ 15-2988-34 to 38	None Detected	N/A	N/A	Pink with Black Dots
6-034	Room 626 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-034	Room 626 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-034	Room 626 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
6-035	Washroom	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink
6-035	Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-035	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-036	Shower & Tub Room	Floor	Vinyl Sheet Flooring 13	Asbestos	Homogeneous w/ 21-5940-1 to 3	None Detected	N/A	N/A	Blue with Beige, Brown and Black Specks
6-036	Shower & Tub Room	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
6-036	Shower & Tub Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-037	Washroom	Floor	Vinyl Sheet Flooring 13	Asbestos	Homogeneous w/ 21-5940-1 to 3	None Detected	N/A	N/A	Blue with Beige, Brown and Black Specks
6-037	Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-037	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-038	Shower & Tub Room	Floor	Vinyl Sheet Flooring 13	Asbestos	Homogeneous w/ 21-5940-1 to 3	None Detected	N/A	N/A	Blue with Beige, Brown and Black Specks
6-038	Shower & Tub Room	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
6-038	Shower & Tub Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-038	Shower & Tub Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-039	Clean Utility	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink
6-039	Clean Utility	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-039	Clean Utility	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-040	Soiled Utility	Floor	Vinyl Sheet Flooring 11	Asbestos	Homogeneous w/ 15-2988-34 to 38	None Detected	N/A	N/A	Pink with Black Dots

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
6-040	Soiled Utility	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-040	Soiled Utility	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-041	Lounge	Floor	Vinyl Sheet Flooring 19	Asbestos	Not Sampled	ACM Assumed	350 SF	Good	Hardwood Design
6-041	Lounge	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-041	Lounge	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
6-042	Janitor's Closet	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
6-042	Janitor's Closet	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED
6-042	Janitor's Closet	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-042	Janitor's Closet	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-043	Room 625 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	175 SF	Good	Cream with Rust Swirls
6-043	Room 625 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-043	Room 625 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-043	Room 625 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
6-044	Room 623 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	Cream with Rust Swirls
6-044	Room 623 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-044	Room 623 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-044	Room 623 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
6-045	Room 621 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	Cream with Rust Swirls
6-045	Room 621 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-045	Room 621 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-045	Room 621 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
6-046	Room 619 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	Cream with Rust Swirls

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
6-046	Room 619 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-046	Room 619 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-046	Room 619 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
6-047	Room 617 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	Cream with Rust Swirls
6-047	Room 617 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-047	Room 617 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-047	Room 617 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
6-048	Room 615 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	Cream with Rust Swirls
6-048	Room 615 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-048	Room 615 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-048	Room 615 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
6-049	Kitchen/Servery	Floor	Vinyl Sheet Flooring 11	Asbestos	15-2988-38*	None Detected	N/A	N/A	Pink with Black Dots *From Fisher Project No. 15-7543, dated Dec. 2015
6-049	Kitchen/Servery	Walls	Drywall (DJC)	Asbestos	15-2988-28 to 30*	None Detected	N/A	N/A	*From Fisher Project No. 15-7543, dated Dec. 2015
6-049	Kitchen/Servery	Ceiling	Ceiling Tile 4	Asbestos	15-2988-31 to 33*	None Detected	N/A	N/A	2' x 4' Pinhole Fissure *From Fisher Project No. 15-7543, dated Dec. 2015
6-049	Kitchen/Servery	Ceiling	Ceiling Tile 6	N/A	N/A	N/A	N/A	N/A	2' x 4' Fibreglass
6-050	Dining Room	Floor	Vinyl Sheet Flooring 9	Asbestos	Homogeneous w/ 18-8899-44 to 46	None Detected	N/A	N/A	Beige
6-050	Dining Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-050	Dining Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-050	Dining Room	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
6-050	Dining Room	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 18-8899-19 to 21	None Detected	N/A	N/A	2' x 4' Pinhole Long Fissure
6-050	Dining Room	Ceiling	Ceiling Tile 4	Asbestos	Homogeneous w/ 15-2988-31 to 33	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
6-051	Corridor	Floor	Vinyl Sheet Flooring 9	Asbestos	Homogeneous w/ 18-8899-44 to 46	None Detected	N/A	N/A	Beige
6-051	Corridor	Walls	Drywall (DJC)	Asbestos	18-8899-67*	None Detected	N/A	N/A	*From Fisher Project No. 18-8834, dated May 2018

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
6-051	Corridor	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
6-052	Electrical Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
6-052	Electrical Room	Walls	Block	N/A	N/A	N/A	N/A	N/A	
6-052	Electrical Room	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
6-053	Activity Room	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink
6-053	Activity Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-053	Activity Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-053	Activity Room	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
6-054	Room 611 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	Cream with Rust Swirls
6-054	Room 611 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-054	Room 611 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-054	Room 611 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
6-055	Room 609 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	Cream with Rust Swirls
6-055	Room 609 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-055	Room 609 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-055	Room 609 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
6-056	Room 607 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	Cream with Rust Swirls
6-056	Room 607 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-056	Room 607 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-056	Room 607 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
6-057	Room 605 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	Cream with Rust Swirls
6-057	Room 605 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-057	Room 605 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
6-057	Room 605 & WR	Door	Paint	Lead	17-5667-07*	<10 ppm	N/A	N/A	Tan *From Fisher Project No. 17-8078, dated Feb. 2017
6-057	Room 605 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
6-058	Room 603 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	Cream with Rust Swirls
6-058	Room 603 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-058	Room 603 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-058	Room 603 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
6-059	Room 601 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	175 SF	Good	Cream with Rust Swirls
6-059	Room 601 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-059	Room 601 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-059	Room 601 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
6-060	Clean Utility	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink
6-060	Clean Utility	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-060	Clean Utility	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-061	Soiled Utility	Floor	Vinyl Sheet Flooring 11	Asbestos	Homogeneous w/ 15-2988-34 to 38	None Detected	N/A	N/A	Pink with Black Dots
6-061	Soiled Utility	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-061	Soiled Utility	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-062	Lounge	Floor	Parquet	N/A	N/A	N/A	N/A	N/A	
6-062	Lounge	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-062	Lounge	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
6-063	Room 602 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	Cream with Rust Swirls
6-063	Room 602 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-063	Room 602 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
6-063	Room 602 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
6-064	Room 604 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	Cream with Rust Swirls
6-064	Room 604 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-064	Room 604 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-064	Room 604 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
6-065	Washroom	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
6-065	Washroom	Floor	Vinyl Sheet Flooring 9	Asbestos	Homogeneous w/ 18-8899-44 to 46	None Detected	N/A	N/A	Beige NOT OBSERVED
6-065	Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-065	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-066	Room 606 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	175 SF	Good	Cream with Rust Swirls
6-066	Room 606 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-066	Room 606 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-066	Room 606 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
6-067	Shower & Tub Room	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
6-067	Shower & Tub Room	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
6-067	Shower & Tub Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-067	Shower & Tub Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-068	Room 608 & WR	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	175 SF	Good	Cream with Rust Swirls
6-068	Room 608 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-068	Room 608 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-068	Room 608 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
6-069	Janitor's Closet	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
6-069	Janitor's Closet	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink NOT OBSERVED

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
6-069	Janitor's Closet	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-069	Janitor's Closet	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-070	Room 610 & WR	Floor	Vinyl Sheet Flooring 10	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	Beige with White and Grey Streaks
6-070	Room 610 & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-070	Room 610 & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-070	Room 610 & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
6-071	Lounge	Floor	Vinyl Sheet Flooring 19	Asbestos	Not Sampled	ACM Assumed	350 SF	Good	Hardwood Design
6-071	Lounge	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-071	Lounge	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-071	Lounge	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
6-072	Linen Chute	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 18-9720-01 to 03	None Detected	N/A	N/A	Pink
6-072	Linen Chute	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-072	Linen Chute	Ceiling	Sprayed Fireproofing	Asbestos	Homogeneous w/ 18-8899-56 to 58 and 19-2282-1 to 4	None Detected	N/A	N/A	
6-072	Linen Chute	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-073	Linen Room	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 18-8899-38 to 40	None Detected	N/A	N/A	Pink with Brown and Beige Smears
6-073	Linen Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-073	Linen Room	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 15-2988-04 to 06	None Detected	N/A	N/A	2' x 4' Random Pinhole
6-074	Electrical/Sprinkler	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
6-074	Electrical/Sprinkler	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2988-28 to 30 & 18-8899-65 to 67	None Detected	N/A	N/A	
6-074	Electrical/Sprinkler	Ceiling	Sprayed Fireproofing	Asbestos	Homogeneous w/ 18-8899-56 to 58 and 19-2282-1 to 4	None Detected	N/A	N/A	
6-075	Stairs # 1	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
6-075	Stairs # 1	Walls	Concrete	N/A	N/A	N/A	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
6-075	Stairs # 1	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A	
PH-001	Penthouse - Foyer	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
PH-001	Penthouse - Foyer	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3754-01 to 03	None Detected	N/A	N/A	
PH-001	Penthouse - Foyer	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3754-01 to 03	None Detected	N/A	N/A	
PH-002	Penthouse	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
PH-002	Penthouse	Floor	Firestop-Blue	Asbestos	22-7881-14 to 16*	None Detected	N/A	N/A	*From Fisher Project No. 22-11869, dated Feb. 2022
PH-002	Penthouse	Walls	Drywall (DJC)	Asbestos	16-3754-01 to 03*	None Detected	N/A	N/A	*From Fisher Project No. 16-7701, dated April 2016
PH-002	Penthouse	Walls	Metal	N/A	N/A	N/A	N/A	N/A	
PH-002	Penthouse	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A	
PH-002	Penthouse	Pipe	Insulation	Asbestos	16-4359-01 to 06*	None Detected	N/A	N/A	Insulation underneath pipe hangers - upper & lower *From Fisher Project No. 16-7846, dated July 2016
PH-003	Penthouse - Hallways	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
PH-003	Penthouse - Hallways	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3754-01 to 03	None Detected	N/A	N/A	
PH-003	Penthouse - Hallways	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A	

Surveyor's Field Notes

APPENDIX II

RESULTS OF BULK SAMPLE ANALYSIS

(NO INFORMATION TO REPORT)

APPENDIX III

SITE DRAWINGS



Legend



Asbestos-Containing Material

1-01

Location Number

NAR

No Access to Room

The drawing does not illustrate locations of drywall joint compound, plaster, window caulking or roofing materials, for reasons discussed in Section 6 of the Standard Operating Procedure for Designated Substance Surveys. Please refer to the Designated Substance Survey Form in Appendix I for information regarding the locations and asbestos or lead-content of these materials.




Figure 1

LOCATION:
2920 Lawrence Avenue East
Toronto, Ontario

BUILDING NAME:
Bendale Acres

Basement Plan Asbestos-Containing Material Locations

CLIENT: City of Toronto

PROJECT NUMBER: FE-P 23-12800 **DATE:** May 2023 **DRW BY:** DC

CAD FILE: FIG1 **SCALE:** Not to Scale **CHK BY:** RS





Legend




Asbestos-Containing Material

1-01

Location Number

NAR

No Access to Room



The drawing does not illustrate locations of drywall joint compound, plaster, window caulking or roofing materials, for reasons discussed in Section 6 of the Standard Operating Procedure for Designated Substance Surveys. Please refer to the Designated Substance Survey Form in Appendix I for information regarding the locations and asbestos or lead-content of these materials.

Figure 3

LOCATION:
2920 Lawrence Avenue East
Toronto, Ontario

BUILDING NAME:
Bendale Acres

Second Floor
Asbestos-Containing Material Locations

CLIENT: City of Toronto

PROJECT NUMBER: FE-P 23-12800 **DATE:** May 2023 **DRW BY:** ZA

CAD FILE: FIG3 **SCALE:** Not to Scale **CHK BY:** RS





Legend



Asbestos-Containing Material

1-01

Location Number

NAR

No Access to Room



The drawing does not illustrate locations of drywall joint compound, plaster, window caulking or roofing materials, for reasons discussed in Section 6 of the Standard Operating Procedure for Designated Substance Surveys. Please refer to the Designated Substance Survey Form in Appendix I for information regarding the locations and asbestos or lead-content of these materials.

Figure 4

LOCATION:
2920 Lawrence Avenue East
Toronto, Ontario

BUILDING NAME:
Bendale Acres

Third Floor
Asbestos-Containing Material Locations

CLIENT: City of Toronto

PROJECT NUMBER: FE-P 23-12800	DATE: May 2023	DRW BY: DC
--------------------------------------	-----------------------	-------------------

CAD FILE: FIG4	SCALE: Not to Scale	CHK BY: RS
-----------------------	----------------------------	-------------------





Legend



Asbestos-Containing Material



Location Number



No Access to Room



The drawing does not illustrate locations of drywall joint compound, plaster, window caulking or roofing materials, for reasons discussed in Section 6 of the Standard Operating Procedure for Designated Substance Surveys. Please refer to the Designated Substance Survey Form in Appendix I for information regarding the locations and asbestos or lead-content of these materials.

Figure 6

LOCATION:
2920 Lawrence Avenue East
Toronto, Ontario

BUILDING NAME:
Bendale Acres

**Fifth Floor
Asbestos-Containing Material Locations**

CLIENT: City of Toronto

PROJECT NUMBER: FE-P 23-12800 **DATE:** May 2023 **DRW BY:** ZA

CAD FILE: FIG6 **SCALE:** Not to Scale **CHK BY:** RS





Legend



Asbestos-Containing Material

1-01

Location Number

NAR

No Access to Room



The drawing does not illustrate locations of drywall joint compound, plaster, window caulking or roofing materials, for reasons discussed in Section 6 of the Standard Operating Procedure for Designated Substance Surveys. Please refer to the Designated Substance Survey Form in Appendix I for information regarding the locations and asbestos or lead-content of these materials.

Figure 7

LOCATION:
2920 Lawrence Avenue East
Toronto, Ontario

BUILDING NAME:
Bendale Acres

Sixth Floor
Asbestos-Containing Material Locations

CLIENT: City of Toronto

PROJECT NUMBER: FE-P 23-12800	DATE: May 2023	DRW BY: DC
CAD FILE: FIG7	SCALE: Not to Scale	CHK BY: RS





Legend



Asbestos-Containing Material

1-01

Location Number

NAR

No Access to Room




Figure 8

LOCATION:
2920 Lawrence Avenue East
Toronto, Ontario

BUILDING NAME:
Bendale Acres

Roof Plan Asbestos-Containing Material Locations

CLIENT: City of Toronto

PROJECT NUMBER: FE-P 23-12800 **DATE:** May 2023 **DRW BY:** DC

CAD FILE: FIG8 **SCALE:** Not to Scale **CHK BY:** RS



APPENDIX IV

SITE PHOTOGRAPHS

(NO INFORMATION TO REPORT)

APPENDIX V

CORRECTIVE ACTIONS INSPECTION REPORT



September 1, 2023

City of Toronto, Corporate Real Estate Management
Metro Hall, 55 John Street
Toronto ON, M5V 3C6

Inder Bhamra, EP, PMP, CSM
Environmental Coordinator

Re: Level I Mould Abatement at Long Term Care Home, 2920 Lawrence Avenue East, Toronto, ON

As requested, Fisher Engineering Limited (Fisher) has provided environmental monitoring services with respect to mould abatement activities recently undertaken at Bendale Acres Long Term Care Home, located at 2920 Lawrence Avenue East, Toronto, Ontario (the "Site"). Mould remediation was initiated following the discovery of mould impacted fiberglass insulation, approximately 30 LF, during the Annual Survey, conducted on May 18, 2023, Fisher Project No. FE 23-12800.

The City of Toronto retained Fisher as the environmental health and safety consultant to provide project monitoring. Fisher retained Furcon Environmental Inc. as the environmental contractor to undertake the specified remedial action. Abatement work was conducted in accordance with Level 1 mould remediation protocols, as outlined by the Environmental Abatement Council of Canada (EACC) Mould Abatement Guidelines, Edition 3 (2015). The fieldwork was conducted on August 28, 2023.

Based on the recommendations provided in a corrective action form, the pipe insulation is to be removed from Valve Room, Location Number B-051, following Level 1 Mould Remediation Procedures, and replaced with new insulation.

Based on the Site observation, the remediation scope of work had been completed and the work area was cleaned to an acceptable level.

Respectfully submitted,

Prepared by:

Reviewed by:

A blue ink signature of Yvonne Hoogeveen.

Yvonne Hoogeveen, P. Eng.
Project Manager

A blue ink signature of David A. Fisher next to a circular professional seal. The seal contains the text 'LICENSED PROFESSIONAL ENGINEER', 'D. A. FISHER', and 'PROVINCE OF ONTARIO'.

David A. Fisher, B.A.Sc., C.Chem., P.Eng.
Principal

Attachment A – Site Photos



Photo 1: View of the pipes after abatement work.



Photo 2: View of the pipes after abatement work.



Photo 3: View of mould impacted pipe Insulation.



Photo 4: View of the pipes after abatement work.