

WEST MOAT PARAPET WALL (NORTH FACE) EXISTING CONDITION



1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16
CRACKED CRACKED CRACKED CHIPPED/MISSING PIECE CRACKED



16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32



33 34 35 36 37



SAMPLES OF LOST OR DAMAGED JOINTS



SAMPLES OF CRACKED AND DAMAGED STONE



CAB STAND CEILING
(SPOTS TO BE REPAIRED AND MATCHING
CONCRETE SURFACE RESTORED)