



Designated Substance Survey Report

Toronto Emergency
Headquarters, Paramedic
Station 53 & Parking Garage
4330 Dufferin Street,
Toronto, Ontario

Prepared for:

City of Toronto

55 John Street, 2nd Floor
Toronto, Ontario, M5V 3C6

December 6, 2023

Pinchin File: 309046.002



Designated Substance Survey Report

Toronto Emergency Headquarters, Paramedic Station 53 & Parking Garage, 4330 Dufferin Street, Toronto, Ontario
City of Toronto

December 6, 2023

Pinchin File: 309046.002

Issued to: City of Toronto
Issued on: December 6, 2023
Pinchin File: 309046.002
Issuing Office: Toronto, ON

Author: _____
Abdullah Qasemzada
Project Coordinator
365.822.1013
aqasemzada@pinchin.com

Reviewer: _____
Andres Gimenez
Senior Project Manager
289.971.1196
agimenez@pinchin.com

Reviewer: _____
Tanya Stanisic, B.Sc. Hons.
Operations Manager
647.502.6665
tstanisic@pinchin.com



EXECUTIVE SUMMARY

City of Toronto (Client) retained Pinchin Ltd. (Pinchin) to conduct a Designated Substance Re-Survey (reassessment) of Toronto Emergency Headquarters, Paramedic Station 53 & Parking Garage located at 4330 Dufferin Street, Toronto, Ontario. Pinchin performed the reassessment on October 16, 2023.

The objective of the reassessment was to document any changes in condition and quantity of specified Designated Substances, polychlorinated biphenyls (PCBs) and mould identified in the previous Designated Substances Survey (2020, Pinchin File No. 274992.001), and develop corrective action plans as required. The results of this reassessment are not intended for construction, renovation, demolition, or project tendering purposes.

SUMMARY OF FINDINGS

The following is a summary of significant findings; refer to the body of the report for detailed findings:

Asbestos: Presumed asbestos-containing materials (ACM) are present as follows and are in good condition:

- Non-friable cement (Transite) pipe present as rainwater leaders throughout the building.
- Non-friable backing paper/adhesive behind vinyl sheet flooring within Office Space.
- Non-friable vinyl floor tiles and associated mastic within File Storage Room.

Lead:

- All paints sampled contain lead concentrations below the City of Toronto action limit of 0.1%.
- Lead may be present within batteries of emergency lights.

Silica: Crystalline silica is present in concrete, mortar, masonry, ceramics, grout, drywall, ceiling tiles, plaster, and asphalt.

Mercury: Mercury vapour is present in lamp tubes.

Polychlorinated Biphenyls (PCBs): Based on the date of construction, PCBs are not present.

Mould and Water Damage: Visible mould and water damage was not observed during the reassessment.

Urea Formaldehyde Foam Insulation (UFFI): Urea Formaldehyde Foam Insulation (UFFI) was not observed during the reassessment.



SUMMARY OF RECOMMENDATIONS

The following is a summary of significant recommendations; refer to the body of the report for detailed recommendations.

1. Perform a reassessment of asbestos materials on an annual basis.
2. Prepare a pre-construction survey and remove all ACM prior to alterations or maintenance work or if ACM may be disturbed by the work.
3. Recycle mercury-containing light tubes when removed from service.
4. Follow appropriate safe work procedures when handling or disturbing asbestos, lead, and silica.

Please refer to Section 5.0 of this report for detailed recommendations regarding administrative and remedial actions.

This Executive Summary is subject to the same standard limitations as contained in the report and must be read in conjunction with the entire report.



Designated Substance Survey Report

Toronto Emergency Headquarters, Paramedic Station 53 & Parking Garage, 4330 Dufferin Street, Toronto, Ontario
City of Toronto

December 6, 2023

Pinchin File: 309046.002

TABLE OF CONTENTS

1.0 INTRODUCTION AND SCOPE 1

 1.1 Scope of Assessment 1

2.0 METHODOLOGY 2

3.0 BACKGROUND INFORMATION 2

 3.1 Building Description 2

 3.2 Existing Reports and Summary of Asbestos Abatement 3

 3.3 Inaccessible Locations 3

4.0 FINDINGS 4

 4.1 Asbestos 4

 4.2 Lead 12

 4.3 Silica 14

 4.4 Mercury 14

 4.5 Polychlorinated Biphenyls 14

 4.6 Mould and Water Damage 15

 4.7 Urea Formaldehyde Foam Insulation (UFFI) 15

5.0 RECOMMENDATIONS 15

 5.1 General 15

 5.2 On-going Management and Maintenance 15

6.0 TERMS AND LIMITATIONS 16

7.0 REFERENCES 16

APPENDICES

APPENDIX I Room-by-Room Inventory Sheet

APPENDIX II-A Asbestos Analytical Certificates (No Information to Report)

APPENDIX II-B Lead Analytical Certificates (No Information to Report)

APPENDIX II-C PCB Analytical Certificates (No Information to Report)

APPENDIX III Drawings

APPENDIX IV Methodology

APPENDIX V Corrective Action Inspection Report (No Information to Report)



1.0 INTRODUCTION AND SCOPE

City of Toronto (Client) retained Pinchin Ltd. (Pinchin) to conduct a Designated Substance Re-Survey (reassessment) of Toronto Emergency Headquarters, Paramedic Station 53 & Parking Garage located at 4330 Dufferin Street, Toronto, Ontario

Pinchin performed the reassessment on October 16, 2023. The surveyor was unaccompanied during the reassessment. The assessed area was occupied at the time of the reassessment.

The objective of the reassessment was to document any changes in condition and quantity of specified Designated Substances, polychlorinated biphenyls (PCBs) and mould identified in the previous Designated Substances Survey (2020, Pinchin File No. 274992.001), and develop corrective action plans as required.

This reassessment is only to be used for the purposes of long-term management and routine maintenance. The results of this reassessment are not to be used for construction, renovation, demolition, or project tendering purposes.

1.1 Scope of Assessment

For the purpose of the reassessment and this report, hazardous building materials are defined as follows:

- Asbestos
- Lead
- Silica
- Mercury
- Mould
- Urea Formaldehyde Foam Insulation (UFFI)

Based on the date of construction and known end of use dates, polychlorinated biphenyls are presumed not to be present in the building.

The following Designated Substances are not typically found in building materials in a composition/state that is hazardous and were not included in this reassessment:

- Arsenic
- Acrylonitrile
- Benzene
- Coke oven emissions



Designated Substance Survey Report

Toronto Emergency Headquarters, Paramedic Station 53 & Parking Garage, 4330 Dufferin Street, Toronto, Ontario
City of Toronto

December 6, 2023

Pinchin File: 309046.002

- Ethylene oxide
- Isocyanates
- Vinyl chloride monomer

2.0 METHODOLOGY

Pinchin conducted an inspection of previously identified hazardous building materials to evaluate the current condition of all accessible identified in the most recent assessment. The surveyor made reference to any existing assessment or abatement reports (as provided by the Client).

The reassessment was performed based on the methodology outlined in the City of Toronto, Facilities Management, Standard Operating Procedure for Designated Substance Surveys.

For further details on the methodology including test methods, refer to Appendix IV.

3.0 BACKGROUND INFORMATION

3.1 Building Description

Description Item	Details
Use	Toronto Paramedic Services Station, Toronto Emergency Services Headquarters and Parking Garage
Number of Floors	The building is four storeys plus one level below grade
Total Area	The total area of the building is approximately 400,000 square feet
Year of Construction	The building was constructed in 1990
Structure	Structural steel, concrete
Exterior Cladding	Metal siding, masonry, concrete
HVAC	Rooftop AC, boiler, hot water heating, natural gas heating
Roof	Built-up roofing, EPDM (Not assessed)
Flooring	Vinyl sheet flooring, vinyl tile, ceramic tile, laminate, carpet, concrete
Interior Walls	Plaster, drywall, ceramic tile, masonry, concrete
Ceilings	Plaster, drywall, acoustic tile, tectum tile



3.2 Existing Reports and Summary of Asbestos Abatement

3.2.1 Review of Previous Reports

Pinchin previously prepared the following report, which has been reviewed as part of this reassessment:

- “Designated Substance Survey Report, Toronto Emergency Headquarters, Paramedic Services Station 53 and Parking Garage, 4330 Dufferin Street, Toronto, Ontario” dated October 23, 2020. Pinchin File No. 274992.001.

3.2.2 Summary of Asbestos Abatement since the Previous Reassessment

Based on observations made during the reassessment, asbestos abatement has not been conducted since the last reassessment.

3.3 Inaccessible Locations

The following rooms or areas were not accessible and are therefore not included in the report:

Area or Room	Reason	Previously identified PACM not inspected, and condition
Hydro Vault (Location 1-071)	Locked, no access	N/A
Garage (Location 1-099)	Locked, no access.	Cement (Transite) pipe
Sprinkler & Pump Room (Location 1-113)	Locked, no access	N/A
Vehicle Bays 1-4 (Location 1-120)	Locked, no access.	Cement (Transite) pipe
Vehicle Bays 5-10 (Location 1-121)	Locked, no access.	Cement (Transite) pipe
Main Switch Room (Location 2-104)	Locked, no access	N/A
UPS Room (Location 2-106)	Locked, no access.	Cement (Transite) pipe
Mechanical Room (Location 2-107)	Locked, no access	N/A
Boardroom (Location 2-138)	Locked, no access	N/A
Office (Location 3-039)	Locked, no access	N/A
Washroom (Location 3-040)	Locked, no access	N/A

4.0 FINDINGS

The following section summarizes the findings of the reassessment and provides a general description of the hazardous materials identified and their locations. No sampling was performed during this reassessment. Reference to the bulk samples refers to samples collected during previous assessments.

For details on approximate quantities, condition, and locations of hazardous materials; refer to the Room-by-Room Inventory Sheet in Appendix I. Any quantities listed in this report or Inventory Sheet are estimated based on visual approximations only and are subject to variation.

4.1 Asbestos


4.1.1 Spray-Applied Insulation

Spray-applied fireproofing and overspray, present on structural steel including beams, trusses, joists, and corrugated steel decks throughout the building, was previously sampled and does not contain asbestos (samples 11850-A-01-01A-G and 2018-A0001A-C).

4.1.2 Pipe Insulation

Previously identified non-asbestos paring cement (samples 11850-A-01-2A to C, 11850-A-01-3A to C, 11850-A-01-4A to C) present on pipe fittings has not been observed since the 2017 assessment.

Pipes observed are either uninsulated or insulated with fibreglass and jacketed in paper.



Uninsulated pipe – Corridor (Location B-001).



Pipes insulated with fibreglass and jacketed in paper– Cleaner Storage (Location B-004).

4.1.3 Duct Insulation

Ducts are either uninsulated or insulated with fiberglass and jacketed in foil.

Mastic was not observed on exterior sections of ducts assessed.

Mastic may be present on exterior sections of ducts in inaccessible spaces such as above solid ceilings, in chases and within shafts.



Uninsulated duct – Corridor (Location B-001).



Duct insulated with fiberglass and jacketed in foil – Central Files Storage (Location B-007).

4.1.4 Mechanical Equipment Insulation

Mechanical equipment observed is either uninsulated or insulated with fiberglass and jacketed in metal.



Uninsulated boiler – Boiler Room (Location B-014).



Hot water tanks insulated with fiberglass – Storage Cages (Location B-002).

4.1.5 Acoustic Ceiling Tiles

Acoustic ceiling tiles are present in the assessed area, as follows:

Size, Type, Pattern	Locations	Sample Number, Composition or Date Code	Asbestos Type
ACT01: 24"x72", lay-in, short random fissure and pinpoint	Refer to the Room-by-Room Inventory Sheet in Appendix I for locations	11850-A-01-19A-C	None detected
ACT02: 24"x48", lay-in, white	Refer to the Room-by-Room Inventory Sheet in Appendix I for locations	11850-A-01-12A-C	None detected
ACT03: 24"x48", lay-in, wide pinpoint	Refer to the Room-by-Room Inventory Sheet in Appendix I for locations	11850-A-01-16A-C	None detected
ACT05: 24"x48", lay-in, short uniform fissure	Refer to the Room-by-Room Inventory Sheet in Appendix I for locations	11850-A-01-18A-C	None detected



Designated Substance Survey Report

Toronto Emergency Headquarters, Paramedic Station 53 & Parking Garage, 4330 Dufferin Street, Toronto, Ontario
City of Toronto

December 6, 2023

Pinchin File: 309046.002

Size, Type, Pattern	Locations	Sample Number, Composition or Date Code	Asbestos Type
ACT06: 24"x48", lay-in, short random fissure with pinpoint drop-down	Refer to the Room-by-Room Inventory Sheet in Appendix I for locations	11850-A-01-14A-C	None detected
ACT07: 24"x48", lay-in, plain white drop-down	Refer to the Room-by-Room Inventory Sheet in Appendix I for locations	11850-A-01-13A-C	None detected
ACT08: 24"x72", lay-in, wide pinpoint	Refer to the Room-by-Room Inventory Sheet in Appendix I for locations	11850-A-01-20A-C	None detected
ACT09: 24"x72", lay-in, widthwise fissure and pinpoint	Refer to the Room-by-Room Inventory Sheet in Appendix I for locations	11850-A-01-21A-C	None detected
ACT10: 24"x72", lay-in, sparse widthwise fissure with pinpoint	Refer to the Room-by-Room Inventory Sheet in Appendix I for locations	Pinchin File No. 239118.003; S0001A-C	None detected
ACT11: 24"x72", lay-in, plain textured drop-down	Refer to the Room-by-Room Inventory Sheet in Appendix I for locations	11850-A-01-22A-C	None detected
ACT12: 24"x72", lay-in, plain drop-down	Refer to the Room-by-Room Inventory Sheet in Appendix I for locations	11850-A-01-23A-C	None detected
ACT13: 24"x48", lay-in, short random fissure with pinpoint	Refer to the Room-by-Room Inventory Sheet in Appendix I for locations	11850-A-01-15A-C	None detected
ACT14: 24"x72", lay-in, large random fissure with pinpoint	Refer to the Room-by-Room Inventory Sheet in Appendix I for locations	11850-A-01-24A-C	None detected
ACT15: 24"x 24", lay-in, plain white	Refer to the Room-by-Room Inventory Sheet in Appendix I for locations	11850-A-01-25A-C	None detected
ACT16: 24"x48", lay-in, plain textured	Refer to the Room-by-Room Inventory Sheet in Appendix I for locations	Fibreglass composition	**None
ACT17: 24"x48", lay-in, plain textured	Refer to the Room-by-Room Inventory Sheet in Appendix I for locations	11850-8019-04 to 06	None detected
ACT19: 24"x48", lay-in, textured pinhole	Refer to the Room-by-Room Inventory Sheet in Appendix I for locations	Date code: 05/14/13	*None
ACT20: 24"x48", lay-in, random fissure and pinhole	Refer to the Room-by-Room Inventory Sheet in Appendix I for locations	Date code: 08/20/16	*None

Size, Type, Pattern	Locations	Sample Number, Composition or Date Code	Asbestos Type
ACT21: 24"x48", lay-in, random fissure and pinhole	Refer to the Room-by-Room Inventory Sheet in Appendix I for locations	Date code: 03/09/16	*None
ACT22: 24"x48", lay-in, random fissure and pinhole	Refer to the Room-by-Room Inventory Sheet in Appendix I for locations	Date code: 2019	*None
ACT23: 24"x48", lay-in, white pinhole	Refer to the Room-by-Room Inventory Sheet in Appendix I for locations	Date code: 07/27/12	*None

*Ceiling tiles are presumed to be non-asbestos based on the date of manufacture determined from the date stamp applied to the top of the tiles. The tiles were manufactured after asbestos stopped being used in acoustic ceiling tiles.

**Ceiling tiles are presumed to be non-asbestos based on the composition of the tiles (e.g. fibreglass).

Non-asbestos metal acoustic ceiling tiles (ACT18: 24"x48", lay-in, uniform dot) was not observed during this reassessment and is no longer present.



Non-asbestos acoustic ceiling tiles (ACT01).



Non-asbestos acoustic ceiling tiles (ACT02).



Non-asbestos acoustic ceiling tiles (ACT10).



Non-asbestos acoustic ceiling tiles (ACT15).

4.1.6 Plaster

Plaster is present on wall and ceiling finishes throughout the South Building.

Asbestos in plaster was banned in 1980; however, based on historical data, it has been found present up until 1986. Plaster in the assessed area was installed on or after 1990 and is presumed not to contain asbestos.

4.1.7 Drywall Joint Compound

Drywall (gypsum board) and drywall joint compound is present as a wall and ceiling finish throughout the building.

Drywall joint compound was previously sampled and does not contain asbestos (samples 12-4832-13 to 18, 12-4832-4 to 9, 13-6484-04 to 09, 12-4788-1 to 3, 10-1303-1 to 3, 13-7419-01 to 03, 13-6484-01 to 09, 13-6174-01 to 03, 14-8019-07 to 11).

Asbestos in drywall joint compound was banned in 1980; however, based on historical data, it has been found present up until 1986. Drywall joint compound in the assessed area was installed on or after 1990 and is presumed not to contain asbestos.

4.1.8 Asbestos Cement Products (Transite)

Cement (Transite) pipe, present as rainwater leaders throughout the building, presumed to contain asbestos based on visual observation. Transite is non-friable and in good condition.



Presumed asbestos-containing Transite pipe – Corridor
(Location 1-098).



Presumed asbestos-containing Transite pipe – Men's /
Women's Change Room (Location 2-145).

4.1.9 Vinyl Sheet Flooring

Vinyl sheet flooring is present as follows:

Pattern, Colour	Locations	Sample Number	Asbestos (Backing / Adhesive)
VSF01: dark blue	Stores Storage Mezzanine (Location 1-020)	11850-A-01-09A-C	None detected
VSF02: beige mosaic	Refer to the Room-by-Room Inventory Sheet in Appendix I for locations	2018-A0003A-C	None detected
VSF03: grey with black fleck	Corridor (Location 2-013)	11850-A-01-10A-C	None detected
VSF04: grey	Office (Location 1-108)	N/A	Presumed asbestos-containing

Asbestos-containing vinyl sheet flooring (VSF04: grey) was not observed in Office (Location 1-108) due to raised computer flooring in the room. Vinyl sheet flooring is presumed present under new flooring. Backing paper/adhesive behind VSF04 is presumed to contain asbestos until sampling proves otherwise. Backing paper/adhesive is a non-friable material but can become friable during removal and the current condition is unknown.



Non-asbestos vinyl sheet flooring (VSF01).



Non-asbestos vinyl sheet flooring (VSF02).



Non-asbestos vinyl sheet flooring (VSF03).

4.1.10 Vinyl Floor Tiles and Mastic

Vinyl floor products and associated mastics are present as follows:


Description	Locations	Sample Number	Asbestos Type (tile)	Asbestos Type (mastic)
VFT01: 12"x12", Light grey mosaic	Refer to the Room-by-Room Inventory Sheet in Appendix I for locations	12-4832-1 to 3	None detected	None detected
VFT02: 12"x12", grey mosaic	Refer to the Room-by-Room Inventory Sheet in Appendix I for locations	12-4832-10 to 12	None detected	None detected
VFT03: 12"x12", rust mosaic	Refer to the Room-by-Room Inventory Sheet in Appendix I for locations	2018-A0002A-C	None detected	None detected
VFT04: 12"x12", grey, white streaks	Refer to the Room-by-Room Inventory Sheet in Appendix I for locations	2017-A0001A-C	None detected	None detected
VFT05: 12"x12", dark green rippled	File Storage (Location 2-122)	N/A	Presumed asbestos-containing	Presumed asbestos-containing



Non-asbestos vinyl floor tiles (VFT01).



Non-asbestos vinyl floor tiles (VFT02).



Non-asbestos vinyl floor tiles (VFT03).



Non-asbestos vinyl floor tiles (VFT04).



Presumed asbestos-containing vinyl floor tiles (VFT05).

4.1.11 Firestopping

White firestopping, present in the Corridor (Location 2-013), was previously sampled, and does not contain asbestos (samples 11850-A-01-07A-C).

Grey firestopping, present in the Office (Location 1-139), was previously sampled, and does not contain asbestos (Pinchin File No. 239118.000, samples 2019-A0001A-C).

Grey (cementitious) firestopping, present at pipe and conduit penetrations in Ground Floor Electrical Room (Location 1-057) and Secondary Electrical Room (Location 1-070), was previously sampled and does not contain asbestos (Pinchin File No. 239118.002, samples A0002A-C).

4.1.12 Caulking and Mastic

Black caulking, present on the support legs of the rooftop condenser units, was previously sampled, and does not contain asbestos (Pinchin File No. 239118.002, samples A0001A-C).

Yellow floor mastic, present beneath raised ceramic floor tiles in the Office (Location 1-140) was previously sampled and does not contain asbestos (Pinchin File No. 239118.001, samples 2019-A0002A-C).

4.1.13 Other Building Materials

Tectum tiles, present as a ceiling finish in the Storage Cages (Location B-002), was previously sampled and does not contain asbestos (samples 11850-A-01-11A-C).

Thin-set, present under ceramic tiles on the floor in the Office (Location 1-139), was previously sampled and does not contain asbestos (Pinchin File No. 239118.001, samples 2019-A0003A-C).



Non-asbestos tectum tiles – Storage Cages (Location B-002).

4.1.14 Excluded Materials

The following is a list of materials which may contain asbestos and was excluded from the reassessment. These materials are presumed to contain asbestos until otherwise proven by sampling and analysis:

- Roofing felts and tar, mastics
- Ceramic tile setting compound
- Elevator and lift brakes
- Electrical components
- Vermiculite
- Concealed adhesives and duct mastics
- Caulking and putties (previously not sampled)
- Soffit and fascia boards
- Fire resistant doors
- Metal clad finishes
- Sealants on pipe threads

4.2 Lead

4.2.1 Paints and Surface Coatings

The following table summarizes the analytical results of paints previously sampled.

Sample Number	Colour, Substrate Description	Sample Location	Lead (%)
14-8019-12	Off-white paint	EMS Communications Room (Location 3-020)	0.003
Pinchin File No. 239118.000; L0001	White paint on drywall wall	Stairwell (Location 1-139)	<0.0054

**Designated Substance Survey Report**Toronto Emergency Headquarters, Paramedic Station 53 & Parking Garage, 4330 Dufferin Street, Toronto, Ontario
City of Toronto

December 6, 2023

Pinchin File: 309046.002

Sample Number	Colour, Substrate Description	Sample Location	Lead (%)
Pinchin File No. 239118.000; L0002	Light green paint on drywall wall	Stairwell (Location 1-139)	<0.0067
Pinchin File No. 239118.000; L0003	Grey paint on metal door frame	Stairwell (Location 1-139)	<0.0049
Pinchin File No. 239118.000; L0004	Off-white paint on drywall wall	Stairwell (Location 1-139), Washroom (Location 1-140)	<0.0048
Pinchin File No. 239118.001; L0005	Beige, drywall wall	Housekeeping (Location 1-141)	<0.0074
Pinchin File No. 239118.002; L0001	Silver, structural steel	Roof (Location 0-000)	0.0076
Pinchin File No. 239118.002; L0002	Off-white, drywall wall	Second Floor Server Room (Location 2-027)	<0.0058
Pinchin File No. 239118.002; L0003	Pale green, concrete block wall	Ground Floor Electrical Room (Location 1-057)	<0.0055
Pinchin File No. 239118.003; L0001	Dark beige, drywall, wall	Classrooms (Locations 1-091, 1-092, 1-097)	<0.0058
Pinchin File No. 239118.003; L0002	White, drywall, bulkhead	Classrooms (Locations 1-091, 1-092, 1-097)	<0.00061
Pinchin File No. 239118.003; L0003	Beige, drywall, wall	Corridor (Location 1-101)	<0.0055
Pinchin File No. 239118.003; L0004	Beige, drywall, wall	Offices (Locations 1-151 to 1-153)	<0.066
Pinchin File No. 239118.003; L0005	White, drywall, wall	Offices (Locations 1-151 to 1-153)	<0.0035
Pinchin File No. 239118.003; L0006	Grey, wood door	Offices (Locations 1-151 to 1-153)	<0.0079

All sampled paints were found to contain lead at concentrations below the City of Toronto action limit of 0.1%. All paints were observed in good condition (i.e. not flaking, peeling, or delaminating).

4.2.2 Lead Products and Applications

Lead-containing batteries may be present in emergency lighting.

4.2.3 Excluded Lead Materials

Lead is known to be present in a number of materials which were not assessed or sampled.



The following materials, where found, should be presumed to contain lead.

- Electrical components, including wiring connectors, grounding conductors, and solder
- Solder on pipe connections
- Glazing on ceramic tiles

4.3 Silica

Crystalline silica is known to be a component of the following materials:

- Poured or pre-cast concrete
- Masonry and mortar
- Ceramic tiles and grout
- Plaster
- Drywall
- Ceiling tiles
- Asphalt

4.4 Mercury

4.4.1 Lamps

Mercury vapour is present in fluorescent lamp tubes.

4.4.2 Mercury-Containing Devices

Mercury-containing devices were not found during the reassessment.

4.5 Polychlorinated Biphenyls

4.5.1 Caulking and Sealants

PCBs were banned in 1980; however, are found to be present in caulking and sealants until 1985.

Caulking and sealants in the assessed area were installed in 1990 and are not suspected to contain PCBs.

4.5.2 Lighting Ballasts

Based on visual observations (evidence of T-8 fixtures) and year of construction (1990), the building and has been comprehensively re-lamped and will not contain PCB ballasts.



4.5.3 Transformers

All transformers in the building are dry type transformers and do not contain PCB-containing dielectric fluids.

4.6 Mould and Water Damage

Visible mould growth and water damage was not observed during the reassessment.

4.7 Urea Formaldehyde Foam Insulation (UFFI)

Urea Formaldehyde Foam Insulation (UFFI) was not observed within the assessed area during the reassessment.

5.0 RECOMMENDATIONS

5.1 General

Perform a detailed intrusive assessment prior to building renovation or demolition operations. The assessment should include; destructive testing (i.e. coring and/or removal of building finishes and components), and sampling of materials not previously tested (i.e. roofing materials, caulking, mastics). This report does not provide sufficient detail for most renovation or demolition.

5.2 On-going Management and Maintenance

The following recommendations are made regarding on-going management and maintenance work involving the hazardous materials identified.

5.2.1 Asbestos

Perform a reassessment of asbestos materials on an annual basis.

Perform a pre-construction survey and remove asbestos-containing materials (ACM) prior to alteration or maintenance work if ACM may be disturbed by the work. Follow appropriate asbestos precautions for the classification of work being performed.

Asbestos-containing materials must be disposed of at a landfill approved to accept asbestos waste.

Update the asbestos inventory report upon completion of any abatement and removal of asbestos-containing materials.



5.2.2 Lead

Disturbance of lead in paint and coatings (or other materials) during maintenance activities may result in over-exposure to lead dust or fumes. The need for work procedures, engineering controls and personal protective equipment will need to be assessed on a project-by-project basis and must comply with provincial standards or guidelines. Performing an exposure assessment during work that disturbs lead in paints and coatings may be able to alleviate the use of some of the precautions specified by these standards or guidelines.

Lead-containing items should be recycled when taken out of service.

5.2.3 Silica

Disturbance of silica-containing products during maintenance activities may result in excessive exposures to airborne silica, especially if performed indoors and dry. Cutting, grinding, drilling or demolition of materials containing silica should be completed only with proper respiratory protection and other worker safety precautions that comply with provincial standards or guidelines.

5.2.4 Mercury

Do not break lamps. Recycle and reclaim mercury from fluorescent lamps when taken out of service. Mercury is classified as a hazardous waste and must be disposed of in accordance with applicable regulations.

6.0 TERMS AND LIMITATIONS

The work performed by Pinchin was conducted in accordance with the City of Toronto, Blanket Contract #47024791.

7.0 REFERENCES

The following legislation and documents were referenced in completing the assessment and this report:

1. Asbestos on Construction Projects and in Buildings and Repair Operations, Ontario Regulation 278/05.
2. Designated Substances, Ontario Regulation 490/09.
3. Lead on Construction Projects, Ministry of Labour Guidance Document.
4. The Environmental Abatement Council of Canada (EACC) Lead Guideline for Construction, Renovation, Maintenance or Repair.
5. Ministry of the Environment Regulation, R.R.O. 1990 Reg. 347 as amended.
6. Ministry of the Environment Regulation, R.R.O. 1990 Reg. 362 as amended.



Designated Substance Survey Report

Toronto Emergency Headquarters, Paramedic Station 53 & Parking Garage, 4330 Dufferin Street, Toronto, Ontario
City of Toronto

December 6, 2023

Pinchin File: 309046.002

7. Silica on Construction Projects, Ministry of Labour Guidance Document.
8. Alert – Mould in Workplace Buildings, Ontario Ministry of Labour.
9. Surface Coating Materials Regulations, SOR/2016-193, Canada Consumer Product Safety Act.
10. Consolidated Transportation of Dangerous Goods Regulations, including Amendment SOR/2019-101, Transportation of Dangerous Goods Act.

\\pinchin.com\lmiss\Job\309000s\0309046.000 CITYOF TORONTO,2022AnnualProgram,HAZ,DSS\0309046.002 COFT,TorontoParamedic,HAZ,REASSMT\13
HQ\Deliverables\4330 - Dufferin - HQ - 2023 Annual DSS Report.docx

Template: Master Report for Hazardous Materials Assessment (Pre-Construction), HAZ, July 29, 2021

APPENDIX I
Room-by-Room Inventory Sheet

APPENDIX I - ROOM-BY-ROOM INVENTORY SHEET

Building Address:	4330 Dufferin Street, Toronto, Ontario	Date(s) of Current Reassessment:	October 16, 2023
Building Name:	Toronto Emergency Services Headquarters, TPS Station 53 and Parking Garage	Organization Completing Reassessment:	Pinchin Ltd.
Original Survey Conducted By:	ECOH Management	Name of Surveyor:	Abdullah Qasemzada
Date(s) of Original Survey:	June 20, 21, 22, 25, 26 & 27, 2007		

NOTES:

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes / Recommended Actions
0-000	Exterior	Roof	Roofing Material	Asbestos	Not Sampled	ACM Assumed	68,000 SF	Good	
0-000	Exterior	Roof	Caulking	Asbestos	A0001A-C*	None Detected	N/A	N/A	*From Pinchin File No. 239118.002 (2019)
0-000	Exterior	Roof	Paint	Lead	L0001	0.0076%	N/A	N/A	Silver paint on structural steel *From Pinchin File No. 239118.002
0-000	Exterior	Windows	Window Caulking	Asbestos	Not Sampled	ACM Assumed	All	Good	
0-000	Exterior	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
SOUTH BUILDING									
B-001	Corridor	Floor	Vinyl Floor Tile (VFT01)	Asbestos	12-4832-1 to 3	None Detected	N/A	N/A	VFT01, 12" x 12", Light Grey Mosaic
B-001	Corridor	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
B-001	Corridor	Walls	Plaster	N/A	N/A	N/A	N/A	N/A	
B-001	Corridor	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
B-001	Corridor	Ceiling	Not Found	N/A	N/A	N/A	N/A	N/A	
B-001	Corridor	Pipe	Uninsulated	N/A	N/A	N/A	N/A	N/A	
B-001	Corridor	Pipe	Fibreglass	N/A	N/A	N/A	N/A	N/A	
B-001	Corridor	Duct	Uninsulated	N/A	N/A	N/A	N/A	N/A	
B-002	Storage Cages	Floor	Vinyl Floor Tile (VFT04)	Asbestos	2017-A0001A-C	None Detected	N/A	N/A	VFT04, 12" x 12", Grey with White Streaks *Pinchin 2017 Survey
B-002	Storage Cages	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
B-002	Storage Cages	Ceiling	Not Found	N/A	N/A	N/A	N/A	N/A	
B-002	Storage Cages	Ceiling	Tectum	Asbestos	11850-A-01-11A* 11850-A-01-11B* 11850-A-01-11C*	None Detected	N/A	N/A	*From Building Environmental Audit, dated 2007
B-002	Storage Cages	Pipe	Uninsulated	N/A	N/A	N/A	N/A	N/A	
B-002	Storage Cages	Pipe	Fibreglass	N/A	N/A	N/A	N/A	N/A	
B-002	Storage Cages	Duct	Uninsulated	N/A	N/A	N/A	N/A	N/A	
B-002	Storage Cages	Mechanical	Fibreglass	N/A	N/A	N/A	N/A	N/A	Hot water tanks
B-003	Elevator Machine Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
B-003	Elevator Machine Room	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
B-003	Elevator Machine Room	Ceiling	Not Found	N/A	N/A	N/A	N/A	N/A	
B-003	Elevator Machine Room	Pipe	Uninsulated	N/A	N/A	N/A	N/A	N/A	
B-004	Cleaner Storage	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
B-004	Cleaner Storage	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
B-004	Cleaner Storage	Ceiling	Not Found	N/A	N/A	N/A	N/A	N/A	
B-004	Cleaner Storage	Pipe	Fibreglass	N/A	N/A	N/A	N/A	N/A	
B-004	Cleaner Storage	Pipe	Uninsulated	N/A	N/A	N/A	N/A	N/A	
B-004	Cleaner Storage	Duct	Fibreglass	N/A	N/A	N/A	N/A	N/A	
B-004	Cleaner Storage	Duct	Uninsulated	N/A	N/A	N/A	N/A	N/A	
B-005	Maintenance Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
B-005	Maintenance Office	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
B-005	Maintenance Office	Ceiling	Not Found	N/A	N/A	N/A	N/A	N/A	
B-005	Maintenance Office	Pipe	Uninsulated	N/A	N/A	N/A	N/A	N/A	
B-005	Maintenance Office	Pipe	Fibreglass	N/A	N/A	N/A	N/A	N/A	
B-005	Maintenance Office	Duct	Uninsulated	N/A	N/A	N/A	N/A	N/A	

APPENDIX I - ROOM-BY-ROOM INVENTORY SHEET

B-006	Electrical Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
B-006	Electrical Room	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
B-006	Electrical Room	Ceiling	Not Found	N/A	N/A	N/A	N/A	N/A	
B-006	Electrical Room	Pipe	Uninsulated	N/A	N/A	N/A	N/A	N/A	
B-007	Central Files Storage	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
B-007	Central Files Storage	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
B-007	Central Files Storage	Ceiling	Not Found	N/A	N/A	N/A	N/A	N/A	
B-007	Central Files Storage	Pipe	Fibreglass	N/A	N/A	N/A	N/A	N/A	
B-007	Central Files Storage	Duct	Fibreglass	N/A	N/A	N/A	N/A	N/A	
B-008	Weight Room	Floor	Rubber	N/A	N/A	N/A	N/A	N/A	
B-008	Weight Room	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
B-008	Weight Room	Ceiling	Acoustic Ceiling Tile (ACT01)	Asbestos	11850-A-01-19	None Detected	N/A	N/A	ACT01, 24" x 72", short random fissure and pinpoint (24" x 24" appearance)
B-008	Weight Room	Ceiling	Not Found	N/A	N/A	N/A	N/A	N/A	
B-008	Weight Room	Pipe	Uninsulated	N/A	N/A	N/A	N/A	N/A	
B-008	Weight Room	Pipe	Fibreglass	N/A	N/A	N/A	N/A	N/A	
B-008	Weight Room	Duct	Uninsulated	N/A	N/A	N/A	N/A	N/A	
B-009	Women's Changeroom	Floor	Vinyl Floor Tile (VFT02)	Asbestos	12-4832-10 to 12	None Detected	N/A	N/A	VFT02, 12" x 12", Grey Mosaic
B-009	Women's Changeroom	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
B-009	Women's Changeroom	Walls	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
B-009	Women's Changeroom	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
B-010	Men's Changeroom	Floor	Vinyl Floor Tile (VFT02)	Asbestos	12-4832-10 to 12	None Detected	N/A	N/A	VFT02, 12" x 12", Grey Mosaic
B-010	Men's Changeroom	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
B-010	Men's Changeroom	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
B-011	File Storage	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
B-011	File Storage	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
B-011	File Storage	Ceiling	Not Found	N/A	N/A	N/A	N/A	N/A	
B-011	File Storage	Pipe	Uninsulated	N/A	N/A	N/A	N/A	N/A	
B-011	File Storage	Pipe	Fibreglass	N/A	N/A	N/A	N/A	N/A	
B-012	Public Order Unit Room	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
B-012	Public Order Unit Room	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
B-012	Public Order Unit Room	Ceiling	Not Found	N/A	N/A	N/A	N/A	N/A	
B-012	Public Order Unit Room	Pipe	Uninsulated	N/A	N/A	N/A	N/A	N/A	
B-013	Document Storage	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
B-013	Document Storage	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
B-013	Document Storage	Ceiling	Not Found	N/A	N/A	N/A	N/A	N/A	
B-013	Document Storage	Pipe	Fibreglass	N/A	N/A	N/A	N/A	N/A	
B-013	Document Storage	Pipe	Uninsulated	N/A	N/A	N/A	N/A	N/A	
B-014	Boiler Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
B-014	Boiler Room	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
B-014	Boiler Room	Ceiling	Not Found	N/A	N/A	N/A	N/A	N/A	
B-014	Boiler Room	Pipe	Uninsulated	N/A	N/A	N/A	N/A	N/A	
B-014	Boiler Room	Pipe	Fibreglass	N/A	N/A	N/A	N/A	N/A	
B-014	Boiler Room	Duct	Uninsulated	N/A	N/A	N/A	N/A	N/A	
B-014	Boiler Room	Duct	Fibreglass	N/A	N/A	N/A	N/A	N/A	
B-014	Boiler Room	Mechanical	Uninsulated	N/A	N/A	N/A	N/A	N/A	Boiler
B-014	Boiler Room	Mechanical	Fibreglass	N/A	N/A	N/A	N/A	N/A	Hot water tanks
B-015	Women's Locker Room	Floor	Vinyl Floor Tile (VFT02)	Asbestos	12-4832-10 to 12	None Detected	N/A	N/A	VFT02, 12" x 12", Grey Mosaic

APPENDIX I - ROOM-BY-ROOM INVENTORY SHEET

B-015	Women's Locker Room	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
B-015	Women's Locker Room	Walls	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
B-015	Women's Locker Room	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
B-015	Women's Locker Room	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
B-016	Men's Locker Room	Floor	Vinyl Floor Tile (VFT02)	Asbestos	12-4832-10 to 12	None Detected	N/A	N/A	VFT02, 12" x 12", Grey Mosaic
B-016	Men's Locker Room	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
B-016	Men's Locker Room	Walls	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
B-016	Men's Locker Room	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
B-016	Men's Locker Room	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
B-017	Printing Shop	Floor	Vinyl Floor Tile (VFT01)	Asbestos	12-4832-1 to 3	None Detected	N/A	N/A	VFT01, 12" x 12", Light Grey Mosaic
B-017	Printing Shop	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
B-017	Printing Shop	Ceiling	Not Found	N/A	N/A	N/A	N/A	N/A	
B-017	Printing Shop	Pipe	Uninsulated	N/A	N/A	N/A	N/A	N/A	
B-017	Printing Shop	Duct	Uninsulated	N/A	N/A	N/A	N/A	N/A	
B-018	Housekeeping	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
B-018	Housekeeping	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
B-018	Housekeeping	Ceiling	Not Found	N/A	N/A	N/A	N/A	N/A	
B-018	Housekeeping	Pipe	Uninsulated	N/A	N/A	N/A	N/A	N/A	
B-018	Housekeeping	Pipe	Fibreglass	N/A	N/A	N/A	N/A	N/A	
WEST BUILDING									
1-001	Stores Supervisor Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
1-001	Stores Supervisor Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-001	Stores Supervisor Office	Ceiling	Acoustic Ceiling Tile (ACT02)	Asbestos	11850-A-01-12A*	None Detected	N/A	N/A	ACT02, 24" x 48", Plain White *From Building Environmental Audit, dated 2007
1-002	Stores General Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
1-002	Stores General Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-002	Stores General Office	Ceiling	Acoustic Ceiling Tile (ACT02)	Asbestos	11850-A-01-12	None Detected	N/A	N/A	ACT02, 24" x 48", Plain White
1-003	Women's Washroom	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
1-003	Women's Washroom	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-003	Women's Washroom	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-004	Stores Corridor/Stairwell	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
1-004	Stores Corridor/Stairwell	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-004	Stores Corridor/Stairwell	Ceiling	Acoustic Ceiling Tile (ACT02)	Asbestos	11850-A-01-12B*	None Detected	N/A	N/A	ACT02, 24" x 48", Plain White *From Building Environmental Audit, dated 2007
1-005	Men's Washroom	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
1-005	Men's Washroom	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-005	Men's Washroom	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-006	Stores Lunch Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
1-006	Stores Lunch Room	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-006	Stores Lunch Room	Ceiling	Acoustic Ceiling Tile (ACT02)	Asbestos	11850-A-01-12	None Detected	N/A	N/A	ACT02, 24" x 48", Plain White
1-007	Stores Warehouse	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
1-007	Stores Warehouse	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-007	Stores Warehouse	Ceiling	Not Found	N/A	N/A	N/A	N/A	N/A	Open to metal above
1-008	Stores Electrical Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
1-008	Stores Electrical Room	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
1-008	Stores Electrical Room	Ceiling	Not Found	N/A	N/A	N/A	N/A	N/A	
1-008	Stores Electrical Room	Pipe	Uninsulated	N/A	N/A	N/A	N/A	N/A	
1-008	Stores Electrical Room	Duct	Uninsulated	N/A	N/A	N/A	N/A	N/A	

APPENDIX I - ROOM-BY-ROOM INVENTORY SHEET

1-009	Stores Locker Room	Floor	Vinyl Floor Tile (VFT02)	Asbestos	12-4832-10 to 12	None Detected	N/A	N/A	VFT02, 12" x 12", Grey Mosaic
1-009	Stores Locker Room	Walls	Drywall Joint Compound (DJC)	Asbestos	12-4832-18*	None Detected	N/A	N/A	*Sampled during 2012 survey
1-009	Stores Locker Room	Walls	Concrete	N/A	N/A	N/A	N/A	N/A	
1-009	Stores Locker Room	Ceiling	Acoustic Ceiling Tile (ACT02)	Asbestos	11850-A-01-12C*	None Detected	N/A	N/A	ACT02, 24" x 48", Plain White *From Building Environmental Audit, dated 2007
1-010	Stores Storage Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
1-010	Stores Storage Room	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-010	Stores Storage Room	Ceiling	Not Found	N/A	N/A	N/A	N/A	N/A	Open to metal above
1-011	Stores Clothing Storage	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
1-011	Stores Clothing Storage	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
1-011	Stores Clothing Storage	Ceiling	Not Found	N/A	N/A	N/A	N/A	N/A	Open to metal above
1-011	Stores Clothing Storage	Pipe	Uninsulated	N/A	N/A	N/A	N/A	N/A	
1-011	Stores Clothing Storage	Pipe	Fibreglass	N/A	N/A	N/A	N/A	N/A	
1-011	Stores Clothing Storage	Duct	Uninsulated	N/A	N/A	N/A	N/A	N/A	
1-012	Stores Sprinkler Valve Room	Floor	Vinyl Floor Tile (VFT02)	Asbestos	12-4832-10 to 12	None Detected	N/A	N/A	VFT02, 12" x 12", Grey Mosaic
1-012	Stores Sprinkler Valve Room	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-012	Stores Sprinkler Valve Room	Walls	Concrete	N/A	N/A	N/A	N/A	N/A	
1-012	Stores Sprinkler Valve Room	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
1-013	Washroom	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
1-013	Washroom	Walls	Concrete	N/A	N/A	N/A	N/A	N/A	
1-013	Washroom	Ceiling	Drywall Joint Compound (DJC)	Not Sampled	None Detected	N/A	N/A	N/A	Based on extensive previous sampling
1-014	Stretcher Repair Area	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
1-014	Stretcher Repair Area	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
1-014	Stretcher Repair Area	Ceiling	Not Found	N/A	N/A	N/A	N/A	N/A	Open to metal above
1-014	Stretcher Repair Area	Pipe	Uninsulated	N/A	N/A	N/A	N/A	N/A	
1-014	Stretcher Repair Area	Pipe	Fibreglass	N/A	N/A	N/A	N/A	N/A	
1-014	Stretcher Repair Area	Duct	Uninsulated	N/A	N/A	N/A	N/A	N/A	
1-014	Stretcher Repair Area	Duct	Fibreglass	N/A	N/A	N/A	N/A	N/A	
1-015	Fleet Garage	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
1-015	Fleet Garage	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
1-015	Fleet Garage	Ceiling	Not Found	N/A	N/A	N/A	N/A	N/A	Open to metal above
1-015	Fleet Garage	Pipe	Uninsulated	N/A	N/A	N/A	N/A	N/A	
1-015	Fleet Garage	Pipe	Fibreglass	N/A	N/A	N/A	N/A	N/A	
1-015	Fleet Garage	Duct	Uninsulated	N/A	N/A	N/A	N/A	N/A	
1-016	Station Post 16	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
1-016	Station Post 16	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
1-016	Station Post 16	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-016	Station Post 16	Pipe	Uninsulated	N/A	N/A	N/A	N/A	N/A	
1-016	Station Post 16	Pipe	Fibreglass	N/A	N/A	N/A	N/A	N/A	
1-016	Station Post 16	Duct	Uninsulated	N/A	N/A	N/A	N/A	N/A	
1-017	Stairwell #8	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
1-017	Stairwell #8	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
1-017	Stairwell #8	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-017	Stairwell #8	Pipe	Uninsulated	N/A	N/A	N/A	N/A	N/A	
1-018	Oil Disposal Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
1-018	Oil Disposal Room	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
1-018	Oil Disposal Room	Ceiling	Not Found	N/A	N/A	N/A	N/A	N/A	Open to metal above

APPENDIX I - ROOM-BY-ROOM INVENTORY SHEET

1-020	Stores Storage Mezzanine	Floor	Vinyl Sheet Flooring (VSF01)	Asbestos	11850-A-01-09A* 11850-A-01-09B* 11850-A-01-09C*	None Detected	N/A	N/A	VSF01, Dark Blue *From Building Environmental Audit, dated 2007
1-020	Stores Storage Mezzanine	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-020	Stores Storage Mezzanine	Ceiling	Not Found	N/A	N/A	N/A	N/A	N/A	Open to metal above
1-021	Stores Storage	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
1-021	Stores Storage	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-021	Stores Storage	Ceiling	Acoustic Ceiling Tile (ACT03)	Asbestos	11850-A-01-16A*	None Detected	N/A	N/A	ACT03, 24" x 24", Wide Pinpoint *From Building Environmental Audit, dated 2007
1-022	Office	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
1-022	Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-022	Office	Ceiling	Acoustic Ceiling Tile (ACT03)	Asbestos	11850-A-01-16C*	None Detected	N/A	N/A	ACT03, 24" x 24", Wide Pinpoint *From Building Environmental Audit, dated 2007
1-023	Entrance	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
1-023	Entrance	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-023	Entrance	Ceiling	Acoustic Ceiling Tile (ACT03)	Asbestos	11850-A-01-16	None Detected	N/A	N/A	ACT03, 24" x 24", Wide Pinpoint
1-024	Change Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
1-024	Change Room	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-024	Change Room	Ceiling	Acoustic Ceiling Tile (ACT03)	Asbestos	11850-A-01-16B*	None Detected	N/A	N/A	ACT03, 24" x 24", Wide Pinpoint *From Building Environmental Audit, dated 2007
1-025	Garage Men's W/C	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
1-025	Garage Men's W/C	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
1-025	Garage Men's W/C	Ceiling	Not Found	N/A	N/A	N/A	N/A	N/A	Open to metal above
1-026	Storage	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
1-026	Storage	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
1-026	Storage	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-026	Storage	Pipe	Uninsulated	N/A	N/A	N/A	N/A	N/A	
1-026	Storage	Pipe	Fibreglass	N/A	N/A	N/A	N/A	N/A	
1-026	Storage	Duct	Uninsulated	N/A	N/A	N/A	N/A	N/A	
1-027	Storage	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
1-027	Storage	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
1-027	Storage	Ceiling	Not Found	N/A	N/A	N/A	N/A	N/A	Open to metal above
1-027	Storage	Pipe	Uninsulated	N/A	N/A	N/A	N/A	N/A	
1-027	Storage	Pipe	Fibreglass	N/A	N/A	N/A	N/A	N/A	
1-027	Storage	Duct	Uninsulated	N/A	N/A	N/A	N/A	N/A	
1-027	Storage	Duct	Fibreglass	N/A	N/A	N/A	N/A	N/A	
1-028	Vestibule	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
1-028	Vestibule	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
1-028	Vestibule	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-029	Stairwell #7	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
1-029	Stairwell #7	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
1-029	Stairwell #7	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
1-029	Stairwell #7	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-030	Tool Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
1-030	Tool Room	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
1-030	Tool Room	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-030	Tool Room	Duct	Uninsulated	N/A	N/A	N/A	N/A	N/A	
1-031	Tool Room	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
1-031	Tool Room	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
1-031	Tool Room	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling

APPENDIX I - ROOM-BY-ROOM INVENTORY SHEET

1-031	Tool Room	Pipe	Uninsulated	N/A	N/A	N/A	N/A	N/A	
1-031	Tool Room	Duct	Uninsulated	N/A	N/A	N/A	N/A	N/A	
1-032	Automotive Parts	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
1-032	Automotive Parts	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-032	Automotive Parts	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-032	Automotive Parts	Structure	Sprayed Fireproofing	Asbestos	2018-A0001A-C*	None Detected	N/A	N/A	*Pinchin 2018 Survey
1-032	Automotive Parts	Pipe	Transite Pipe	Asbestos	Not Sampled	ACM Assumed	All	N/A	NOT OBSERVED
1-033	Fleet Technician Office	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
1-033	Fleet Technician Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-033	Fleet Technician Office	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-033	Fleet Technician Office	Ceiling	Acoustic Ceiling Tile (ACT19)	Asbestos	Date code 05/14/13	None	N/A	N/A	ACT19, 24" x 48", Textured pinhole (date code: 05/14/13)
1-033	Fleet Technician Office	Structure	Sprayed Fireproofing	Asbestos	2018-A0001A-C	None Detected	N/A	N/A	*Pinchin 2018 Survey
1-033	Fleet Technician Office	Pipe	Uninsulated	N/A	N/A	N/A	N/A	N/A	
1-033	Fleet Technician Office	Duct	Uninsulated	N/A	N/A	N/A	N/A	N/A	
1-034	Corridor	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
1-034	Corridor	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
1-034	Corridor	Ceiling	Acoustic Ceiling Tile (ACT23)	Asbestos	Date code 07/27/12	None	N/A	N/A	ACT23, 24" x 48", white pinhole, lay-in
1-034	Corridor	Pipe	Uninsulated	N/A	N/A	N/A	N/A	N/A	
1-034	Corridor	Pipe	Fibreglass	N/A	N/A	N/A	N/A	N/A	
1-035	Fleet Operations Supervisor	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
1-035	Fleet Operations Supervisor	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
1-035	Fleet Operations Supervisor	Ceiling	Acoustic Ceiling Tile (ACT23)	Asbestos	Date code 07/27/12	None	N/A	N/A	ACT23, 24" x 48", white pinhole, lay-in
1-035	Fleet Operations Supervisor	Pipe	Uninsulated	N/A	N/A	N/A	N/A	N/A	
1-035	Fleet Operations Supervisor	Pipe	Fibreglass	N/A	N/A	N/A	N/A	N/A	
1-036	Drivers Training	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
1-036	Drivers Training	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
1-036	Drivers Training	Ceiling	Acoustic Ceiling Tile (ACT23)	Asbestos	Date code 07/27/12	None	N/A	N/A	ACT23, 24" x 48", white pinhole, lay-in
1-036	Drivers Training	Pipe	Uninsulated	N/A	N/A	N/A	N/A	N/A	
1-036	Drivers Training	Pipe	Fibreglass	N/A	N/A	N/A	N/A	N/A	
1-037	Closet	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
1-037	Closet	Walls	Concrete	N/A	N/A	N/A	N/A	N/A	
1-037	Closet	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-038	Vestibule	Floor	Metal	N/A	N/A	N/A	N/A	N/A	
1-038	Vestibule	Walls	Concrete	N/A	N/A	N/A	N/A	N/A	
1-038	Vestibule	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-039	Stairwell	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
1-039	Stairwell	Walls	Concrete	N/A	N/A	N/A	N/A	N/A	
1-039	Stairwell	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-040	Washroom	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
1-040	Washroom	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-040	Washroom	Ceiling	Acoustic Ceiling Tile (ACT06)	Asbestos	11850-A-01-14	None Detected	N/A	N/A	ACT06, 24" x 48", Short Random Fissure with Pinpoint Drop-Down
1-040	Washroom	Pipe	Uninsulated	N/A	N/A	N/A	N/A	N/A	
1-040	Washroom	Pipe	Fibreglass	N/A	N/A	N/A	N/A	N/A	
1-040	Washroom	Duct	Uninsulated	N/A	N/A	N/A	N/A	N/A	
1-041	Housekeeping	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
1-041	Housekeeping	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling

APPENDIX I - ROOM-BY-ROOM INVENTORY SHEET

1-041	Housekeeping	Ceiling	Not Found	N/A	N/A	N/A	N/A	N/A	Open to metal above
1-041	Housekeeping	Pipe	Uninsulated	N/A	N/A	N/A	N/A	N/A	
1-041	Housekeeping	Pipe	Fibreglass	N/A	N/A	N/A	N/A	N/A	
1-041	Housekeeping	Duct	Uninsulated	N/A	N/A	N/A	N/A	N/A	
CENTRE BUILDING									
1-042	Lunch Room	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
1-042	Lunch Room	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
1-042	Lunch Room	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-042	Lunch Room	Ceiling	Acoustic Ceiling Tile (ACT07)	Asbestos	11850-A-01-13	None Detected	N/A	N/A	ACT07, 24" x 48", Plain White Drop-Down
1-042	Lunch Room	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-042	Lunch Room	Structure	Sprayed Fireproofing	Asbestos	11850-A-01-01	None Detected	N/A	N/A	
1-043	Corridor	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
1-043	Corridor	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-043	Corridor	Ceiling	Acoustic Ceiling Tile (ACT07)	Asbestos	11850-A-01-13A*	None Detected	N/A	N/A	ACT07, 24" x 48", Plain White Drop-Down *From Building Environmental Audit, dated 2007
1-043	Corridor	Structure	Sprayed Fireproofing	Asbestos	11850-A-01-01G*	None Detected	N/A	N/A	*From Building Environmental Audit, dated 2007
1-044	Women's Washroom	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
1-044	Women's Washroom	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-044	Women's Washroom	Structure	Sprayed Fireproofing	Asbestos	11850-A-01-01	None Detected	N/A	N/A	*No Access above ceiling
1-045	Men's Washroom	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
1-045	Men's Washroom	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-045	Men's Washroom	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-046	Electrical Room	Floor	Vinyl Floor Tile (VFT02)	Asbestos	12-4832-10 to 12	None Detected	N/A	N/A	VFT02, 12" x 12", Grey Mosaic
1-046	Electrical Room	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-046	Electrical Room	Walls	Concrete	N/A	N/A	N/A	N/A	N/A	
1-046	Electrical Room	Ceiling	Not Found	N/A	N/A	N/A	N/A	N/A	
1-046	Electrical Room	Structure	Sprayed Fireproofing	Asbestos	11850-A-01-01E*	None Detected	N/A	N/A	*From Building Environmental Audit, dated 2007
1-046	Electrical Room	Pipe	Uninsulated	N/A	N/A	N/A	N/A	N/A	
1-046	Electrical Room	Duct	Uninsulated	N/A	N/A	N/A	N/A	N/A	
1-047	Lan Room	Floor	Vinyl Floor Tile (VFT02)	Asbestos	12-4832-10 to 12	None Detected	N/A	N/A	VFT02, 12" x 12", Grey Mosaic
1-047	Lan Room	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-047	Lan Room	Walls	Concrete	N/A	N/A	N/A	N/A	N/A	
1-047	Lan Room	Ceiling	Not Found	N/A	N/A	N/A	N/A	N/A	
1-047	Lan Room	Structure	Sprayed Fireproofing	Asbestos	11850-A-01-01D*	None Detected	N/A	N/A	*From Building Environmental Audit, dated 2007
1-048	Stairwell	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
1-048	Stairwell	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
1-048	Stairwell	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-049	Vestibule	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
1-049	Vestibule	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-049	Vestibule	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-050	Elevator Mechanical Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
1-050	Elevator Mechanical Room	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-050	Elevator Mechanical Room	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-050	Elevator Mechanical Room	Structure	Sprayed Fireproofing	Asbestos	11850-A-01-01	None Detected	N/A	N/A	
WEST BUILDING									
1-051	Storage	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
1-051	Storage	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	

APPENDIX I - ROOM-BY-ROOM INVENTORY SHEET

1-051	Storage	Ceiling	Acoustic Ceiling Tile (ACT19)	Asbestos	Date code 05/14/13	None	N/A	N/A	ACT19, 24" x 48", Textured pinhole (date code: 05/14/13)
1-051	Storage	Ceiling	Not Found	N/A	N/A	N/A	N/A	N/A	
1-051	Storage	Pipe	Uninsulated	N/A	N/A	N/A	N/A	N/A	
1-051	Storage	Duct	Uninsulated	N/A	N/A	N/A	N/A	N/A	
1-052	Communication Engineering Lab	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
1-052	Communication Engineering Lab	Walls	Concrete	N/A	N/A	N/A	N/A	N/A	
1-052	Communication Engineering Lab	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-052	Communication Engineering Lab	Pipe	Uninsulated	N/A	N/A	N/A	N/A	N/A	
1-052	Communication Engineering Lab	Duct	Uninsulated	N/A	N/A	N/A	N/A	N/A	
CENTRE BUILDING									
1-053	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
1-053	Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-053	Office	Ceiling	Acoustic Ceiling Tile (ACT07)	Asbestos	11850-A-01-13	None Detected	N/A	N/A	ACT07, 24" x 48", Plain White Drop-Down
1-053	Office	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-053	Office	Structure	Sprayed Fireproofing	Asbestos	11850-A-01-01	None Detected	N/A	N/A	
1-054	Electrical Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
1-054	Electrical Room	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-054	Electrical Room	Structure	Sprayed Fireproofing	Asbestos	11850-A-01-01	None Detected	N/A	N/A	
1-054	Electrical Room	Pipe	Uninsulated	N/A	N/A	N/A	N/A	N/A	
1-054	Electrical Room	Pipe	Fibreglass	N/A	N/A	N/A	N/A	N/A	
1-055	Closet	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
1-055	Closet	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-055	Closet	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-056	Corridor	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
1-056	Corridor	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-056	Corridor	Ceiling	Acoustic Ceiling Tile (ACT07)	Asbestos	11850-A-01-13	None Detected	N/A	N/A	ACT07, 24" x 48", Plain White Drop-Down
1-056	Corridor	Structure	Sprayed Fireproofing	Asbestos	11850-A-01-01	None Detected	N/A	N/A	
1-057	Electrical Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
1-057	Electrical Room	Walls	Paint	Lead	L0003	<0.0055%	N/A	N/A	Pale green paint on concrete block *From Pinchin File No. 239118.002
1-057	Electrical Room	Walls	Fire Stop	Asbestos	A0002A-C*	None Detected	N/A	N/A	*From Pinchin File No. 239118.002 (2019)
1-057	Electrical Room	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
1-057	Electrical Room	Ceiling	Not Found	N/A	N/A	N/A	N/A	N/A	Open to metal above
1-058	Stairwell	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
1-058	Stairwell	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
1-058	Stairwell	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-058	Stairwell	Pipe	Uninsulated	N/A	N/A	N/A	N/A	N/A	
1-059	General Offices	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
1-059	General Offices	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-059	General Offices	Ceiling	Acoustic Ceiling Tile (ACT07)	Asbestos	11850-A-01-13	None Detected	N/A	N/A	ACT07, 24" x 48", Plain White Drop-Down
1-059	General Offices	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-059	General Offices	Structure	Sprayed Fireproofing	Asbestos	11850-A-01-01C*	None Detected	N/A	N/A	*From Building Environmental Audit, dated 2007
1-060	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
1-060	Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-060	Office	Ceiling	Acoustic Ceiling Tile (ACT07)	Asbestos	11850-A-01-13	None Detected	N/A	N/A	ACT07, 24" x 48", Plain White Drop-Down
1-060	Office	Structure	Sprayed Fireproofing	Asbestos	11850-A-01-01	None Detected	N/A	N/A	
1-061	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
1-061	Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling

APPENDIX I - ROOM-BY-ROOM INVENTORY SHEET

1-061	Office	Ceiling	Acoustic Ceiling Tile (ACT07)	Asbestos	11850-A-01-13	None Detected	N/A	N/A	ACT07, 24" x 48", Plain White Drop-Down
1-061	Office	Structure	Sprayed Fireproofing	Asbestos	11850-A-01-01	None Detected	N/A	N/A	
1-062	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
1-062	Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-062	Office	Ceiling	Acoustic Ceiling Tile (ACT07)	Asbestos	11850-A-01-13	None Detected	N/A	N/A	ACT07, 24" x 48", Plain White Drop-Down
1-062	Office	Structure	Sprayed Fireproofing	Asbestos	11850-A-01-01	None Detected	N/A	N/A	
1-063	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
1-063	Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-063	Office	Ceiling	Acoustic Ceiling Tile (ACT07)	Asbestos	11850-A-01-13	None Detected	N/A	N/A	ACT07, 24" x 48", Plain White Drop-Down
1-063	Office	Structure	Acoustic Ceiling Tile (ACT07)	Asbestos	11850-A-01-01	None Detected	N/A	N/A	
1-064	Office	Floor	Acoustic Ceiling Tile (ACT07)	N/A	N/A	N/A	N/A	N/A	
1-064	Office	Walls	Acoustic Ceiling Tile (ACT07)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-064	Office	Ceiling	Acoustic Ceiling Tile (ACT07)	Asbestos	11850-A-01-13	None Detected	N/A	N/A	ACT07, 24" x 48", Plain White Drop-Down
1-064	Office	Structure	Sprayed Fireproofing	Asbestos	11850-A-01-01	None Detected	N/A	N/A	
1-065	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
1-065	Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-065	Office	Ceiling	Acoustic Ceiling Tile (ACT07)	Asbestos	11850-A-01-13	None Detected	N/A	N/A	ACT07, 24" x 48", Plain White Drop-Down
1-065	Office	Structure	Sprayed Fireproofing	Asbestos	11850-A-01-01	None Detected	N/A	N/A	
NORTH BUILDING									
1-066	Stairwell #5	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
1-066	Stairwell #5	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-066	Stairwell #5	Walls	Concrete	N/A	N/A	N/A	N/A	N/A	
1-066	Stairwell #5	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-067	Office	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
1-067	Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-067	Office	Walls	Concrete	N/A	N/A	N/A	N/A	N/A	
1-067	Office	Ceiling	Acoustic Ceiling Tile (ACT01)	Asbestos	11850-A-01-19	None Detected	N/A	N/A	ACT01, 24" x 72", short random fissure and pinpoint (24" x 24" appearance)
1-068	Corridor	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
1-068	Corridor	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-068	Corridor	Pipe	Transite Pipe	Asbestos	Not Sampled	ACM Assumed	100 LF	Good	
1-068	Corridor	Ceiling	Not Found	N/A	N/A	N/A	N/A	N/A	
1-068	Corridor	Pipe	Uninsulated	N/A	N/A	N/A	N/A	N/A	
1-068	Corridor	Pipe	Fibreglass	N/A	N/A	N/A	N/A	N/A	
1-068	Corridor	Duct	Fibreglass	N/A	N/A	N/A	N/A	N/A	
1-069	Audio Visual Room	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
1-069	Audio Visual Room	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-069	Audio Visual Room	Walls	Mastic**	Asbestos	11850-A-01-08A* 11850-A-01-08B* 11850-A-01-08C*	None Detected	N/A	N/A	**From Acoustic Wall Tiles *From Building Environmental Audit, dated 2007
1-069	Audio Visual Room	Ceiling	Acoustic Ceiling Tile (ACT02)	Asbestos	11850-A-01-12	None Detected	N/A	N/A	ACT02, 24" x 48", Plain White
1-069	Audio Visual Room	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-070	Secondary Electric Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
1-070	Secondary Electric Room	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-070	Secondary Electric Room	Walls	Concrete	N/A	N/A	N/A	N/A	N/A	
1-070	Secondary Electric Room	Ceiling	Not Found	N/A	N/A	N/A	N/A	N/A	Open to metal above
1-070	Secondary Electric Room	Pipe	Uninsulated	N/A	N/A	N/A	N/A	N/A	
1-071	Hydro Vault	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	No Access to Room
1-071	Hydro Vault	Walls	Block	N/A	N/A	N/A	N/A	N/A	No Access to Room

APPENDIX I - ROOM-BY-ROOM INVENTORY SHEET

1-071	Hydro Vault	Ceiling	Not Found	N/A	N/A	N/A	N/A	N/A	No Access to Room
1-072	General Offices	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
1-072	General Offices	Walls	Drywall Joint Compound (DJC)	Asbestos	12-4832-8*	None Detected	N/A	N/A	*Sampled during 2012 survey
1-072	General Offices	Ceiling	Acoustic Ceiling Tile (ACT08)	Asbestos	11850-A-01-20B*	None Detected	N/A	N/A	ACT08, 24" x 72", Wide Pinpoint (24" x 24" appearance) *From Building Environmental Audit, dated 2007
1-073	Corridor	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
1-073	Corridor	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-073	Corridor	Ceiling	Not Found	N/A	N/A	N/A	N/A	N/A	
1-073	Corridor	Pipe	Uninsulated	N/A	N/A	N/A	N/A	N/A	
1-073	Corridor	Duct	Fibreglass	N/A	N/A	N/A	N/A	N/A	
1-073	Corridor	Duct	Uninsulated	N/A	N/A	N/A	N/A	N/A	
1-074	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
1-074	Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-074	Office	Ceiling	Acoustic Ceiling Tile (ACT08)	Asbestos	11850-A-01-20	None Detected	N/A	N/A	ACT08, 24" x 72", Wide Pinpoint (24" x 24" appearance)
1-075	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
1-075	Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-075	Office	Ceiling	Acoustic Ceiling Tile (ACT08)	Asbestos	11850-A-01-20	None Detected	N/A	N/A	ACT08, 24" x 72", Wide Pinpoint (24" x 24" appearance)
1-076	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
1-076	Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-076	Office	Ceiling	Acoustic Ceiling Tile (ACT01)	Asbestos	11850-A-01-19A*	None Detected	N/A	N/A	ACT01, 24" x 72", short random fissure and pinpoint (24" x 24" appearance) *From Building Environmental Audit, dated 2007
1-076	Office	Ceiling	Acoustic Ceiling Tile (ACT08)	Asbestos	11850-A-01-20A* 11850-A-01-20C*	None Detected	N/A	N/A	ACT08, 24" x 72", Wide Pinpoint (24" x 24" appearance) *From Building Environmental Audit, dated 2007
1-077	Kitchen/Lunchroom	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
1-077	Kitchen/Lunchroom	Walls	Drywall Joint Compound (DJC)	Asbestos	12-4832-9*	None Detected	N/A	N/A	*Sampled during 2012 survey
1-077	Kitchen/Lunchroom	Ceiling	Acoustic Ceiling Tile (ACT08)	Asbestos	11850-A-01-20	None Detected	N/A	N/A	ACT08, 24" x 72", Wide Pinpoint (24" x 24" appearance)
1-078	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
1-078	Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-078	Office	Ceiling	Acoustic Ceiling Tile (ACT08)	Asbestos	11850-A-01-20	None Detected	N/A	N/A	ACT08, 24" x 72", Wide Pinpoint (24" x 24" appearance)
1-079	Kitchen	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
1-079	Kitchen	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-079	Kitchen	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-080	Electrical Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
1-080	Electrical Room	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-080	Electrical Room	Walls	Concrete	N/A	N/A	N/A	N/A	N/A	
1-080	Electrical Room	Ceiling	Not Found	N/A	N/A	N/A	N/A	N/A	Open to metal above
1-080	Electrical Room	Pipe	Uninsulated	N/A	N/A	N/A	N/A	N/A	
1-080	Electrical Room	Pipe	Fibreglass	N/A	N/A	N/A	N/A	N/A	
1-080	Electrical Room	Duct	Fibreglass	N/A	N/A	N/A	N/A	N/A	
1-081	Quiet Room	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
1-081	Quiet Room	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-081	Quiet Room	Ceiling	Acoustic Ceiling Tile (ACT07)	Asbestos	11850-A-01-13	None Detected	N/A	N/A	ACT07, 24" x 48", Plain White Drop-Down
1-082	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
1-082	Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-082	Office	Ceiling	Acoustic Ceiling Tile (ACT01)	Asbestos	11850-A-01-19	None Detected	N/A	N/A	ACT01, 24" x 72", short random fissure and pinpoint (24" x 24" appearance)
1-083	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
1-083	Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling

APPENDIX I - ROOM-BY-ROOM INVENTORY SHEET

1-083	Office	Ceiling	Acoustic Ceiling Tile (ACT01)	Asbestos	11850-A-01-19	None Detected	N/A	N/A	ACT01, 24" x 72", short random fissure and pinpoint (24" x 24" appearance)
1-084	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
1-084	Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-084	Office	Ceiling	Acoustic Ceiling Tile (ACT01)	Asbestos	11850-A-01-19	None Detected	N/A	N/A	ACT01, 24" x 72", short random fissure and pinpoint (24" x 24" appearance)
1-084	Office	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-085	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
1-085	Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-085	Office	Ceiling	Not Found	N/A	N/A	N/A	N/A	N/A	Open to metal above
1-085	Office	Pipe	Uninsulated	N/A	N/A	N/A	N/A	N/A	
1-085	Office	Pipe	Fibreglass	N/A	N/A	N/A	N/A	N/A	
1-085	Office	Duct	Fibreglass	N/A	N/A	N/A	N/A	N/A	
1-086	Corridor	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
1-086	Corridor	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-086	Corridor	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-086	Corridor	Ceiling	Not Found	N/A	N/A	N/A	N/A	N/A	
1-087	Multi-media Storage	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
1-087	Multi-media Storage	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-087	Multi-media Storage	Ceiling	Acoustic Ceiling Tile (ACT09)	Asbestos	11850-A-01-21C*	None Detected	N/A	N/A	ACT09, 24" x 72", Fissure Widthwise with Pinpoint *From Building Environmental Audit, dated 2007
1-088	Men's Washroom	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
1-088	Men's Washroom	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-088	Men's Washroom	Ceiling	Acoustic Ceiling Tile (ACT09)	Asbestos	11850-A-01-21B*	None Detected	N/A	N/A	ACT09, 24" x 72", Fissure Widthwise with Pinpoint *From Building Environmental Audit, dated 2007
1-089	Women's Washroom	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
1-089	Women's Washroom	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-089	Women's Washroom	Ceiling	Acoustic Ceiling Tile (ACT09)	Asbestos	11850-A-01-21A*	None Detected	N/A	N/A	ACT09, 24" x 72", Fissure Widthwise with Pinpoint *From Building Environmental Audit, dated 2007
1-090	Kitchen	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
1-090	Kitchen	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-090	Kitchen	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-090	Kitchen	Pipe	Uninsulated	N/A	N/A	N/A	N/A	N/A	
1-091	Classroom 1	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
1-091	Classroom 1	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-091	Classroom 1	Ceiling	Acoustic Ceiling Tile (ACT09)	Asbestos	11850-A-01-21	None Detected	N/A	N/A	ACT09, 24" x 72", Fissure Widthwise with Pinpoint
1-091	Classroom 1	Ceiling	Acoustic Ceiling Tile (ACT10)	Asbestos	S0001A-C*	None Detected	N/A	N/A	ACT10, 24" x 72", Sparse Fissure Widthwise with Pinpoint *From Pinchin File No. 239118.003 (2019)
1-092	Classroom 2	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
1-092	Classroom 2	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-092	Classroom 2	Ceiling	Acoustic Ceiling Tile (ACT09)	Asbestos	11850-A-01-21	None Detected	N/A	N/A	ACT09, 24" x 72", Fissure Widthwise with Pinpoint
1-092	Classroom 2	Ceiling	Acoustic Ceiling Tile (ACT10)	Asbestos	S0001A-C*	None Detected	N/A	N/A	ACT10, 24" x 72", Sparse Fissure Widthwise with Pinpoint *From Pinchin File No. 239118.003 (2019)
1-093	Storage	Floor	Vinyl Floor Tile (VFT01)	Asbestos	12-4832-1 to 3	None Detected	N/A	N/A	VFT01, 12" x 12", Light Grey Mosaic
1-093	Storage	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-093	Storage	Ceiling	Acoustic Ceiling Tile (ACT09)	Asbestos	11850-A-01-21	None Detected	N/A	N/A	ACT09, 24" x 72", Fissure Widthwise with Pinpoint
1-093	Storage	Pipe	Uninsulated	N/A	N/A	N/A	N/A	N/A	
1-093	Storage	Pipe	Fibreglass	N/A	N/A	N/A	N/A	N/A	
1-093	Storage	Duct	Uninsulated	N/A	N/A	N/A	N/A	N/A	
1-094	Stairwell #4	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	

APPENDIX I - ROOM-BY-ROOM INVENTORY SHEET

1-094	Stairwell #4	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-094	Stairwell #4	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-095	Corridor	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
1-095	Corridor	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-095	Corridor	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-096	Museum / Storage	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
1-096	Museum / Storage	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-096	Museum / Storage	Ceiling	Not Found	N/A	N/A	N/A	N/A	N/A	Open to metal above
1-097	Classroom 3	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
1-097	Classroom 3	Walls	Paint	Lead	L0001*	<0.0058%	N/A	N/A	Dark beige paint on drywall *From Pinchin File No. 239118.003 (2019)
1-097	Classroom 3	Walls	Paint	Lead	L0002*	<0.00061%	N/A	N/A	White paint on drywall bulkhead *From Pinchin File No. 239118.003 (2019)
1-097	Corridor	Walls	Paint	Lead	L0003*	<0.0055%	N/A	N/A	Beige paint on drywall *From Pinchin File No. 239118.003 (2019)
1-097	Classroom 3	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-097	Classroom 3	Ceiling	Acoustic Ceiling Tile (ACT09)	Asbestos	11850-A-01-21	None Detected	N/A	N/A	ACT09, 24" x 72", Fissure Widthwise with Pinpoint
1-097	Classroom 3	Ceiling	Acoustic Ceiling Tile (ACT10)	Asbestos	S0001A-C*	None Detected	N/A	N/A	ACT10, 24" x 72", Sparse Fissure Widthwise with Pinpoint *From Pinchin File No. 239118.003 (2019)
1-097	Classroom 3	Pipe	Uninsulated	N/A	N/A	N/A	N/A	N/A	
1-097	Classroom 3	Duct	Uninsulated	N/A	N/A	N/A	N/A	N/A	
1-098	Corridor	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
1-098	Corridor	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
1-098	Corridor	Ceiling	Acoustic Ceiling Tile (ACT01)	Asbestos	11850-A-01-19	None Detected	N/A	N/A	ACT01, 24" x 72", short random fissure and pinpoint (24" x 24" appearance)
1-098	Corridor	Pipe	Transite Pipe	Asbestos	Not Sampled	ACM Assumed	30 LF	Good	
1-098	Corridor	Pipe	Uninsulated	N/A	N/A	N/A	N/A	N/A	
1-098	Corridor	Duct	Uninsulated	N/A	N/A	N/A	N/A	N/A	
1-099	Garage	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	No Access to Room
1-099	Garage	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	No Access to Room Based on extensive previous sampling
1-099	Garage	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	No Access to Room Based on extensive previous sampling
1-099	Garage	Pipe	Transite Pipe	Asbestos	Not Sampled	ACM Assumed	20 LF	Unknown	No Access to Room
1-100	Bell Room	Floor	Vinyl Floor Tile (VFT03)	Asbestos	2018-A0002A-C*	None Detected	N/A	N/A	VFT03, 12" x 12", Rust Mosaic and mastic *Pinchin 2018 Survey
1-100	Bell Room	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-100	Bell Room	Walls	Concrete	N/A	N/A	N/A	N/A	N/A	
1-100	Bell Room	Ceiling	Not Found	N/A	N/A	N/A	N/A	N/A	
1-100	Bell Room	Pipe	Uninsulated	N/A	N/A	N/A	N/A	N/A	
1-100	Bell Room	Duct	Uninsulated	N/A	N/A	N/A	N/A	N/A	
1-100	Bell Room	Pipe	Fibreglass	N/A	N/A	N/A	N/A	N/A	
1-101	Corridor	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
1-101	Corridor	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-101	Corridor	Walls	Block	N/A	N/A	N/A	N/A	N/A	
1-101	Corridor	Ceiling	Acoustic Ceiling Tile (ACT09)	Asbestos	11850-A-01-21	None Detected	N/A	N/A	ACT09, 24" x 72", Fissure Widthwise with Pinpoint
1-102	Women's Locker Room	Floor	Vinyl Floor Tile (VFT01)	Asbestos	12-4832-1 to 3	None Detected	N/A	N/A	VFT01, 12" x 12", Light Grey Mosaic
1-102	Women's Locker Room	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
1-102	Women's Locker Room	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-102	Women's Locker Room	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-103	Men's Washroom	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
1-103	Men's Washroom	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-103	Men's Washroom	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-104	Housekeeping	Floor	Vinyl Floor Tile (VFT01)	Asbestos	12-4832-1 to 3	None Detected	N/A	N/A	VFT01, 12" x 12", Light Grey Mosaic

APPENDIX I - ROOM-BY-ROOM INVENTORY SHEET

1-104	Housekeeping	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-104	Housekeeping	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-104	Housekeeping	Pipe	Fibreglass	N/A	N/A	N/A	N/A	N/A	
1-104	Housekeeping	Pipe	Uninsulated	N/A	N/A	N/A	N/A	N/A	
1-105	Corridor	Floor	Vinyl Sheet Flooring (VSF02)	Asbestos	2018-A0003A-C*	None Detected	N/A	N/A	VSF02, Beige Mosaic *Pinchin 2018 Survey
1-105	Corridor	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-105	Corridor	Ceiling	Acoustic Ceiling Tile (ACT01)	Asbestos	11850-A-01-19	None Detected	N/A	N/A	ACT01, 24" x 72", short random fissure and pinpoint (24" x 24" appearance)
1-106	Mechanical Room	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
1-106	Mechanical Room	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-106	Mechanical Room	Ceiling	Not Found	N/A	N/A	N/A	N/A	N/A	Open to metal above
1-106	Mechanical Room	Pipe	Fibreglass	N/A	N/A	N/A	N/A	N/A	
1-106	Mechanical Room	Pipe	Uninsulated	N/A	N/A	N/A	N/A	N/A	
1-107	Server Room	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
1-107	Server Room	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-107	Server Room	Ceiling	Acoustic Ceiling Tile (ACT11)	Asbestos	11850-A-01-22	None Detected	N/A	N/A	ACT11, 24" x 72", Plain Textured Drop-Down
1-108	Office	Floor	Vinyl Sheet Flooring (VSF04)	Asbestos	Not Sampled	None Detected	200 SF	Unknown	Not Observed VSF04, 12" x 12", grey, white streaks.
1-108	Office	Floor	Raised Flooring	N/A	N/A	N/A	N/A	N/A	
1-108	Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-108	Office	Ceiling	Acoustic Ceiling Tile (ACT12)	Asbestos	11850-A-01-23B* 11850-A-01-23C*	None Detected	N/A	N/A	ACT12, 24" x 72", Plain Drop-Down (appearance as 24" x 24") *From Building Environmental Audit, dated 2007
1-109	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
1-109	Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-109	Office	Ceiling	Acoustic Ceiling Tile (ACT08)	Asbestos	11850-A-01-20	None Detected	N/A	N/A	ACT08, 24" x 72", Wide Pinpoint (24" x 24" appearance)
1-109	Office	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-110	Meeting Room	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
1-110	Meeting Room	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-110	Meeting Room	Ceiling	Acoustic Ceiling Tile (ACT08)	Asbestos	11850-A-01-20	None Detected	N/A	N/A	ACT08, 24" x 72", Wide Pinpoint (24" x 24" appearance)
1-111	Lunch/Break Room	Floor	Vinyl Sheet Flooring (VSF02)	Asbestos	2018-A0003A-C	None Detected	N/A	N/A	VSF02, Beige Mosaic *Pinchin 2018 Survey
1-111	Lunch/Break Room	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-111	Lunch/Break Room	Ceiling	Acoustic Ceiling Tile (ACT01)	Asbestos	11850-A-01-19	None Detected	N/A	N/A	ACT01, 24" x 72", short random fissure and pinpoint (24" x 24" appearance)
1-111	Lunch/Break Room	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-112	Men's Locker Room	Floor	Vinyl Floor Tile (VFT01)	Asbestos	12-4832-1 to 3	None Detected	N/A	N/A	VFT01, 12" x 12", Light Grey Mosaic
1-112	Men's Locker Room	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
1-112	Men's Locker Room	Walls	Drywall Joint Compound (DJC)	Asbestos	12-4832-7*	None Detected	N/A	N/A	*Sampled during 2012 survey
1-112	Men's Locker Room	Ceiling	Acoustic Ceiling Tile (ACT01)	Asbestos	11850-A-01-19	None Detected	N/A	N/A	ACT01, 24" x 72", short random fissure and pinpoint (24" x 24" appearance)
1-112	Men's Locker Room	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-113	Sprinkler & Pump Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	No Access to Room
1-113	Sprinkler & Pump Room	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	No Access to Room Based on extensive previous sampling
1-113	Sprinkler & Pump Room	Ceiling	Not Found	N/A	N/A	N/A	N/A	N/A	No Access to Room Open to metal above
1-114	Training Room	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
1-114	Training Room	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-114	Training Room	Ceiling	Acoustic Ceiling Tile (ACT12)	Asbestos	11850-A-01-23	None Detected	N/A	N/A	ACT12, 24" x 72", Plain Drop-Down (24" x 24" appearance)
1-115	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
1-115	Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-115	Office	Ceiling	Acoustic Ceiling Tile (ACT12)	Asbestos	11850-A-01-23	None Detected	N/A	N/A	ACT12, 24" x 72", Plain Drop-Down (24" x 24" appearance)
1-116	Corridor	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
1-116	Corridor	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling

APPENDIX I - ROOM-BY-ROOM INVENTORY SHEET

1-116	Corridor	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-119	Communications Center	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
1-119	Communications Center	Walls	Drywall Joint Compound (DJC)	Asbestos	13-6484-04 to 09*	None Detected	N/A	N/A	*From Fisher Project No.13-6592, dated July 2013
1-119	Communications Center	Ceiling	Acoustic Ceiling Tile (ACT12)	Asbestos	11850-A-01-23	None Detected	N/A	N/A	ACT12, 24" x 72", Plain Drop-Down (24" x 24" appearance)
1-120	Vehicle Bays 1-4	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	No Access to Room
1-120	Vehicle Bays 1-4	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	No Access to Room Based on extensive previous sampling
1-120	Vehicle Bays 1-4	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	No Access to Room Based on extensive previous sampling
1-120	Vehicle Bays 1-4	Pipe	Parging Cement	Asbestos	11850-A-01-04	None Detected	N/A	N/A	No Access to Room
1-120	Vehicle Bays 1-4	Pipe	Transite Pipe	Asbestos	Not Sampled	ACM Assumed	45 LF	Unknown	No Access to Room
1-121	Vehicle Bays 5-10	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	No Access to Room
1-121	Vehicle Bays 5-10	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	No Access to Room Based on extensive previous sampling
1-121	Vehicle Bays 5-10	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	No Access to Room Based on extensive previous sampling
1-121	Vehicle Bays 5-10	Pipe	Parging Cement	Asbestos	11850-A-01-04	None Detected	N/A	N/A	No Access to Room
1-121	Vehicle Bays 5-10	Pipe	Transite Pipe	Asbestos	Not Sampled	ACM Assumed	45 LF	Unknown	No Access to Room
SOUTH BUILDING									
1-122	Stairwell #2	Floor	Vinyl Floor Tile (VFT01)	Asbestos	12-4832-1 to 3	None Detected	N/A	N/A	VFT01, 12" x 12", Light Grey Mosaic Present on Basement Landing
1-122	Stairwell #2	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
1-122	Stairwell #2	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
1-122	Stairwell #2	Walls	Plaster	N/A	N/A	N/A	N/A	N/A	
1-122	Stairwell #2	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-122	Stairwell #2	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A	
1-122	Stairwell #2	Pipe	Uninsulated	N/A	N/A	N/A	N/A	N/A	*No Access to Room above ceiling
1-123	Stairwell #1	Floor	Vinyl Floor Tile (VFT01)	Asbestos	12-4832-1 to 3	None Detected	N/A	N/A	VFT01, 12" x 12", Light Grey Mosaic Present on Basement Landing
1-123	Stairwell #1	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
1-123	Stairwell #1	Walls	Plaster	N/A	N/A	N/A	N/A	N/A	
1-123	Stairwell #1	Walls	Concrete	N/A	N/A	N/A	N/A	N/A	
1-123	Stairwell #1	Ceiling	Not Found	N/A	N/A	N/A	N/A	N/A	Open to metal above
1-123	Stairwell #1	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A	
1-124	Main Foyer	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
1-124	Main Foyer	Walls	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
1-124	Main Foyer	Walls	Plaster	N/A	N/A	N/A	N/A	N/A	
1-124	Main Foyer	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-124	Main Foyer	Ceiling	Drywall Joint Compound (DJC)	Asbestos	12-4788-1* 12-4788-2* 12-4788-3*	None Detected	N/A	N/A	*Sampled during 2012 survey
1-124	Main Foyer	Ceiling	Not Found	N/A	N/A	N/A	N/A	N/A	Open to Above
1-125	Vestibule	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
1-125	Vestibule	Walls	Metal	N/A	N/A	N/A	N/A	N/A	
1-125	Vestibule	Ceiling	Not Found	N/A	N/A	N/A	N/A	N/A	Open to metal above
1-125	Vestibule	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-126	Vending Machine Area	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
1-126	Vending Machine Area	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-126	Vending Machine Area	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-127	Storage	Floor	Vinyl Floor Tile (VFT02)	Asbestos	12-4832-10 to 12	None Detected	N/A	N/A	VFT02, 12" x 12", Grey Mosaic
1-127	Storage	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-127	Storage	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-128	Housekeeping	Floor	Vinyl Floor Tile (VFT02)	Asbestos	12-4832-10 to 12	None Detected	N/A	N/A	VFT02, 12" x 12", Grey Mosaic

APPENDIX I - ROOM-BY-ROOM INVENTORY SHEET

1-128	Housekeeping	Walls	Drywall Joint Compound (DJC)	Asbestos	10-1303-1* 10-1303-2* 10-1303-3*	None Detected	N/A	N/A	*From 2010 Annual Designated Substances Reassessment Survey
1-128	Housekeeping	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-129	Corridor	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
1-129	Corridor	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-129	Corridor	Ceiling	Acoustic Ceiling Tile (ACT01)	Asbestos	11850-A-01-19	None Detected	N/A	N/A	ACT01, 24" x 72", short random fissure and pinpoint (24" x 24" appearance)
1-129	Corridor	Pipe	Uninsulated	N/A	N/A	N/A	N/A	N/A	
1-129	Corridor	Pipe	Fibreglass	N/A	N/A	N/A	N/A	N/A	
1-129	Corridor	Duct	Uninsulated	N/A	N/A	N/A	N/A	N/A	
1-129	Corridor	Duct	Fibreglass	N/A	N/A	N/A	N/A	N/A	
1-130	Kitchen	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
1-130	Kitchen	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-130	Kitchen	Walls	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
1-130	Kitchen	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-131	Electrical Room	Floor	Vinyl Floor Tile (VFT01)	Asbestos	12-4832-1 to 3	None Detected	N/A	N/A	VFT01, 12" x 12", Light Grey Mosaic
1-131	Electrical Room	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
1-131	Electrical Room	Walls	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
1-131	Electrical Room	Ceiling	Not Found	N/A	N/A	N/A	N/A	N/A	
1-131	Electrical Room	Duct	Uninsulated	N/A	N/A	N/A	N/A	N/A	
1-132	General Offices	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
1-132	General Offices	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-132	General Offices	Ceiling	Acoustic Ceiling Tile (ACT01)	Asbestos	11850-A-01-19	None Detected	N/A	N/A	ACT01, 24" x 72", short random fissure and pinpoint (24" x 24" appearance)
1-132	General Offices	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-132	General Offices	Pipe	Uninsulated	N/A	N/A	N/A	N/A	N/A	
1-132	General Offices	Pipe	Fibreglass	N/A	N/A	N/A	N/A	N/A	
1-132	General Offices	Duct	Uninsulated	N/A	N/A	N/A	N/A	N/A	
1-132	General Offices	Duct	Fibreglass	N/A	N/A	N/A	N/A	N/A	
1-133	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
1-133	Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-133	Office	Ceiling	Acoustic Ceiling Tile (ACT01)	Asbestos	11850-A-01-19	None Detected	N/A	N/A	ACT01, 24" x 72", short random fissure and pinpoint (24" x 24" appearance)
1-133	Office	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-133	Office	Pipe	Uninsulated	N/A	N/A	N/A	N/A	N/A	
1-133	Office	Pipe	Fibreglass	N/A	N/A	N/A	N/A	N/A	
1-133	Office	Duct	Uninsulated	N/A	N/A	N/A	N/A	N/A	
1-133	Office	Duct	Fibreglass	N/A	N/A	N/A	N/A	N/A	
1-134	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
1-134	Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-134	Office	Ceiling	Acoustic Ceiling Tile (ACT01)	Asbestos	11850-A-01-19	None Detected	N/A	N/A	ACT01, 24" x 72", short random fissure and pinpoint (24" x 24" appearance)
1-134	Office	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-134	Office	Pipe	Uninsulated	N/A	N/A	N/A	N/A	N/A	
1-134	Office	Pipe	Fibreglass	N/A	N/A	N/A	N/A	N/A	
1-134	Office	Duct	Uninsulated	N/A	N/A	N/A	N/A	N/A	
1-134	Office	Duct	Fibreglass	N/A	N/A	N/A	N/A	N/A	
1-135	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
1-135	Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-135	Office	Ceiling	Acoustic Ceiling Tile (ACT01)	Asbestos	11850-A-01-19	None Detected	N/A	N/A	ACT01, 24" x 72", short random fissure and pinpoint (24" x 24" appearance)
1-136	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	

APPENDIX I - ROOM-BY-ROOM INVENTORY SHEET

1-136	Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-136	Office	Ceiling	Acoustic Ceiling Tile (ACT01)	Asbestos	11850-A-01-19	None Detected	N/A	N/A	ACT01, 24" x 72", short random fissure and pinpoint (24" x 24" appearance)
1-136	Office	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-137	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
1-137	Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-137	Office	Ceiling	Acoustic Ceiling Tile (ACT01)	Asbestos	11850-A-01-19	None Detected	N/A	N/A	ACT01, 24" x 72", short random fissure and pinpoint (24" x 24" appearance)
1-137	Office	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-137	Office	Pipe	Uninsulated	N/A	N/A	N/A	N/A	N/A	
1-137	Office	Pipe	Fibreglass	N/A	N/A	N/A	N/A	N/A	
1-137	Office	Duct	Uninsulated	N/A	N/A	N/A	N/A	N/A	
1-137	Office	Duct	Fibreglass	N/A	N/A	N/A	N/A	N/A	
1-138	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
1-138	Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-138	Office	Ceiling	Acoustic Ceiling Tile (ACT01)	Asbestos	11850-A-01-19	None Detected	N/A	N/A	ACT01, 24" x 72", short random fissure and pinpoint (24" x 24" appearance)
1-138	Office	Pipe	Uninsulated	N/A	N/A	N/A	N/A	N/A	
1-138	Office	Pipe	Fibreglass	N/A	N/A	N/A	N/A	N/A	
1-138	Office	Duct	Uninsulated	N/A	N/A	N/A	N/A	N/A	
1-138	Office	Duct	Fibreglass	N/A	N/A	N/A	N/A	N/A	
1-139	Office	Floor	Ceramic Tile	Asbestos	2019-A0003A-C*	None Detected	N/A	N/A	*From Pinchin File No. 239118.001 (2019)
1-139	Office	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
1-139	Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-139	Office	Ceiling	Acoustic Ceiling Tile (ACT01)	Asbestos	11850-A-01-19	None Detected	N/A	N/A	ACT01, 24" x 72", short random fissure and pinpoint (24" x 24" appearance)
1-139	Office	Walls	Fire Stop	Asbestos	2019-A0001A-C*	None Detected	N/A	N/A	*From Pinchin File No. 239118.000 (2019)
1-139	Office	Pipe	Uninsulated	N/A	N/A	N/A	N/A	N/A	
1-139	Office	Pipe	Fibreglass	N/A	N/A	N/A	N/A	N/A	
1-139	Office	Duct	Uninsulated	N/A	N/A	N/A	N/A	N/A	
1-139	Office	Duct	Fibreglass	N/A	N/A	N/A	N/A	N/A	
1-140	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
1-140	Office	Floor	Mastic	Asbestos	2019-A0002A-C*	N/A	N/A	N/A	*From Pinchin File No. 239118.001 (2019)
1-140	Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-140	Office	Ceiling	Acoustic Ceiling Tile (ACT01)	Asbestos	11850-A-01-19	None Detected	N/A	N/A	ACT01, 24" x 72", short random fissure and pinpoint (24" x 24" appearance)
1-141	Office	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
1-141	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
1-141	Office	Walls	Paint	Lead	2019-L0005	<0.0074	N/A	N/A	Beige paint on drywall *From Pinchin File No. 239118.001
1-141	Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-141	Office	Ceiling	Acoustic Ceiling Tile (ACT01)	Asbestos	11850-A-01-19	None Detected	N/A	N/A	ACT01, 24" x 72", short random fissure and pinpoint (24" x 24" appearance)
1-141	Office	Ceiling	Acoustic Ceiling Tile (ACT22)	Asbestos	Date Code 2019	N/A	N/A	N/A	ACT22, 24" x 48", pinhole and random fissure (Date Code: 2019)
1-142	LAN Room	Floor	Vinyl Floor Tile (VFT01)	Asbestos	12-4832-1 to 3	None Detected	N/A	N/A	VFT01, 12" x 12", Light Grey Mosaic
1-142	LAN Room	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
1-142	LAN Room	Ceiling	Not Found	N/A	N/A	N/A	N/A	N/A	
1-143	Women's Washroom	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
1-143	Women's Washroom	Walls	Concrete	N/A	N/A	N/A	N/A	N/A	
1-143	Women's Washroom	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-144	Men's Washroom	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
1-144	Men's Washroom	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
1-144	Men's Washroom	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-145	Shower Room	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	

APPENDIX I - ROOM-BY-ROOM INVENTORY SHEET

1-145	Shower Room	Walls	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
1-145	Shower Room	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-146	Housekeeping	Floor	Vinyl Floor Tile (VFT02)	Asbestos	12-4832-10 to 12	None Detected	N/A	N/A	VFT02, 12" x 12", Grey Mosaic
1-146	Housekeeping	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
1-146	Housekeeping	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-146	Housekeeping	Pipe	Uninsulated	N/A	N/A	N/A	N/A	N/A	
1-146	Housekeeping	Pipe	Fibreglass	N/A	N/A	N/A	N/A	N/A	
1-147	Corridor	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
1-147	Corridor	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
1-147	Corridor	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-147	Corridor	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-148	Corridor	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
1-148	Corridor	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-148	Corridor	Ceiling	Acoustic Ceiling Tile (ACT20)	Asbestos	Date Code 08/20/16	N/A	N/A	N/A	ACT20, 24" x 48", random fissure and pinhole (Date Code: 08/20/16)
1-148	Corridor	Pipe	Uninsulated	N/A	N/A	N/A	N/A	N/A	
1-148	Corridor	Pipe	Fibreglass	N/A	N/A	N/A	N/A	N/A	
1-148	Corridor	Duct	Uninsulated	N/A	N/A	N/A	N/A	N/A	
1-149	Kitchen	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
1-149	Kitchen	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-149	Kitchen	Walls	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
1-149	Kitchen	Ceiling	Acoustic Ceiling Tile (ACT20)	Asbestos	Date Code 08/20/16	N/A	N/A	N/A	ACT20, 24" x 48", random fissure and pinhole (Date Code: 08/20/16)
1-149	Kitchen	Pipe	Uninsulated	N/A	N/A	N/A	N/A	N/A	
1-149	Kitchen	Duct	Uninsulated	N/A	N/A	N/A	N/A	N/A	
1-150	Office	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
1-150	Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-150	Office	Ceiling	Acoustic Ceiling Tile (ACT20)	Asbestos	Date Code 08/20/16	N/A	N/A	N/A	ACT20, 24" x 48", random fissure and pinhole (Date Code: 08/20/16)
1-150	Office	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-150	Office	Pipe	Uninsulated	N/A	N/A	N/A	N/A	N/A	
1-150	Office	Duct	Fibreglass	N/A	N/A	N/A	N/A	N/A	
1-151	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
1-151	Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-151	Office	Walls	Paint	Lead	L0004*	<0.0066%	N/A	N/A	Beige paint on drywall *From Pinchin File No. 239118.003 (2019)
1-151	Office	Walls	Paint	Lead	L0005*	<0.0035%	N/A	N/A	White paint on drywall *From Pinchin File No. 239118.003 (2019)
1-151	Office	Walls	Paint	Lead	L0006*	<0.0079%	N/A	N/A	Grey paint on wood door *From Pinchin File No. 239118.003 (2019)
1-151	Office	Ceiling	Acoustic Ceiling Tile (ACT20)	Asbestos	Date Code 08/20/16	N/A	N/A	N/A	ACT20, 24" x 48", random fissure and pinhole (Date Code: 08/20/16)
1-151	Office	Pipe	Uninsulated	N/A	N/A	N/A	N/A	N/A	
1-151	Office	Pipe	Fibreglass	N/A	N/A	N/A	N/A	N/A	
1-152	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
1-152	Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-152	Office	Ceiling	Acoustic Ceiling Tile (ACT20)	Asbestos	Date Code 08/20/16	N/A	N/A	N/A	ACT20, 24" x 48", random fissure and pinhole (Date Code: 08/20/16)
1-153	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
1-153	Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-153	Office	Ceiling	Acoustic Ceiling Tile (ACT20)	Asbestos	Date Code 08/20/16	N/A	N/A	N/A	ACT20, 24" x 48", random fissure and pinhole (Date Code: 08/20/16)
1-153	Office	Pipe	Uninsulated	N/A	N/A	N/A	N/A	N/A	
1-153	Office	Pipe	Fibreglass	N/A	N/A	N/A	N/A	N/A	
1-154	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
1-154	Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling

APPENDIX I - ROOM-BY-ROOM INVENTORY SHEET

1-154	Office	Ceiling	Acoustic Ceiling Tile (ACT20)	Asbestos	Date Code 08/20/16	N/A	N/A	N/A	ACT20, 24" x 48", random fissure and pinhole (Date Code: 08/20/16)
1-155	Office	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
1-155	Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-155	Office	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-155	Office	Ceiling	Acoustic Ceiling Tile (ACT20)	Asbestos	Date Code 08/20/16	N/A	N/A	N/A	ACT20, 24" x 48", random fissure and pinhole (Date Code: 08/20/16)
1-156	First Aid Room	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
1-156	First Aid Room	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-156	First Aid Room	Ceiling	Acoustic Ceiling Tile (ACT20)	Asbestos	Date Code 08/20/16	N/A	N/A	N/A	ACT20, 24" x 48", random fissure and pinhole (Date Code: 08/20/16)
1-156	First Aid Room	Pipe	Uninsulated	N/A	N/A	N/A	N/A	N/A	
1-156	First Aid Room	Pipe	Fibreglass	N/A	N/A	N/A	N/A	N/A	
1-157	Server Room	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
1-157	Server Room	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-157	Server Room	Ceiling	Acoustic Ceiling Tile (ACT20)	Asbestos	Date Code 08/20/16	N/A	N/A	N/A	ACT20, 24" x 48", random fissure and pinhole (Date Code: 08/20/16)
1-158	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
1-158	Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-158	Office	Ceiling	Acoustic Ceiling Tile (ACT20)	Asbestos	Date Code 08/20/16	N/A	N/A	N/A	ACT20, 24" x 48", random fissure and pinhole (Date Code: 08/20/16)
1-158	Office	Pipe	Uninsulated	N/A	N/A	N/A	N/A	N/A	
1-158	Office	Pipe	Fibreglass	N/A	N/A	N/A	N/A	N/A	
1-159	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
1-159	Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-159	Office	Ceiling	Acoustic Ceiling Tile (ACT20)	Asbestos	Date Code 08/20/16	N/A	N/A	N/A	ACT20, 24" x 48", random fissure and pinhole (Date Code: 08/20/16)
1-159	Office	Pipe	Uninsulated	N/A	N/A	N/A	N/A	N/A	
1-159	Office	Pipe	Fibreglass	N/A	N/A	N/A	N/A	N/A	
1-160	Storage	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
1-160	Storage	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-160	Storage	Ceiling	Acoustic Ceiling Tile (ACT20)	Asbestos	Date Code 08/20/16	N/A	N/A	N/A	ACT20, 24" x 48", random fissure and pinhole (Date Code: 08/20/16)
1-160	Storage	Pipe	Uninsulated	N/A	N/A	N/A	N/A	N/A	
1-160	Storage	Pipe	Fibreglass	N/A	N/A	N/A	N/A	N/A	
CENTRE BUILDING									
1-161	IT Storage	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
1-161	IT Storage	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-161	IT Storage	Ceiling	Acoustic Ceiling Tile (ACT07)	Asbestos	11850-A-01-13	None Detected	N/A	N/A	ACT07, 24" x 48", Plain White Drop-Down
1-161	IT Storage	Structure	Sprayed Fireproofing	Asbestos	11850-A-01-01	None Detected	N/A	N/A	
1-162	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
1-162	Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-162	Office	Ceiling	Acoustic Ceiling Tile (ACT07)	Asbestos	11850-A-01-13	None Detected	N/A	N/A	ACT07, 24" x 48", Plain White Drop-Down
1-162	Office	Structure	Sprayed Fireproofing	Asbestos	11850-A-01-01	None Detected	N/A	N/A	
1-163	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
1-163	Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-163	Office	Ceiling	Acoustic Ceiling Tile (ACT07)	Asbestos	11850-A-01-13	None Detected	N/A	N/A	ACT07, 24" x 48", Plain White Drop-Down
1-163	Office	Structure	Sprayed Fireproofing	Asbestos	11850-A-01-01	None Detected	N/A	N/A	
WEST BUILDING									
1-164	Storage	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
1-164	Storage	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
1-164	Storage	Ceiling	Not Found	N/A	N/A	N/A	N/A	N/A	Open to metal above
1-165	Bay	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
1-165	Bay	Walls	Block	N/A	N/A	N/A	N/A	N/A	

APPENDIX I - ROOM-BY-ROOM INVENTORY SHEET

1-165	Bay	Ceiling	Not Found	N/A	N/A	N/A	N/A	N/A	Open to metal above
WEST BUILDING									
2-001	Vestibule	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
2-001	Vestibule	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-001	Vestibule	Ceiling	Acoustic Ceiling Tile (ACT06)	Asbestos	11850-A-01-14	None Detected	N/A	N/A	ACT06, 24" x 48", Short Random Fissure with Pinpoint Drop-Down
2-002	Kitchen/Lounge	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
2-002	Kitchen/Lounge	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-002	Kitchen/Lounge	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-003	Women's Washroom	Floor	Vinyl Floor Tile (VFT01)	Asbestos	12-4832-1 to 3	None Detected	N/A	N/A	VFT01, 12" x 12", Light Grey Mosaic
2-003	Women's Washroom	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-003	Women's Washroom	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-004	Men's Washroom	Floor	Vinyl Floor Tile (VFT01)	Asbestos	12-4832-1 to 3	None Detected	N/A	N/A	VFT01, 12" x 12", Light Grey Mosaic
2-004	Men's Washroom	Walls	Drywall Joint Compound (DJC)	Asbestos	12-4832-17*	None Detected	N/A	N/A	*Sampled during 2012 survey
2-004	Men's Washroom	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-005	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
2-005	Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-005	Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-006	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
2-006	Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-006	Office	Ceiling	Acoustic Ceiling Tile (ACT06)	Asbestos	11850-A-01-14B*	None Detected	N/A	N/A	ACT06, 24" x 48", Short Random Fissure with Pinpoint Drop-Down *From Building Environmental Audit, dated 2007
2-007	Storage	Floor	Vinyl Floor Tile (VFT01)	Asbestos	12-4832-1 to 3	None Detected	N/A	N/A	VFT01, 12" x 12", Light Grey Mosaic
2-007	Storage	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-007	Storage	Ceiling	Acoustic Ceiling Tile (ACT13)	Asbestos	11850-A-01-15A* 11850-A-01-15B* 11850-A-01-15C*	None Detected	N/A	N/A	ACT13, 24" x 48", Short Random Fissure with Pinpoint *From Building Environmental Audit, dated 2007
2-007	Storage	Pipe	Uninsulated	N/A	N/A	N/A	N/A	N/A	
2-007	Storage	Pipe	Fibreglass	N/A	N/A	N/A	N/A	N/A	
2-007	Storage	Duct	Uninsulated	N/A	N/A	N/A	N/A	N/A	
2-008	Housekeeping	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
2-008	Housekeeping	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-008	Housekeeping	Ceiling	Not Found	N/A	N/A	N/A	N/A	N/A	Open to metal above
2-008	Housekeeping	Pipe	Fibreglass	N/A	N/A	N/A	N/A	N/A	
2-008	Housekeeping	Pipe	Uninsulated	N/A	N/A	N/A	N/A	N/A	
2-009	Lunch/Break Room	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
2-009	Lunch/Break Room	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-009	Lunch/Break Room	Walls	Concrete	N/A	N/A	N/A	N/A	N/A	
2-009	Lunch/Break Room	Ceiling	Not Found	N/A	N/A	N/A	N/A	N/A	Open to metal above
2-010	Housekeeping	Floor	Vinyl Floor Tile (VFT01)	Asbestos	12-4832-1 to 3	None Detected	N/A	N/A	VFT01, 12" x 12", Light Grey Mosaic
2-010	Housekeeping	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-010	Housekeeping	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-010	Housekeeping	Pipe	Fibreglass	N/A	N/A	N/A	N/A	N/A	
2-010	Housekeeping	Pipe	Uninsulated	N/A	N/A	N/A	N/A	N/A	
2-011	Women's Washroom	Floor	Vinyl Floor Tile (VFT01)	Asbestos	12-4832-1 to 3	None Detected	N/A	N/A	VFT01, 12" x 12", Light Grey Mosaic
2-011	Women's Washroom	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-011	Women's Washroom	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-012	Men's Washroom	Floor	Vinyl Floor Tile (VFT01)	Asbestos	12-4832-1 to 3	None Detected	N/A	N/A	VFT01, 12" x 12", Light Grey Mosaic
2-012	Men's Washroom	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling

APPENDIX I - ROOM-BY-ROOM INVENTORY SHEET

2-012	Men's Washroom	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-013	Corridor	Floor	Vinyl Floor Tile (VFT01)	Asbestos	12-4832-1 to 3	None Detected	N/A	N/A	VFT01, 12" x 12", Light Grey Mosaic
2-013	Corridor	Floor	Vinyl Sheet Flooring (VSF03)	Asbestos	11850-A-01-10A* 11850-A-01-10B* 11850-A-01-10C*	None Detected	N/A	N/A	VSF03, Grey with Black Fleck *From Building Environmental Audit, dated 2007
2-013	Corridor	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-013	Corridor	Ceiling	Acoustic Ceiling Tile (ACT02)	Asbestos	11850-A-01-12	None Detected	N/A	N/A	ACT02, 24" x 48", Plain White
2-013	Corridor	Other	Fire Stop	Asbestos	11850-A-01-07A* 11850-A-01-07B* 11850-A-01-07C*	None Detected	N/A	N/A	White *From Building Environmental Audit, dated 2007
2-014	Mechanical Room	Floor	Vinyl Floor Tile (VFT01)	Asbestos	12-4832-1 to 3	None Detected	N/A	N/A	VFT01, 12" x 12", Light Grey Mosaic
2-014	Mechanical Room	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-014	Mechanical Room	Ceiling	Not Found	N/A	N/A	N/A	N/A	N/A	Open to metal above
2-014	Mechanical Room	Pipe	Uninsulated	N/A	N/A	N/A	N/A	N/A	
2-014	Mechanical Room	Pipe	Fibreglass	N/A	N/A	N/A	N/A	N/A	
2-014	Mechanical Room	Duct	Uninsulated	N/A	N/A	N/A	N/A	N/A	
2-014	Mechanical Room	Duct	Fibreglass	N/A	N/A	N/A	N/A	N/A	
2-015	General Offices	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
2-015	General Offices	Walls	Drywall Joint Compound (DJC)	Asbestos	12-4832-16*	None Detected	N/A	N/A	*Sampled during 2012 survey
2-015	General Offices	Walls	Concrete	N/A	N/A	N/A	N/A	N/A	
2-015	General Offices	Ceiling	Acoustic Ceiling Tile (ACT06)	Asbestos	11850-A-01-14	None Detected	N/A	N/A	ACT06, 24" x 48", Short Random Fissure with Pinpoint Drop-Down
2-016	Washroom	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
2-016	Washroom	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-016	Washroom	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-017	Manager Fleet Operation	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
2-017	Manager Fleet Operation	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-017	Manager Fleet Operation	Ceiling	Acoustic Ceiling Tile (ACT06)	Asbestos	11850-A-01-14	None Detected	N/A	N/A	ACT06, 24" x 48", Short Random Fissure with Pinpoint Drop-Down
2-018	Friendship Fund Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
2-018	Friendship Fund Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-018	Friendship Fund Office	Ceiling	Acoustic Ceiling Tile (ACT06)	Asbestos	11850-A-01-14A*	None Detected	N/A	N/A	ACT06, 24" x 48", Short Random Fissure with Pinpoint Drop-Down *From Building Environmental Audit, dated 2007
2-019	Storage	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
2-019	Storage	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-019	Storage	Ceiling	Not Found	N/A	N/A	N/A	N/A	N/A	Open to metal above
2-020	Corridor	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
2-020	Corridor	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-020	Corridor	Ceiling	Not Found	N/A	N/A	N/A	N/A	N/A	Open to metal above
2-021	Washroom	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
2-021	Washroom	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-021	Washroom	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-022	Corridor	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
2-022	Corridor	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-022	Corridor	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-023	Kitchen	Floor	Vinyl Floor Tile (VFT02)	Asbestos	12-4832-10 to 12	None Detected	N/A	N/A	VFT02, 12" x 12", Grey Mosaic
2-023	Kitchen	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-023	Kitchen	Ceiling	Not Found	N/A	N/A	N/A	N/A	N/A	Open to metal above
2-023	Kitchen	Pipe	Fibreglass	N/A	N/A	N/A	N/A	N/A	
2-023	Kitchen	Pipe	Uninsulated	N/A	N/A	N/A	N/A	N/A	
CENTRE BUILDING									
2-024	Corridor	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	

APPENDIX I - ROOM-BY-ROOM INVENTORY SHEET

2-024	Corridor	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-024	Corridor	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-024	Corridor	Structure	Sprayed Fireproofing	Asbestos	11850-A-01-01	None Detected	N/A	N/A	
2-025	Men's Washroom	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
2-025	Men's Washroom	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-025	Men's Washroom	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-025	Men's Washroom	Structure	Sprayed Fireproofing	Asbestos	11850-A-01-01B*	None Detected	N/A	N/A	*From Building Environmental Audit, dated 2007
2-026	Women's Washroom	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
2-026	Women's Washroom	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-026	Women's Washroom	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-026	Women's Washroom	Structure	Sprayed Fireproofing	Asbestos	11850-A-01-01	None Detected	N/A	N/A	
2-027	Server Room	Floor	Vinyl Floor Tile (VFT02)	Asbestos	12-4832-10* 12-4832-11* 12-4832-12*	None Detected	N/A	N/A	VFT02, 12" x 12", Grey Mosaic *Sampled during 2012 survey
2-027	Server Room	Walls	Drywall Joint Compound (DJC)	Asbestos	12-4832-15*	None Detected	N/A	N/A	*Sampled during 2012 survey
2-027	Server Room	Walls	Paint	Lead	L0002	<0.0058%	N/A	N/A	Off-white paint on drywall *From Pinchin File No. 239118.002
2-027	Server Room	Ceiling	Acoustic Ceiling Tile (ACT07)	Asbestos	11850-A-01-13	None Detected	N/A	N/A	ACT07, 24" x 48", Plain White Drop-Down
2-027	Server Room	Structure	Sprayed Fireproofing	Asbestos	11850-A-01-01	None Detected	N/A	N/A	
2-027	Server Room	Pipe	Uninsulated	N/A	N/A	N/A	N/A	N/A	
2-027	Server Room	Duct	Fibreglass	N/A	N/A	N/A	N/A	N/A	
2-027	Server Room	Duct	Uninsulated	N/A	N/A	N/A	N/A	N/A	
2-028	Corridor	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
2-028	Corridor	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-028	Corridor	Ceiling	Acoustic Ceiling Tile (ACT07)	Asbestos	11850-A-01-13B*	None Detected	N/A	N/A	ACT07, 24" x 48", Plain White Drop-Down *From Building Environmental Audit, dated 2007
2-028	Corridor	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-028	Corridor	Structure	Sprayed Fireproofing	Asbestos	11850-A-01-01	None Detected	N/A	N/A	
2-029	Electrical Room	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
2-029	Electrical Room	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-029	Electrical Room	Walls	Concrete	N/A	N/A	N/A	N/A	N/A	
2-029	Electrical Room	Structure	Sprayed Fireproofing	Asbestos	11850-A-01-01	None Detected	N/A	N/A	
2-029	Electrical Room	Pipe	Uninsulated	N/A	N/A	N/A	N/A	N/A	
2-029	Electrical Room	Duct	Uninsulated	N/A	N/A	N/A	N/A	N/A	
2-030	LAN Room	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
2-030	LAN Room	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-030	LAN Room	Walls	Concrete	N/A	N/A	N/A	N/A	N/A	
2-030	LAN Room	Structure	Sprayed Fireproofing	Asbestos	11850-A-01-01	None Detected	N/A	N/A	
2-030	LAN Room	Pipe	Uninsulated	N/A	N/A	N/A	N/A	N/A	
2-030	LAN Room	Duct	Uninsulated	N/A	N/A	N/A	N/A	N/A	
2-031	Police Communications	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
2-031	Police Communications	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-031	Police Communications	Ceiling	Acoustic Ceiling Tile (ACT07)	Asbestos	11850-A-01-13	None Detected	N/A	N/A	ACT07, 24" x 48", Plain White Drop-Down
2-031	Police Communications	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-031	Police Communications	Structure	Sprayed Fireproofing	Asbestos	11850-A-01-01	None Detected	N/A	N/A	
2-032	Sprinkler Room	Floor	Vinyl Floor Tile (VFT02)	Asbestos	12-4832-10 to 12	None Detected	N/A	N/A	VFT02, 12" x 12", Grey Mosaic
2-032	Sprinkler Room	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-032	Sprinkler Room	Structure	Sprayed Fireproofing	Asbestos	11850-A-01-01	None Detected	N/A	N/A	
2-032	Sprinkler Room	Ceiling	Not Found	N/A	N/A	N/A	N/A	N/A	

APPENDIX I - ROOM-BY-ROOM INVENTORY SHEET

2-032	Sprinkler Room	Pipe	Uninsulated	N/A	N/A	N/A	N/A	N/A	
2-032	Sprinkler Room	Pipe	Fibreglass	N/A	N/A	N/A	N/A	N/A	
2-032	Sprinkler Room	Duct	Uninsulated	N/A	N/A	N/A	N/A	N/A	
2-033	Vestibule	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
2-033	Vestibule	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-033	Vestibule	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-033	Vestibule	Pipe	Uninsulated	N/A	N/A	N/A	N/A	N/A	
2-033	Vestibule	Pipe	Fibreglass	N/A	N/A	N/A	N/A	N/A	
NORTH BUILDING									
2-036	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
2-036	Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-036	Office	Ceiling	Acoustic Ceiling Tile (ACT06)	Asbestos	11850-A-01-14	None Detected	N/A	N/A	ACT06, 24" x 48", Short Random Fissure with Pinpoint Drop-Down
2-036	Office	Pipe	Transite Pipe	Asbestos	Not Sampled	ACM Assumed	16 LF	Good	
2-037	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
2-037	Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-037	Office	Ceiling	Acoustic Ceiling Tile (ACT)	N/A	N/A	N/A	N/A	N/A	
2-037	Office	Pipe	Transite Pipe	Asbestos	Not Sampled	ACM Assumed	8 LF	Good	
2-039	Women's Washroom	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
2-039	Women's Washroom	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-039	Women's Washroom	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-040	Men's Washroom	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
2-040	Men's Washroom	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-040	Men's Washroom	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-041	Storage	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
2-041	Storage	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-041	Storage	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-042	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
2-042	Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-042	Office	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-043	Women's Locker Room	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
2-043	Women's Locker Room	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-043	Women's Locker Room	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-044	Men's Locker Room	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
2-044	Men's Locker Room	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-044	Men's Locker Room	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-045	Corridor	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
2-045	Corridor	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-045	Corridor	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-046	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
2-046	Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-046	Office	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-047	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
2-047	Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-047	Office	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-048	Corridor	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
2-048	Corridor	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-048	Corridor	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling

APPENDIX I - ROOM-BY-ROOM INVENTORY SHEET

2-049	Washroom	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
2-049	Washroom	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-049	Washroom	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-050	Kitchen	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
2-050	Kitchen	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-050	Kitchen	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-051	Housekeeping	Floor	Vinyl Floor Tile (VFT02)	Asbestos	12-4832-10 to 12	None Detected	N/A	N/A	VFT02, 12" x 12", Grey Mosaic
2-051	Housekeeping	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-051	Housekeeping	Walls	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
2-051	Housekeeping	Walls	Concrete	N/A	N/A	N/A	N/A	N/A	
2-051	Housekeeping	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-051	Housekeeping	Pipe	Uninsulated	N/A	N/A	N/A	N/A	N/A	
2-051	Housekeeping	Pipe	Fibreglass	N/A	N/A	N/A	N/A	N/A	
2-052	Washroom	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
2-052	Washroom	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-052	Washroom	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-053	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
2-053	Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-053	Office	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-054	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
2-054	Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-054	Office	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-055	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
2-055	Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-055	Office	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-056	Accounting	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
2-056	Accounting	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-056	Accounting	Ceiling	Acoustic Ceiling Tile (ACT06)	Asbestos	11850-A-01-14	None Detected	N/A	N/A	ACT06, 24" x 48", Short Random Fissure with Pinpoint Drop-Down
2-057	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
2-057	Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-057	Office	Ceiling	Acoustic Ceiling Tile (ACT06)	Asbestos	11850-A-01-14	None Detected	N/A	N/A	ACT06, 24" x 48", Short Random Fissure with Pinpoint Drop-Down
2-058	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
2-058	Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-058	Office	Ceiling	Acoustic Ceiling Tile (ACT06)	Asbestos	11850-A-01-14	None Detected	N/A	N/A	ACT06, 24" x 48", Short Random Fissure with Pinpoint Drop-Down
2-059	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
2-059	Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-059	Office	Ceiling	Acoustic Ceiling Tile (ACT06)	Asbestos	11850-A-01-14	None Detected	N/A	N/A	ACT06, 24" x 48", Short Random Fissure with Pinpoint Drop-Down
2-060	Closet	Floor	Vinyl Floor Tile (VFT02)	Asbestos	12-4832-10 to 12	None Detected	N/A	N/A	VFT02, 12" x 12", Grey Mosaic
2-060	Closet	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-060	Closet	Ceiling	Acoustic Ceiling Tile (ACT06)	Asbestos	11850-A-01-14	None Detected	N/A	N/A	ACT06, 24" x 48", Short Random Fissure with Pinpoint Drop-Down
2-061	Professional Standards	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
2-061	Professional Standards	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-061	Professional Standards	Ceiling	Acoustic Ceiling Tile (ACT06)	Asbestos	11850-A-01-14	None Detected	N/A	N/A	ACT06, 24" x 48", Short Random Fissure with Pinpoint Drop-Down
2-062	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
2-062	Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-062	Office	Ceiling	Acoustic Ceiling Tile (ACT06)	Asbestos	11850-A-01-14	None Detected	N/A	N/A	ACT06, 24" x 48", Short Random Fissure with Pinpoint Drop-Down
2-063	Internal Relation	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	

APPENDIX I - ROOM-BY-ROOM INVENTORY SHEET

2-063	Internal Relation	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-063	Internal Relation	Ceiling	Acoustic Ceiling Tile (ACT06)	Asbestos	11850-A-01-14	None Detected	N/A	N/A	ACT06, 24" x 48", Short Random Fissure with Pinpoint Drop-Down
2-064	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
2-064	Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-064	Office	Ceiling	Acoustic Ceiling Tile (ACT06)	Asbestos	11850-A-01-14	None Detected	N/A	N/A	ACT06, 24" x 48", Short Random Fissure with Pinpoint Drop-Down
2-065	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
2-065	Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-065	Office	Ceiling	Acoustic Ceiling Tile (ACT06)	Asbestos	11850-A-01-14	None Detected	N/A	N/A	ACT06, 24" x 48", Short Random Fissure with Pinpoint Drop-Down
2-066	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
2-066	Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-066	Office	Ceiling	Acoustic Ceiling Tile (ACT06)	Asbestos	11850-A-01-14	None Detected	N/A	N/A	ACT06, 24" x 48", Short Random Fissure with Pinpoint Drop-Down
2-067	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
2-067	Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-067	Office	Ceiling	Acoustic Ceiling Tile (ACT06)	Asbestos	11850-A-01-14	None Detected	N/A	N/A	ACT06, 24" x 48", Short Random Fissure with Pinpoint Drop-Down
2-068	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
2-068	Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-068	Office	Ceiling	Acoustic Ceiling Tile (ACT06)	Asbestos	11850-A-01-14	None Detected	N/A	N/A	ACT06, 24" x 48", Short Random Fissure with Pinpoint Drop-Down
2-069	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
2-069	Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-069	Office	Ceiling	Acoustic Ceiling Tile (ACT06)	Asbestos	11850-A-01-14	None Detected	N/A	N/A	ACT06, 24" x 48", Short Random Fissure with Pinpoint Drop-Down
2-070	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
2-070	Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-070	Office	Ceiling	Acoustic Ceiling Tile (ACT06)	Asbestos	11850-A-01-14	None Detected	N/A	N/A	ACT06, 24" x 48", Short Random Fissure with Pinpoint Drop-Down
2-071	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
2-071	Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-071	Office	Ceiling	Acoustic Ceiling Tile (ACT06)	Asbestos	11850-A-01-14	None Detected	N/A	N/A	ACT06, 24" x 48", Short Random Fissure with Pinpoint Drop-Down
2-072	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
2-072	Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-072	Office	Ceiling	Acoustic Ceiling Tile (ACT06)	Asbestos	11850-A-01-14	None Detected	N/A	N/A	ACT06, 24" x 48", Short Random Fissure with Pinpoint Drop-Down
2-073	Education & Development	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
2-073	Education & Development	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-073	Education & Development	Ceiling	Acoustic Ceiling Tile (ACT06)	Asbestos	11850-A-01-14	None Detected	N/A	N/A	ACT06, 24" x 48", Short Random Fissure with Pinpoint Drop-Down
2-074	Meeting Room	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
2-074	Meeting Room	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-074	Meeting Room	Ceiling	Acoustic Ceiling Tile (ACT06)	Asbestos	11850-A-01-14	None Detected	N/A	N/A	ACT06, 24" x 48", Short Random Fissure with Pinpoint Drop-Down
2-075	Copy Room	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
2-075	Copy Room	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-075	Copy Room	Ceiling	Acoustic Ceiling Tile (ACT06)	Asbestos	11850-A-01-14	None Detected	N/A	N/A	ACT06, 24" x 48", Short Random Fissure with Pinpoint Drop-Down
2-076	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
2-076	Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-076	Office	Ceiling	Acoustic Ceiling Tile (ACT06)	Asbestos	11850-A-01-14	None Detected	N/A	N/A	ACT06, 24" x 48", Short Random Fissure with Pinpoint Drop-Down
2-077	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
2-077	Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-077	Office	Ceiling	Acoustic Ceiling Tile (ACT06)	Asbestos	11850-A-01-14	None Detected	N/A	N/A	ACT06, 24" x 48", Short Random Fissure with Pinpoint Drop-Down
2-078	Corridor	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
2-078	Corridor	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-078	Corridor	Ceiling	Acoustic Ceiling Tile (ACT22)	Asbestos	Date code: 2019	None	N/A	N/A	ACT22, 24" x 48", pinhole and random fissure (Date Code: 2019)

APPENDIX I - ROOM-BY-ROOM INVENTORY SHEET

2-079	General Offices	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
2-079	General Offices	Walls	Drywall Joint Compound (DJC)	Asbestos	13-7419-01 to 03*	None Detected	N/A	N/A	*From Fisher Project No.13-6761, dated December 2013
2-079	General Offices	Ceiling	Acoustic Ceiling Tile (ACT06)	Asbestos	11850-A-01-14	None Detected	N/A	N/A	ACT06, 24" x 48", Short Random Fissure with Pinpoint Drop-Down
2-080	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
2-080	Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-080	Office	Ceiling	Acoustic Ceiling Tile (ACT22)	Asbestos	Date code: 2019	None	N/A	N/A	ACT22, 24" x 48", pinhole and random fissure (Date Code: 2019)
2-081	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
2-081	Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-081	Office	Ceiling	Acoustic Ceiling Tile (ACT22)	Asbestos	Date code: 2019	None	N/A	N/A	ACT22, 24" x 48", pinhole and random fissure (Date Code: 2019)
2-082	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
2-082	Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-082	Office	Ceiling	Acoustic Ceiling Tile (ACT22)	Asbestos	Date code: 2019	None	N/A	N/A	ACT22, 24" x 48", pinhole and random fissure (Date Code: 2019)
2-083	General Offices	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
2-083	General Offices	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-083	General Offices	Ceiling	Acoustic Ceiling Tile (ACT22)	Asbestos	Date code: 2019	None	N/A	N/A	ACT22, 24" x 48", pinhole and random fissure (Date Code: 2019)
2-83	General Offices	Ceiling	Acoustic Ceiling Tile (ACT05)	Asbestos	11850-A-01-18A* 11850-A-01-18B* 11850-A-01-18C*	None Detected	N/A	N/A	ACT05, 24" x 48", Short Uniform Fissure *From Building Environmental Audit, dated 2007
2-083	General Offices	Pipe	Transite Pipe	Asbestos	Not Sampled	ACM Assumed	30 LF	Good	
2-084	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
2-084	Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-084	Office	Ceiling	Acoustic Ceiling Tile (ACT22)	Asbestos	Date code: 2019	None	N/A	N/A	ACT22, 24" x 48", pinhole and random fissure (Date Code: 2019)
2-085	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
2-085	Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-085	Office	Ceiling	Acoustic Ceiling Tile (ACT22)	Asbestos	Date code: 2019	None	N/A	N/A	ACT22, 24" x 48", pinhole and random fissure (Date Code: 2019)
2-086	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
2-086	Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-086	Office	Ceiling	Acoustic Ceiling Tile (ACT22)	Asbestos	Date code: 2019	None	N/A	N/A	ACT22, 24" x 48", pinhole and random fissure (Date Code: 2019)
2-087	Office	Floor	Acoustic Ceiling Tile (ACT22)	N/A	N/A	N/A	N/A	N/A	
2-087	Office	Walls	Acoustic Ceiling Tile (ACT22)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-087	Office	Ceiling	Acoustic Ceiling Tile (ACT22)	Asbestos	Date code: 2019	None	N/A	N/A	ACT22, 24" x 48", pinhole and random fissure (Date Code: 2019)
2-088	Office	Floor	Acoustic Ceiling Tile (ACT22)	N/A	N/A	N/A	N/A	N/A	
2-088	Office	Walls	Acoustic Ceiling Tile (ACT22)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-088	Office	Ceiling	Acoustic Ceiling Tile (ACT22)	Asbestos	Date code: 2019	None	N/A	N/A	ACT22, 24" x 48", pinhole and random fissure (Date Code: 2019)
2-088	Office	Pipe	Transite Pipe	Asbestos	Not Sampled	ACM Assumed	12 LF	Good	
2-089	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
2-089	Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-089	Office	Ceiling	Acoustic Ceiling Tile (ACT22)	Asbestos	Date code: 2019	None	N/A	N/A	ACT22, 24" x 48", pinhole and random fissure (Date Code: 2019)
2-089	Office	Pipe	Transite Pipe	Asbestos	Not Sampled	ACM Assumed	12 LF	Good	
2-090	General Offices	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
2-090	General Offices	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-090	General Offices	Ceiling	Acoustic Ceiling Tile (ACT22)	Asbestos	Date code: 2019	None	N/A	N/A	ACT22, 24" x 48", pinhole and random fissure (Date Code: 2019)
2-090	General Offices	Pipe	Transite Pipe	Asbestos	Not Sampled	ACM Assumed	80 LF	Good	
2-091	Kitchen	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
2-091	Kitchen	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-091	Kitchen	Ceiling	Acoustic Ceiling Tile (ACT22)	Asbestos	Date code: 2019	None	N/A	N/A	ACT22, 24" x 48", pinhole and random fissure (Date Code: 2019)
2-091	Kitchen	Pipe	Transite Pipe	Asbestos	Not Sampled	ACM Assumed	10 LF	Good	
2-092	Washroom	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	

APPENDIX I - ROOM-BY-ROOM INVENTORY SHEET

2-092	Washroom	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-092	Washroom	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-092	Washroom	Pipe	Transite Pipe	Asbestos	Not Sampled	ACM Assumed	6 LF	Good	
2-093	Washroom	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
2-093	Washroom	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
2-093	Washroom	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-093	Washroom	Pipe	Transite Pipe	Asbestos	Not Sampled	ACM Assumed	10 LF	Good	
2-094	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
2-094	Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-094	Office	Ceiling	Acoustic Ceiling Tile (ACT22)	Asbestos	Date code: 2019	None	N/A	N/A	ACT22, 24" x 48", pinhole and random fissure (Date Code: 2019)
2-094	Office	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-095	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
2-095	Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-095	Office	Ceiling	Acoustic Ceiling Tile (ACT22)	Asbestos	Date code: 2019	None	N/A	N/A	ACT22, 24" x 48", pinhole and random fissure (Date Code: 2019)
2-096	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
2-096	Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-096	Office	Ceiling	Acoustic Ceiling Tile (ACT22)	Asbestos	Date code: 2019	None	N/A	N/A	ACT22, 24" x 48", pinhole and random fissure (Date Code: 2019)
2-097	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
2-097	Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-097	Office	Ceiling	Acoustic Ceiling Tile (ACT22)	Asbestos	Date code: 2019	None	N/A	N/A	ACT22, 24" x 48", pinhole and random fissure (Date Code: 2019)
2-098	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
2-098	Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-098	Office	Ceiling	Acoustic Ceiling Tile (ACT22)	Asbestos	Date code: 2019	None	N/A	N/A	ACT22, 24" x 48", pinhole and random fissure (Date Code: 2019)
2-099	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
2-099	Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-099	Office	Ceiling	Acoustic Ceiling Tile (ACT22)	Asbestos	Date code: 2019	None	N/A	N/A	ACT22, 24" x 48", pinhole and random fissure (Date Code: 2019)
2-100	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
2-100	Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-100	Office	Ceiling	Acoustic Ceiling Tile (ACT22)	Asbestos	Date code: 2019	None	N/A	N/A	ACT22, 24" x 48", pinhole and random fissure (Date Code: 2019)
2-101	Boardroom	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
2-101	Boardroom	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-101	Boardroom	Ceiling	Acoustic Ceiling Tile (ACT22)	Asbestos	Date code: 2019	None	N/A	N/A	ACT22, 24" x 48", pinhole and random fissure (Date Code: 2019)
2-102	Stairwell #3	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
2-102	Stairwell #3	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
2-102	Stairwell #3	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-102	Stairwell #3	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-103	Corridor	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
2-103	Corridor	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
2-103	Corridor	Ceiling	Not Found	N/A	N/A	N/A	N/A	N/A	Open to metal above
2-104	Main Switch Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	No access to room
2-104	Main Switch Room	Walls	Concrete	N/A	N/A	N/A	N/A	N/A	No access to room
2-104	Main Switch Room	Ceiling	Not Found	N/A	N/A	N/A	N/A	N/A	No access to room Open to metal above
2-104	Main Switch Room	Pipe	Parging Cement	Asbestos	11850-A-01-02A* 11850-A-01-02B* 11850-A-01-02C*	None Detected	N/A	N/A	No access to room White from Generator *From Building Environmental Audit, dated 2007
2-104	Main Switch Room	Pipe	Parging Cement	Asbestos	11850-A-01-03C*	None Detected	N/A	N/A	No access to room Beige from fitting - powder like *From Building Environmental Audit, dated 2007
2-106	UPS Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	No access to room

APPENDIX I - ROOM-BY-ROOM INVENTORY SHEET

2-106	UPS Room	Walls	Drywall Joint Compound (DJC)	Asbestos	13-6484-01 to 09	None Detected	N/A	N/A	No access to room *From Fisher Project No.13-6592, dated July 2013
2-106	UPS Room	Walls	Concrete	N/A	N/A	N/A	N/A	N/A	No access to room
2-106	UPS Room	Ceiling	Not Found	N/A	N/A	N/A	N/A	N/A	No access to room Open to metal above
2-106	UPS Room	Pipe	Parging Cement	Asbestos	11850-A-01-04A*	None Detected	N/A	N/A	No access to room Beige from fitting - non-powder *From Building Environmental Audit, dated 2007
2-106	UPS Room	Pipe	Transite Pipe	Asbestos	Not Sampled	ACM Assumed	1 SF	Unknown	No access to room
2-107	Mechanical Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	No access to room
2-107	Mechanical Room	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	No access to room
2-107	Mechanical Room	Ceiling	Not Found	N/A	N/A	N/A	N/A	N/A	No access to room Open to metal above
2-107	Mechanical Room	Pipe	Parging Cement	Asbestos	11850-A-01-04B* 11850-A-01-04C*	None Detected	N/A	N/A	No access to room Beige from fitting - non-powder *From Building Environmental Audit, dated 2007
2-108	Cooling Tower Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	No access to room Outside
2-108	Cooling Tower Room	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	No access to room Outside
2-108	Cooling Tower Room	Ceiling	Not Found	N/A	N/A	N/A	N/A	N/A	No access to room Open to above
2-108	Cooling Tower Room	Pipe	Parging Cement	Asbestos	11850-A-01-03A* 11850-A-01-03B*	None Detected	N/A	N/A	No access to room Beige from fitting - powder like *From Building Environmental Audit, dated 2007
SOUTH BUILDING									
2-109	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
2-109	Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-109	Office	Ceiling	Acoustic Ceiling Tile (ACT01)	Asbestos	11850-A-01-19B*	None Detected	N/A	N/A	ACT01, 24" x 72", short random fissure and pinpoint (24" x 24" appearance) *From Building Environmental Audit, dated 2007
2-109	Office	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-109	Office	Pipe	Fibreglass	N/A	N/A	N/A	N/A	N/A	
2-109	Office	Duct	Fibreglass	N/A	N/A	N/A	N/A	N/A	
2-110	Corridor	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
2-110	Corridor	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-110	Corridor	Walls	Plaster	N/A	N/A	N/A	N/A	N/A	
2-110	Corridor	Ceiling	Acoustic Ceiling Tile (ACT01)	Asbestos	11850-A-01-19	None Detected	N/A	N/A	ACT01, 24" x 72", short random fissure and pinpoint (24" x 24" appearance)
2-111	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
2-111	Office	Walls	Drywall Joint Compound (DJC)	Asbestos	12-4832-4* 12-4832-5*	None Detected	N/A	N/A	*Sampled during 2012 survey
2-111	Office	Ceiling	Acoustic Ceiling Tile (ACT01)	Asbestos	11850-A-01-19	None Detected	N/A	N/A	ACT01, 24" x 72", short random fissure and pinpoint (24" x 24" appearance)
2-111	Office	Pipe	Uninsulated	N/A	N/A	N/A	N/A	N/A	
2-111	Office	Pipe	Fibreglass	N/A	N/A	N/A	N/A	N/A	
2-111	Office	Duct	Uninsulated	N/A	N/A	N/A	N/A	N/A	
2-111	Office	Duct	Fibreglass	N/A	N/A	N/A	N/A	N/A	
2-112	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
2-112	Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-112	Office	Ceiling	Acoustic Ceiling Tile (ACT01)	Asbestos	11850-A-01-19	None Detected	N/A	N/A	ACT01, 24" x 72", short random fissure and pinpoint (24" x 24" appearance)
2-112	Office	Pipe	Acoustic Ceiling Tile (ACT01)	N/A	N/A	N/A	N/A	N/A	
2-112	Office	Pipe	Acoustic Ceiling Tile (ACT01)	N/A	N/A	N/A	N/A	N/A	
2-112	Office	Duct	Acoustic Ceiling Tile (ACT01)	N/A	N/A	N/A	N/A	N/A	
2-112	Office	Duct	Acoustic Ceiling Tile (ACT01)	N/A	N/A	N/A	N/A	N/A	
2-113	Office	Floor	Acoustic Ceiling Tile (ACT01)	N/A	N/A	N/A	N/A	N/A	
2-113	Office	Walls	Acoustic Ceiling Tile (ACT01)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-113	Office	Ceiling	Acoustic Ceiling Tile (ACT01)	Asbestos	11850-A-01-19	None Detected	N/A	N/A	ACT01, 24" x 72", short random fissure and pinpoint (24" x 24" appearance)
2-113	Office	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-114	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	

APPENDIX I - ROOM-BY-ROOM INVENTORY SHEET

2-114	Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-114	Office	Ceiling	Acoustic Ceiling Tile (ACT01)	Asbestos	11850-A-01-19	None Detected	N/A	N/A	ACT01, 24" x 72", short random fissure and pinpoint (24" x 24" appearance)
2-114	Office	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-114	Office	Pipe	Uninsulated	N/A	N/A	N/A	N/A	N/A	
2-114	Office	Pipe	Fibreglass	N/A	N/A	N/A	N/A	N/A	
2-114	Office	Duct	Uninsulated	N/A	N/A	N/A	N/A	N/A	
2-114	Office	Duct	Fibreglass	N/A	N/A	N/A	N/A	N/A	
2-115	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
2-115	Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-115	Office	Ceiling	Acoustic Ceiling Tile (ACT01)	Asbestos	11850-A-01-19	None Detected	N/A	N/A	ACT01, 24" x 72", short random fissure and pinpoint (24" x 24" appearance)
2-115	Office	Ceiling	Acoustic Ceiling Tile (ACT01)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-115	Office	Pipe	Acoustic Ceiling Tile (ACT01)	N/A	N/A	N/A	N/A	N/A	
2-115	Office	Pipe	Acoustic Ceiling Tile (ACT01)	N/A	N/A	N/A	N/A	N/A	
2-115	Office	Duct	Acoustic Ceiling Tile (ACT01)	N/A	N/A	N/A	N/A	N/A	
2-115	Office	Duct	Acoustic Ceiling Tile (ACT01)	N/A	N/A	N/A	N/A	N/A	
2-116	Office	Floor	Acoustic Ceiling Tile (ACT01)	N/A	N/A	N/A	N/A	N/A	
2-116	Office	Walls	Acoustic Ceiling Tile (ACT01)	Asbestos	12-4832-6*	None Detected	N/A	N/A	*Sampled during 2012 survey
2-116	Office	Ceiling	Acoustic Ceiling Tile (ACT01)	Asbestos	11850-A-01-19	None Detected	N/A	N/A	ACT01, 24" x 72", short random fissure and pinpoint (24" x 24" appearance)
2-116	Office	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-116	Office	Pipe	Uninsulated	N/A	N/A	N/A	N/A	N/A	
2-116	Office	Pipe	Fibreglass	N/A	N/A	N/A	N/A	N/A	
2-116	Office	Duct	Uninsulated	N/A	N/A	N/A	N/A	N/A	
2-116	Office	Duct	Fibreglass	N/A	N/A	N/A	N/A	N/A	
2-117	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
2-117	Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-117	Office	Ceiling	Acoustic Ceiling Tile (ACT01)	Asbestos	11850-A-01-19	None Detected	N/A	N/A	ACT01, 24" x 72", short random fissure and pinpoint (24" x 24" appearance)
2-117	Office	Pipe	Uninsulated	N/A	N/A	N/A	N/A	N/A	
2-117	Office	Pipe	Fibreglass	N/A	N/A	N/A	N/A	N/A	
2-117	Office	Duct	Uninsulated	N/A	N/A	N/A	N/A	N/A	
2-117	Office	Duct	Fibreglass	N/A	N/A	N/A	N/A	N/A	
2-118	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
2-118	Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-118	Office	Ceiling	Acoustic Ceiling Tile (ACT01)	Asbestos	11850-A-01-19	None Detected	N/A	N/A	ACT01, 24" x 72", short random fissure and pinpoint (24" x 24" appearance)
2-118	Office	Pipe	Uninsulated	N/A	N/A	N/A	N/A	N/A	
2-118	Office	Pipe	Fibreglass	N/A	N/A	N/A	N/A	N/A	
2-118	Office	Duct	Uninsulated	N/A	N/A	N/A	N/A	N/A	
2-118	Office	Duct	Fibreglass	N/A	N/A	N/A	N/A	N/A	
2-119	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
2-119	Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-119	Office	Ceiling	Acoustic Ceiling Tile (ACT01)	Asbestos	11850-A-01-19	None Detected	N/A	N/A	ACT01, 24" x 72", short random fissure and pinpoint (24" x 24" appearance)
2-119	Office	Pipe	Uninsulated	N/A	N/A	N/A	N/A	N/A	
2-119	Office	Pipe	Fibreglass	N/A	N/A	N/A	N/A	N/A	
2-119	Office	Duct	Uninsulated	N/A	N/A	N/A	N/A	N/A	
2-119	Office	Duct	Fibreglass	N/A	N/A	N/A	N/A	N/A	
2-120	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
2-120	Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-120	Office	Ceiling	Acoustic Ceiling Tile (ACT01)	Asbestos	11850-A-01-19	None Detected	N/A	N/A	ACT01, 24" x 72", short random fissure and pinpoint (24" x 24" appearance)

APPENDIX I - ROOM-BY-ROOM INVENTORY SHEET

2-120	Office	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-120	Office	Pipe	Uninsulated	N/A	N/A	N/A	N/A	N/A	
2-120	Office	Pipe	Fibreglass	N/A	N/A	N/A	N/A	N/A	
2-120	Office	Duct	Uninsulated	N/A	N/A	N/A	N/A	N/A	
2-120	Office	Duct	Fibreglass	N/A	N/A	N/A	N/A	N/A	
2-121	Housekeeping	Floor	Vinyl Floor Tile (VFT01)	Asbestos	12-4832-1 to 3	None Detected	N/A	N/A	VFT01, 12" x 12", Light Grey Mosaic
2-121	Housekeeping	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-121	Housekeeping	Walls	Concrete	N/A	N/A	N/A	N/A	N/A	
2-121	Housekeeping	Ceiling	Acoustic Ceiling Tile (ACT01)	Asbestos	11850-A-01-19	None Detected	N/A	N/A	ACT01, 24" x 72", short random fissure and pinpoint (24" x 24" appearance)
2-121	Housekeeping	Pipe	Uninsulated	N/A	N/A	N/A	N/A	N/A	
2-121	Housekeeping	Pipe	Fibreglass	N/A	N/A	N/A	N/A	N/A	
2-122	File Storage	Floor	Vinyl Floor Tile (VFT01)	Asbestos	12-4832-1* 12-4832-2* 12-4832-3*	None Detected	N/A	N/A	Not observed during 2020 survey VFT01, 12" x 12", Light Grey Mosaic *Sampled during 2012 survey.
2-122	File Storage	Floor	Vinyl Floor Tile (VFT05)	Asbestos	Not Sampled	ACM Assumed	80 SF	Good	VFT05, 12" x 12", dark green rippled
2-122	File Storage	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-122	File Storage	Ceiling	Acoustic Ceiling Tile (ACT01)	Asbestos	11850-A-01-19	None Detected	N/A	N/A	ACT01, 24" x 72", short random fissure and pinpoint (24" x 24" appearance)
2-122	File Storage	Pipe	Uninsulated	N/A	N/A	N/A	N/A	N/A	
2-122	File Storage	Pipe	Fibreglass	N/A	N/A	N/A	N/A	N/A	
2-122	File Storage	Duct	Uninsulated	N/A	N/A	N/A	N/A	N/A	
2-122	File Storage	Duct	Fibreglass	N/A	N/A	N/A	N/A	N/A	
2-123	Server Room	Floor	Vinyl Floor Tile (VFT01)	Asbestos	12-4832-1 to 3	None Detected	N/A	N/A	VFT01, 12" x 12", Light Grey Mosaic
2-123	Server Room	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
2-123	Server Room	Ceiling	Not Found	N/A	N/A	N/A	N/A	N/A	
2-124	File Storage	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
2-124	File Storage	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-124	File Storage	Ceiling	Acoustic Ceiling Tile (ACT01)	Asbestos	11850-A-01-19	None Detected	N/A	N/A	ACT01, 24" x 72", short random fissure and pinpoint (24" x 24" appearance)
2-124	File Storage	Pipe	Uninsulated	N/A	N/A	N/A	N/A	N/A	
2-124	File Storage	Pipe	Fibreglass	N/A	N/A	N/A	N/A	N/A	
2-124	File Storage	Duct	Uninsulated	N/A	N/A	N/A	N/A	N/A	
2-124	File Storage	Duct	Fibreglass	N/A	N/A	N/A	N/A	N/A	
2-125	General Offices	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
2-125	General Offices	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-125	General Offices	Ceiling	Acoustic Ceiling Tile (ACT01)	Asbestos	11850-A-01-19	None Detected	N/A	N/A	ACT01, 24" x 72", short random fissure and pinpoint (24" x 24" appearance)
2-125	General Offices	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-125	General Offices	Pipe	Uninsulated	N/A	N/A	N/A	N/A	N/A	
2-125	General Offices	Pipe	Fibreglass	N/A	N/A	N/A	N/A	N/A	
2-125	General Offices	Duct	Uninsulated	N/A	N/A	N/A	N/A	N/A	
2-125	General Offices	Duct	Fibreglass	N/A	N/A	N/A	N/A	N/A	
2-126	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
2-126	Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-126	Office	Ceiling	Acoustic Ceiling Tile (ACT01)	Asbestos	11850-A-01-19	None Detected	N/A	N/A	ACT01, 24" x 72", short random fissure and pinpoint (24" x 24" appearance)
2-126	Office	Pipe	Uninsulated	N/A	N/A	N/A	N/A	N/A	
2-126	Office	Pipe	Fibreglass	N/A	N/A	N/A	N/A	N/A	
2-126	Office	Duct	Uninsulated	N/A	N/A	N/A	N/A	N/A	
2-126	Office	Duct	Fibreglass	N/A	N/A	N/A	N/A	N/A	
2-127	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
2-127	Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling

APPENDIX I - ROOM-BY-ROOM INVENTORY SHEET

2-127	Office	Ceiling	Acoustic Ceiling Tile (ACT01)	Asbestos	11850-A-01-19	None Detected	N/A	N/A	ACT01, 24" x 72", short random fissure and pinpoint (24" x 24" appearance)
2-128	Women's Washroom	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
2-128	Women's Washroom	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
2-128	Women's Washroom	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-129	Electrical Room	Floor	Vinyl Floor Tile (VFT01)	Asbestos	12-4832-1 to 3	None Detected	N/A	N/A	VFT01, 12" x 12", Light Grey Mosaic
2-129	Electrical Room	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
2-129	Electrical Room	Ceiling	Not Found	N/A	N/A	N/A	N/A	N/A	Open to metal above
2-130	Men's Washroom	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
2-130	Men's Washroom	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
2-130	Men's Washroom	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-131	Kitchen/Lounge	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
2-131	Kitchen/Lounge	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-131	Kitchen/Lounge	Ceiling	Acoustic Ceiling Tile (ACT01)	Asbestos	11850-A-01-19	None Detected	N/A	N/A	ACT01, 24" x 72", short random fissure and pinpoint (24" x 24" appearance)
2-131	Kitchen/Lounge	Pipe	Uninsulated	N/A	N/A	N/A	N/A	N/A	
2-131	Kitchen/Lounge	Pipe	Fibreglass	N/A	N/A	N/A	N/A	N/A	
2-132	Copy Room	Room doesn't exist (combined with 2-131)							
2-132	Copy Room	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-132	Copy Room	Ceiling	Acoustic Ceiling Tile (ACT01)	Asbestos	11850-A-01-19	None Detected	N/A	N/A	ACT01, 24" x 72", short random fissure and pinpoint (24" x 24" appearance)
2-133	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
2-133	Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-133	Office	Ceiling	Acoustic Ceiling Tile (ACT01)	Asbestos	11850-A-01-19	None Detected	N/A	N/A	ACT01, 24" x 72", short random fissure and pinpoint (24" x 24" appearance)
2-133	Office	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-133	Office	Pipe	Uninsulated	N/A	N/A	N/A	N/A	N/A	
2-133	Office	Pipe	Fibreglass	N/A	N/A	N/A	N/A	N/A	
2-133	Office	Duct	Uninsulated	N/A	N/A	N/A	N/A	N/A	
2-133	Office	Duct	Fibreglass	N/A	N/A	N/A	N/A	N/A	
2-134	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
2-134	Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-134	Office	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-134	Office	Ceiling	Acoustic Ceiling Tile (ACT01)	Asbestos	11850-A-01-19	None Detected	N/A	N/A	ACT01, 24" x 72", short random fissure and pinpoint (24" x 24" appearance)
2-135	Room doesn't exist.								
2-136	Film Room	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
2-136	Film Room	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-136	Film Room	Ceiling	Acoustic Ceiling Tile (ACT01)	Asbestos	11850-A-01-19	None Detected	N/A	N/A	ACT01, 24" x 72", short random fissure and pinpoint (24" x 24" appearance)
2-136	Film Room	Pipe	Uninsulated	N/A	N/A	N/A	N/A	N/A	
2-126	Film Room	Pipe	Fibreglass	N/A	N/A	N/A	N/A	N/A	
2-136	Film Room	Duct	Uninsulated	N/A	N/A	N/A	N/A	N/A	
2-137	Boardroom	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
2-137	Boardroom	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-137	Boardroom	Ceiling	Acoustic Ceiling Tile (ACT01)	Asbestos	11850-A-01-19	None Detected	N/A	N/A	ACT01, 24" x 72", short random fissure and pinpoint (24" x 24" appearance)
2-138	Boardroom	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	No Access to Room
2-138	Boardroom	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	No Access to Room Based on extensive previous sampling
2-138	Boardroom	Ceiling	Not Found	N/A	N/A	N/A	N/A	N/A	No Access to Room
2-139	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
2-139	Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-139	Office	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling

APPENDIX I - ROOM-BY-ROOM INVENTORY SHEET

2-139	Office	Ceiling	Acoustic Ceiling Tile (ACT12)	Asbestos	11850-A-01-23A*	None Detected	N/A	N/A	ACT12, 24" x 72", Plain Drop-Down (24" x 24" appearance) *From Building Environmental Audit, dated 2007
NORTH BUILDING									
2-140	Corridor	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
2-140	Corridor	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-140	Corridor	Ceiling	Acoustic Ceiling Tile (ACT21)	Asbestos	Date Code 03/09/16	N/A	N/A	N/A	ACT21, 24" x 48", random fissure and pinhole (Date Code: 03/09/16)
2-140	Corridor	Pipe	Transite Pipe	Asbestos	Not Sampled	ACM Assumed	25 LF	Good	
2-141	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
2-141	Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-141	Office	Ceiling	Acoustic Ceiling Tile (ACT21)	Asbestos	Date Code 03/09/16	N/A	N/A	N/A	ACT21, 24" x 48", random fissure and pinhole (Date Code: 03/09/16)
2-141	Office	Pipe	Transite Pipe	Asbestos	Not Sampled	ACM Assumed	16 LF	N/A	NOT OBSERVED
2-142	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
2-142	Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-142	Office	Ceiling	Acoustic Ceiling Tile (ACT01)	Asbestos	11850-A-01-19	None Detected	N/A	N/A	ACT01, 24" x 72", short random fissure and pinpoint (24" x 24" appearance)
WEST BUILDING									
2-143	Storage Room	Floor	Vinyl Floor Tile (VFT02)	Asbestos	12-4832-10 to 12	None Detected	N/A	N/A	VFT02, 12" x 12", Grey Mosaic
2-143	Storage Room	Walls	Drywall Panel	N/A	N/A	N/A	N/A	N/A	
2-143	Storage Room	Ceiling	Not Found	N/A	N/A	N/A	N/A	N/A	
2-144	Office	Floor	Vinyl Floor Tile (VFT02)	Asbestos	12-4832-10 to 12	None Detected	N/A	N/A	VFT02, 12" x 12", Grey Mosaic
2-144	Office	Walls	Vinyl Floor Tile (VFT02)	N/A	N/A	N/A	N/A	N/A	
2-144	Office	Ceiling	Vinyl Floor Tile (VFT02)	N/A	N/A	N/A	N/A	N/A	Open to metal above
2-145	Men's / Women's Change Room	Floor	Vinyl Floor Tile (VFT02)	Asbestos	12-4832-10 to 12	None Detected	N/A	N/A	VFT02, 12" x 12", Grey Mosaic
2-145	Men's / Women's Change Room	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
2-145	Men's / Women's Change Room	Walls	Drywall Panel	N/A	N/A	N/A	N/A	N/A	
2-145	Men's / Women's Change Room	Ceiling	Not Found	N/A	N/A	N/A	N/A	N/A	Open to metal above
2-145	Men's / Women's Change Room	Pipe	Uninsulated	N/A	N/A	N/A	N/A	N/A	
2-145	Men's / Women's Change Room	Pipe	Fibreglass	N/A	N/A	N/A	N/A	N/A	
2-145	Men's / Women's Change Room	Pipe	Transite Pipe	Asbestos	Not Sampled	ACM Assumed	30 LF	Good	
2-145	Men's / Women's Change Room	Duct	Uninsulated	N/A	N/A	N/A	N/A	N/A	
NORTH BUILDING									
2-146	Electrical Closet	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
2-146	Electrical Closet	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
2-146	Electrical Closet	Ceiling	Acoustic Ceiling Tile (ACT21)	Asbestos	Date Code 03/09/16	N/A	N/A	N/A	ACT21, 24" x 48", random fissure and pinhole (Date Code: 03/09/16)
2-146	Electrical Closet	Pipe	Uninsulated	N/A	N/A	N/A	N/A	N/A	
2-146	Electrical Closet	Duct	Fibreglass	N/A	N/A	N/A	N/A	N/A	
CENTRE BUILDING									
3-001	Vestibule	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
3-001	Vestibule	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
3-001	Vestibule	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
3-001	Vestibule	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
3-003	Corridor	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
3-003	Corridor	Walls	Drywall Joint Compound (DJC)	Asbestos	13-6174-01 to 03*	None Detected	N/A	N/A	*From Fisher Project No.13-6570, dated June 2013
3-003	Corridor	Ceiling	Acoustic Ceiling Tile (ACT07)	Asbestos	11850-A-01-13C*	None Detected	N/A	N/A	ACT07, 24" x 48", Plain White Drop-Down *From Building Environmental Audit, dated 2007
3-003	Corridor	Structure	Sprayed Fireproofing	Asbestos	11850-A-01-01	None Detected	N/A	N/A	
3-003	Corridor	Pipe	Uninsulated	N/A	N/A	N/A	N/A	N/A	
3-003	Corridor	Pipe	Fibreglass	N/A	N/A	N/A	N/A	N/A	

APPENDIX I - ROOM-BY-ROOM INVENTORY SHEET

3-003	Corridor	Duct	Uninsulated	N/A	N/A	N/A	N/A	N/A	
3-003	Corridor	Duct	Fibreglass	N/A	N/A	N/A	N/A	N/A	
3-004	LAN Room	Floor	Vinyl Floor Tile (VFT02)	Asbestos	12-4832-10 to 12	None Detected	N/A	N/A	VFT02, 12" x 12", Grey Mosaic
3-004	LAN Room	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
3-004	LAN Room	Walls	Concrete	N/A	N/A	N/A	N/A	N/A	
3-004	LAN Room	Ceiling	Not Found	N/A	N/A	N/A	N/A	N/A	
3-004	LAN Room	Structure	Sprayed Fireproofing	Asbestos	11850-A-01-01	None Detected	N/A	N/A	
3-005	Electrical Room	Floor	Vinyl Floor Tile (VFT02)	Asbestos	12-4832-10 to 12	None Detected	N/A	N/A	VFT02, 12" x 12", Grey Mosaic
3-005	Electrical Room	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
3-005	Electrical Room	Walls	Concrete	N/A	N/A	N/A	N/A	N/A	
3-005	Electrical Room	Ceiling	Not Found	N/A	N/A	N/A	N/A	N/A	
3-005	Electrical Room	Structure	Sprayed Fireproofing	Asbestos	11850-A-01-01	None Detected	N/A	N/A	
3-005	Electrical Room	Duct	Uninsulated	N/A	N/A	N/A	N/A	N/A	
3-006	Unisex Washroom	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
3-006	Unisex Washroom	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
3-006	Unisex Washroom	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
3-007	Men's Washroom	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
3-007	Men's Washroom	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
3-007	Men's Washroom	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
3-008	Women's Washroom	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
3-008	Women's Washroom	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
3-008	Women's Washroom	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
3-009	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
3-009	Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
3-009	Office	Ceiling	Acoustic Ceiling Tile (ACT07)	Asbestos	11850-A-01-13	None Detected	N/A	N/A	ACT07, 24" x 48", Plain White Drop-Down
3-009	Office	Structure	Sprayed Fireproofing	Asbestos	11850-A-01-01	None Detected	N/A	N/A	
3-009	Office	Pipe	Uninsulated	N/A	N/A	N/A	N/A	N/A	
3-009	Office	Pipe	Fibreglass	N/A	N/A	N/A	N/A	N/A	
3-009	Office	Duct	Uninsulated	N/A	N/A	N/A	N/A	N/A	
3-009	Office	Duct	Fibreglass	N/A	N/A	N/A	N/A	N/A	
3-010	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
3-010	Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
3-010	Office	Ceiling	Acoustic Ceiling Tile (ACT07)	Asbestos	11850-A-01-13	None Detected	N/A	N/A	ACT07, 24" x 48", Plain White Drop-Down
3-010	Office	Structure	Sprayed Fireproofing	Asbestos	11850-A-01-01	None Detected	N/A	N/A	
3-010	Office	Pipe	Uninsulated	N/A	N/A	N/A	N/A	N/A	
3-010	Office	Pipe	Fibreglass	N/A	N/A	N/A	N/A	N/A	
3-010	Office	Duct	Uninsulated	N/A	N/A	N/A	N/A	N/A	
3-010	Office	Duct	Fibreglass	N/A	N/A	N/A	N/A	N/A	
3-011	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
3-011	Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
3-011	Office	Ceiling	Acoustic Ceiling Tile (ACT07)	Asbestos	11850-A-01-13	None Detected	N/A	N/A	ACT07, 24" x 48", Plain White Drop-Down
3-011	Office	Structure	Acoustic Ceiling Tile (ACT07)	Asbestos	11850-A-01-01	None Detected	N/A	N/A	
3-011	Office	Pipe	Acoustic Ceiling Tile (ACT07)	N/A	N/A	N/A	N/A	N/A	
3-011	Office	Pipe	Acoustic Ceiling Tile (ACT07)	N/A	N/A	N/A	N/A	N/A	
3-011	Office	Duct	Acoustic Ceiling Tile (ACT07)	N/A	N/A	N/A	N/A	N/A	
3-011	Office	Duct	Acoustic Ceiling Tile (ACT07)	N/A	N/A	N/A	N/A	N/A	
3-012	Office	Floor	Acoustic Ceiling Tile (ACT07)	N/A	N/A	N/A	N/A	N/A	

APPENDIX I - ROOM-BY-ROOM INVENTORY SHEET

3-012	Office	Walls	Acoustic Ceiling Tile (ACT07)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
3-012	Office	Ceiling	Acoustic Ceiling Tile (ACT07)	Asbestos	11850-A-01-13	None Detected	N/A	N/A	ACT07, 24" x 48", Plain White Drop-Down
3-012	Office	Structure	Sprayed Fireproofing	Asbestos	11850-A-01-01	None Detected	N/A	N/A	
3-012	Office	Pipe	Uninsulated	N/A	N/A	N/A	N/A	N/A	
3-012	Office	Pipe	Fibreglass	N/A	N/A	N/A	N/A	N/A	
3-012	Office	Duct	Uninsulated	N/A	N/A	N/A	N/A	N/A	
3-012	Office	Duct	Fibreglass	N/A	N/A	N/A	N/A	N/A	
3-013	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
3-013	Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
3-013	Office	Ceiling	Acoustic Ceiling Tile (ACT07)	Asbestos	11850-A-01-13	None Detected	N/A	N/A	ACT07, 24" x 48", Plain White Drop-Down
3-013	Office	Structure	Sprayed Fireproofing	Asbestos	11850-A-01-01	None Detected	N/A	N/A	
3-014	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
3-014	Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
3-014	Office	Ceiling	Acoustic Ceiling Tile (ACT07)	Asbestos	11850-A-01-13	None Detected	N/A	N/A	ACT07, 24" x 48", Plain White Drop-Down
3-014	Office	Structure	Sprayed Fireproofing	Asbestos	11850-A-01-01	None Detected	N/A	N/A	
3-015	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
3-015	Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
3-015	Office	Ceiling	Acoustic Ceiling Tile (ACT07)	Asbestos	11850-A-01-13	None Detected	N/A	N/A	ACT07, 24" x 48", Plain White Drop-Down
3-015	Office	Structure	Sprayed Fireproofing	Asbestos	11850-A-01-01	None Detected	N/A	N/A	
3-015	Office	Pipe	Uninsulated	N/A	N/A	N/A	N/A	N/A	
3-015	Office	Pipe	Fibreglass	N/A	N/A	N/A	N/A	N/A	
3-015	Office	Duct	Uninsulated	N/A	N/A	N/A	N/A	N/A	
3-015	Office	Duct	Fibreglass	N/A	N/A	N/A	N/A	N/A	
3-016	Lunch/Break Room	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
3-016	Lunch/Break Room	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
3-016	Lunch/Break Room	Ceiling	Acoustic Ceiling Tile (ACT07)	Asbestos	11850-A-01-13	None Detected	N/A	N/A	ACT07, 24" x 48", Plain White Drop-Down
3-016	Lunch/Break Room	Structure	Sprayed Fireproofing	Asbestos	11850-A-01-01	None Detected	N/A	N/A	
3-017	Housekeeping	Floor	Vinyl Floor Tile (VFT02)	Asbestos	12-4832-10 to 12	None Detected	N/A	N/A	VFT02, 12" x 12", Grey Mosaic
3-017	Housekeeping	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
3-017	Housekeeping	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
3-017	Housekeeping	Structure	Sprayed Fireproofing	Asbestos	11850-A-01-01A*	None Detected	N/A	N/A	*From Building Environmental Audit, dated 2007
3-018	Storage	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
3-018	Storage	Walls	Drywall Joint Compound (DJC)	Asbestos	12-4832-13* 12-4832-14*	None Detected	N/A	N/A	*Sampled during 2012 survey
3-018	Storage	Ceiling	Acoustic Ceiling Tile (ACT07)	Asbestos	11850-A-01-13	None Detected	N/A	N/A	ACT07, 24" x 48", Plain White Drop-Down
3-018	Storage	Pipe	Uninsulated	N/A	N/A	N/A	N/A	N/A	
3-018	Storage	Pipe	Fibreglass	N/A	N/A	N/A	N/A	N/A	
3-018	Storage	Duct	Uninsulated	N/A	N/A	N/A	N/A	N/A	
3-018	Storage	Duct	Fibreglass	N/A	N/A	N/A	N/A	N/A	
3-019	Chief's Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
3-019	Chief's Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
3-019	Chief's Office	Ceiling	Acoustic Ceiling Tile (ACT07)	Asbestos	11850-A-01-13	None Detected	N/A	N/A	ACT07, 24" x 48", Plain White Drop-Down
3-019	Chief's Office	Structure	Sprayed Fireproofing	Asbestos	11850-A-01-01	None Detected	N/A	N/A	
3-020	EMS Communications	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
3-020	EMS Communications	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
3-020	EMS Communications	Walls	Paint	Lead	14-8019-12*	0.003%	N/A	N/A	Off-white paint *From Fisher Project No.14-6825, dated Feb. 2014
3-020	EMS Communications	Ceiling	Acoustic Ceiling Tile (ACT16)	N/A	N/A	N/A	N/A	N/A	ACT16, 24" x 48", Plain textured (Fibreglass)

APPENDIX I - ROOM-BY-ROOM INVENTORY SHEET

3-020	EMS Communications	Structure	Sprayed Fireproofing	Asbestos	11850-A-01-01	None Detected	N/A	N/A	
3-020	EMS Communications	Walls	Duct Insulation	Asbestos	14-8019-01* 14-8019-02* 14-8019-03*	None Detected	N/A	N/A	*From Fisher Project No.14-6825, dated Feb. 2014
3-020	EMS Communications	Ceiling	Acoustic Ceiling Tile (ACT17)	Asbestos	14-8019-04* 14-8019-05* 14-8019-06*	None Detected	N/A	N/A	ACT17, 24" x 48", Plain Textured *From Fisher Project No.14-6825, dated Feb. 2014
3-020	EMS Communications	Walls	Drywall Joint Compound (DJC)	Asbestos	14-8019-07 to 11*	None Detected	N/A	N/A	*From Fisher Project No.14-6825, dated Feb. 2014
SOUTH BUILDING									
3-021	Vestibule	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
3-021	Vestibule	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
3-021	Vestibule	Walls	Plaster	N/A	N/A	N/A	N/A	N/A	
3-021	Vestibule	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
3-022	Reception	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
3-022	Reception	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
3-022	Reception	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
3-022	Reception	Ceiling	Acoustic Ceiling Tile (ACT01)	Asbestos	11850-A-01-19	None Detected	N/A	N/A	ACT01, 24" x 72", short random fissure and pinpoint (24" x 24" appearance)
3-022	Reception	Pipe	Uninsulated	N/A	N/A	N/A	N/A	N/A	
3-022	Reception	Pipe	Fibreglass	N/A	N/A	N/A	N/A	N/A	
3-022	Reception	Duct	Uninsulated	N/A	N/A	N/A	N/A	N/A	
3-023	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
3-023	Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
3-023	Office	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
3-023	Office	Ceiling	Acoustic Ceiling Tile (ACT01)	Asbestos	11850-A-01-19	None Detected	N/A	N/A	ACT01, 24" x 72", short random fissure and pinpoint (24" x 24" appearance)
3-024	General Offices	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
3-024	General Offices	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
3-024	General Offices	Ceiling	Acoustic Ceiling Tile (ACT01)	Asbestos	11850-A-01-19	None Detected	N/A	N/A	ACT01, 24" x 72", short random fissure and pinpoint (24" x 24" appearance)
3-024	General Offices	Pipe	Uninsulated	N/A	N/A	N/A	N/A	N/A	
3-024	General Offices	Pipe	Fibreglass	N/A	N/A	N/A	N/A	N/A	
3-024	General Offices	Duct	Uninsulated	N/A	N/A	N/A	N/A	N/A	
3-024	General Offices	Duct	Fibreglass	N/A	N/A	N/A	N/A	N/A	
3-025	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
3-025	Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
3-025	Office	Ceiling	Acoustic Ceiling Tile (ACT01)	Asbestos	11850-A-01-19	None Detected	N/A	N/A	ACT01, 24" x 72", short random fissure and pinpoint (24" x 24" appearance)
3-025	Office	Pipe	Uninsulated	N/A	N/A	N/A	N/A	N/A	
3-025	Office	Pipe	Fibreglass	N/A	N/A	N/A	N/A	N/A	
3-025	Office	Duct	Uninsulated	N/A	N/A	N/A	N/A	N/A	
3-025	Office	Duct	Fibreglass	N/A	N/A	N/A	N/A	N/A	
3-026	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
3-026	Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
3-026	Office	Ceiling	Acoustic Ceiling Tile (ACT01)	Asbestos	11850-A-01-19C*	None Detected	N/A	N/A	ACT01, 24" x 72", short random fissure and pinpoint (24" x 24" appearance) *From Building Environmental Audit, dated 2007
3-026	Office	Pipe	Uninsulated	N/A	N/A	N/A	N/A	N/A	
3-026	Office	Pipe	Fibreglass	N/A	N/A	N/A	N/A	N/A	
3-026	Office	Duct	Uninsulated	N/A	N/A	N/A	N/A	N/A	
3-026	Office	Duct	Fibreglass	N/A	N/A	N/A	N/A	N/A	
3-027	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
3-027	Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
3-027	Office	Ceiling	Acoustic Ceiling Tile (ACT01)	Asbestos	11850-A-01-19	None Detected	N/A	N/A	ACT01, 24" x 72", short random fissure and pinpoint (24" x 24" appearance)

APPENDIX I - ROOM-BY-ROOM INVENTORY SHEET

3-027	Office	Pipe	Uninsulated	N/A	N/A	N/A	N/A	N/A	
3-027	Office	Pipe	Fibreglass	N/A	N/A	N/A	N/A	N/A	
3-027	Office	Duct	Uninsulated	N/A	N/A	N/A	N/A	N/A	
3-027	Office	Duct	Fibreglass	N/A	N/A	N/A	N/A	N/A	
3-028	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
3-028	Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
3-028	Office	Ceiling	Acoustic Ceiling Tile (ACT01)	Asbestos	11850-A-01-19	None Detected	N/A	N/A	ACT01, 24" x 72", short random fissure and pinpoint (24" x 24" appearance)
3-028	Office	Pipe	Uninsulated	N/A	N/A	N/A	N/A	N/A	
3-028	Office	Pipe	Fibreglass	N/A	N/A	N/A	N/A	N/A	
3-028	Office	Duct	Uninsulated	N/A	N/A	N/A	N/A	N/A	
3-028	Office	Duct	Fibreglass	N/A	N/A	N/A	N/A	N/A	
3-029	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
3-029	Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
3-029	Office	Ceiling	Acoustic Ceiling Tile (ACT01)	Asbestos	11850-A-01-19	None Detected	N/A	N/A	ACT01, 24" x 72", short random fissure and pinpoint (24" x 24" appearance)
3-029	Office	Pipe	Uninsulated	N/A	N/A	N/A	N/A	N/A	
3-029	Office	Pipe	Fibreglass	N/A	N/A	N/A	N/A	N/A	
3-029	Office	Duct	Uninsulated	N/A	N/A	N/A	N/A	N/A	
3-029	Office	Duct	Fibreglass	N/A	N/A	N/A	N/A	N/A	
3-030	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
3-030	Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
3-030	Office	Ceiling	Acoustic Ceiling Tile (ACT01)	Asbestos	11850-A-01-19	None Detected	N/A	N/A	ACT01, 24" x 72", short random fissure and pinpoint (24" x 24" appearance) *From Building Environmental Audit, dated 2007
3-030	Office	Pipe	Uninsulated	N/A	N/A	N/A	N/A	N/A	
3-030	Office	Pipe	Fibreglass	N/A	N/A	N/A	N/A	N/A	
3-030	Office	Duct	Uninsulated	N/A	N/A	N/A	N/A	N/A	
3-030	Office	Duct	Fibreglass	N/A	N/A	N/A	N/A	N/A	
3-031	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
3-031	Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
3-031	Office	Ceiling	Acoustic Ceiling Tile (ACT01)	Asbestos	11850-A-01-19	None Detected	N/A	N/A	ACT01, 24" x 72", short random fissure and pinpoint (24" x 24" appearance)
3-032	Housekeeping	Floor	Vinyl Floor Tile (VFT01)	Asbestos	12-4832-1 to 3	None Detected	N/A	N/A	VFT01, 12" x 12", Light Grey Mosaic
3-032	Housekeeping	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
3-032	Housekeeping	Ceiling	Acoustic Ceiling Tile (ACT01)	Asbestos	11850-A-01-19	None Detected	N/A	N/A	ACT01, 24" x 72", short random fissure and pinpoint (24" x 24" appearance)
3-033	Server Room	Floor	Vinyl Floor Tile (VFT01)	Asbestos	12-4832-1 to 3	None Detected	N/A	N/A	VFT01, 12" x 12", Light Grey Mosaic
3-033	Server Room	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
3-033	Server Room	Ceiling	Not Found	N/A	N/A	N/A	N/A	N/A	Open to metal above
3-034	Copy Room	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
3-034	Copy Room	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
3-034	Copy Room	Ceiling	Acoustic Ceiling Tile (ACT01)	Asbestos	11850-A-01-19	None Detected	N/A	N/A	ACT01, 24" x 72", short random fissure and pinpoint (24" x 24" appearance)
3-034	Copy Room	Pipe	Uninsulated	N/A	N/A	N/A	N/A	N/A	
3-034	Copy Room	Pipe	Fibreglass	N/A	N/A	N/A	N/A	N/A	
3-034	Copy Room	Duct	Uninsulated	N/A	N/A	N/A	N/A	N/A	
3-034	Copy Room	Duct	Fibreglass	N/A	N/A	N/A	N/A	N/A	
3-035	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
3-035	Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
3-035	Office	Ceiling	Acoustic Ceiling Tile (ACT01)	Asbestos	11850-A-01-19	None Detected	N/A	N/A	ACT01, 24" x 72", short random fissure and pinpoint (24" x 24" appearance)
3-036	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
3-036	Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling

APPENDIX I - ROOM-BY-ROOM INVENTORY SHEET

3-036	Office	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
3-036	Office	Ceiling	Acoustic Ceiling Tile (ACT01)	Asbestos	11850-A-01-19	None Detected	N/A	N/A	ACT01, 24" x 72", short random fissure and pinpoint (24" x 24" appearance)
3-037	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
3-037	Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
3-037	Office	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
3-037	Office	Ceiling	Acoustic Ceiling Tile (ACT01)	Asbestos	11850-A-01-19	None Detected	N/A	N/A	ACT01, 24" x 72", short random fissure and pinpoint (24" x 24" appearance)
3-038	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
3-038	Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
3-038	Office	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
3-038	Office	Ceiling	Acoustic Ceiling Tile (ACT01)	Asbestos	11850-A-01-19	None Detected	N/A	N/A	ACT01, 24" x 72", short random fissure and pinpoint (24" x 24" appearance)
3-039	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	No Access to Room
3-039	Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	No Access to Room Based on extensive previous sampling
3-039	Office	Ceiling	Acoustic Ceiling Tile (ACT01)	Asbestos	11850-A-01-19	None Detected	N/A	N/A	No Access to Room ACT01, 24" x 72", short random fissure and pinpoint (24" x 24" appearance)
3-039	Office	Pipe	Uninsulated	N/A	N/A	N/A	N/A	N/A	No Access to Room
3-039	Office	Pipe	Fibreglass	N/A	N/A	N/A	N/A	N/A	No Access to Room
3-040	Washroom	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	No Access to Room
3-040	Washroom	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	No Access to Room Based on extensive previous sampling
3-040	Washroom	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	No Access to Room Based on extensive previous sampling
3-040	Washroom	Pipe	Uninsulated	N/A	N/A	N/A	N/A	N/A	No Access to Room
3-040	Washroom	Pipe	Fibreglass	N/A	N/A	N/A	N/A	N/A	No Access to Room
3-041	Corridor	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
3-041	Corridor	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
3-041	Corridor	Ceiling	Acoustic Ceiling Tile (ACT01)	Asbestos	11850-A-01-19	None Detected	N/A	N/A	ACT01, 24" x 72", short random fissure and pinpoint (24" x 24" appearance)
3-041	Corridor	Ceiling	Acoustic Ceiling Tile (ACT14)	Asbestos	11850-A-01-24A* 11850-A-01-24B*	None Detected	N/A	N/A	ACT14, 24" x 72", Large random fissure with pinpoint *From Building Environmental Audit, dated 2007
3-041	Corridor	Pipe	Uninsulated	N/A	N/A	N/A	N/A	N/A	
3-041	Corridor	Pipe	Fibreglass	N/A	N/A	N/A	N/A	N/A	
3-042	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
3-042	Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
3-042	Office	Ceiling	Acoustic Ceiling Tile (ACT01)	Asbestos	11850-A-01-19	None Detected	N/A	N/A	ACT01, 24" x 72", short random fissure and pinpoint (24" x 24" appearance)
3-042	Office	Ceiling	Acoustic Ceiling Tile (ACT14)	Asbestos	11850-A-01-24C*	None Detected	N/A	N/A	ACT14, 24" x 72", Large random fissure with pinpoint *From Building Environmental Audit, dated 2007
3-042	Office	Pipe	Uninsulated	N/A	N/A	N/A	N/A	N/A	
3-042	Office	Pipe	Fibreglass	N/A	N/A	N/A	N/A	N/A	
3-043	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
3-043	Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
3-043	Office	Ceiling	Acoustic Ceiling Tile (ACT01)	Asbestos	11850-A-01-19	None Detected	N/A	N/A	ACT01, 24" x 72", short random fissure and pinpoint (24" x 24" appearance)
3-044	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
3-044	Office	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
3-044	Office	Ceiling	Acoustic Ceiling Tile (ACT01)	Asbestos	11850-A-01-19	None Detected	N/A	N/A	ACT01, 24" x 72", short random fissure and pinpoint (24" x 24" appearance)
3-044	Office	Pipe	Uninsulated	N/A	N/A	N/A	N/A	N/A	
3-044	Office	Pipe	Fibreglass	N/A	N/A	N/A	N/A	N/A	
3-045	Boardroom	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
3-045	Boardroom	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
3-045	Boardroom	Ceiling	Acoustic Ceiling Tile (ACT15)	Asbestos	11850-A-01-25A* 11850-A-01-25B* 11850-A-01-25C*	None Detected	N/A	N/A	ACT15, 24" x 24", Plain white *From Building Environmental Audit, dated 2007
3-046	File Storage	Floor	Vinyl Floor Tile (VFT01)	Asbestos	12-4832-1 to 3	None Detected	N/A	N/A	VFT01, 12" x 12", Light Grey Mosaic

APPENDIX I - ROOM-BY-ROOM INVENTORY SHEET

3-046	File Storage	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
3-046	File Storage	Ceiling	Acoustic Ceiling Tile (ACT01)	Asbestos	11850-A-01-19	None Detected	N/A	N/A	ACT01, 24" x 72", short random fissure and pinpoint (24" x 24" appearance)
3-047	Men's Washroom	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
3-047	Men's Washroom	Walls	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
3-047	Men's Washroom	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
3-048	Women's Washroom	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
3-048	Women's Washroom	Walls	Ceramic Tile	N/A	N/A	N/A	N/A	N/A	
3-048	Women's Washroom	Ceiling	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
3-049	Electrical Room	Floor	Vinyl Floor Tile (VFT01)	Asbestos	12-4832-1 to 3	None Detected	N/A	N/A	VFT01, 12" x 12", Light Grey Mosaic
3-049	Electrical Room	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
3-049	Electrical Room	Ceiling	Not Found	N/A	N/A	N/A	N/A	N/A	Open to metal above
3-050	Kitchen	Floor	Laminate	N/A	N/A	N/A	N/A	N/A	Wood
3-050	Kitchen	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
3-050	Kitchen	Ceiling	Acoustic Ceiling Tile (ACT21)	Asbestos	Date Code 03/09/16	N/A	N/A	N/A	ACT21, 24" x 48", random fissure and pinhole (Date Code: 03/09/16)
SOUTH BUILDING									
4-001	Mechanical Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
4-001	Mechanical Room	Walls	Drywall Joint Compound (DJC)	Asbestos	Not Sampled	None Detected	N/A	N/A	Based on extensive previous sampling
4-001	Mechanical Room	Walls	Concrete	N/A	N/A	N/A	N/A	N/A	
4-001	Mechanical Room	Ceiling	Not Found	N/A	N/A	N/A	N/A	N/A	Open to metal above
4-001	Mechanical Room	Pipe	Uninsulated	N/A	N/A	N/A	N/A	N/A	
4-001	Mechanical Room	Pipe	Fibreglass	N/A	N/A	N/A	N/A	N/A	
4-001	Mechanical Room	Duct	Uninsulated	N/A	N/A	N/A	N/A	N/A	
4-001	Mechanical Room	Duct	Fibreglass	N/A	N/A	N/A	N/A	N/A	
4-002	Mechanical Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
4-002	Mechanical Room	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
4-002	Mechanical Room	Ceiling	Not Found	N/A	N/A	N/A	N/A	N/A	Open to metal above
PARKING GARAGE									
P-000	Exterior	Roof	Not Found	N/A	N/A	N/A	N/A	N/A	
P-000	Exterior	Windows	Not Found	N/A	N/A	N/A	N/A	N/A	
P-000	Exterior	Walls	Concrete	N/A	N/A	N/A	N/A	N/A	
P-001	Parking Lower Level	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
P-001	Parking Lower Level	Walls	Concrete	N/A	N/A	N/A	N/A	N/A	
P-001	Parking Lower Level	Ceiling	Not Found	N/A	N/A	N/A	N/A	N/A	
P-001	Parking Lower Level	Pipe	Uninsulated	N/A	N/A	N/A	N/A	N/A	
P-001	Parking Lower Level	Pipe	Fibreglass	N/A	N/A	N/A	N/A	N/A	
P-002	Mechanical Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
P-002	Mechanical Room	Walls	Concrete	N/A	N/A	N/A	N/A	N/A	
P-002	Mechanical Room	Ceiling	Not Found	N/A	N/A	N/A	N/A	N/A	
P-002	Mechanical Room	Pipe	Fibreglass	N/A	N/A	N/A	N/A	N/A	
P-003	Parking Upper Level	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
P-003	Parking Upper Level	Walls	Concrete	N/A	N/A	N/A	N/A	N/A	
P-003	Parking Upper Level	Ceiling	Not Found	N/A	N/A	N/A	N/A	N/A	

APPENDIX II-A

Asbestos Analytical Certificates (No Information to Report)


APPENDIX II-B

Lead Analytical Certificates (No Information to Report)

APPENDIX II-C

PCB Analytical Certificates (No Information to Report)

APPENDIX III
Drawings



LEGEND:

(X) PINCHIN LOCATION NUMBER

NAR NO ACCESS TO ROOM

 PRESUMED ASBESTOS-CONTAINING MATERIAL

NOT ALL KNOWN OR ASSUMED DESIGNATED SUBSTANCES ARE IDENTIFIED ON THE DRAWING. REFER TO THE DESIGNATED SUBSTANCE SURVEY REPORT FOR A COMPLETE LIST OF KNOWN AND SUSPECTED HAZARDOUS BUILDING MATERIALS.

LEGEND IS COLOUR DEPENDENT. NON-COLOUR COPIES MAY ALTER INTERPRETATION.

CLIENT:

CITY OF TORONTO

LOCATION:

TPS HEADQUARTERS,
TPS STATION 53, & PARKING GARAGE
4330 DUFFERIN STREET, TORONTO, ON

TITLE:

DESIGNATED SUBSTANCE
SURVEY
SITE PLAN

DATE:

NOVEMBER 2023

PROJECT # :

309046.002

DRAWN BY:

AQ

DRAWING:

CHECKED BY:

AG

1 OF 15

SCALE:

NTS



LEGEND:

(X) PINCHIN LOCATION NUMBER

NAR NO ACCESS TO ROOM

 PRESUMED ASBESTOS-CONTAINING MATERIAL

NOT ALL KNOWN OR ASSUMED DESIGNATED SUBSTANCES ARE IDENTIFIED ON THE DRAWING. REFER TO THE DESIGNATED SUBSTANCE SURVEY REPORT FOR A COMPLETE LIST OF KNOWN AND SUSPECTED HAZARDOUS BUILDING MATERIALS.

LEGEND IS COLOUR DEPENDENT. NON-COLOUR COPIES MAY ALTER INTERPRETATION.

CLIENT:

CITY OF TORONTO

LOCATION:

TPS HEADQUARTERS,
TPS STATION 53, & PARKING GARAGE
4330 DUFFERIN STREET, TORONTO, ON

TITLE:

DESIGNATED SUBSTANCE
SURVEY
WEST BUILDING - GROUND FLOOR

DATE:

NOVEMBER 2023

PROJECT #:

309046.002

DRAWN BY:

AQ

DRAWING:


2 OF 15


CHECKED BY:

AG

SCALE:

NTS





LEGEND:

(X) PINCHIN LOCATION NUMBER

NAR NO ACCESS TO ROOM

PRESUMED ASBESTOS-CONTAINING MATERIAL

NOT ALL KNOWN OR ASSUMED DESIGNATED SUBSTANCES ARE IDENTIFIED ON THE DRAWING. REFER TO THE DESIGNATED SUBSTANCE SURVEY REPORT FOR A COMPLETE LIST OF KNOWN AND SUSPECTED HAZARDOUS BUILDING MATERIALS.

LEGEND IS COLOUR DEPENDENT. NON-COLOUR COPIES MAY ALTER INTERPRETATION.

CLIENT:

CITY OF TORONTO

LOCATION:

TPS HEADQUARTERS,
TPS STATION 53, & PARKING GARAGE
4330 DUFFERIN STREET, TORONTO, ON

TITLE:

DESIGNATED SUBSTANCE
SURVEY
WEST BUILDING - 2ND FLOOR

DATE:

NOVEMBER 2023

PROJECT # :

309046.002

DRAWN BY:

AQ

DRAWING:


CHECKED BY:

AG

3 OF 15

SCALE:

NTS



LEGEND:

(X) PINCHIN LOCATION NUMBER

NAR NO ACCESS TO ROOM

PRESUMED ASBESTOS-CONTAINING MATERIAL

NOT ALL KNOWN OR ASSUMED DESIGNATED SUBSTANCES ARE IDENTIFIED ON THE DRAWING. REFER TO THE DESIGNATED SUBSTANCE SURVEY REPORT FOR A COMPLETE LIST OF KNOWN AND SUSPECTED HAZARDOUS BUILDING MATERIALS.

LEGEND IS COLOUR DEPENDENT. NON-COLOUR COPIES MAY ALTER INTERPRETATION.

CLIENT:

CITY OF TORONTO

LOCATION:

TPS HEADQUARTERS,
TPS STATION 53, & PARKING GARAGE
4330 DUFFERIN STREET, TORONTO, ON

TITLE:

DESIGNATED SUBSTANCE
SURVEY
CENTRE BUILDING - GROUND FLOOR

DATE:

NOVEMBER 2023

PROJECT # :

309046.002

DRAWN BY:

AQ

DRAWING:


4 OF 15

CHECKED BY:

AG

SCALE:

NTS



LEGEND:

(X) PINCHIN LOCATION NUMBER

NAR NO ACCESS TO ROOM

 PRESUMED ASBESTOS-CONTAINING MATERIAL

NOT ALL KNOWN OR ASSUMED DESIGNATED SUBSTANCES ARE IDENTIFIED ON THE DRAWING. REFER TO THE DESIGNATED SUBSTANCE SURVEY REPORT FOR A COMPLETE LIST OF KNOWN AND SUSPECTED HAZARDOUS BUILDING MATERIALS.

LEGEND IS COLOUR DEPENDENT. NON-COLOUR COPIES MAY ALTER INTERPRETATION.

CLIENT:

CITY OF TORONTO

LOCATION:

TPS HEADQUARTERS,
TPS STATION 53, & PARKING GARAGE
4330 DUFFERIN STREET, TORONTO, ON

TITLE:

DESIGNATED SUBSTANCE
SURVEY
CENTRE BUILDING - 2ND FLOOR

DATE:

NOVEMBER 2023

PROJECT # :

309046.002

DRAWN BY:

AQ

DRAWING:


CHECKED BY:

AG

5 OF 15

SCALE:

NTS



LEGEND:

(X) PINCHIN LOCATION NUMBER

NAR NO ACCESS TO ROOM

 PRESUMED ASBESTOS-CONTAINING MATERIAL

NOT ALL KNOWN OR ASSUMED DESIGNATED SUBSTANCES ARE IDENTIFIED ON THE DRAWING. REFER TO THE DESIGNATED SUBSTANCE SURVEY REPORT FOR A COMPLETE LIST OF KNOWN AND SUSPECTED HAZARDOUS BUILDING MATERIALS.

LEGEND IS COLOUR DEPENDENT. NON-COLOUR COPIES MAY ALTER INTERPRETATION.

CLIENT:

CITY OF TORONTO

LOCATION:

TPS HEADQUARTERS,
TPS STATION 53, & PARKING GARAGE
4330 DUFFERIN STREET, TORONTO, ON

TITLE:

DESIGNATED SUBSTANCE
SURVEY
CENTRE BUILDING - 3RD FLOOR

DATE:

NOVEMBER 2023

PROJECT # :

309046.002

DRAWN BY:

AQ

DRAWING:

CHECKED BY:

AG

6 OF 15

SCALE:

NTS



LEGEND:

(X) PINCHIN LOCATION NUMBER

NAR NO ACCESS TO ROOM

 PRESUMED ASBESTOS-CONTAINING MATERIAL

NOT ALL KNOWN OR ASSUMED DESIGNATED SUBSTANCES ARE IDENTIFIED ON THE DRAWING. REFER TO THE DESIGNATED SUBSTANCE SURVEY REPORT FOR A COMPLETE LIST OF KNOWN AND SUSPECTED HAZARDOUS BUILDING MATERIALS.

LEGEND IS COLOUR DEPENDENT. NON-COLOUR COPIES MAY ALTER INTERPRETATION.

CLIENT:

CITY OF TORONTO

LOCATION:

TPS HEADQUARTERS,
TPS STATION 53, & PARKING GARAGE
4330 DUFFERIN STREET, TORONTO, ON

TITLE:

DESIGNATED SUBSTANCE
SURVEY
NORTH BUILDING - GROUND FLOOR

DATE:

NOVEMBER 2023

PROJECT # :

309046.002

DRAWN BY:

AQ

DRAWING:


CHECKED BY:

AG

7 OF 15

SCALE:

NTS





LEGEND:

(X) PINCHIN LOCATION NUMBER

NAR NO ACCESS TO ROOM

 PRESUMED ASBESTOS-CONTAINING MATERIAL

NOT ALL KNOWN OR ASSUMED DESIGNATED SUBSTANCES ARE IDENTIFIED ON THE DRAWING. REFER TO THE DESIGNATED SUBSTANCE SURVEY REPORT FOR A COMPLETE LIST OF KNOWN AND SUSPECTED HAZARDOUS BUILDING MATERIALS.

LEGEND IS COLOUR DEPENDENT. NON-COLOUR COPIES MAY ALTER INTERPRETATION.

CLIENT:

CITY OF TORONTO

LOCATION:

TPS HEADQUARTERS,
TPS STATION 53, & PARKING GARAGE
4330 DUFFERIN STREET, TORONTO, ON

TITLE:

DESIGNATED SUBSTANCE
SURVEY
NORTH BUILDING - 2ND FLOOR

DATE:

NOVEMBER 2023

PROJECT # :

309046.002

DRAWN BY:

AQ

DRAWING:


CHECKED BY:


AG

8 OF 15

SCALE:

NTS





LEGEND:

(X) PINCHIN LOCATION NUMBER

NAR NO ACCESS TO ROOM

 PRESUMED ASBESTOS-CONTAINING MATERIAL

NOT ALL KNOWN OR ASSUMED DESIGNATED SUBSTANCES ARE IDENTIFIED ON THE DRAWING. REFER TO THE DESIGNATED SUBSTANCE SURVEY REPORT FOR A COMPLETE LIST OF KNOWN AND SUSPECTED HAZARDOUS BUILDING MATERIALS.

LEGEND IS COLOUR DEPENDENT. NON-COLOUR COPIES MAY ALTER INTERPRETATION.

CLIENT:

CITY OF TORONTO

LOCATION:

TPS HEADQUARTERS,
TPS STATION 53, & PARKING GARAGE
4330 DUFFERIN STREET, TORONTO, ON

TITLE:

DESIGNATED SUBSTANCE
SURVEY
SOUTH BUILDING - BASEMENT

DATE:

NOVEMBER 2023

PROJECT # :

309046.002

DRAWN BY:

AQ

DRAWING:


CHECKED BY:

AG

9 OF 15

SCALE:

NTS



LEGEND:

(X) PINCHIN LOCATION NUMBER

NAR NO ACCESS TO ROOM

 PRESUMED ASBESTOS-CONTAINING MATERIAL

NOT ALL KNOWN OR ASSUMED DESIGNATED SUBSTANCES ARE IDENTIFIED ON THE DRAWING. REFER TO THE DESIGNATED SUBSTANCE SURVEY REPORT FOR A COMPLETE LIST OF KNOWN AND SUSPECTED HAZARDOUS BUILDING MATERIALS.

LEGEND IS COLOUR DEPENDENT. NON-COLOUR COPIES MAY ALTER INTERPRETATION.

CLIENT:

CITY OF TORONTO

LOCATION:

TPS HEADQUARTERS,
TPS STATION 53, & PARKING GARAGE
4330 DUFFERIN STREET, TORONTO, ON

TITLE:

DESIGNATED SUBSTANCE
SURVEY
SOUTH BUILDING - GROUND FLOOR

DATE:

NOVEMBER 2023

PROJECT # :

309046.002

DRAWN BY:

AQ

DRAWING:


10 OF 15

CHECKED BY:

AG

SCALE:

NTS



LEGEND:

(X) PINCHIN LOCATION NUMBER

NAR NO ACCESS TO ROOM

 PRESUMED ASBESTOS-CONTAINING MATERIAL

NOT ALL KNOWN OR ASSUMED DESIGNATED SUBSTANCES ARE IDENTIFIED ON THE DRAWING. REFER TO THE DESIGNATED SUBSTANCE SURVEY REPORT FOR A COMPLETE LIST OF KNOWN AND SUSPECTED HAZARDOUS BUILDING MATERIALS.

LEGEND IS COLOUR DEPENDENT. NON-COLOUR COPIES MAY ALTER INTERPRETATION.

CLIENT:

CITY OF TORONTO

LOCATION:

TPS HEADQUARTERS,
TPS STATION 53, & PARKING GARAGE
4330 DUFFERIN STREET, TORONTO, ON

TITLE:

DESIGNATED SUBSTANCE
SURVEY
SOUTH BUILDING - 2ND FLOOR

DATE:

NOVEMBER 2023

PROJECT # :

309046.002

DRAWN BY:

AQ

DRAWING:


CHECKED BY:

AG

11 OF 15

SCALE:

NTS



LEGEND:

(X) PINCHIN LOCATION NUMBER

NAR NO ACCESS TO ROOM

 PRESUMED ASBESTOS-CONTAINING MATERIAL

NOT ALL KNOWN OR ASSUMED DESIGNATED SUBSTANCES ARE IDENTIFIED ON THE DRAWING. REFER TO THE DESIGNATED SUBSTANCE SURVEY REPORT FOR A COMPLETE LIST OF KNOWN AND SUSPECTED HAZARDOUS BUILDING MATERIALS.

LEGEND IS COLOUR DEPENDENT. NON-COLOUR COPIES MAY ALTER INTERPRETATION.

CLIENT:

CITY OF TORONTO

LOCATION:

TPS HEADQUARTERS,
TPS STATION 53, & PARKING GARAGE
4330 DUFFERIN STREET, TORONTO, ON

TITLE:

DESIGNATED SUBSTANCE
SURVEY
SOUTH BUILDING - 3RD FLOOR

DATE:

NOVEMBER 2023

PROJECT # :

309046.002

DRAWN BY:

AQ

DRAWING:



CHECKED BY:

AG

12 OF 15

SCALE:

NTS



LEGEND:

(X) PINCHIN LOCATION NUMBER

NAR NO ACCESS TO ROOM

 PRESUMED ASBESTOS-CONTAINING MATERIAL

NOT ALL KNOWN OR ASSUMED DESIGNATED SUBSTANCES ARE IDENTIFIED ON THE DRAWING. REFER TO THE DESIGNATED SUBSTANCE SURVEY REPORT FOR A COMPLETE LIST OF KNOWN AND SUSPECTED HAZARDOUS BUILDING MATERIALS.

LEGEND IS COLOUR DEPENDENT. NON-COLOUR COPIES MAY ALTER INTERPRETATION.

CLIENT:

CITY OF TORONTO

LOCATION:

TPS HEADQUARTERS,
TPS STATION 53, & PARKING GARAGE
4330 DUFFERIN STREET, TORONTO, ON

TITLE:

DESIGNATED SUBSTANCE
SURVEY
SOUTH BUILDING - PENTHOUSE

DATE:

NOVEMBER 2023

PROJECT # :

309046.002

DRAWN BY:

AQ

DRAWING:

CHECKED BY:

AG

13 OF 15

SCALE:

NTS



LEGEND:

(X) PINCHIN LOCATION NUMBER

NAR NO ACCESS TO ROOM

 PRESUMED ASBESTOS-CONTAINING MATERIAL

NOT ALL KNOWN OR ASSUMED DESIGNATED SUBSTANCES ARE IDENTIFIED ON THE DRAWING. REFER TO THE DESIGNATED SUBSTANCE SURVEY REPORT FOR A COMPLETE LIST OF KNOWN AND SUSPECTED HAZARDOUS BUILDING MATERIALS.

LEGEND IS COLOUR DEPENDENT. NON-COLOUR COPIES MAY ALTER INTERPRETATION.

CLIENT:

CITY OF TORONTO

LOCATION:

TPS HEADQUARTERS,
TPS STATION 53, & PARKING GARAGE
4330 DUFFERIN STREET, TORONTO, ON

TITLE:

DESIGNATED SUBSTANCE
SURVEY
PARKING STRUCTURE - UPPER LEVEL

DATE:

NOVEMBER 2023

PROJECT # :

309046.002

DRAWN BY:

AQ

DRAWING:


CHECKED BY:

AG

14 OF 15

SCALE:

NTS





LEGEND:

(X) PINCHIN LOCATION NUMBER

NAR NO ACCESS TO ROOM

 PRESUMED ASBESTOS-CONTAINING MATERIAL

NOT ALL KNOWN OR ASSUMED DESIGNATED SUBSTANCES ARE IDENTIFIED ON THE DRAWING. REFER TO THE DESIGNATED SUBSTANCE SURVEY REPORT FOR A COMPLETE LIST OF KNOWN AND SUSPECTED HAZARDOUS BUILDING MATERIALS.

LEGEND IS COLOUR DEPENDENT. NON-COLOUR COPIES MAY ALTER INTERPRETATION.

CLIENT:

CITY OF TORONTO

LOCATION:

TPS HEADQUARTERS,
TPS STATION 53, & PARKING GARAGE
4330 DUFFERIN STREET, TORONTO, ON

TITLE:

DESIGNATED SUBSTANCE
SURVEY
PARKING STRUCTURE - LOWER LEVEL

DATE:

NOVEMBER 2023

PROJECT # :

309046.002

DRAWN BY:

AQ

DRAWING:


CHECKED BY:

AG

15 OF 15

SCALE:

NTS



APPENDIX IV
Methodology

1.0 GENERAL

The following survey methodology is based on the requirements of the *Standard Operation Procedure for Designated Substance Surveys*, dated April, 2014, provided by the City of Toronto (the “SOP”).

Pinchin conducted a room-by-room survey (rooms, corridors, service areas, exterior, etc.) to identify the hazardous building materials as defined in Section 1.1. Information regarding the approximate quantity, location, and condition of hazardous building materials encountered and visually estimated quantities were recorded on the *Survey Form*, provided by the City of Toronto, found in Appendix IV. The locations of any samples collected were recorded on small-scale plans, found in Appendix I.

Drawings (i.e., floor plans), previous reports, and Survey Forms, were referenced where provided.

1.1 Limitations on Scope

The survey excludes the following:

- Owner or occupant articles (e.g. stored items, furniture, appliances, etc.);
- Underground materials or equipment (e.g. vessels, drums, underground storage tanks, pipes, etc.);
- Building envelope, structural components, inaccessible or concealed materials or other items where sampling may cause consequential damage to the property.
- Energized systems (e.g. internal boiler components, elevators, mechanical or electrical components);
- Controlled products (e.g. stored chemicals, operational or process-related substances); and
- Materials not typically associated with construction (e.g. settled dust, spills, residual contamination from prior spills, etc.).

The survey was limited to non-intrusive testing. Concealed spaces such as those above solid ceilings and within shafts and pipe chases were accessed via existing access panels only. Pinchin did not conduct demolition of walls, solid ceilings, structural items, interior finishes or exterior building finishes, to determine the presence of concealed materials.

1.2 Asbestos

Pinchin conducted an inspection for the presence of friable and non-friable asbestos-containing materials (ACM). A friable material is a material that when dry can be crumbled, pulverized or powdered by hand pressure.



Pinchin collected samples at a rate that is in compliance with Table 1 of O.Reg. 278/05. A separate set of samples was collected of each of homogenous material sampled. A homogenous material is defined by the US EPA¹ as material that is uniform in texture and appearance, was installed at one time, and is unlikely to consist of more than one type or formulation of material. The homogeneous materials are determined by visual examination, available information on the phases of the construction and prior renovations.

The following materials were sampled:

- All friable materials historically known to contain asbestos, regardless of year of installation, not identified in previous reports;
- Friable materials previously sampled in insufficient quantity to conclude the materials are non-asbestos, in accordance with the requirements of O.Reg. 278/05;
- Friable materials previously reported to contain less than 1% asbestos, if sampled prior to the Ministry of Labour defining an asbestos-containing material as a material containing contains 0.5 percent or more asbestos by weight;
- Non-friable acoustic ceiling tiles;
- Non-friable vinyl floor tiles and mastic.

The following materials were **not** sampled:

- Materials previously identified in previous reports provided as asbestos-containing;
- Materials previously confirmed to be non-asbestos in accordance with O.Reg. 278/05;
- Unless damaged the following materials were not sampled: plaster, drywall joint compound, mastic, window caulking, roofing materials, vinyl sheet flooring. Materials not sampled are assumed to contain asbestos.
- Materials where sampling poses an inherent, imminent danger to the Assessor such as high voltage wiring, materials present at heights greater than 12 feet, or those in confined spaces. These materials are assumed to be asbestos-containing.

In some cases, manufactured products such as asbestos cement pipe are visually identified without sample confirmation.

¹ Environmental Protection Agency

Pinchin submits the bulk samples to a NVLAP² accredited laboratory for analysis. The analysis is performed in accordance with Test Method EPA/600/R-93/116: Method for the Determination of Asbestos in Bulk Building Materials, July 1993.

The asbestos analysis is completed using a stop positive approach. Only one result of greater than the regulated criteria (0.5%) is required to determine that a material is asbestos-containing, but all samples must be analyzed to conclusively determine that a material is non-asbestos. The laboratory stops analyzing samples from a homogeneous material once a result greater than the regulated criteria is detected in any of the samples of that material. All samples of a homogeneous material are analyzed if no asbestos is detected. In some cases, all samples are analyzed in the sample set regardless of result. Where building materials are described in the report as non-asbestos, or described as containing no asbestos, this is subject to the limitations of the analytical method used, and should be understood to mean no asbestos was detected.

Asbestos materials are evaluated in order to make recommendations regarding remedial work. The priority for remedial action is based on several factors:

- Friability (friable or non-friable).
- Condition (good, fair, poor, debris, based on definitions in the SOP).
- Accessibility (ranking from accessible to all building users to inaccessible).
- Visibility (whether the material is obscured by other building components).
- Efficiency of the work (for example, if damaged ACM is being removed in an area, it may be most practical to remove all ACM in the area even if it is in good condition).

This includes friability, condition and efficiency and practicality of the work.

1.3 Lead

Pinchin collected samples of damaged paint not identified in a previous report. Drawings included show sample locations.

Analysis for lead in paints or surface coatings is performed in accordance with EPA Method No. 3050B/Method No. 7420; flame atomic absorption at an accredited laboratory.

For this report, all paints containing lead at a concentration 0.1% or greater are discussed. Paint was evaluated for condition.

Lead building products (e.g. batteries, lead sheeting, flashing) are identified by visual observation only.

² National Voluntary Laboratory Accreditation Program

1.4 Silica

Pinchin identifies building materials suspected of containing crystalline silica (e.g. concrete, cement, tile, brick, masonry, mortar) by knowledge of current and historic applications and visual inspection only. Pinchin does not perform sampling of these materials for laboratory analysis of crystalline silica content.

1.5 Mercury

Building materials/products/equipment (e.g. thermostats, barometers, pressure gauges, light tubes), suspected to contain mercury were identified by visual inspection only. Dismantling of equipment suspected of containing mercury was not performed. Sampling of these materials for laboratory analysis of mercury content was not performed.

Mercury spills or damaged mercury-containing equipment was recorded where observed.

1.6 Polychlorinated Biphenyls

Pinchin determines the potential for light ballast and wet transformers to contain PCBs based on the age of the building, a review of maintenance records and examination of labels or nameplates on equipment, where present and accessible. The information is compared to known ban dates of PCBs and Environment Canada publications.

Dry type transformers are assumed to be free of dielectric fluids and hence non-PCB.

Pinchin records spills or leakage of suspect PCB-containing fluids where observed.

Fluids (mineral oil, hydraulic or Askaral) in transformers or other equipment are not sampled for PCB content.

Non-liquid forms of PCBs (i.e. sealants or caulking) are not sampled for PCB content.

1.7 Visible Mould

Pinchin identifies the presence of mould if visibly present in a significant quantity on exposed building surfaces. If any mould growth is concealed within wall cavities it is not addressed in this survey.

APPENDIX V

Corrective Action Inspection Report (No Information to Report)