#### PART 1 GENERAL

# 1.1 General and Related Work

- .1 Read this Section in conjunction with all drawings and all other Sections so as to comply with the requirements of Division 1 and the General Conditions of the Contract.
- .2 Related work specified elsewhere:

Section 02 82 00.01 Asbestos Abatement – Type 1 Procedures

Section 02 82 00.02 Asbestos Abatement – Type 2 Procedures

- .3 Site Conditions identifies all known hazardous building materials within the Project Area. The information provided is for general reference only. Each Contractor must confirm existing conditions on site prior to tender close:
  - .1 The specification fulfils the requirements of Section 30 of the Ontario Occupational Health and Safety Act.
  - .2 The specification fulfils the requirements of the Section 10 of Ontario Regulation 278/05.
- .4 The Outline of Work identifies the locations of hazardous building materials to be removed as part of this project:
  - .1 It is the intent that work prescribed this Section will result in the removal of all hazardous materials as outlined and the decontamination of all surfaces or materials which may have been or become contaminated by hazardous materials either during or prior to work of this Contract.

#### 1.2 Site Conditions

- .1 Refer to the report entitled "'Hazardous Building Materials Assessment (Pre-Construction) Roof Sections A, B, C, D, E and Specified Interior Areas", dated December 16, 2024, prepared by Pinchin Ltd., file number 348218.007.
- .2 Refer to Drawings HR-01 through HR-03 for the locations of identified hazardous materials.
- .3 Asbestos:
  - .1 The following materials have been confirmed to contain asbestos:
    - .1 Black tar present on deck, below gypsum board, where gypsum board is present on the deck of Roof sections B and C, containing chrysotile asbestos. The associated gypsum layer is to be treated as asbestos due to contamination from the tar.
    - .2 Drywall with drywall joint compound, containing chrysotile asbestos, is present as wall finishes in the following locations:
      - .1 Corridor 101H (Location 100)

- .2 Corridor 103H (Location 102)
- .3 Paint/primer, containing chrysotile asbestos, is present on masonry block walls, in the following locations:
  - .1 Kitchen K05 (Location 97)
  - .2 Office K05A (Location 98)
  - .3 Storage K04 (Location 99)
  - .4 Serving Corridor 101H (Location 100)
  - .5 Corridor 103H (Location 102)
  - .6 Cafeteria K02 (Location 103)
  - .7 Storage 100-0(Location 104)
  - .8 Storage 103A (Location 105)
  - .9 Mechanical Room K03 (Location 186)
  - .10 Staff Room K01 (Location 190)
  - .11 Dishwashing (Location 201)
- .4 9"x9" Blue and White Streak Vinyl Floor Tile, containing Chrysotile asbestos, is present in the following locations:
  - .1 Storage Room 100-0 (Location 104)
- .5 Texture finish on asbestos cement (transite) panels (both containing asbestos) on soffits throughout the exterior of the building.
- .2 The following materials have been presumed to contain asbestos:
  - .1 Terrazzo flooring in the following areas:
    - .1 Kitchen K05 (Location 97)
    - .2 Office K05A (Location 98)
    - .3 Storage K04 (Location 99)
    - .4 Serving Corridor 101H (Location 100)
    - .5 Dishwashing (Location 201)
- .4 Lead:
- .1 Any paints present on metal flashing are well adhered paints and can be disposed of as regular construction waste.
- .2 The following paint finishes have been confirmed to be lead-based (>0.5%):
  - .1 Black paint on exterior metal siding on the rooftop mechanical room:
- .3 The following building materials are presumed, or have been confirmed, to contain lead:
  - .1 Solid batteries in Emergency Lighting
- .5 Mercury:
  - .1 The following building materials are presumed; or have been confirmed to contain mercury:
    - .1 Fluorescent lamp tubes in light fixtures.
- .6 Silica:
  - .1 The following building materials are presumed, or have been confirmed, to contain silica:
    - .1 Brick masonry and mortar.
    - .2 Precast concrete deck

- .3 Gravel roof ballast
- .4 Siporex roof deck
- .7 Polychlorinated Biphenyls:
  - .1 PCB containing materials are not suspected to be present.
- .8 Mould:
  - .1 Mould growth was not observed during the assessment.
- .9 Remaining designated substances including arsenic, acrylonitrile, benzene, coke oven emissions, ethylene oxide, isocyanates, vinyl chloride monomer, are not typically found in building materials in a composition/state that is hazardous and are not presumed to be present within the Work Areas.

#### 1.3 Outline of Work

- .1 Coordinate the following items with the Owner's Project Manager and the Construction Manager, including but not limited to: electrical isolations, GFI connection, water connections, HVAC and exhaust ventilation system isolation (where required), bin placement, schedule, disconnects, etc.
- .2 Refer to the Contract Drawings prepared by Barry Bryan Associates (BBA) for the extent of construction work and the Work Areas.
- .3 Refer to Drawings HR-01 through HR-03 for the extent of the Abatement Work Areas.
- .4 Remove and dispose of the following materials as clean waste prior to hazardous materials abatement work without disturbing asbestos-containing materials:
  - .1 Remove 4-ply roof felt, fibreboard and fibreglass insulation as clean waste from roof sections B and C. Do not impact the Mopped organic felt and tar layer, or any materials below.
  - .2 Maximize waste diversion by use of recycling.
- .5 Using procedures prescribed in the Sections identified in Related Work, remove and dispose of the following using Type 1 procedures as marked by the General Contractor:
  - .1 Approximately 7,500 square feet of asbestos-containing tar, tar contaminated gypsum board and adjacent felt layer from roof sections B and C.
- .6 Using procedures prescribed in the Section identified in Related Work, perform the following using Type 2 procedures as marked by the General Contractor:
  - .1 Removal and/or installation of affixed items to masonry block walls with asbestos containing paint/primer, where required, using power tools equipped with a HEPA vacuum with shroud in the following locations:
    - .1 Kitchen K05 (Location 97)
    - .2 Office K05A (Location 98)

- .3 Storage K04 (Location 99)
- .4 Serving Corridor 101H (Location 100)
- .5 Corridor 103H (Location 102)
- .6 Cafeteria K02 (Location 103)
- .7 Storage 100-0 (Location 104)
- .8 Storage 103A (Location 105)
- .9 Mechanical Room K03 (Location 186)
- .10 Staff Room K01 (Location 190)
- .11 Dishwashing (Location 201)
- .2 Removal and/or installation of affixed items, and repair of drywall walls with asbestos containing drywall joint compound, where required, using power tools equipped with a HEPA vacuum with shroud in the following areas:
  - .1 Serving Corridor 101H (Location 100)
  - .2 Corridor 103H (Location 102)
- .7 Where lead-based paint has the potential to be disturbed, the paint should be removed following procedures detailed in the document titled *Lead on Construction Projects*, prepared by the Ministry of Labour, Immigration, Training and Skills Development.
- .8 Items painted with paints containing elevated levels of lead may be a hazardous waste. Test lead-painted materials for leachable lead and other metals prior to disposal. Metallic components coated with lead paint do not require leachate testing and can be disposed of as non-hazardous construction and demolition waste.
- .9 Visit the site prior to tender close to confirm the location and extent of any hazardous building materials or materials contaminated by hazardous materials.
- .10 Protect surfaces, building fabrics and items remaining within the Abatement Work Area.
- .11 Isolate the Abatement Work Area from adjoining Occupied and Non-Occupied Areas whether present at an interior or exterior location.
- .12 Maintain emergency and fire exits from Abatement Work Area, or establish alternative exits satisfactory to Provincial Fire Marshall and local authorities having jurisdiction. Maintain extra routes from occupied areas. Place emergency exit signs at locations to clearly mark exit route. Seal emergency exit doors so as not to impede use of door during emergency evacuation.
- .13 Remove and dispose of as appropriate waste, building components, materials and items contaminated by hazardous materials that cannot be effectively cleaned.
- .14 Final clean work area to remove visible signs of asbestos and other hazardous materials, other debris or settled dust.
- Apply lock-down agent to exposed surfaces throughout the work area and to surfaces from which any hazardous materials have been removed:
  - .1 Do not apply lock-down to materials which would be damaged by its application.

.16 Unless otherwise specified, the handling, removal, clean-up or repair of hazardous materials or surfaces contaminated with hazardous materials is to be performed following wet removal techniques.

#### 1.4 Schedule

- .1 Provide necessary manpower, supervision, equipment and materials to maintain and complete the project on schedule.
- .2 Work Hours:
  - .1 Coordinate all work, scheduling and phasing with the Owner.
- .3 Provide 48 hours written notice to the Abatement Consultant of any request to work outside normal working hours. Obtain written approval before proceeding.

#### 1.5 Definitions

- .1 <u>Abatement Consultant:</u> Owner's Representative providing site reviews and air monitoring.
- .2 <u>Abatement Contractor:</u> Contractor or sub-contractor performing work of this section.
- .3 <u>Abatement Work Area</u>: Area where work takes place which will, or may, disturb hazardous materials.
- .4 <u>Amended Water</u>: Water with wetting agent added for the purpose of reducing surface tension to allow thorough wetting of materials.
- .5 <u>Asbestos:</u> Any of the fibrous silicates defined in Regulation 278/05 including: actinolite, amosite, anthophyllite, chrysotile, crocidolite and tremolite.
- .6 <u>Asbestos-Containing Material (ACM)</u>: Material identified under Site Conditions including any debris, overspray, fallen material and settled dust.
- .7 <u>Authorized Visitors</u>: Building Owner, Abatement Consultant, or designated representative, and persons representing regulatory agencies.
- .8 <u>Competent Worker:</u> A worker who is qualified because of knowledge, training and experience to perform the work, is familiar with Regulation 278/05 and the Occupational Health and Safety Act, and has knowledge of the potential or actual danger to health and safety in the work.
- .9 <u>Contaminated Waste</u>: Material identified under Site Conditions, including fallen material, settled dust, other debris and materials or equipment deemed to be contaminated by the Abatement Consultant.

- .10 <u>DOP Test</u>: A testing method used to determine the integrity of the Negative Pressure unit or vacuum using a Dispersed Oil Particulate (DOP) or Poly Alpha Olefin (PAO) HEPA filter leak test. This test is to be conducted on site where units are to be installed. Refer to the Environmental Abatement Council of Ontario (EACO) DOP/PAO Testing Guideline 2013 or ANSI/ASME N510-2007.
- .11 <u>Friable Material</u>: Material that when dry can be crumbled, pulverized or powdered by hand pressure and includes such material that is crumbled, pulverized or powdered.
- .12 <u>HEPA:</u> High Efficiency Particulate Aerosol filter that is at least 99.97 percent efficient in collecting a 0.3 micrometre aerosol.
- .13 <u>Milestone Review</u>: Review of the Abatement Work Area at a defined point in the abatement operation.
- .14 <u>Non-Friable Material</u>: Material that when dry cannot be crumbled, pulverized or powdered by hand pressure.
- .15 Occupied Area: Any area of the building or adjoining space outside the Abatement Work Area.
- .16 <u>Personnel:</u> All Contractor's employees, sub-contractors employees, supervisors.
- .17 <u>PCBs:</u> Monochlorinated or Polychlorinated Biphenyls (or any mixture of both).
- .18 <u>PCB Material:</u> means solid material containing PCBs at a concentration of more than fifty milligrams per kilogram (mg/kg) or 50 parts per million (ppm), or liquid with greater than 2 mg/kg or ppm.
- .19 <u>Remove:</u> Remove means remove and dispose of (as applicable type of waste) unless followed by other instruction (e.g. remove and turn over to Owner).

# 1.6 Regulations and Guidelines

- .1 Comply with Federal, Provincial, and local requirements, provided that in any case of conflict among those requirements or with these Specifications, the more stringent requirements shall apply. Work shall be performed under regulations in effect at the time work is performed.
- .2 Where regulations are not present, follow accepted industry standards and applicable Guideline documents.
- .3 Regulations and Guidelines include but are not limited to the following:
  - .1 Ministry of Labour Occupational Health and Safety Act Regulations for Construction Projects including Revised Statutes of Ontario 1990, Chapter 0.1 and Ontario Regulation 278/05.
  - .2 Ministry of the Environment and Climate Change Regulation for the disposal of waste, including R.R.O. 1990, Reg. 347 as amended.

- .3 PCB Regulations, SOR 2008-273 and R.R.O. 1990, Reg 362.
- .4 Regulation 490/09 Designated Substances.
- .5 Environmental Abatement Council of Ontario (EACO), Lead Guideline For Construction, Renovation, Maintenance or Repair, October 2014.
- .6 Ministry of Labour, Guideline, Silica on Construction Projects, 2011.

# 1.7 Quality Assurance

- .1 Removal and handling of hazardous materials is to be performed by persons trained in the methods, procedures and industry practices for Abatement.
- .2 Ensure work proceeds to schedule, meeting all requirements of this Specification.
- .3 Complete work so that at no time airborne dust, visible debris, or water runoff contaminate areas outside the Abatement Work Area.
- Any contamination of surrounding area (indicated by visual review or air monitoring) shall necessitate the clean-up of affected area, and in the same manner applicable to an Abatement Work Area at no cost to the Owner.
- .5 All work involving electrical, mechanical, carpentry, glazing, etc., shall be performed by licensed persons experienced and qualified for the work required.

# 1.8 Supervision

- .1 Provide on site for each work shift, a Shift Superintendent(s), who has authority regarding all aspects related to manpower, equipment and production.
- .2 Supervisory personnel must hold a recognized certificate proving attendance at an asbestos removal training course (2 day minimum duration) and have performed supervisory functions on at least five (5) other asbestos abatement projects of similar size and complexity.
- .3 At all times during work, the Overall or Shift Superintendent(s) must be on site. Failure to comply with this requirement will result in a stoppage of all work, at no cost to the Owner.
- .4 Replace supervisory personnel, with approved replacements, within three (3) working days of a written request from the Owner. Owner reserves the right to request replacement of supervisory personnel without explanation.
- .5 Do not replace supervisory personnel without written approval from the Owner.

# 1.9 Instruction and Training

.1 Instruction and training must be provided by a competent person.

.2 All workers completing Type 1 and Type 2 asbestos abatement must be trained in compliance with Section 19 of O. Reg. 278/05.

# 1.10 Notification

- .1 Before commencing work, notify orally and in writing, an inspector at the office of the Ontario Ministry of Labour nearest the project site, where required.
- .2 Inform all trades on site of the presence and location of hazardous materials identified in the Contract documents.
- .3 Notify the Owner or Owner's Representative, the Joint Occupational Health and Safety Committee and the Provincial Ministry of Labour, if suspected asbestos-containing materials not identified in the contract documents are discovered during the course of the work. Stop work in these areas immediately.
- .4 Notify Sanitary Landfill site as per O.Reg. 347/90 as amended.

#### 1.11 Submittals

- .1 Submit to client prior to starting work:
  - .1 Provincial Workers' Compensation Board Clearance Certificate.
  - .2 Insurance certificates.
  - .3 Copy of Company Health and Safety Policy and applicable programs.
  - .4 Ministry of Labour Notice of Project form.
  - .5 Copy of Certificate of Approval for disposal of hazardous materials waste and location of landfill.
  - .6 Pre-removal damage survey of the Abatement Work Area(s), waste transport routes, and bin storage areas
- .2 Submit to client the following information regarding personnel prior to starting work:
  - .1 Where required, proof in the form of a certificate that supervisory personnel have been certified as supervisors under the Ministry of Training, Colleges and Universities course 253S.
  - .2 Where required, proof in the form of a certificate that supervisory personnel have attended a training course on asbestos removal or are certified as supervisors under the Ministry of Training, Colleges and Universities course 253S.
  - .3 Written statement that personnel have had instruction on hazards of exposure to hazardous materials identified within this scope, the use of respirator, protective clothing, worker and waste decontamination procedures, and all aspects of work procedures and protective measures.

- .4 WHMIS training certificates for all personnel.
- .5 Certificate proving that each worker on site has been fit tested for the respirator appropriate for the work being performed.
- .6 Proof of training for the following site-specific hazards or conditions identified:
  - .1 Working at Heights
- .3 Submit to client the following information regarding HEPA filtered devices prior to construction of enclosure or asbestos abatement:
  - .1 Performance data on HEPA filtered vacuums including DOP tests no more than 3 months old.
  - .2 Performance data on negative air units including DOP tests which must be no more than 3 months old if the unit is vented outdoors or which must be performed on site immediately prior to initial usage and when HEPA filters are changed if the unit is vented indoors.
  - .3 DOP tests to be performed by an independent testing company:
    - .1 DOP testing company is required to submit a detailed technical report of testing protocol, including Introduction, Methodology, Results, Conclusions, and Recommendations, including results of the Air-Aerosol Mixing Uniformity test as per ASME N510-1989 (1995).
    - .2 DOP testing company must also provide calibration certificates from an independent calibration firm or from the manufacturer of the testing equipment for both the aerosol photometer and the pressure gauge on the aerosol generator dated within 1 calendar year from the on-site testing date.
    - .3 DOP testing company must also provide the National Sanitation Foundation (NSF) certification name and number of the on-site technician performing the testing.
  - .4 Proof of calibration of DOP testing equipment.
- .4 Submit to client the following prior to isolating the work area:
  - .1 Safety Data Sheets for chemicals or material used in the course of the Abatement Project.
- .5 Submit to client the following upon completion of the work.
  - .1 Manifests, waybills, bills of ladings etc. as applicable for each type of waste.

#### 1.12 Insurance

- .1 Maintain a Commercial General Liability Policy with an insurance company acceptable to Pinchin Ltd. And Kawartha Pine Ridge District School Board. The intent of this policy is to hold Pinchin Ltd. and Kawartha Pine Ridge District School Board harmless as it relates to claims for Bodily Injury or Property Damage or both, relating to the contract. Commercial General Liability insurance shall be provided on an "occurrence" basis to cover injury or damage (whether detected or not during the policy period) which happens during the policy period.
- .2 Maintain an Automobile or Fleet Policy, and Non-owned Automobile Policy with an insurance company acceptable to Pinchin Ltd. And Kawartha Pine Ridge District School Board. The intent of these policies is to hold Pinchin Ltd. And Kawartha Pine Ridge District School Board harmless as it relates to claims for Bodily Injury or Property Damage or both, relating to the contract.
- .3 Maintain a Pollution Liability Policy (or asbestos/lead liability policy or specific coverage under the CGL for asbestos/lead abatement) with an insurance company acceptable to Pinchin Ltd. And Kawartha Pine Ridge District School Board. The intent of this policy is to hold Pinchin Ltd. And Kawartha Pine Ridge District School Board harmless as it relates to claims for Bodily Injury or Property Damage or both, relating to the contract. Pollution Liability shall be provided on an "occurrence" basis to cover injury or damage (whether detected or not during the policy period) which happens during the policy period. Without limiting the generality of the foregoing, the policy shall insure the operations of abatement and shall not contain any environmental and/or health hazard exclusions relating to remediation operations.
- .4 Forward all certificates to Pinchin Ltd. And Kawartha Pine Ridge District School Board before work is commenced, showing Pinchin Ltd. And Kawartha Pine Ridge District School Board as additional insured as their interest may appear.
- .5 Pinchin Ltd. And Kawartha Pine Ridge District School Board may request a certified true copy of the policies.
- .6 The limits will not be less than:

.1 Commercial General Liability \$5,000,000.00

.2 Automobile \$2,000,000.00

.3 Pollution Policy \$5,000,000.00

#### 1.13 Site Review

.1 From commencement of work until completion of clean-up operations, the Abatement Consultant is empowered by the Owner to review for compliance with the requirements of governing authorities, adherence to specified procedures and materials, and to reviewt for final cleanliness and completion.

- .2 The Abatement Consultant is empowered by the Owner to order a shutdown of work when leakage of asbestos from the controlled work area has occurred or is likely to occur.
- Any deviation from the requirements of the Specifications or governing authorities that is not approved in writing may result in a stoppage of work, at no cost to the Owner.
- .4 Additional labour or materials expended by the Contractor to rectify unsatisfactory conditions and to provide performance to the level specified shall be at no additional cost to the Owner.
- .5 Site review and air monitoring performed as a result of Contractor's failure to perform satisfactorily regarding quality, safety, or schedule, shall be back charged to the Contractor.
- .6 Facilitate review and provide access as necessary. Make good work disturbed by review and testing at no cost to the Owner.
- .7 Refer to the Sections identified in Related Work for specified milestone reviews which are to take place at defined points throughout the abatement operation specific to each phase or work area.
- .8 Provide 24 hours written notice to the Abatement Consultant of any request for scheduling of milestone reviews or transportation of waste through Occupied Areas.
- .9 The following Milestone Reviews may take place, at the Owner's cost, as outlined in each related specification section OR which will be confirmed at the initial start-up meeting:
  - .1 Milestone Review Clean Site Preparation
    - .1 Review of preparations and set-up prior to contaminated work in the Abatement Work Area.
  - .2 Milestone Review Visual Clearance
    - .1 Review of Abatement Work Area after completion of all abatement, but prior to application of lock-down agents or dismantling of enclosure.
- .10 Refer to the Sections identified in Related Work for specified milestone reviews which are to take place at defined points throughout the abatement operation specific to each phase or work area.
- Do not proceed with next phase of work until written approval of each milestone is received from the Abatement Consultant.

#### 1.14 Worker Protection

- .1 Instruct workers before allowing entry to the Abatement Work Area. Instruction shall include training in use of respirators, dress, showering, entry and exiting from an Abatement Work Area, and all other aspects of work procedures and protective measures.
- .2 Workers shall not eat, drink, chew gum or tobacco, vape or smoke in the Abatement Work Area.

- .3 Workers shall be fully protected at all times when possibility of disturbance of hazardous materials exists.
- .4 Provide soap, towels and facilities for washing of hands and face, which shall be used by all personnel when leaving the Abatement Work Area.

# .5 Respiratory Protection

- .1 Refer to each particular Section of the Specification for specified type of respiratory equipment specific to each phase or work area.
- .2 Respirators shall be:
  - .1 Certified by the National Institute of Occupational Safety and Health (NIOSH) or other testing agency acceptable to the Ministry of Labour.
  - .2 Fitted so that there is an effective seal between the respirator and the worker's face. Ensure that no person required to enter an Abatement Work Area has facial hair which affects the seal between respirator and face.
  - .3 Assigned to a worker for their exclusive use.
  - .4 Maintained in accordance with manufacturer's specifications.
  - .5 Cleaned, disinfected and inspected by a competent person after use on each shift, or more often if required.
  - .6 Repaired or have damaged or deteriorated parts replaced.
  - .7 Stored in a clean and sanitary location.
  - .8 Provided with new filters as necessary, according to manufacturer's instructions.
  - .9 Worn by personnel who have been fit checked by qualitative or quantitative fit-testing.
  - .10 Instruction on proper use of respirators must be provided by a competent person as defined by the Occupational Health and Safety Act.
- .3 Provide protective clothing, to all personnel which:
  - .1 Is made of a material that does not readily retain nor permit penetration of asbestos fibres or lead/silica dust.
  - .2 Consists of head covering and full body covering that fits snugly at the ankles, wrists and neck.
  - .3 Once coveralls are worn, treat and dispose of as contaminated waste.
  - .4 Is replaced or repaired if torn or ripped.
- .4 Use hard hats, safety footwear and other protective equipment and apparel required by applicable construction safety regulations.

#### 1.15 Visitor Protection

- .1 Provide clean protective clothing and equipment to Authorized Visitors.
- .2 Instruct Authorized Visitors in the use of protective clothing and Abatement Work Area entry and exit procedures.

- .3 Authorized visitors are required to be fit tested on respirators, prior to entering Abatement Work Area:
  - .1 Respirator worn must be compliant with Section 13 and Table 2 of O.Reg. 278/05.

# 1.16 Signage

- .1 <u>Asbestos Abatement Signs:</u> Post signs at access points to the Abatement Work Area, stating at minimum, the following:
  - .1 There is an asbestos dust hazard.
  - .2 Access to the work area is restricted to persons wearing protective clothing and equipment.
- .2 <u>Lead Abatement Signs</u>: Post signs at access points to the Abatement Work Area, stating at minimum, the following:
  - .1 There is a lead dust, fume or mist hazard.
  - .2 Access to the work area is restricted to authorized persons.
  - .3 Respirators must be worn in the work area.
- .3 <u>Vehicles, Bins and Asbestos Waste Containers:</u> Post signs on both sides of every vehicle used for the transportation of asbestos waste and on every asbestos waste container. Signs must display thereon in large, easily legible letters that contrast in colour with the background the word "CAUTION" in letters not less than ten centimetres in height and the words:
  - .1 CONTAINS ASBESTOS FIBRES
  - .2 Avoid Creating Dust and Spillage
  - .3 Asbestos May be Harmful To Your Health
  - .4 Wear Approved Protective Equipment.
- .4 Place placards in accordance with Transportation of Dangerous Goods Act.

# 1.17 Waste and Material Handling

- .1 Waste bins must be placed on grade or in receiving.
- .2 All bins for hazardous materials must be covered and locked when waste transfer is not being performed.
- .3 Ensure redundant non-ACM, rubble, debris, etc. removed during contaminated work are treated, packaged, transported and disposed of as appropriate waste.

- .4 Clean, wash and apply Post Removal Sealant to metal waste prior to removal from Abatement Work Area. Recycle metals.
- .5 Clean, wash and apply Post Removal Sealant to non-porous materials prior to disposal as clean waste. Obtain prior written approval from the Abatement Consultant for each individual type of material.
- .6 Clean and wash equipment prior to removal from Abatement Work Area if removed prior to completion.
- .7 Place all equipment, tools and unused materials that cannot be cleaned in Abatement Waste Containers.
- .8 As work progresses, and at regular intervals, transport the sealed and labelled waste containers from the Abatement Work Area to waste bin.
- .9 Place items in bins according to waste classification. Place asbestos waste, lead waste, metals, non-asbestos waste, etc. in separate bins.
- .10 Removal of waste containers and decontaminated tools and materials from the Abatement Work Area shall be performed as follows:
  - .1 Remove any visible contamination from the surface of non-porous or cleanable waste being removed from the Abatement Work Area. If the item can be cleaned, remove it from the site as clean waste.
  - .2 Place waste or item in Waste Container and seal closed.
  - .3 Wet wipe outside of Waste Container.
  - .4 Within Decontamination Facility, Transfer Room or at the perimeter of the Abatement Work Area, place in second Waste Container. Seal closed.
  - .5 Remove waste containers and transport to appropriate bin.
  - .6 Asbestos waste must not be allowed to fall from one level to the next when being transferred to the waste container.
- .11 Transport waste and materials via the predetermined routes and exits. Arrange waste transfer route with Owner. Use a closed, covered cart to transport through Occupied Areas.
- .12 Provide workers transporting waste with means to access full personal protective equipment and all tools required to properly clean up spilled material in the case of a rupture of a Waste Container.
- .13 Pick-up and drop off of garbage bin shall be at pre-approved times, and must not interfere with the Owners operations.
- .14 Transport hazardous waste to landfill or waste transfer station licensed by the provincial Ministry of the Environment.

.15 Cooperate with the provincial Ministry of the Environment inspectors and immediately carry out instructions for remedial work at dump to maintain environment, at no additional cost to the Owner.

#### PART 2 PRODUCTS AND FACILITIES

# 2.1 Materials and Equipment

- .1 Refer to the Sections identified in Related Work for specified materials, equipment or facilities specific to each phase or work area.
- .2 Materials and equipment must be in good condition and free of debris and fibrous materials. Disposable items must be of new materials only.
- .3 <u>Airless Sprayer:</u> AC powered pressure washer that allows wetting agent to mix with water, uses no air or compressed air, and has a nozzle to regulate power and pressure.
- .4 <u>Amended Water:</u> Water with wetting agent added for purpose of reducing surface tension to allow thorough wetting of materials.
- .5 <u>Asbestos Waste Container:</u> A container acceptable to disposal site, Ministry of the Environment, and Ministry of Labour, comprised of the following:
  - .1 Dust tight.
  - .2 Suitable for the type of waste.
  - .3 Impervious to asbestos.
  - .4 Identified as asbestos waste.
- .6 <u>Ground Fault Panel:</u> Electrical panel as follows:
  - .1 Ground fault circuit interrupters of sufficient capacity to power temporary electrical equipment and lights in Asbestos Work Area.
  - .2 Interrupters to have a 5 mA ground fault protection.
  - .3 Necessary accessories including main switch disconnect, ground fault interrupter lights, test switch to ensure unit is working, and reset switch.
  - .4 Openings sealed to prevent moisture or dust penetration.
  - .5 Inspected by the Electrical Safety Authority.
  - .6 Panel uses CSA approved parts and been constructed, inspected and installed by a licensed electrician.
  - .7 Provide one Ground Fault Panel for each 5,000 square feet (500 square metres) of Abatement Work Area.

- .7 <u>HEPA Vacuum</u>: Vacuum with necessary fittings, tools and attachments. Discharged air must pass through a HEPA filter.
- .8 <u>Post Removal Sealant (or Lockdown):</u> Sealant that when applied to surfaces serves the function of trapping residual asbestos fibres or other dust. Product must have flame spread and smoke development ratings both less than 50. Product shall leave no stain when dry. Post Removal Sealant shall be compatible with replacement insulation or fireproofing where required and capable of withstanding service temperature of substrate. Apply to manufacturer's instructions.
- .9 <u>Protective Clothing</u>: Disposable coveralls complete with head covering and full body covering that fits snugly at the ankles, wrists and neck.
- .10 <u>Rip-Proof Polyethylene Sheeting</u>: 8 mil (0.20 mm) fabric made up from 5 mil (0.13 mm) weave and two (2) layers of 1.5 mil (0.05 mm) poly laminate or approved equal. In sheet size to minimize on-site seams and overlaps.
- .11 <u>Sprayer:</u> Garden type portable manual sprayer or water hose with spray attachment if suitable.
- .12 <u>Tape:</u> Duct tape or tape suitable for sealing polyethylene to surfaces under both dry and wet conditions in the presence of Amended Water.
- .13 <u>Wetting Agent</u>: Non-sudsing surfactant added to water to reduce surface tension and increase wetting ability.

#### PART 3 EXECUTION

.1 Refer to the Sections identified in Related Work for specified procedures for work area preparation, maintenance, site dismantlement, application of lock-down agent and all other procedures for the safe handling, removal and clean-up of hazardous materials specific to each phase or work area.

#### END OF SECTION

\PIN-PET-FS01\job\34800s\0348218.000 KPRDSB,MSCPS,47Tupper,Millbrook,Haz,Roof\0348218.007 KPRDSB,Courtice,1717Nash,Haz,Roof\Deliverables\Specs\02 81 00 Hazardous Materials - General Provisions ON.docx

#### PART 1 GENERAL

#### 1.1 General and Related Work

- .1 Read this Section in conjunction with all drawings and all other Sections so as to comply with the requirements of Division 1 and the General Conditions of the Contract.
- .2 Requirements specified elsewhere:
  - .1 Section 02 81 00 Hazardous Materials General Provisions

# 1.2 Outline of Work

- .1 Refer to Section 02 81 00 Hazardous Materials General Provisions for the Outline of Work.
- .2 Refer to Drawings HR-01 through HR-03 for the extent of the Abatement Work Areas.
- .3 The intent of this Section is to provide safe work practices and procedures to govern the handling, removal, clean-up and disposal of asbestos-containing materials following Type 1 procedures, and Pinchin and Owner specific requirements.

#### 1.3 Personal Protection

- .1 Protect all personnel at all times when possibility of disturbance of ACM exists:
  - .1 Provide non-powered half-face respirators with P100 high efficiency (HEPA) cartridge filters when requested by personnel.
  - .2 When requested by personnel, provide protective clothing.
- .2 Provide protective clothing, to all personnel entering the Abatement Work Area.
- .3 Wear hard hats, safety shoes and other personal protective equipment required by applicable construction safety regulations.

#### 1.4 Site Review

- .1 Refer to Part 1.13 Site Review in Section 02 81 00 General Provisions.
- .2 The following Milestone Reviews are to be scheduled:
  - .1 Milestone Review Clean Site Preparation
  - .2 Milestone Review Visual Clearance

#### PART 2 PRODUCTS AND FACILITIES

.1 Refer to Section 02 81 00.

# PART 3 EXECUTION

# 3.1 Site Preparation

- .1 Isolate, at panel, and disconnect existing power supply to Abatement Work Area. Power supply to remaining areas of building must not be disrupted during work of this section:
  - .1 Lock-out/tag-out power at electrical panels.
  - .2 Mark/tag any items within or passing through the Abatement Work Area that are to remain live including but not limited to cable, conduit, wire, fixtures, equipment panels, etc.
- .2 Provide power from ground fault interrupt circuits.
- .3 Provide amended water for wetting ACM, and adequate method of wetting (garden sprayers, airless sprayers, etc).

.4 Without disturbing asbestos-containing materials, remove and dispose of non-hazardous materials as clean waste prior to asbestos removal work, where possible.

# 3.2 Maintenance of Abatement Work Area

- .1 Maintain Abatement Work Area in tidy condition.
- .2 Remove any standing water on polyethylene/floor at the end of every shift.
- .3 Turn off water supply to any hoses and reduce pressure in hose, prior to leaving the Abatement Work Area at end of shift.

# 3.3 Asbestos Removal - General

- .1 Do not use powered tools or non-hand held tools.
- .2 Do not use compressed air, leaf blowers or dry sweeping to clean or remove dust or debris.
- Do not break, cut, drill, abrade, grind, sand or vibrate ACM if it cannot be wetted. Type 2 procedures would be required if the material cannot be wetted due to hazard or damage.
- .4 Wet ACM prior to work and keep ACM wet throughout the removal process.
- .5 Frequently and at regular intervals during the work, clean up dust and waste using HEPA vacuums and/or wet sweeping or mopping.
- .6 Frequently and at regular intervals, place all waste in asbestos waste containers.
- .7 Immediately upon completion of work, clean area with HEPA vacuum and/or wet sweeping or mopping.

# 3.4 Asbestos Removal - Removal of Other Non-Friable Asbestos Materials

- .1 Remove top layers of non-asbestos built-up roofing materials and dispose as regular waste prior to abatement work. Once complete, begin removal of asbestos-containing materials and asbestos-contaminated materials as outlined in the following provisions:
  - .1 Wet all material to be disturbed.
  - .2 Undo fasteners if necessary to remove material.
  - .3 Break material only if unavoidable, and wet material if broken during work.
  - .4 Use only non-powered hand-held tools to remove ACM.
  - .5 Scrape to remove material adhered to substrate.
  - .6 Place removed ACM directly into an asbestos waste container.

# 3.5 Abatement Work Area Dismantling

- .1 Wash or HEPA vacuum equipment and tools used in contaminated Abatement Work Area to remove all asbestos contamination, or place in Asbestos Waste Containers prior to being removed from Abatement Work Area.
- .2 Place tools and equipment used in contaminated work site but not cleaned in polyethylene bags prior to removal from Abatement Work Area.
- .3 Clean work area with HEPA vacuum or wet cleaning methods at completion of work.

# 3.6 Waste and Material Handling

.1 Refer to Section 02 81 00.

#### END OF SECTION

\PIN-PET-FS01\job\348000s\0348218.000 KPRDSB,MSCPS,47Tupper,Millbrook,Haz,Roof\0348218.007 KPRDSB,Courtice,1717Nash,Haz,Roof\Deliverables\Specs\02 82 00.01 Asbestos Abatement - Type 1 Precautions ON.docx

#### PART 1 GENERAL

# 1.1 General and Related Work

- .1 Read this Section in conjunction with all drawings and all other Sections so as to comply with the requirements of Division 1 and the General Conditions of the Contract.
- .2 Requirements specified elsewhere:
  - .1 Section 02 81 00 Hazardous Materials General Provisions

#### 1.2 Outline of Work

- .1 Refer to Section 02 81 00 Hazardous Materials General Provisions for the Outline of Work.
- .2 Refer to Drawings HR-01 through HR-03 for the extent of the Abatement Work Areas.
- .3 The intent of this Section is to provide safe work practices and procedures to govern the handling, removal, clean-up and disposal of asbestos-containing materials following Type 2 procedures, and Pinchin and Owner specific requirements.

# 1.3 Personal Protection

- .1 Protect all personnel at all times when possibility of disturbance of ACM exists.
- .2 Provide the following minimum respiratory protection to all personnel:
  - .1 Non-powered half-face respirators with P100 high efficiency (HEPA) cartridge filters.
- .3 Provide protective clothing, to all personnel entering the Abatement Work Area.
- .4 Wear hard hats, safety shoes and other personal protective equipment required by applicable construction safety regulations.

#### 1.4 Site Reviews

- .1 Refer to Part 1.13 Site Reviews in Section 02 81 00 General Provisions.
- .2 The following Milestone Reviews are to be scheduled:
  - .1 Milestone Review Clean Site Preparation
  - .2 Milestone Review Bulk Removal Review
  - .3 Milestone Review Visual Clearance
  - .4 Milestone Review Post-Abatement Sampling

#### PART 2 PRODUCTS AND FACILITIES

.1 Refer to Section 02 81 00.

# 2.2 Hoarding Walls

- .1 <u>Type A Hoarding Wall:</u> One layer of rip-proof polyethylene sheeting installed floor to ceiling, secured with telescopic poles, clips, or other suitable methods.
- .2 <u>Windows:</u> Install sufficient transparent windows area in hoarding walls to allow observation of entire work area from outside the enclosure where existing solid walls do not make up the perimeter.

# 2.3 Curtained Doorways

- .1 Construct as follows:
  - .1 Install two flap doors, full width and height of door opening at all doors to Abatement Work Area and both ends of Transfer Room.
  - .2 Construct each flap door of two layers of polyethylene sheeting with all edges reinforced with tape. Use wood strapping to securely fasten flap doors to head and alternate jambs.
  - .3 Install weights attached to bottom edge of each door flap.
  - .4 Provide direction arrows on flaps to indicate opening.

# PART 3 EXECUTION

# 3.1 Site Preparation - General

- .1 Remove stored or non-fixed items from the Abatement Work Area including but not limited to equipment, furniture, waste etc. Store in area provided by Owner.
- .2 Moving of equipment, tools, supplies, and stored materials that can be performed without disturbing ACM will be performed by others.
- .3 Remove visible dust and friable material from all surfaces in the work area including those to be worked on, using HEPA Vacuums or wet wiping.
- .4 Isolate, at panel, and disconnect existing power supply to Abatement Work Area. Power supply to remaining areas of building must not be disrupted during work of this section:
  - .1 Lock-out/tag-out power at electrical panels.
  - .2 Mark/tag any items within or passing through the Abatement Work Area that are to remain live including but not limited to cable, conduit, wire, fixtures, equipment panels, etc.
- .5 Provide power from ground fault interrupt circuits.
- .6 Shut down HVAC systems serving the Abatement Work Area.
  - .1 Install polyethylene sheeting over openings in ducts and diffusers and seal.
  - .2 HVAC to remaining areas of building must not be disrupted during work of this section.
  - .3 System shall remain inoperative until completion of work, unless ducts can be effectively capped.
  - .4 Perform work at scheduled times after shutting down HVAC systems affecting the Abatement Work Area.
- .7 Provide amended water for wetting ACM, and adequate method of wetting (garden sprayers, airless sprayers, etc).

# 3.2 Site Preparation – Enclosure Required

- .1 Install polyethylene enclosure complete with Windows at Abatement Work Areas for the following work:
  - .1 Removal of friable asbestos-containing materials (less than 1 square metre).
  - .2 Removal of a false ceiling (or part of) where asbestos-containing material is presumed or known to be present on the surface.

- .2 Install polyethylene sheeting on floors of Abatement Work Area. Use sufficient layers to provide adequate protection for carpeting and equipment:
  - .1 Minimum requirement over carpet is one layer of 6 mil polyethylene under one layer of rip-proof polyethylene.
  - .2 Cover floors first so that polyethylene on walls is overlapped by at least 305 mm.
- .3 Construct Type A Hoarding Walls between Abatement Work Area perimeter and occupied areas.
- .4 Install polyethylene sheeting at openings in walls (as required) and seal.
- .5 Install 6 mil polyethylene sheeting on walls within the Abatement Work Area., including existing walls that make up, or are within, the Abatement Work Area.
- .6 Provide a completely sealed polyethylene top for free standing enclosures.
- .7 Extend to underside of ceiling system, enclosures for access into ceilings. Enclosure may be supported from the ceiling system if ceiling can support the polyethylene.
- .8 Install Curtained Doorways.
- .9 Install one layer of 6 mil polyethylene sheeting so as to protect all equipment and finishes in the Abatement Work Area that may be damaged. Items to remain include but are not limited to:
  - .1 Millwork.
  - .2 Doors.
  - .3 Bulkheads.
  - .4 Toilet Partitions.
  - .5 Plumbing fixtures.
  - .6 Electrical Equipment.
  - .7 Mechanical Equipment.
  - .8 Kitchen Equipment.
- .10 Install temporary lighting in enclosure to a level that will provide for safe and efficient use of work area minimum 550 LUX.
- .11 Establish negative pressure in Abatement Work Areas as follows:
  - .1 Use DOP tested HEPA Vacuum.
  - .2 Insert vacuum hose into enclosure, leave HEPA vacuum outside enclosure. Provide enough hose to reach all areas of enclosure.
  - .3 Operate HEPA vacuum continuously at all times when ACM might be disturbed.
- .12 Place required tools to complete the abatement with the Abatement Work Area.
- .13 Install Signage in clearly visible locations and in sufficient numbers to adequately warn of an asbestos dust hazard.

# 3.3 Site Preparation – No Enclosure Required

- .1 Install caution tape around work area where existing walls are not present.
- .2 Cover walls, floors, finishes, millwork, equipment and furnishings remaining in the Abatement Work Area with polyethylene sheeting before disturbing ACM to control the spread of dust.

- .3 Install one layer of 6 mil polyethylene sheeting so as to protect all equipment and finishes in the Abatement Work Area that may be damaged. Items to remain include but are not limited to:
  - .1 Millwork.
  - .2 Doors.
  - .3 Bulkheads.
  - .4 Toilet Partitions.
  - .5 Plumbing fixtures.
  - .6 Electrical Equipment.
  - .7 Mechanical Equipment.
  - .8 Kitchen Equipment.
- .4 Install Signage in clearly visible locations and in sufficient numbers to adequately warn of an asbestos dust hazard.
- .5 Install temporary lighting in enclosure to a level that will provide for safe and efficient use of work area minimum 550 LUX.
- .6 Place HEPA vacuum in Abatement Work Area.
- .7 Place required tools to complete the abatement with the Abatement Work Area.

# 3.4 Maintenance of Abatement Work Area

- .1 Inspect polyethylene sheeting and ensure it is effectively sealed and taped. Repair damage and remedy defects immediately.
- .2 Inspect electrical panels and ensure locks and tags are on panels prior to entering the Abatement Work Area.
- .3 Inspect HEPA filtered negative pressure machines including discharge ducting at the beginning and end of each working period. Review must be performed by competent person.
- .4 Maintain Abatement Work Area in tidy condition.
- .5 Remove standing water on polyethylene/floor at the end of every shift.
- .6 Turn off water supply to any hoses and reduce pressure in hose, prior to leaving the Abatement Work Area at end of shift.

# 3.5 Asbestos Removal - General

- .1 Do not use compressed air to clean or remove dust or debris.
- .2 Frequently and at regular intervals during the work, clean up dust and waste using HEPA vacuums and/or wet sweeping or mopping.
- .3 Frequently and at regular intervals, place all waste in asbestos waste containers.
- .4 Immediately upon completion of work, clean area with HEPA vacuum and/or wet sweeping or mopping.

# 3.6 Asbestos Removal - Drywall with Asbestos Drywall Joint Compound (greater than 1 square metre)

.1 Use the procedures described above under *Site Preparation –Enclosure Required*.

- .2 Protect drywall around area to be removed by covering with polyethylene and taping seams to wall.
- .3 Cut drywall and remove using non-powered hand-held tools. Place directly into polyethylene waste bag, or sealed container until at waste bin.
- .4 Remove all screws and fasteners in studs or strapping.
- .5 Remove studs and strapping where specified. Clean metal studs and remove from Abatement Work Area.
- .6 Wet clean or HEPA vacuum the entire Abatement Work Area, including surfaces not covered with polyethylene sheeting. Any materials or equipment removed to access ACM that are to be reused, must be wet cleaned or vacuumed prior to reinstatement.

# 3.7 Drilling On Masonry Block Walls with Asbestos Containing Primer/Paint AND Drywall with Asbestos Containing Drywall Joint Compound with HEPA Filtered Power Tools

- .1 Use the procedures described above under *Site Preparation –No Enclosure Required*.
- .2 Wet all material to be disturbed.
- .3 Turn on HEPA vacuum. Vacuum to remain operation throughout work.
- .4 IF power tool can disconnect from HEPA vacuum, remove tool, and HEPA vacuum tool and bit, blade, etc, and shrouds.
- .5 Wet clean or HEPA vacuum the entire Abatement Work Area, including surfaces not covered with polyethylene sheeting. Any materials or equipment removed to access ACM that are to be reused, must be wet cleaned or vacuumed prior to reinstatement.

# 3.8 Abatement Work Area Dismantling

- .1 Wash or HEPA vacuum equipment and tools used in contaminated Abatement Work Area to remove all asbestos contamination, or place in Asbestos Waste Containers prior to being removed from Abatement Work Area.
- .2 Place tools and equipment used in contaminated work site but not cleaned in polyethylene bags prior to removal from Abatement Work Area.
- .3 Clean polyethylene sheeting and drop sheets which with HEPA vacuum or wet cleaning methods at completion of work.
- .4 Wet drop sheets and polyethylene sheeting.
- .5 Carefully roll polyethylene sheeting and drop sheets toward the centre of enclosure. As polyethylene is rolled away, immediately remove visible debris beneath with a HEPA vacuum.
- .6 Remove remaining polyethylene sheeting and tape, and dispose of as asbestos waste.
- .7 Place polyethylene sheeting, drop sheets, tape, disposal clothing and other contaminated waste in asbestos waste containers, wet wipe and place in second asbestos waste container.
- .8 Remove remaining site isolation, seals, tape, etc.
- .9 Remove seals, tape, Signage etc.
- .10 Immediately upon shutting down negative air units, seal air inlet grill and exhaust vent with polyethylene and tape.

- .11 Seal openings in HEPA vacuums.
- .12 Remove and dispose of the pre-filters from HEPA filtered negative pressure machines as asbestos waste.
- .13 Remove HEPA filtered negative pressure machines and discharge ducting or HEPA vacuums.
- .14 Remove temporary lights.
- .15 Remove ground fault panels.
- .16 Place contaminated materials including polyethylene sheeting, drop sheets, seals, tape, disposable coveralls, and other contaminated waste in asbestos waste containers.

# 3.9 Waste and Material Handling

.1 Refer to Section 02 81 00.

#### 3.10 Re-Establishment of Items

- .1 Upon completion of work:
  - .1 Move items that were removed from Abatement Work Area prior to work, back into same location within Abatement Work Area.
  - .2 Clean, mop and vacuum Abatement Work Area.

#### END OF SECTION

\PIN-PET-FS01\job\348000s\0348218.000 KPRDSB,MSCPS,47Tupper,Millbrook,Haz,Roof\0348218.007 KPRDSB,Courtice,1717Nash,Haz,Roof\Deliverables\Specs\02 82 00.02 Asbestos Abatement - Type 2 Precautions ON docx





