

## DESIGNATED SUBSTANCES and HAZARDOUS MATERIALS SURVEY



### LONG TERM CARE HOMES & SERVICES Castlevue - Wychwood Tower 351 Christie Street Toronto, Ontario

Presented to:

**Sara Reid**

City of Toronto  
Corporate Real Estate Management

Project Number: FE 24-13855

August 30, 2024

## EXECUTIVE SUMMARY

Fisher Engineering Limited was retained by the City of Toronto, Corporate Real Estate Management to conduct a reassessment survey for designated substances and hazardous materials in the Toronto Long Term Care Homes & Services building named Castlevue-Wychwood Tower, located at 351 Christie Street in Toronto, Ontario.

The objective of the survey was to determine the condition of previously identified asbestos-containing materials (ACM), identify and assess the condition of designated substances and other hazardous materials, and, if necessary, provide recommendations to assist the City of Toronto in fulfilling requirements to achieve regulatory compliance, as set forth under the Ontario Occupational Health and Safety Act, and enforced by the Ontario Ministry of Labour regulations for designated substances; O. Reg. 490/09 – Designated Substances and O. Reg. 278/05 – Asbestos on Construction Projects and in Buildings and Repair Operations.

This document should be filed as an addendum to the original survey report, which was issued by Fisher Environmental Ltd. on May 13, 2015.

These Designated Substances and Hazardous Materials survey report is intended for management purposes only. It is not to be used to establish the presence of designated substances or hazardous materials in building materials prior to renovation or demolition activities. A pre-renovation/pre-demolition audit of the work area for designated substances and hazardous materials should be conducted prior to any work activities that may disturb building materials potentially containing designated substances or hazardous materials.

Iqbal Fattah of Fisher Engineering Limited performed the fieldwork on May 9, 2024.

## FINDINGS

The following presents a brief outline of findings within the facility. Refer to the main body and appendices of the report for specific details, quantities, conditions and locations of Designated Substances and Hazardous Materials within the facility.

Material	Findings
Asbestos	<p>Confirmed ACM were identified in the facility as follows:</p> <ul style="list-style-type: none"><li>• Roofing Material (west penthouse) – 0.5-5 % Chrysotile,</li><li>• Parging Cement – 70% Chrysotile,</li><li>• Hot Water Tank Insulation – 40-70% Chrysotile,</li><li>• Drywall Joint Compound (some areas) – 0.5-5 % Chrysotile,</li><li>• Vinyl Floor Tile 1 (12" x 12" Tan with Rust Streaks) – 0.5-5 % Chrysotile,</li><li>• Vinyl Floor Tile 2 (12" x 12" Beige with Black Streaks) – 0.5-5 % Chrysotile,</li><li>• Vinyl Floor Tile 8 (12" x 12" Beige (underneath VSF)) – 0.5-5 % Chrysotile,</li><li>• Vinyl Floor Tile 11 (12" x 12" White (under white VSF)) – 0.5-5 % Chrysotile.</li></ul> <p>Assumed ACM were identified in the facility as follows:</p> <ul style="list-style-type: none"><li>• Window Caulking,</li><li>• Ceiling Tiles – five (5) varieties,</li></ul>

Material	Findings
	<ul style="list-style-type: none"> <li>Vinyl Floor Tiles – seven (7) varieties, and,</li> <li>Vinyl Sheet Flooring – sixteen (16) varieties.</li> </ul> <p>All confirmed or assumed ACM were observed in GOOD condition, except for one damaged asbestos-containing fitting in Laundry Room, B-007.</p>
Lead	Paint finishes were generally noted to be in GOOD condition throughout the Site. During the disturbance of any painted surfaces that contain lead, it is recommended that appropriate procedures and use of respirators be followed to protect workers.
Mercury	Mercury can be found in fluorescent light bulbs and building thermostats.
Silica	As the building is constructed of concrete block and brick, with concrete floors, silica is expected to be found within these components of the building.
Other Designated Substances	No evidence of Acrylonitrile, Arsenic, Benzene, Coke Oven Emissions, Ethylene Oxide, Isocyanates, and Vinyl Chloride was found during the building survey.
PCB	No PCB containing equipment with the potential exception of fluorescent lighting ballasts was observed.
UFFI	No UFFI containing insulation was observed on site.
Mould	During the visual inspection of the surveyed areas, visible mould growth and water staining on non-ACM ceiling tiles, fibreglass insulation, blower compartment, and on the AHU were observed. Mould growth was observed on asbestos-containing parging cement fittings in East Mechanical Room, B-053. Efflorescence was observed on the concrete floor in West Mechanical Room, B-013.

## RECOMMENDATIONS

Fisher Engineering Limited would report any deficiencies and recommendations to the City of Toronto using a 2024 Reassessment Program Corrective Actions Reporting Form. On completion of the recommended actions, an Addendum is made to confirm completion of all corrective actions.

# TABLE OF CONTENTS

---

<b>EXECUTIVE SUMMARY .....</b>	<b>I</b>
<b>1. INTRODUCTION AND REGULATORY REQUIREMENTS .....</b>	<b>1</b>
1.1 INTRODUCTION AND SCOPE .....	1
<b>2. SURVEY METHODOLOGY .....</b>	<b>1</b>
2.1 GENERAL APPROACH .....	1
2.2 SURVEY METHODOLOGY .....	1
<b>3. FINDINGS AND RECOMMENDATIONS .....</b>	<b>2</b>
3.1 ASBESTOS .....	2
3.1.1 Findings .....	2
3.1.2 Recommendations .....	3
3.2 LEAD .....	3
3.2.1 Findings .....	4
3.2.2 Recommendations .....	4
3.3 ACRYLONITRILE .....	4
3.3.1 Findings .....	4
3.3.2 Recommendations .....	4
3.4 ARSENIC .....	5
3.4.1 Findings .....	5
3.4.2 Recommendations .....	5
3.5 BENZENE .....	5
3.5.1 Findings .....	5
3.5.2 Recommendations .....	5
3.6 COKE OVEN EMISSIONS .....	5
3.6.1 Findings .....	6
3.6.2 Recommendations .....	6
3.7 ETHYLENE OXIDES .....	6
3.7.1 Findings .....	6
3.7.2 Recommendations .....	6
3.8 ISOCYANATES .....	6
3.8.1 Findings .....	6
3.8.2 Recommendations .....	6
3.9 MERCURY .....	6
3.9.1 Findings .....	7
3.9.2 Recommendations .....	7
3.10 SILICA .....	7
3.10.1 Findings .....	7
3.10.2 Recommendations .....	7
3.11 VINYL CHLORIDE .....	7
3.11.1 Findings .....	8
3.11.2 Recommendations .....	8
3.12 POLYCHLORINATED BIPHENYLS (PCBs) .....	8
3.12.1 Findings .....	8
3.12.2 Recommendations .....	8
3.13 UREA FORMALDEHYDE FOAM INSULATION (UFFI) .....	8
3.13.1 Findings .....	9
3.13.2 Recommendations .....	9
3.14 MOULD .....	9
3.14.1 Findings .....	9
3.14.2 Recommendations .....	10
<b>4. CORRECTIVE ACTIONS .....</b>	<b>10</b>

---



## TABLE OF CONTENTS

---

5. STATEMENT OF LIMITATIONS.....	10
6. SIGN-OFF .....	11

**APPENDIX I – DESIGNATED SUBSTANCES AND HAZARDOUS MATERIALS INVENTORY SHEET**

**APPENDIX II – RESULTS OF BULK SAMPLE ANALYSIS**

**APPENDIX III – SITE DRAWINGS**

**APPENDIX IV – SITE PHOTOGRAPHS**

**APPENDIX V – CORRECTIVE ACTIONS INSPECTION REPORT**

## **1. INTRODUCTION AND REGULATORY REQUIREMENTS**

### **1.1 Introduction and Scope**

Fisher Engineering Limited was retained by the City of Toronto, Corporate Real Estate Management to conduct a reassessment survey for designated substances and hazardous materials in the Toronto Long Term Care Homes & Services building named Castleview-Wychwood Tower, located at 351 Christie Street in Toronto, Ontario.

The objective of the survey was to determine the condition of previously identified asbestos-containing materials (ACM), identify and assess the condition of designated substances and other hazardous materials, and, if necessary, provide recommendations to assist the City of Toronto in fulfilling requirements to achieve regulatory compliance, as set forth under the Ontario Occupational Health and Safety Act, and enforced by the Ontario Ministry of Labour regulations for designated substances; O. Reg. 490/09 – Designated Substances and O. Reg. 278/05 – Asbestos on Construction Projects and in Buildings and Repair Operations.

This document should be filed as an addendum to the original survey report, which was issued by Fisher Environmental Ltd. on May 13, 2015.

The Designated Substances and Hazardous Materials survey report is intended for management purposes only. It is not to be used to establish the presence of designated substances or hazardous materials in building materials prior to renovation or demolition activities. A pre-renovation/pre-demolition audit of the work area for designated substances and hazardous materials should be conducted prior to any work activities that may disturb building materials potentially containing designated materials or hazardous substances.

Iqbal Fattah of Fisher Engineering Limited performed the fieldwork on May 9, 2024.

## **2. SURVEY METHODOLOGY**

### **2.1 General Approach**

To ensure familiarity with the building, the Surveyor made reference to the previous assessment and reassessment reports provided by the City of Toronto prior to commencing the survey. The Surveyor also made reference to facility floor plans included in the previous assessment reports or provided independently by the City of Toronto. Site drawings identifying locations of asbestos-containing materials, if present, are included in Appendix III. Site photographs are included in Appendix IV.

### **2.2 Survey Methodology**

The City of Toronto provided the consultant with the previous Designated Substances and Hazardous Materials Survey report and/or other survey reports identified for the facility, if available. Prior to conducting the current survey, previous reports were reviewed by Fisher Engineering Limited and the current report is updated with all available information regarding ACM, including that from past assessments and reassessments.

The survey was conducted in compliance with the Ontario Ministry of Labour (MOL) regulations for designated substances; O. Reg. 490/09 - *Designated Substances* and O. Reg. 278/05 - *Asbestos on Construction Projects and in Buildings and Repair Operations* made under the Occupational Health and Safety Act (OHSA), R.S.O. 1990.

The Surveyor conducted a visual reassessment of all known and assumed asbestos-containing materials in all accessible areas of the building, as detailed in past survey reports, and recorded the condition (GOOD, FAIR, or POOR) of each known or assumed ACM on the Designated Substances and Hazardous Materials Inventory Sheet. The Surveyor also recorded detailed descriptions of previously unidentified potential ACM, if observed. Please refer to Appendix I for the updated Designated Substances and Hazardous Materials Inventory Sheet.

Materials confirmed to be asbestos-containing during previous assessments were not sampled for this reassessment survey. Additionally, samples were not collected of materials that were previously confirmed to be non-asbestos by the requirements of O. Reg. 278/05.

Any other potential asbestos-containing materials noted during the reassessment survey that had not been identified in a previous survey, or were not sampled in accordance with the requirements of O. Reg. 278/05, were noted as part of the reassessment.

The Designated Substances and Hazardous Materials Survey is based on a walk-through inspection of the facility and shall be conducted room by room to establish locations, conditions and types of designated substances. The survey shall also include an examination for the presence of polychlorinated biphenyls (PCBs), urea-formaldehyde foam insulation (UFFI), and visible mould growth.

### **3. FINDINGS AND RECOMMENDATIONS**

#### **3.1 Asbestos**

Asbestos fibres may be released into the air by the disturbance of ACM during product use, demolition work, building or home maintenance, repair and remodeling. In general, exposure may occur only when the ACM is disturbed in some way to release particles and fibres into the air.

##### **3.1.1 Findings**

Previously identified confirmed or assumed ACM include the following:

- Roofing Material,
- Window Caulking,
- Drywall Joint Compound,
- Hot Water Tank Insulation,
- Parging Cement,
- Ceiling Tiles – five (5) varieties,

- Vinyl Floor Tiles – eleven (11) varieties, and,
- Vinyl Sheet Flooring – sixteen (16) varieties.

Vinyl Sheet Flooring 21 (Grey Wood Laminate like Pattern) not identified during previous surveys, was observed in location 1-055 Office.

Vinyl Sheet Flooring 27 (Grey with Brown Swirls) not identified during previous surveys, was observed in location 2-002 Corridor.

No samples were collected for analysis during the current survey.

### 3.1.2 Recommendations

All assumed and confirmed ACM were observed to be in GOOD condition, with the exception of one (1) damaged pipe fitting with asbestos-containing paring cement in the Laundry Room, B-007. The damaged asbestos-containing paring cement should be repaired or removed following Type 2 (Glove Bag) Asbestos Abatement procedures.

Any other building materials suspected to contain asbestos which are not outlined in this report should be assumed to be asbestos-containing until sample analysis determines asbestos content.

O. Reg. 278/05 requires that an Asbestos Management Program (AMP) be implemented as long as ACM are present in a building. The AMP, original survey report and subsequent reassessment reports must be available at the work place, and must identify the type of asbestos, and where asbestos can be found on a room-by-room basis.

**NOTE:** Interpretation of all sources of asbestos-related information, including but not limited to the original asbestos survey report, asbestos reassessment reports, room-by-room survey data, survey drawings and reports from previous asbestos abatement projects, should be completed by a competent person trained in the historical application of asbestos in building materials, building design and preferably by a person with site-specific knowledge and/or experience.

Information contained within any of the above-noted sources may not relieve the Regulatory responsibility of building Owners, or project Employers/Constructors, to complete a detailed site inspection prior to commencement of a project.

This report should not be used as a substitute for a detailed site inspection to identify asbestos-containing building materials, which must be specifically tailored to the scope and nature of any given project, and completed prior to any maintenance, renovation or demolition work that may cause disturbance to building materials.

## 3.2 Lead

Most lead in the environment comes from human activities such as burning fossil fuels, mining and manufacturing. Lead is used in the production of batteries, ammunition, metal products such as solder and pipes, and x-ray devices. Exposure happens when eating food or drinking water that contains lead. Deteriorated lead paint can contribute to lead dust. The main target for lead toxicity is the nervous system.

The regulation for lead applies to every employer and worker at a workplace where lead is present, produced, processed, used, handled or stored and at which a worker is likely to be exposed to lead.

Additionally, in 2004 the MOL issued *Guideline: Lead on Construction Projects* outlining practices that should be followed during construction projects to protect workers' from exposure to lead. This includes the methods and equipment employed in the removal of lead containing coatings that reduce the creation of dust, providing appropriate facilities for workers to wash after each shift, and providing protective clothing and respirators where necessary.

### **3.2.1 Findings**

Paint finishes were generally noted to be in GOOD condition throughout the Site. Based on the age of the building, it is possible that lead-based paint and lead plumbing are present within the building. During the current survey, no lead samples were collected for analysis. No other indication of lead containing materials was observed during the building audit, with the exception of that which may be contained within batteries.

### **3.2.2 Recommendations**

During the disturbance of any painted surfaces that contain lead, it would be recommended that appropriate procedures and use of respirators be followed to protect workers.

No immediate corrective actions were recommended with regard to lead.

## **3.3 Acrylonitrile**

Acrylonitrile is used to make other chemicals such as plastics, synthetic rubber and acrylic fibres. Breathing high concentrations of acrylonitrile will cause nose and throat irritation, tightness in chest, difficulty breathing, nausea, dizziness, weakness, headache, impaired judgment and convulsions. These symptoms usually disappear when exposure has stopped. If spilled on the skin, acrylonitrile will burn the skin and cause blisters and redness. Acrylonitrile is believed to be carcinogenic.

### **3.3.1 Findings**

Acrylonitrile based polymers may have been utilized in the production of some of the building construction materials (e.g. paints, sealants, and adhesives). Although these polymers are generally volatile, they are expected to produce significant acrylonitrile exposure only during or shortly after application of the subject material. If present on site, acrylonitrile would not be expected to be a concern during future renovation or demolition works. Acrylonitrile was not evident in its pure form anywhere within the subject areas of the building.

### **3.3.2 Recommendations**

No immediate corrective actions were recommended with regard to acrylonitrile.

### **3.4 Arsenic**

Inorganic arsenic compounds are mainly used to preserve wood. Organic arsenic compounds are used as pesticides. Arsenic occurs naturally in soil and minerals and therefore may enter air and water. Breathing high levels of arsenic may cause sore throat and irritated lungs. Ingesting high levels of arsenic can result in death. Arsenic is a suspected carcinogenic substance.

#### **3.4.1 Findings**

Low levels of arsenic may be contained within paints or coatings utilized on building construction materials, however exposure levels resulting from personal contact are not expected to be significant. Arsenic or arsenic containing compounds were not encountered during the building survey works.

#### **3.4.2 Recommendations**

No immediate corrective actions were recommended with regard to arsenic.

### **3.5 Benzene**

Benzene is colourless liquid with a sweet odour. Benzene utilization has historically been associated with solvents, paints, stains, adhesives, and in the manufacturing of various rubber products. While its current use in building materials has greatly decreased due to an increased awareness of associated health concerns, it may still be present in trace quantities in various industrial solvents. Gasoline sold in Canada contains approximately 4% benzene.

Breathing very high levels of benzene can result in death, while high levels may cause drowsiness, dizziness, rapid heart rate, headaches, and unconsciousness.

#### **3.5.1 Findings**

While it may be expected, given the age of the building, that the original construction materials utilized did contain some trace levels of benzene, it is likely that any has since volatilized and would not exceed the permissible exposure values. During future renovation or demolition works, it would not be expected to be a concern. No evidence of benzene was noted during the building survey, with the exception of that which may be contained in regular gasoline fuel burning equipment.

#### **3.5.2 Recommendations**

No immediate corrective actions were recommended with regard to benzene.

### **3.6 Coke Oven Emissions**

Coke oven emissions are released during the carbonization of bituminous coal for the production of coke. Exposure routes include inhalation, skin and / or eye contact. Coke oven emissions are potential occupational carcinogens.

### 3.6.1 Findings

This substance would not be expected to be found in the building. No evidence of the burning of coke was found during the building survey.

### 3.6.2 Recommendations

No immediate corrective actions were recommended with regard to coke oven emissions.

## 3.7 *Ethylene Oxides*

Ethylene oxide is a man-made chemical used primarily to make ethylene glycol (antifreeze and polyester). Breathing low levels of ethylene oxides for a prolonged period of time causes eye, skin and respiratory irritations, and can affect nervous system. Higher levels of exposure for shorter time produce symptoms that are similar but more severe.

### 3.7.1 Findings

This substance would not be expected to be found in the building. No evidence of ethylene oxides was found during the building survey.

### 3.7.2 Recommendations

No immediate corrective actions were recommended with regard to ethylene oxides.

## 3.8 *Isocyanates*

Isocyanates are a family of highly reactive, low molecular weight chemicals. They are widely used in the manufacture of flexible and rigid foams, fibres, and coatings such as paints and varnishes, and elastomers and various building materials (e.g. spray on polyurethane products). Isocyanates are powerful irritants to the eyes, skin, and respiratory and gastrointestinal tracts.

### 3.8.1 Findings

Use of isocyanates or isocyanate compounds would not be expected in the building. No evidence of isocyanates was found during the building survey.

### 3.8.2 Recommendations

No immediate corrective actions were recommended with regard to isocyanates.

## 3.9 *Mercury*

Mercury is a naturally occurring metal. It is a shiny, silver-white and odourless liquid. It combines with other elements to form inorganic compounds or salts. Metallic mercury is used to produce chlorine gas and caustic soda, and is used in thermostats and thermometers, fluorescent light bulbs, dental fillings and batteries. Exposure occurs when breathing vapours from spills, incinerators, etc.

The nervous system is very sensitive to all forms of mercury. Exposure to high levels of metallic inorganic or organic mercury can permanently damage the brain, kidneys and developing fetus. Short-term exposure may cause lung damage, nausea, vomiting and diarrhea as well as skin and eye irritation.



### 3.9.1 Findings

Mercury can be found in fluorescent light bulbs and building thermostats. Prior to future renovation or demolition works, it would be recommended that these products be safely removed. The disposal of mercury containing items are regulated under the Environmental Protection Act, and it would be recommended that for disposal purposes any mercury containing thermostats and fluorescent light bulbs be disposed of at an MOE licensed receiver. With the exception of fluorescent light bulbs and building thermostats, no other evidence of mercury was noted during the building survey.

### 3.9.2 Recommendations

No immediate corrective actions were recommended with regard to mercury.

## 3.10 Silica

Silica is a crystalline compound occurring abundantly as quartz, sand, and many other minerals, and used to manufacture a variety of materials, especially glass and concrete. When mining this substance, silica can be deadly when it becomes airborne. If inhaled, silica dust can cause silicosis which can be fatal.

Additionally, in 2004 the MOL issued *Guideline: Silica on Construction Projects* outlining practices that should be followed during construction projects to protect workers' from exposure to silica. This includes the methods and equipment employed in the removal of silica containing materials that reduce the creation of dust, providing appropriate facilities for workers to wash after each shift, and providing protective clothing and respirators where necessary.

### 3.10.1 Findings

As the building is constructed of concrete block and brick, with concrete floors, silica is expected to be found within these components of the building. During any significant renovation or demolition works where concrete dust is generated, dust suppression techniques should be utilized to control worker exposure to silica. Silica is expected to be present in concrete and masonry products in the building.

### 3.10.2 Recommendations

No immediate corrective actions were recommended with regard to silica.

## 3.11 Vinyl Chloride

Vinyl chloride is used to make polyvinyl chloride (PVC) which is found in a variety of plastic products, including pipes, wires, cable coatings and packaging materials. Breathing high levels of vinyl chloride can cause dizziness, unconsciousness and death. Prolonged exposure causes changes in liver, nerve damage, immune reactions and changes in blood flow.

### 3.11.1 Findings

PVC pipe is generally stable and does not allow for the liberation of vinyl chloride, under normal conditions. During future renovation or demolition works, this substance would not be expected to be a concern. Vinyl chloride was not evident in its pure form, anywhere in the subject dwellings.

### 3.11.2 Recommendations

No immediate corrective actions were recommended with regard to vinyl chloride.

## 3.12 *Polychlorinated Biphenyls (PCBs)*

PCBs are mixtures of synthetic organic chemicals with the same basic chemical structure and similar physical properties ranging from oily liquids to waxy solids. Due to their non-flammability, chemical stability, high boiling point and electrical insulating properties, PCBs were used in hundreds of industrial and commercial applications including electrical, heat transfer, and hydraulic equipment; as plasticizers in paints, plastics and rubber products; in pigments, dyes and carbonless copy paper and many other applications.

PCBs have been demonstrated to cause a variety of adverse health effects. PCBs have been shown to cause cancer.

### 3.12.1 Findings

No PCB containing equipment with the potential exception of fluorescent lighting ballasts was observed on site. The disposal of PCB containing equipment is regulated under MOE Reg. 558, and it would be recommended that during any ballast replacement works the generated ballasts be evaluated for PCB content, with any PCB ballasts being consolidated and sent for disposal to an MOE licensed PCB receiver under waste class 243D.

### 3.12.2 Recommendations

It would be recommended that during any ballast replacement works the generated ballasts be evaluated for PCB content. Any PCB ballasts identified should be consolidated and sent for disposal to an MOE licensed PCB receiver under waste class 243D.

## 3.13 *Urea Formaldehyde Foam Insulation (UFFI)*

UFFI was developed in Europe in the 1950s as an improved means of insulating difficult-to-reach cavities in house walls. UFFI is composed of a mixture of urea-formaldehyde resin, a foaming agent, and compressed air. It was commonly injected into exterior wood frame walls in order to insulate difficult to reach cavities, until its ban in Canada in December 1980. When the mixture is injected into the wall, urea and formaldehyde unite and "cure" into an insulating foam plastic. In the insulating process, a slight excess of formaldehyde was often added to ensure complete "curing" with the urea to produce the urea-formaldehyde foam. That excess was given off during the curing, almost entirely within a day or two of injection. Properly installed, UFFI might not have resulted in any problem. Unfortunately, however, UFFI was sometimes improperly installed or used in locations where it should not have been.

While small amounts of formaldehyde are harmless, it is an irritating and toxic gas in significant concentrations. Symptoms of overexposure to formaldehyde include irritation to eyes, nose, and throat; persistent cough and respiratory distress; skin irritation; nausea; headache; and dizziness.

#### **3.13.1 Findings**

No UFFI containing insulation was observed on site.

#### **3.13.2 Recommendations**

No immediate corrective action is recommended with regard to UFFI.

### **3.14 Mould**

Mould contamination inside buildings has become a concern to both building owners and occupants. Exposure to moulds is known to cause a variety of health effects in some people. Many fungal spores are considered to be allergenic to susceptible persons, though individual susceptibility varies greatly.

Elevated levels of indoor mould are usually attributed to the chronic moist conditions due to water leaks, floods or elevated humidity. Under these conditions, already low levels of fungal spores in air from plants and other sources may multiply on cellulose containing materials such as carpets, wallboards, and wood, and result in mould contamination and, if left untreated, can be destructive to certain building materials.

Currently, no Canadian regulations govern the presence of mould and/or water-damaged materials in the workplace environment. However, the Health Canada document "Fungal Contamination in Public Buildings: Health Effects and Investigation Methodology" (2004) concludes that current knowledge supports the need to prevent damp conditions and mould growth and remediate any fungal growth and/or contamination in buildings.

Therefore, the presence of mould growth, mould-contaminated materials and/or water-damaged materials in the occupied environment is interpreted as a failure of Health Canada guidelines for microbial contamination in indoor environments, and as such, requires remedial action.

The MOL issued a document titled "Alert: Mould in Workplace Buildings." This document explains the MOL's position with respect to the presence of mould in workplace buildings.

The Environmental Abatement Council of Canada (EACC) has provided guidelines regarding investigation and remediation works Mould Abatement Guidelines Edition 3 (2015). Mould Guidelines for the EACC to protect the health of workers who may be exposed to mould during building renovations.

#### **3.14.1 Findings**

During the visual inspection of the surveyed areas, visible mould growth and/or water staining on non-ACM ceiling tiles, fibreglass insulation, blower compartment, and AHU were observed in the following locations: Volunteer Storage, B-012; West Mechanical Room, B-013; East Mechanical Room, B-053; Activity Room, 2-050; Dining Room, 4-035; Room

410C, 4-049; Room 402W, 4-004; Room 509W, 5-012; Room 509C, 5-048; Room 620C, 6-060; Lobby, 7-001; Corridor, 7-038; and Central Penthouse Mechanical Room, PH-001.

Visible mould growth was observed on asbestos-containing parging cement fittings in East Mechanical Room, B-053. Efflorescence was observed on the concrete floor in West Mechanical Room, B-013.

### 3.14.2 Recommendations

Removal of the non-ACM mould-impacted building materials should be conducted as a Level 1 Mould Remediation Operations, based on EACC guidelines. Following abatement, the source of water ingress should be determined and addressed to prevent potential future fungal amplification.

Removal of mould impacted canvas on ACM parging cement fittings in East Mechanical Room, B-053 should be conducted as Level 1 Mould Remediation Operations, based on EACC guidelines.

## 4. CORRECTIVE ACTIONS

Fisher Engineering Limited communicated the reported deficiencies and recommendations for corrective actions to the City of Toronto. Suggested abatement activities in East Mechanical Room, B-053 and Laundry Room, B-007, have been completed and an Addendum was made to this report to confirm completion of the corrective actions. Details of the abatement work can be found in the Corrective Actions Inspection Report (Project No. FE 24-14158), which is provided in Appendix V.

However, to our knowledge, the other suggested abatement activities have not been completed at the time of issuance of this report. On completion of the recommended actions, an Addendum should be made to this report to confirm completion of all corrective actions.

## 5. STATEMENT OF LIMITATIONS

Fisher Engineering Limited accepts responsibility for the competent performance of its duties in executing this assignment within the normal standards of the profession, but disclaims responsibility for consequential damages, if any.

The extent of the building survey of designated substances and hazardous materials is based on prior agreement of the scope of work with the client, and the rationale given in this report. The building survey findings rely on professional interpretation of selective sampling and analysis. Sample analysis results have been applied to homogenous materials in unsampled locations; it was not within the scope of work to carry out an exhaustive sampling and analysis program. For non-accessible building spaces, the likelihood of the presence or absence of asbestos and other designated substances has been described, but such assessment is not a definitive statement of presence or absence.

This report was prepared for the City of Toronto, Corporate Real Estate Management. The scope of services performed may not be appropriate for the purposes of other users, and

any use or reuse of this document or its findings or recommendations represented herein is at the sole risk of any other user.

We trust that the information provided in the report meets your current requirements. If you have any questions or concerns, please do not hesitate to contact the undersigned.

## 6. SIGN-OFF

We trust that this report meets with City of Toronto requirements and we thank you for the opportunity to be of service. Should you have any questions, please do not hesitate to contact us.

Fisher Engineering Limited

**Prepared By:**



Iqbal Fattah, M.Sc.  
Project Manager

**Reviewed By:**




David Fisher, P. Eng., C. Chem.  
Principal

## **APPENDIX I**

### **DESIGNATED SUBSTANCES AND HAZARDOUS MATERIALS INVENTORY SHEET**

# APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Building Address:	351 Christie Street	Date(s) of Current Reassessment:	May 9, 2024
Building Name:	Castleview-Wychwood Tower	Organization Completing Reassessment:	Fisher Engineering Limited / Project FE 24-13855
Original Survey Conducted By:	Fisher Environmental Ltd.	Name of Surveyor:	Iqbal Fattah
Date(s) of Original Survey:	May 13, 2015	Signature of Surveyor:	

**Summary of Findings**  
All Hazardous materials were found in GOOD condition.

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
0-00	Exterior	Roof	Roofing Material	Asbestos	17-7151-01 to 03*	0.5-5% Chrysotile	All	Good	West Penthouse *From Fisher Project No 17-8428, dated Sept. 2017
0-00	Exterior	Roof	Mastic	Asbestos	17-7151-04 to 06*	None Detected	N/A	N/A	Black - West Penthouse *From Fisher Project No 17-8428, dated Sept. 2017
0-00	Exterior	Roof	Roof Patch (Roofing Felt)	Asbestos	17-7151-07 to 09*	None Detected	N/A	N/A	Roof Patch, Block - West Penthouse *From Fisher Project No 17-8428, dated Sept. 2017
0-00	Exterior	Roof	Roofing Material	Asbestos	17-7151-10 to 12*	None Detected	N/A	N/A	Centre Penthouse *From Fisher Project No 17-8428, dated Sept. 2017
0-00	Exterior	Roof	Roofing Material	Asbestos	17-7151-13 to 15*	Trace (<0.5% Chrysotile)	All	Good	Black Caulking - Centre Penthouse *From Fisher Project No 17-8428, dated Sept. 2017
0-00	Exterior	Roof	Roofing Material	Asbestos	17-7151-16 to 18*	None Detected	N/A	N/A	East Penthouse *From Fisher Project No 17-8428, dated Sept. 2017
0-00	Exterior	Windows	Window Caulking	Asbestos	Not Sampled	ACM Assumed	All	Good	
0-00	Exterior	Walls	Brick	N/A	N/A	N/A	N/A	N/A	
B-001	Corridor	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
B-001	Corridor	Walls	Block/Concrete	N/A	N/A	N/A	N/A	N/A	
B-001	Corridor	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-01 to 03 & 17-7557-19 to 21 & 18-8513-1 to 3	None Detected	N/A	N/A	
B-001	Corridor	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-001	Corridor	Pipe	Parging Cement	Asbestos	Homogeneous w/ 082407-15 to 17	70% Chrysotile	80 Fittings	Good	
B-002	Morgue	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
B-002	Morgue	Walls	Block	N/A	N/A	N/A	N/A	N/A	
B-002	Morgue	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-003	Soiled Linen	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
B-003	Soiled Linen	Walls	Block	N/A	N/A	N/A	N/A	N/A	
B-003	Soiled Linen	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-004	Elevator Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	



APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
B-004	Elevator Room	Walls	Block	N/A	N/A	N/A	N/A	N/A	
B-004	Elevator Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-01 to 03 & 17-7557-19 to 21 & 18-8513-1 to 3	None Detected	N/A	N/A	
B-004	Elevator Room	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-005	Storage	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 17-7557-01 to 03	0.5-5% Chrysotile	220 SF	Good	12" x 12" Beige with Black Streaks
B-005	Storage	Walls	Block/Concrete	N/A	N/A	N/A	N/A	N/A	
B-005	Storage	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-005	Storage	Pipe	Parging Cement	Asbestos	Homogeneous w/ 082407-15 to 17	70% Chrysotile	3 Fittings	Good	
B-006	Compressor Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	NO ACCESS
B-006	Compressor Room	Walls	Block	N/A	N/A	N/A	N/A	N/A	
B-006	Compressor Room	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-007	Laundry Room	Floor	Vinyl Floor Tile 2	Asbestos	17-7557-01 to 03*	0.5-5% Chrysotile	250 SF	Good	12" x 12" Beige with Black Streaks *From Fisher Project No. 17-8527, dated Nov. 2017
B-007	Laundry Room	Floor	Vinyl Floor Tile 4	Asbestos	17-7557-04 to 06*	None Detected	N/A	N/A	12" x 12" Dark Beige with Brown Streaks *From Fisher Project No. 17-8527, dated Nov. 2017
B-007	Laundry Room	Floor	Vinyl Floor Tile 10	Asbestos	17-7557-07 to 09*	None Detected	N/A	N/A	12" x 12" Tan (under white VSF) *From Fisher Project No. 17-8527, dated Nov. 2017
B-007	Laundry Room	Floor	Vinyl Floor Tile 11	Asbestos	17-7557-10 to 12*	0.5-5% Chrysotile	90 SF	Good	12" x 12" White (under white VSF) *From Fisher Project No. 17-8527, dated Nov. 2017
B-007	Laundry Room	Floor	Vinyl Sheet Flooring 15	Asbestos	17-7557-13 to 15*	None Detected	N/A	N/A	Beige Mosaic *From Fisher Project No. 17-8527, dated Nov. 2017
B-007	Laundry Room	Floor	Vinyl Sheet Flooring 16	Asbestos	17-7557-16 to 18*	None Detected	N/A	N/A	White Mosaic *From Fisher Project No. 17-8527, dated Nov. 2017
B-007	Laundry Room	Floor	Vinyl Floor Tile 13	Asbestos	Not Sampled	ACM Assumed	8 SF	Good	12" x 12" Yellow
B-007	Laundry Room	Walls	Block/Concrete	N/A	N/A	N/A	N/A	N/A	
B-007	Laundry Room	Walls	Drywall (DJC)	Asbestos	17-7557-19 to 21*	None Detected	N/A	N/A	*From Fisher Project No. 17-8527, dated Nov. 2017
B-007	Laundry Room	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-007	Laundry Room	Pipe	Parging Cement	Asbestos	Homogeneous w/ 082407-15 to 17	70% Chrysotile	10 Fittings	Good	
B-008	Clean Linen	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 16-4653-10 to 12	0.5-5% Chrysotile	145 SF	Good	12" x 12" Tan with Rust Streaks
B-008	Clean Linen	Walls	Block	N/A	N/A	N/A	N/A	N/A	
B-008	Clean Linen	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-009	Storage	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 16-4653-10 to 12	0.5-5% Chrysotile	65 SF	Good	12" x 12" Tan with Rust Streaks
B-009	Storage	Walls	Block	N/A	N/A	N/A	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
B-009	Storage	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-01 to 03 & 17-7557-19 to 21 & 18-8513-1 to 3	None Detected	N/A	N/A	
B-010	Storage	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
B-010	Storage	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-01 to 03 & 17-7557-19 to 21 & 18-8513-1 to 3	None Detected	N/A	N/A	
B-010	Storage	Walls	Block	N/A	N/A	N/A	N/A	N/A	
B-010	Storage	Walls	Paint	Lead	16-5449-01*	670 ppm	N/A	N/A	Dark Beige *From Fisher Project No. 16-8029, dated Dec. 2016
B-010	Storage	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-011	Paint Shop	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
B-011	Paint Shop	Walls	Block	N/A	N/A	N/A	N/A	N/A	
B-011	Paint Shop	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-012	Volunteer Storage	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
B-012	Volunteer Storage	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 16-4653-10 to 12	0.5-5% Chrysotile	65 SF	Good	12" x 12" Tan with Rust Streaks under carpet
B-012	Volunteer Storage	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-01 to 03 & 17-7557-19 to 21 & 18-8513-1 to 3	None Detected	N/A	N/A	
B-012	Volunteer Storage	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
B-012	Volunteer Storage	Pipe	Parging Cement	Asbestos	Homogeneous w/ 082407-15 to 17	70% Chrysotile	N/A	N/A	NOT OBSERVED
B-013	West Mechanical Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
B-013	West Mechanical Room	Walls	Block	N/A	N/A	N/A	N/A	N/A	
B-013	West Mechanical Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-01 to 03 & 17-7557-19 to 21 & 18-8513-1 to 3	None Detected	N/A	N/A	
B-013	West Mechanical Room	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-013	West Mechanical Room	Other	Hot Water Tank Insulation	Asbestos	082407-12 to 14*	40-70% Chrysotile	All	Good	*From Building Asbestos Survey Report, dated 2007
B-013	West Mechanical Room	Pipe	Parging Cement	Asbestos	082407-15 to 17*	70% Chrysotile	60 Fittings	Good	*From Building Asbestos Survey Report, dated 2007
B-014	Storage	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
B-014	Storage	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-01 to 03 & 17-7557-19 to 21 & 18-8513-1 to 3	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
B-014	Storage	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
B-014	Storage	Ceiling	Ceiling Tile 4	Asbestos	Not Sampled	ACM Assumed	80 SF	Good	2' x 4' Long Fissure
B-015	Washroom	Floor	Vinyl Floor Tile 4	Asbestos	Homogeneous w/ 17-7557-04 to 06	None Detected	N/A	N/A	12" x 12" Dark Beige with Brown Streaks
B-015	Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-01 to 03 & 17-7557-19 to 21 & 18-8513-1 to 3	None Detected	N/A	N/A	
B-015	Washroom	Ceiling	Ceiling Tile 4	Asbestos	Not Sampled	ACM Assumed	35 SF	Good	2' x 4' Long Fissure
B-016	Pharmacy Storage	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
B-016	Pharmacy Storage	Walls	Block	N/A	N/A	N/A	N/A	N/A	
B-016	Pharmacy Storage	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-01 to 03 & 17-7557-19 to 21 & 18-8513-1 to 3	None Detected	N/A	N/A	
B-016	Pharmacy Storage	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-016	Pharmacy Storage	Pipe	Parging Cement	Asbestos	Homogeneous w/ 082407-15 to 17	70% Chrysotile	2 Fittings	Good	
B-017	Female Washroom	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
B-017	Female Washroom	Walls	Block	N/A	N/A	N/A	N/A	N/A	
B-017	Female Washroom	Ceiling	Drywall (DJC)	Asbestos	16-3996-01*	None Detected	N/A	N/A	*From Fisher Project No. 16-7778, dated May 2016
B-018	Pharmacy	Floor	Vinyl Floor Tile 5	Asbestos	Not Sampled	ACM Assumed	1200 SF	Good	12" x 12" Off White with Blue Specks
B-018	Pharmacy	Walls	Block	N/A	N/A	N/A	N/A	N/A	
B-018	Pharmacy	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
B-019	Male Washroom	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
B-019	Male Washroom	Walls	Block	N/A	N/A	N/A	N/A	N/A	
B-019	Male Washroom	Ceiling	Drywall (DJC)	Asbestos	16-3996-02*	None Detected	N/A	N/A	*From Fisher Project No. 16-7778, dated May 2016
B-020	Staff Room	Floor	Vinyl Floor Tile 5	Asbestos	Not Sampled	ACM Assumed	65 SF	Good	12" x 12" Off White with Blue Specks
B-020	Staff Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-01 to 03 & 17-7557-19 to 21 & 18-8513-1 to 3	None Detected	N/A	N/A	
B-020	Staff Room	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
B-021	Office	Floor	Vinyl Floor Tile 5	Asbestos	Not Sampled	ACM Assumed	115 SF	Good	12" x 12" Off White with Blue Specks

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
B-021	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-01 to 03 & 17-7557-19 to 21 & 18-8513-1 to 3	None Detected	N/A	N/A	
B-021	Office	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
B-022	Lockers	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	<b>NO ACCESS</b>
B-022	Lockers	Walls	Block	N/A	N/A	N/A	N/A	N/A	
B-022	Lockers	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-023	Main Kitchen	Floor	Flooring Material	Asbestos	21-6394-4 to 6*	None Detected	N/A	N/A	Wash Basin Counter *From Fisher Project No. 21-11172, dated April 2021
B-023	Main Kitchen	Floor	Vinyl Sheet Flooring 26	Asbestos	21-6394-7 to 9*	None Detected	N/A	N/A	Blue with white dots *From Fisher Project No. 21-11172, dated April 2021
B-023	Main Kitchen	Floor	Mastic	Asbestos	21-6394-10 to 12*	None Detected	N/A	N/A	Black - Under VSF *From Fisher Project No. 21-11172, dated April 2021
B-023	Main Kitchen	Floor	Vinyl Sheet Flooring 17	Asbestos	18-8513-10 to 12*	None Detected	N/A	N/A	Grey with Black Dots *From Fisher Project No. 18-8767, dated April 2018 NOT OBSERVED
B-023	Main Kitchen	Floor	Vinyl Sheet Flooring 19	Asbestos	18-8513-13 to 15*	None Detected	N/A	N/A	Dark Grey with Black Dots *From Fisher Project No. 18-8767, dated April 2018 NOT OBSERVED
B-023	Main Kitchen	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
B-023	Main Kitchen	Walls	Grout	Asbestos	21-6394-13 to 15*	None Detected	N/A	N/A	Behind the ceramic tiles *From Fisher Project No. 21-11172, dated April 2021
B-023	Main Kitchen	Walls	Cement Board	Asbestos	21-6394-1 to 3*	None Detected	N/A	N/A	Between the ceramic tiles *From Fisher Project No. 21-11172, dated April 2021
B-023	Main Kitchen	Ceiling	Ceiling Tile 3	N/A	N/A	N/A	N/A	N/A	2' x 4' Plain - Fibreglass
B-024	Washroom	Floor	Vinyl Sheet Flooring 4	Asbestos	16-3996-22 to 24*	None Detected	N/A	N/A	Off white with Blue and White Dots *From Fisher Project No. 16-7778, dated May 2016
B-024	Washroom	Walls	Block	N/A	N/A	N/A	N/A	N/A	
B-024	Washroom	Ceiling	Drywall (DJC)	Asbestos	16-3996-03*	None Detected	N/A	N/A	*From Fisher Project No. 16-7778, dated May 2016
B-025	Storage	Floor	Vinyl Sheet Flooring 4	Asbestos	Homogeneous w/ 16-3996-22 to 24	None Detected	N/A	N/A	Off white with Blue and White Dots
B-025	Storage	Walls	Block	N/A	N/A	N/A	N/A	N/A	
B-025	Storage	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-01 to 03 & 17-7557-19 to 21 & 18-8513-1 to 3	None Detected	N/A	N/A	
B-026	Housekeeping	Floor	Vinyl Sheet Flooring 5	Asbestos	Homogeneous w/ 18-8513-04 to 06	None Detected	N/A	N/A	Red with Black Dots
B-026	Housekeeping	Walls	Ceramic/Concrete	N/A	N/A	N/A	N/A	N/A	
B-026	Housekeeping	Ceiling	Ceiling Tile 2	Asbestos	Not Sampled	ACM Assumed	20 SF	Good	2' x 4' Random Pinhole
B-027	Storage	Floor	Vinyl Sheet Flooring 5	Asbestos	18-8513-04 to 06*	None Detected	N/A	N/A	Red with Black Dots *From Fisher Project No. 18-8767, dated April 2018

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
B-027	Storage	Floor	Vinyl Sheet Flooring 18	Asbestos	18-8513-07 to 09*	None Detected	N/A	N/A	Pink with Black Dots *From Fisher Project No. 18-8767, dated April 2018
B-027	Storage	Walls	Drywall (DJC)	Asbestos	18-8513-01 to 03*	None Detected	N/A	N/A	*From Fisher Project No. 18-8767, dated Apr. 2018
B-027	Storage	Walls	Concrete	N/A	N/A	N/A	N/A	N/A	
B-027	Storage	Ceiling	Ceiling Tile 3	N/A	N/A	N/A	N/A	N/A	2' x 4' Plain - Fibreglass
B-028	Electrical Room	Floor	Vinyl Sheet Flooring 5	Asbestos	Homogeneous w/ 18-8513-04 to 06	None Detected	N/A	N/A	Red with Black Dots
B-028	Electrical Room	Walls	Block	N/A	N/A	N/A	N/A	N/A	
B-028	Electrical Room	Ceiling	Ceiling Tile 2	Asbestos	Not Sampled	ACM Assumed	30 SF	Good	2' x 4' Random Pinhole
B-029	Storage	Floor	Vinyl Sheet Flooring 26	Asbestos	Homogeneous w/ 21-6394-7 to 9	None Detected	N/A	N/A	Blue with white dots
B-029	Storage	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-01 to 03 & 17-7557-19 to 21 & 18-8513-1 to 3	None Detected	N/A	N/A	
B-029	Storage	Ceiling	Ceiling Tile 3	N/A	N/A	N/A	N/A	N/A	2' x 4' Plain - Fibreglass
B-030	Office	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 16-4653-10 to 12	0.5-5% Chrysotile	90 SF	Good	12" x 12" Tan with Rust Streaks
B-030	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-01 to 03 & 17-7557-19 to 21 & 18-8513-1 to 3	None Detected	N/A	N/A	
B-030	Office	Ceiling	Ceiling Tile 3	N/A	N/A	N/A	N/A	N/A	2' x 4' Plain - Fibreglass
B-031	Office	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
B-031	Office	Walls	Block	N/A	N/A	N/A	N/A	N/A	
B-031	Office	Ceiling	Ceiling Tile 3	N/A	N/A	N/A	N/A	N/A	2' x 4' Plain - Fibreglass
B-032	Compressor Room	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
B-032	Compressor Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-01 to 03 & 17-7557-19 to 21 & 18-8513-1 to 3	None Detected	N/A	N/A	
B-032	Compressor Room	Ceiling	Ceiling Tile 3	N/A	N/A	N/A	N/A	N/A	2' x 4' Plain - Fibreglass
B-033	Kitchen Mech Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
B-033	Kitchen Mech Room	Walls	Block/Concrete	N/A	N/A	N/A	N/A	N/A	
B-033	Kitchen Mech Room	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-034	Elevator Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
B-034	Elevator Room	Floor	Paint	Lead	20-5196-1*	294 ppm	N/A	N/A	Dark Grey Paint *From Fisher Project No. 20-10578, dated Sept. 2020

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
B-034	Elevator Room	Walls	Block	N/A	N/A	N/A	N/A	N/A	
B-034	Elevator Room	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-035	Telephone Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
B-035	Telephone Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-01 to 03 & 17-7557-19 to 21 & 18-8513-1 to 3	None Detected	N/A	N/A	
B-035	Telephone Room	Walls	Block	N/A	N/A	N/A	N/A	N/A	
B-035	Telephone Room	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-036	Storage	Floor	Vinyl Sheet Flooring 2	Asbestos	Not Sampled	ACM Assumed	90 SF	Good	Off White with Brown Specks
B-036	Storage	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-01 to 03 & 17-7557-19 to 21 & 18-8513-1 to 3	None Detected	N/A	N/A	
B-036	Storage	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
B-037	Male Washroom	Floor	Vinyl Sheet Flooring 2	Asbestos	Not Sampled	ACM Assumed	195 SF	Good	Off White with Brown Specks
B-037	Male Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-01 to 03 & 17-7557-19 to 21 & 18-8513-1 to 3	None Detected	N/A	N/A	
B-037	Male Washroom	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-038	Male Lockers	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3996-28 to 30	None Detected	N/A	N/A	Tan with Black and White Dots
B-038	Male Lockers	Walls	Block/Concrete	N/A	N/A	N/A	N/A	N/A	
B-038	Male Lockers	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-039	Storage	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
B-039	Storage	Walls	Block	N/A	N/A	N/A	N/A	N/A	
B-039	Storage	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-040	Transformer Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
B-040	Transformer Room	Walls	Block	N/A	N/A	N/A	N/A	N/A	
B-040	Transformer Room	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-041	Electrical Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
B-041	Electrical Room	Walls	Block	N/A	N/A	N/A	N/A	N/A	
B-041	Electrical Room	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
B-042	Female Lockers	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 16-4653-10 to 12	0.5-5% Chrysotile	720 SF	Good	12" x 12" Tan with Rust Streaks
B-042	Female Lockers	Walls	Block	N/A	N/A	N/A	N/A	N/A	
B-042	Female Lockers	Ceiling	Ceiling Tile 2	Asbestos	Not Sampled	ACM Assumed	720 SF	Good	2' x 4' Random Pinhole
B-043	Female Washroom	Floor	Vinyl Sheet Flooring 2	Asbestos	Not Sampled	ACM Assumed	175 SF	Good	Off White with Brown Specks
B-043	Female Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 16-4653-10 to 12	0.5-5% Chrysotile	N/A	N/A	12" x 12" Tan with Rust Streaks NOT OBSERVED
B-043	Female Washroom	Walls	Block	N/A	N/A	N/A	N/A	N/A	
B-043	Female Washroom	Ceiling	Ceiling Tile 2	Asbestos	Not Sampled	ACM Assumed	175 SF	Good	2' x 4' Random Pinhole
B-044	Male Washroom	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
B-044	Male Washroom	Walls	Block	N/A	N/A	N/A	N/A	N/A	
B-044	Male Washroom	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-045	Female Washroom	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
B-045	Female Washroom	Walls	Block	N/A	N/A	N/A	N/A	N/A	
B-045	Female Washroom	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-045	Female Washroom	Pipe	Parging Cement	Asbestos	Homogeneous w/ 082407-15 to 17	70% Chrysotile	N/A	N/A	NOT OBSERVED
B-046	Maintenance Dept	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
B-046	Maintenance Dept	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 16-4653-10 to 12	0.5-5% Chrysotile	125 SF	Good	12" x 12" Tan with Rust Streaks
B-046	Maintenance Dept	Walls	Block/Concrete	N/A	N/A	N/A	N/A	N/A	
B-046	Maintenance Dept	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-01 to 03 & 17-7557-19 to 21 & 18-8513-1 to 3	None Detected	N/A	N/A	
B-046	Maintenance Dept	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-046	Maintenance Dept	Pipe	Parging Cement	Asbestos	Homogeneous w/ 082407-15 to 17	70% Chrysotile	8 Fittings	Good	In the office room
B-047	Storage	Floor	Vinyl Floor Tile 3	Asbestos	Not Sampled	ACM Assumed	70 SF	Good	12" x 12" Blue with White Streaks
B-047	Storage	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-01 to 03 & 17-7557-19 to 21 & 18-8513-1 to 3	None Detected	N/A	N/A	
B-047	Storage	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-048	Storage	Floor	Vinyl Floor Tile 3	Asbestos	Not Sampled	ACM Assumed	720 SF	Good	12" x 12" Blue with White Streaks
B-048	Storage	Walls	Block	N/A	N/A	N/A	N/A	N/A	



APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
B-048	Storage	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-048	Storage	Pipe	Parging Cement	Asbestos	Homogeneous w/ 082407-15 to 17	70% Chrysotile	4 Fittings	Good	
B-049	Storage	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
B-049	Storage	Walls	Block	N/A	N/A	N/A	N/A	N/A	
B-049	Storage	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-050	Storage	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
B-050	Storage	Walls	Block	N/A	N/A	N/A	N/A	N/A	
B-050	Storage	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-051	Male Lockers	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3996-28 to 30	None Detected	N/A	N/A	Tan with Black and White Dots
B-051	Male Lockers	Walls	Block	N/A	N/A	N/A	N/A	N/A	
B-051	Male Lockers	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
B-051	Male Lockers	Pipe	Parging Cement	Asbestos	Homogeneous w/ 082407-15 to 17	70% Chrysotile	N/A	N/A	NOT OBSERVED
B-052	Male Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3996-28 to 30	None Detected	N/A	N/A	Tan with Black and White Dots
B-052	Male Washroom	Walls	Block	N/A	N/A	N/A	N/A	N/A	
B-052	Male Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
B-053	East Mechanical Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
B-053	East Mechanical Room	Walls	Block	N/A	N/A	N/A	N/A	N/A	
B-053	East Mechanical Room	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-053	East Mechanical Room	Pipe	Parging Cement	Asbestos	Homogeneous w/ 082407-15 to 17	70% Chrysotile	15 Fittings	Good	
1-001	West Vestibule	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	40 SF	Good	Grey Mosaic
1-001	West Vestibule	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-01 to 07	None Detected	N/A	N/A	
1-001	West Vestibule	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-01 to 07	None Detected	N/A	N/A	
1-002	Entry	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A	
1-002	Entry	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-01 to 07	None Detected	N/A	N/A	
1-002	Entry	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
1-003	East Vestibule	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	40 SF	Good	Grey Mosaic
1-003	East Vestibule	Walls	Drywall (DJC)	Asbestos	17-7152-01*	None Detected	N/A	N/A	*From Fisher Project No.17-8428, dated Sept. 2017

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
1-003	East Vestibule	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-01 to 07	None Detected	N/A	N/A	
1-004	Corridor	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A	
1-004	Corridor	Walls	Drywall (DJC)	Asbestos	17-7152-02*	None Detected	N/A	N/A	*From Fisher Project No.17-8428, dated Sept. 2017
1-004	Corridor	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
1-005	Female Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3996-28 to 30	None Detected	N/A	N/A	Tan with Black and White Dots
1-005	Female Washroom	Walls	Block/Concrete	N/A	N/A	N/A	N/A	N/A	
1-005	Female Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-01 to 07	None Detected	N/A	N/A	
1-006	Male Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3996-28 to 30	None Detected	N/A	N/A	Tan with Black and White Dots
1-006	Male Washroom	Walls	Block/Concrete	N/A	N/A	N/A	N/A	N/A	
1-006	Male Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-01 to 07	None Detected	N/A	N/A	
1-007	Kitchen	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
1-007	Kitchen	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
1-007	Kitchen	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-01 to 07	None Detected	N/A	N/A	
1-008	Auditorium	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 16-4653-10 to 12	0.5-5% Chrysotile	2600 SF	Good	12" x 12" Tan with Rust Streaks
1-008	Auditorium	Walls	Drywall (DJC)	Asbestos	17-7152-03*	None Detected	N/A	N/A	*From Fisher Project No.17-8428, dated Sept. 2017
1-008	Auditorium	Ceiling	Wood Panels	N/A	N/A	N/A	N/A	N/A	
1-008	Auditorium	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
1-009	Storage	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
1-009	Storage	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-01 to 07	None Detected	N/A	N/A	
1-009	Storage	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-01 to 07	None Detected	N/A	N/A	
1-010	Lobby	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A	
1-010	Lobby	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-01 to 07	None Detected	N/A	N/A	
1-010	Lobby	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
1-011	Gift Shop	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	180 SF	Good	Grey Mosaic
1-011	Gift Shop	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-01 to 07	None Detected	N/A	N/A	
1-011	Gift Shop	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
1-012	Stairs # 2	Floor	Vinyl Floor Tile 1	Asbestos	16-4653-12*	0.5-5% Chrysotile	20 SF	Good	12" x 12" Tan with Rust Streaks *From Fisher Project No. 16-7715, dated Aug. 2016

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
1-012	Stairs # 2	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
1-012	Stairs # 2	Walls	Concrete	N/A	N/A	N/A	N/A	N/A	
1-012	Stairs # 2	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
1-013	West Corridor	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A	
1-013	West Corridor	Walls	Drywall (DJC)	Asbestos	17-7152-04*	None Detected	N/A	N/A	*From Fisher Project No.17-8428, dated Sept. 2017
1-013	West Corridor	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
1-014	Office	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 16-4653-10 to 12	0.5-5% Chrysotile	225 SF	Good	12" x 12" Tan with Rust Streaks
1-014	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-01 to 07	None Detected	N/A	N/A	
1-014	Office	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
1-015	Beauty Salon	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 16-4653-10 to 12	0.5-5% Chrysotile	530 SF	Good	12" x 12" Tan with Rust Streaks
1-015	Beauty Salon	Floor	Vinyl Floor Tile 12	Asbestos	17-7557-25 to 27*	None Detected	N/A	N/A	12" x 12" Grey with Black Specks *From Fisher Project No. 17-8527, dated Nov. 2017
1-015	Beauty Salon	Walls	Drywall (DJC)	Asbestos	17-7557-22 and 23*	None Detected	N/A	N/A	*From Fisher Project No. 17-8527, dated Nov. 2017
1-015	Beauty Salon	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
1-016	Building Services Office	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 16-4653-10 to 12	0.5-5% Chrysotile	160 SF	Good	12" x 12" Tan with Rust Streaks
1-016	Building Services Office	Walls	Drywall (DJC)	Asbestos	17-7557-24*	None Detected	N/A	N/A	*From Fisher Project No. 17-8527, dated Nov. 2017
1-016	Building Services Office	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
1-017	Female Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3996-28 to 30	None Detected	N/A	N/A	Tan with Black and White Dots
1-017	Female Washroom	Walls	Block	N/A	N/A	N/A	N/A	N/A	
1-017	Female Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-01 to 07	None Detected	N/A	N/A	
1-018	Male Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3996-28 to 30	None Detected	N/A	N/A	Tan with Black and White Dots
1-018	Male Washroom	Walls	Block	N/A	N/A	N/A	N/A	N/A	
1-018	Male Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-01 to 07	None Detected	N/A	N/A	
1-019	Computer Room	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A	
1-019	Computer Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-01 to 07	None Detected	N/A	N/A	
1-019	Computer Room	Ceiling	Ceiling Tile 5	Asbestos	Not Sampled	ACM Assumed	210 SF	Good	2' x 4' Pinhole Long Fissure
1-019a	Server Room	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 16-4653-10 to 12	0.5-5% Chrysotile	40 SF	Good	12" x 12" Tan with Rust Streaks
1-019a	Server Room	Walls	Block	N/A	N/A	N/A	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
1-019a	Server Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-01 to 07	None Detected	N/A	N/A	
1-020	Volunteer Office	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A	<b>NO ACCESS</b>
1-020	Volunteer Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-01 to 07	None Detected	N/A	N/A	
1-020	Volunteer Office	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	
1-021	Chapel	Floor	Laminate	N/A	N/A	N/A	N/A	N/A	2' x 4' Pinhole Fissure
1-021	Chapel	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-01 to 07	None Detected	N/A	N/A	
1-021	Chapel	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-01 to 07	None Detected	N/A	N/A	
1-022	Chapel Storage	Floor	Laminate	N/A	N/A	N/A	N/A	N/A	
1-022	Chapel Storage	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-01 to 07	None Detected	N/A	N/A	
1-022	Chapel Storage	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
1-023	Housekeeping	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
1-023	Housekeeping	Walls	Block	N/A	N/A	N/A	N/A	N/A	
1-023	Housekeeping	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-01 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
1-024	Stairs # 1	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
1-024	Stairs # 1	Walls	Concrete	N/A	N/A	N/A	N/A	N/A	
1-024	Stairs # 1	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
1-025	Arts & Crafts	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 16-4653-10 to 12	0.5-5% Chrysotile	2060 SF	Good	12" x 12" Tan with Rust Streaks
1-025	Arts & Crafts	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-01 to 07	None Detected	N/A	N/A	
1-025	Arts & Crafts	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
1-026	Office	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 16-4653-10 to 12	0.5-5% Chrysotile	70 SF	Good	12" x 12" Tan with Rust Streaks
1-026	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-01 to 07	None Detected	N/A	N/A	
1-026	Office	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
1-027	Storage	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 16-4653-10 to 12	0.5-5% Chrysotile	70 SF	Good	12" x 12" Tan with Rust Streaks
1-027	Storage	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-01 to 07	None Detected	N/A	N/A	
1-027	Storage	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
1-028	Office	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 16-4653-10 to 12	0.5-5% Chrysotile	70 SF	Good	12" x 12" Tan with Rust Streaks
1-028	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-01 to 07	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
1-028	Office	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
1-029	Wellness Room	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 16-4653-10 to 12	0.5-5% Chrysotile	280 SF	Good	12" x 12" Tan with Rust Streaks
1-029	Wellness Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-01 to 07	None Detected	N/A	N/A	
1-029	Wellness Room	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
1-030	Office	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 16-4653-10 to 12	0.5-5% Chrysotile	145 SF	Good	12" x 12" Tan with Rust Streaks
1-030	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-01 to 07	None Detected	N/A	N/A	
1-030	Office	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
1-031	Storage	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 16-4653-10 to 12	0.5-5% Chrysotile	250 SF	Good	12" x 12" Tan with Rust Streaks
1-031	Storage	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-01 to 07	None Detected	N/A	N/A	
1-031	Storage	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
1-032	Programs Office	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 16-4653-10 to 12	0.5-5% Chrysotile	145 SF	Good	12" x 12" Tan with Rust Streaks
1-032	Programs Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-01 to 07	None Detected	N/A	N/A	
1-032	Programs Office	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
1-033	Rehab Room	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 16-4653-10 to 12	0.5-5% Chrysotile	275 SF	Good	12" x 12" Tan with Rust Streaks
1-033	Rehab Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-01 to 07	None Detected	N/A	N/A	
1-033	Rehab Room	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
1-034	Office	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 16-4653-10 to 12	0.5-5% Chrysotile	140 SF	Good	12" x 12" Tan with Rust Streaks
1-034	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-01 to 07	None Detected	N/A	N/A	
1-034	Office	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
1-035	Office	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 16-4653-10 to 12	0.5-5% Chrysotile	80 SF	Good	12" x 12" Tan with Rust Streaks
1-035	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-01 to 07	None Detected	N/A	N/A	
1-035	Office	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
1-036	Dining Room	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A	
1-036	Dining Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-01 to 07	None Detected	N/A	N/A	
1-036	Dining Room	Ceiling	Ceiling Tile 6	Asbestos	082407-22 to 24*	None Detected	N/A	N/A	2' x 4' Pinhole Textured *From Building Asbestos Survey Report, dated 2007
1-037	Servery	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A	
1-037	Servery	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-01 to 07	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
1-037	Servery	Ceiling	Wood Panels	N/A	N/A	N/A	N/A	N/A	
1-037	Servery	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
1-037	Servery	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-01 to 07	None Detected	N/A	N/A	
1-038	Reception	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A	
1-038	Reception	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-01 to 07	None Detected	N/A	N/A	
1-038	Reception	Ceiling	Ceiling Tile 5	Asbestos	Not Sampled	ACM Assumed	60 SF	Good	2' x 4' Pinhole Long Fissure
1-039	East Corridor	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A	
1-039	East Corridor	Walls	Drywall (DJC)	Asbestos	17-7152-05*	None Detected	N/A	N/A	*From Fisher Project No.17-8428, dated Sept. 2017
1-039	East Corridor	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
1-040	Stairs # 3	Floor	Vinyl Floor Tile 1	Asbestos	16-4653-10, 11*	0.5-5% Chrysotile	20 SF	Good	12" x 12" Tan with Rust Streaks *From Fisher Project No. 16-7715, dated Aug. 2016
1-040	Stairs # 3	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
1-040	Stairs # 3	Walls	Concrete	N/A	N/A	N/A	N/A	N/A	
1-040	Stairs # 3	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
1-041	Conference Room	Floor	Laminate	N/A	N/A	N/A	N/A	N/A	
1-041	Conference Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-01 to 07	None Detected	N/A	N/A	
1-041	Conference Room	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
1-042	Office	Floor	Laminate	N/A	N/A	N/A	N/A	N/A	
1-042	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-01 to 07	None Detected	N/A	N/A	
1-042	Office	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
1-043	Office	Floor	Laminate	N/A	N/A	N/A	N/A	N/A	
1-043	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-01 to 07	None Detected	N/A	N/A	
1-043	Office	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
1-044	Office	Floor	Laminate	N/A	N/A	N/A	N/A	N/A	
1-044	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-01 to 07	None Detected	N/A	N/A	
1-044	Office	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
1-045	Office	Floor	Laminate	N/A	N/A	N/A	N/A	N/A	
1-045	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-01 to 07	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
1-045	Office	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
1-046	Office	Floor	Laminate	N/A	N/A	N/A	N/A	N/A	
1-046	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-01 to 07	None Detected	N/A	N/A	
1-046	Office	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
1-047	Corridor	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 16-4653-10 to 12	0.5-5% Chrysotile	725 SF	Good	12" x 12" Tan with Rust Streaks
1-047	Corridor	Walls	Drywall (DJC)	Asbestos	17-7152-06*	None Detected	N/A	N/A	*From Fisher Project No.17-8428, dated Sept. 2017
1-047	Corridor	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
1-048	Admin Office	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 16-4653-10 to 12	0.5-5% Chrysotile	675 SF	Good	12" x 12" Tan with Rust Streaks
1-048	Admin Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-01 to 07	None Detected	N/A	N/A	
1-048	Admin Office	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
1-049	Hub Room	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 16-4653-10 to 12	0.5-5% Chrysotile	65 SF	Good	<b>NO ACCESS</b> 12" x 12" Tan with Rust Streaks
1-049	Hub Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-01 to 07	None Detected	N/A	N/A	
1-049	Hub Room	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
1-050	Office	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 16-4653-10 to 12	0.5-5% Chrysotile	80 SF	Good	12" x 12" Tan with Rust Streaks
1-050	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-01 to 07	None Detected	N/A	N/A	
1-050	Office	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
1-051	Office	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 16-4653-10 to 12	0.5-5% Chrysotile	65 SF	Good	12" x 12" Tan with Rust Streaks
1-051	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-01 to 07	None Detected	N/A	N/A	
1-051	Office	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
1-052	Office	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 16-4653-10 to 12	0.5-5% Chrysotile	100 SF	Good	12" x 12" Tan with Rust Streaks
1-052	Office	Walls	Drywall (DJC)	Asbestos	24-3424-1 to 3*	None Detected	N/A	N/A	*From Fisher Project No. 24-14184, dated Sept 2024
1-052	Office	Walls	Paint	Lead	24-3424-4*	1563 ppm	100 SF	Good	Cream *From Fisher Project No. 24-14184, dated Sept 2024
1-052	Office	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
1-053	Office	Floor	Laminate	N/A	N/A	N/A	N/A	N/A	
1-053	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-01 to 07	None Detected	N/A	N/A	
1-053	Office	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
1-054	Washroom	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A	



APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
1-054	Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-01 to 07	None Detected	N/A	N/A	
1-054	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-01 to 07	None Detected	N/A	N/A	
1-055	Office	Floor	Vinyl Sheet Flooring 21	Asbestos	Homogeneous w/ 18-1053-01 to 03	None Detected	N/A	N/A	Grey Wood Laminate like Pattern
1-055	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-01 to 07	None Detected	N/A	N/A	
1-055	Office	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
1-056	Office	Floor	Laminate	N/A	N/A	N/A	N/A	N/A	
1-056	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-01 to 07	None Detected	N/A	N/A	
1-056	Office	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
1-057	Staff Development	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 16-4653-10 to 12	0.5-5% Chrysotile	450 SF	Good	12" x 12" Tan with Rust Streaks
1-057	Staff Development	Walls	Block	N/A	N/A	N/A	N/A	N/A	
1-057	Staff Development	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
1-058	Storage	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 16-4653-10 to 12	0.5-5% Chrysotile	100 SF	Good	12" x 12" Tan with Rust Streaks
1-058	Storage	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-01 to 07	None Detected	N/A	N/A	
1-058	Storage	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
1-059	Lounge	Floor	Laminate	N/A	N/A	N/A	N/A	N/A	
1-059	Lounge	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-01 to 07	None Detected	N/A	N/A	
1-059	Lounge	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
1-060	Stairs # 4	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
1-060	Stairs # 4	Walls	Concrete	N/A	N/A	N/A	N/A	N/A	
1-060	Stairs # 4	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
1-061	Stairs from Basement	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 16-4653-10 to 12	0.5-5% Chrysotile	60 SF	Good	12" x 12" Tan with Rust Streaks
1-061	Stairs from Basement	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
1-061	Stairs from Basement	Walls	Concrete	N/A	N/A	N/A	N/A	N/A	
1-061	Stairs from Basement	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
1-062	Lounge	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 16-4653-10 to 12	0.5-5% Chrysotile	660 SF	Good	12" x 12" Tan with Rust Streaks
1-062	Lounge	Floor	Vinyl Floor Tile 6	Asbestos	Not Sampled	ACM Assumed	100 SF	Good	12" x 12" Beige Mosaic
1-062	Lounge	Floor	Vinyl Floor Tile 7	Asbestos	Not Sampled	ACM Assumed	10 SF	Good	12" x 12" Beige with White and Brown Smears

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
1-062	Lounge	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-01 to 07	None Detected	N/A	N/A	
1-062	Lounge	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
1-063	Resident Laundry Room	Floor	Vinyl Sheet Flooring 27	Asbestos	Not Sampled	ACM Assumed	600 SF	Good	Grey with Brown Swirls
1-063	Resident Laundry Room	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 16-4653-10 to 12	0.5-5% Chrysotile	N/A	N/A	12" x 12" Tan with Rust Streaks NOT OBSERVED
1-063	Resident Laundry Room	Floor	Vinyl Floor Tile 14	Asbestos	18-1246-1 to 3*	None Detected	N/A	N/A	12" x 12" Off-white with Brown Smears *From Project No. 18-9112, dated Nov. 2018 NOT OBSERVED
1-063	Resident Laundry Room	Walls	Paint	Lead	18-1246-12*	41 ppm	N/A	N/A	Light Green *From Project No. 18-9112, dated Nov. 2018
1-063	Resident Laundry Room	Walls	Paint	Lead	18-1246-13*	13 ppm	N/A	N/A	Light Brown *From Project No. 18-9112, dated Nov. 2018
1-063	Resident Laundry Room	Walls	Paint	Lead	18-1246-14*	<10 ppm	N/A	N/A	Dark Brown *From Project No. 18-9112, dated Nov. 2018
1-063	Resident Laundry Room	Walls	Drywall (DJC)	Asbestos	18-1246-6 to 8*	0.5-5% Chrysotile	1500 SF	Good	*From Project No. 18-9112, dated Nov. 2018
1-063	Resident Laundry Room	Windows	Putty	Asbestos	18-1246-9 to 11*	0.5-5% Chrysotile	N/A	N/A	Black, around window panes *From Project No. 18-9112, dated Nov. 2018 NOT OBSERVED
1-063	Resident Laundry Room	Ceiling	Drywall (DJC)	Asbestos	18-1246-4, 5*	0.5-5% Chrysotile	N/A	N/A	*From Project No. 18-9112, dated Nov. 2018 NOT OBSERVED
1-063	Resident Laundry Room	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
1-064	Female Washroom	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
1-064	Female Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-01 to 07	None Detected	N/A	N/A	
1-064	Female Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-01 to 07	None Detected	N/A	N/A	
1-065	Storage	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 16-4653-10 to 12	0.5-5% Chrysotile	60 SF	Good	12" x 12" Tan with Rust Streaks
1-065	Storage	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-01 to 07	None Detected	N/A	N/A	
1-065	Storage	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-01 to 07	None Detected	N/A	N/A	
1-066	Female Lockers	Floor	Vinyl Floor Tile 6	Asbestos	Not Sampled	ACM Assumed	620 SF	Good	12" x 12" Beige Mosaic
1-066	Female Lockers	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-01 to 07	None Detected	N/A	N/A	
1-066	Female Lockers	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
1-067	Female Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3996-28 to 30	None Detected	N/A	N/A	Tan with Black and White Dots
1-067	Female Washroom	Walls	Block	N/A	N/A	N/A	N/A	N/A	
1-067	Female Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-01 to 07	None Detected	N/A	N/A	
1-068	Male Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3996-28 to 30	None Detected	N/A	N/A	Tan with Black and White Dots
1-068	Male Washroom	Walls	Block	N/A	N/A	N/A	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
1-068	Male Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-01 to 07	None Detected	N/A	N/A	
1-069	Office	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 16-4653-10 to 12	0.5-5% Chrysotile	130 SF	Good	12" x 12" Tan with Rust Streaks
1-069	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-01 to 07	None Detected	N/A	N/A	
1-069	Office	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
1-070	Office	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 16-4653-10 to 12	0.5-5% Chrysotile	100 SF	Good	12" x 12" Tan with Rust Streaks
1-070	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-01 to 07	None Detected	N/A	N/A	
1-070	Office	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
1-071	Office	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 16-4653-10 to 12	0.5-5% Chrysotile	100 SF	Good	12" x 12" Tan with Rust Streaks
1-071	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-01 to 07	None Detected	N/A	N/A	
1-071	Office	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
1-072	Office	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 16-4653-10 to 12	0.5-5% Chrysotile	130 SF	Good	12" x 12" Tan with Rust Streaks
1-072	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-01 to 07	None Detected	N/A	N/A	
1-072	Office	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
1-073	Nurse's Office	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 16-4653-10 to 12	0.5-5% Chrysotile	100 SF	Good	12" x 12" Tan with Rust Streaks
1-073	Nurse's Office	Walls	Drywall (DJC)	Asbestos	17-7152-07*	None Detected	N/A	N/A	*From Fisher Project No.17-8428, dated Sept. 2017
1-073	Nurse's Office	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
1-074	Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 16-4653-10 to 12	0.5-5% Chrysotile	20 SF	Good	12" x 12" Tan with Rust Streaks
1-074	Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-01 to 07	None Detected	N/A	N/A	
1-074	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-01 to 07	None Detected	N/A	N/A	
1-074	Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
1-075	Computer Room	Floor	Vinyl Sheet Flooring 28	Asbestos	Not Sampled	ACM Assumed	200 SF	Good	Light Grey with White and Grey Mosaic
1-075	Computer Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-01 to 07	None Detected	N/A	N/A	
1-075	Computer Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-01 to 07	None Detected	N/A	N/A	
2-001	Lobby	Floor	Vinyl Sheet Flooring 11	Asbestos	Not Sampled	ACM Assumed	2000 SF	Good	Brown Mosaic
2-001	Lobby	Walls	Drywall (DJC)	Asbestos	17-7152-08*	None Detected	N/A	N/A	*From Fisher Project No.17-8428, dated Sept. 2017
2-001	Lobby	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
2-002	Corridor	Floor	Vinyl Sheet Flooring 27	Asbestos	Not Sampled	ACM Assumed	1450 SF	Good	Grey with Brown Swirls

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
2-002	Corridor	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-08 to 13 & 16-3996-04 to 06	None Detected	N/A	N/A	
2-002	Corridor	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
2-003	Room 201W	Floor	Vinyl Sheet Flooring 11	Asbestos	Not Sampled	ACM Assumed	220 SF	Good	Brown Mosaic
2-003	Room 201W	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-08 to 13 & 16-3996-04 to 06	None Detected	N/A	N/A	
2-003	Room 201W	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
2-004	Room 202W & WR	Floor	Vinyl Sheet Flooring 11	Asbestos	Not Sampled	ACM Assumed	220 SF	Good	Brown Mosaic
2-004	Room 202W & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-08 to 13 & 16-3996-04 to 06	None Detected	N/A	N/A	
2-004	Room 202W & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-08 to 13 & 16-3996-04 to 06	None Detected	N/A	N/A	
2-004	Room 202W & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
2-005	Room 203W	Floor	Vinyl Sheet Flooring 11	Asbestos	Not Sampled	ACM Assumed	220 SF	Good	Brown Mosaic
2-005	Room 203W	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-08 to 13 & 16-3996-04 to 06	None Detected	N/A	N/A	
2-005	Room 203W	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
2-006	Room 204W & WR	Floor	Vinyl Sheet Flooring 11	Asbestos	Not Sampled	ACM Assumed	220 SF	Good	Brown Mosaic
2-006	Room 204W & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-08 to 13 & 16-3996-04 to 06	None Detected	N/A	N/A	
2-006	Room 204W & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-08 to 13 & 16-3996-04 to 06	None Detected	N/A	N/A	
2-006	Room 204W & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
2-007	Room 205W & WR	Floor	Vinyl Sheet Flooring 11	Asbestos	Not Sampled	ACM Assumed	220 SF	Good	Brown Mosaic
2-007	Room 205W & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-08 to 13 & 16-3996-04 to 06	None Detected	N/A	N/A	
2-007	Room 205W & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-08 to 13 & 16-3996-04 to 06	None Detected	N/A	N/A	
2-007	Room 205W & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
2-008	Lounge	Floor	Vinyl Sheet Flooring 11	Asbestos	Not Sampled	ACM Assumed	220 SF	Good	Brown Mosaic
2-008	Lounge	Walls	Drywall (DJC)	Asbestos	17-7152-09*	None Detected	N/A	N/A	*From Fisher Project No.17-8428, dated Sept. 2017

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
2-008	Lounge	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-08 to 13 & 16-3996-04 to 06	None Detected	N/A	N/A	
2-008	Lounge	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
2-009	Room 206W	Floor	Vinyl Sheet Flooring 11	Asbestos	Not Sampled	ACM Assumed	220 SF	Good	Brown Mosaic
2-009	Room 206W	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-08 to 13 & 16-3996-04 to 06	None Detected	N/A	N/A	
2-009	Room 206W	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
2-010	Room 207W & WR	Floor	Vinyl Sheet Flooring 11	Asbestos	Not Sampled	ACM Assumed	220 SF	Good	Brown Mosaic
2-010	Room 207W & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-08 to 13 & 16-3996-04 to 06	None Detected	N/A	N/A	
2-010	Room 207W & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-08 to 13 & 16-3996-04 to 06	None Detected	N/A	N/A	
2-010	Room 207W & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
2-011	Room 208W & WR	Floor	Vinyl Sheet Flooring 11	Asbestos	Not Sampled	ACM Assumed	220 SF	Good	Brown Mosaic
2-011	Room 208W & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-08 to 13 & 16-3996-04 to 06	None Detected	N/A	N/A	
2-011	Room 208W & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-08 to 13 & 16-3996-04 to 06	None Detected	N/A	N/A	
2-011	Room 208W & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
2-012	Room 209W	Floor	Vinyl Sheet Flooring 11	Asbestos	Not Sampled	ACM Assumed	220 SF	Good	Brown Mosaic
2-012	Room 209W	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-08 to 13 & 16-3996-04 to 06	None Detected	N/A	N/A	
2-012	Room 209W	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
2-013	Room 210W & WR	Floor	Vinyl Sheet Flooring 11	Asbestos	Not Sampled	ACM Assumed	220 SF	Good	Brown Mosaic
2-013	Room 210W & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-08 to 13 & 16-3996-04 to 06	None Detected	N/A	N/A	
2-013	Room 210W & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-08 to 13 & 16-3996-04 to 06	None Detected	N/A	N/A	
2-013	Room 210W & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
2-014	Room 211W	Floor	Vinyl Sheet Flooring 11	Asbestos	Not Sampled	ACM Assumed	220 SF	Good	Brown Mosaic
2-014	Room 211W	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-08 to 13 & 16-3996-04 to 06	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
2-014	Room 211W	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
2-015	Room 212W & WR	Floor	Vinyl Sheet Flooring 11	Asbestos	Not Sampled	ACM Assumed	220 SF	Good	Brown Mosaic
2-015	Room 212W & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-08 to 13 & 16-3996-04 to 06	None Detected	N/A	N/A	
2-015	Room 212W & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-08 to 13 & 16-3996-04 to 06	None Detected	N/A	N/A	
2-015	Room 212W & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
2-016	Room 213W & WR	Floor	Vinyl Sheet Flooring 11	Asbestos	Not Sampled	ACM Assumed	220 SF	Good	Brown Mosaic
2-016	Room 213W & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-08 to 13 & 16-3996-04 to 06	None Detected	N/A	N/A	
2-016	Room 213W & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-08 to 13 & 16-3996-04 to 06	None Detected	N/A	N/A	
2-016	Room 213W & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
2-017	Room 214W	Floor	Vinyl Sheet Flooring 11	Asbestos	Not Sampled	ACM Assumed	220 SF	Good	Brown Mosaic
2-017	Room 214W	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-08 to 13 & 16-3996-04 to 06	None Detected	N/A	N/A	
2-017	Room 214W	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
2-018	Room 215W & WR	Floor	Vinyl Sheet Flooring 11	Asbestos	Not Sampled	ACM Assumed	220 SF	Good	Brown Mosaic
2-018	Room 215W & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-08 to 13 & 16-3996-04 to 06	None Detected	N/A	N/A	
2-018	Room 215W & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-08 to 13 & 16-3996-04 to 06	None Detected	N/A	N/A	
2-018	Room 215W & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
2-019	Lounge	Floor	Vinyl Sheet Flooring 11	Asbestos	Not Sampled	ACM Assumed	220 SF	Good	Brown Mosaic
2-019	Lounge	Walls	Drywall (DJC)	Asbestos	17-7152-10*	None Detected	N/A	N/A	*From Fisher Project No.17-8428, dated Sept. 2017
2-019	Lounge	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
2-020	Room 216W	Floor	Vinyl Sheet Flooring 11	Asbestos	Not Sampled	ACM Assumed	220 SF	Good	Brown Mosaic
2-020	Room 216W	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-08 to 13 & 16-3996-04 to 06	None Detected	N/A	N/A	
2-020	Room 216W	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
2-021	Room 217W & WR	Floor	Vinyl Sheet Flooring 11	Asbestos	Not Sampled	ACM Assumed	220 SF	Good	Brown Mosaic

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
2-021	Room 217W & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-08 to 13 & 16-3996-04 to 06	None Detected	N/A	N/A	
2-021	Room 217W & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-08 to 13 & 16-3996-04 to 06	None Detected	N/A	N/A	
2-021	Room 217W & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
2-022	Room 218W & WR	Floor	Vinyl Sheet Flooring 11	Asbestos	Not Sampled	ACM Assumed	220 SF	Good	Brown Mosaic
2-022	Room 218W & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-08 to 13 & 16-3996-04 to 06	None Detected	N/A	N/A	
2-022	Room 218W & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-08 to 13 & 16-3996-04 to 06	None Detected	N/A	N/A	
2-022	Room 218W & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
2-023	Room 219W	Floor	Vinyl Sheet Flooring 11	Asbestos	Not Sampled	ACM Assumed	220 SF	Good	Brown Mosaic
2-023	Room 219W	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-08 to 13 & 16-3996-04 to 06	None Detected	N/A	N/A	
2-023	Room 219W	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
2-024	Room 220W & WR	Floor	Vinyl Sheet Flooring 11	Asbestos	Not Sampled	ACM Assumed	220 SF	Good	Brown Mosaic
2-024	Room 220W & WR	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-08 to 13 & 16-3996-04 to 06	None Detected	N/A	N/A	
2-024	Room 220W & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-08 to 13 & 16-3996-04 to 06	None Detected	N/A	N/A	
2-024	Room 220W & WR	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
2-025	Shower & Tub Room	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
2-025	Shower & Tub Room	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
2-025	Shower & Tub Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-08 to 13 & 16-3996-04 to 06	None Detected	N/A	N/A	
2-026	Waiting Room	Floor	Vinyl Sheet Flooring 11	Asbestos	Not Sampled	ACM Assumed	220 SF	Good	Brown Mosaic
2-026	Waiting Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-08 to 13 & 16-3996-04 to 06	None Detected	N/A	N/A	
2-026	Waiting Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-08 to 13 & 16-3996-04 to 06	None Detected	N/A	N/A	
2-027	Reception	Floor	Vinyl Sheet Flooring 11	Asbestos	Not Sampled	ACM Assumed	160 SF	Good	Brown Mosaic
2-027	Reception	Walls	Drywall (DJC)	Asbestos	17-7152-11*	None Detected	N/A	N/A	*From Fisher Project No.17-8428, dated Sept. 2017



APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
2-027	Reception	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-08 to 13 & 16-3996-04 to 06	None Detected	N/A	N/A	
2-028	Treatment Room	Floor	Vinyl Sheet Flooring 11	Asbestos	Not Sampled	ACM Assumed	120 SF	Good	Brown Mosaic
2-028	Treatment Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-08 to 13 & 16-3996-04 to 06	None Detected	N/A	N/A	
2-028	Treatment Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-08 to 13 & 16-3996-04 to 06	None Detected	N/A	N/A	
2-029	Med. Room	Floor	Vinyl Sheet Flooring 24	Asbestos	18-1053-04 to 06*	None Detected	N/A	N/A	Light Grey with Off White Pattern * From Fisher Project No. 18-9072, dated Oct. 2018
2-029	Med. Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-08 to 13 & 16-3996-04 to 06	None Detected	N/A	N/A	
2-029	Med. Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-08 to 13 & 16-3996-04 to 06	None Detected	N/A	N/A	
2-030	Storage	Floor	Vinyl Sheet Flooring 11	Asbestos	Not Sampled	ACM Assumed	60 SF	Good	Brown Mosaic
2-030	Storage	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-08 to 13 & 16-3996-04 to 06	None Detected	N/A	N/A	
2-030	Storage	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-08 to 13 & 16-3996-04 to 06	None Detected	N/A	N/A	
2-031	Office	Floor	Vinyl Sheet Flooring 11	Asbestos	Not Sampled	ACM Assumed	80 SF	Good	Brown Mosaic
2-031	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-08 to 13 & 16-3996-04 to 06	None Detected	N/A	N/A	
2-031	Office	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-08 to 13 & 16-3996-04 to 06	None Detected	N/A	N/A	
2-032	Storage	Floor	Vinyl Sheet Flooring 11	Asbestos	Not Sampled	ACM Assumed	60 SF	Good	Brown Mosaic
2-032	Storage	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-08 to 13 & 16-3996-04 to 06	None Detected	N/A	N/A	
2-032	Storage	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-08 to 13 & 16-3996-04 to 06	None Detected	N/A	N/A	
2-033	Tub Room	Floor	Vinyl Sheet Flooring 12	Asbestos	Not Sampled	ACM Assumed	100 SF	Good	Off White with Grey Spots
2-033	Tub Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-08 to 13 & 16-3996-04 to 06	None Detected	N/A	N/A	
2-033	Tub Room	Ceiling	Ceiling Tile 7	Asbestos	Not Sampled	ACM Assumed	100 SF	Good	2' x 4' Pinhole Small Fissure
2-034	Shower & WR	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
2-034	Shower & WR	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	



APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
2-034	Shower & WR	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-08 to 13 & 16-3996-04 to 06	None Detected	N/A	N/A	
2-035	Utility	Floor	Vinyl Sheet Flooring 11	Asbestos	Not Sampled	ACM Assumed	80 SF	Good	<b>NO ACCESS</b> Brown Mosaic
2-035	Utility	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
2-035	Utility	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-08 to 13 & 16-3996-04 to 06	None Detected	N/A	n/A	
2-036	Housekeeping	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
2-036	Housekeeping	Walls	Block	N/A	N/A	N/A	N/A	N/A	
2-036	Housekeeping	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-08 to 13 & 16-3996-04 to 06	None Detected	N/A	N/A	
2-037	Office	Floor	Vinyl Sheet Flooring 11	Asbestos	Not Sampled	ACM Assumed	55 SF	Good	Brown Mosaic
2-037	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-08 to 13 & 16-3996-04 to 06	None Detected	N/A	N/A	
2-037	Office	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-08 to 13 & 16-3996-04 to 06	None Detected	N/A	N/A	
2-038	Disposal Chute	Floor	Vinyl Sheet Flooring 11	Asbestos	Not Sampled	ACM Assumed	30 SF	Good	<b>NO ACCESS</b> Brown Mosaic
2-038	Disposal Chute	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-08 to 13 & 16-3996-04 to 06	None Detected	N/A	N/A	
2-038	Disposal Chute	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-08 to 13 & 16-3996-04 to 06	None Detected	N/A	N/A	
2-039	Storage	Floor	Vinyl Sheet Flooring 11	Asbestos	Not Sampled	ACM Assumed	80 SF	Good	Brown Mosaic
2-039	Storage	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-08 to 13 & 16-3996-04 to 06	None Detected	N/A	N/A	
2-039	Storage	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
2-040	Resident Kitchen	Floor	Vinyl Sheet Flooring 11	Asbestos	Not Sampled	ACM Assumed	300 SF	Good	Brown Mosaic
2-040	Resident Kitchen	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-08 to 13 & 16-3996-04 to 06	None Detected	N/A	N/A	
2-040	Resident Kitchen	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
2-041	Dining Room	Floor	Vinyl Sheet Flooring 11	Asbestos	Not Sampled	ACM Assumed	2400 SF	Good	Brown Mosaic
2-041	Dining Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-08 to 13 & 16-3996-04 to 06	None Detected	N/A	N/A	
2-041	Dining Room	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
2-042	Servery	Floor	Vinyl Sheet Flooring 23	Asbestos	Not Sampled	ACM Assumed	430 SF	Good	Light Cream with Black Dots
2-042	Servery	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-08 to 13 & 16-3996-04 to 06	None Detected	N/A	N/A	
2-042	Servery	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-08 to 13 & 16-3996-04 to 06	None Detected	N/A	N/A	
2-042	Servery	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
2-043	Multi Purpose Room	Floor	Vinyl Sheet Flooring 11	Asbestos	Not Sampled	ACM Assumed	220 SF	Good	Brown Mosaic
2-043	Multi Purpose Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-08 to 13 & 16-3996-04 to 06	None Detected	N/A	N/A	
2-043	Multi Purpose Room	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
2-044	Lounge	Floor	Vinyl Sheet Flooring 11	Asbestos	Not Sampled	ACM Assumed	300 SF	Good	Brown Mosaic
2-044	Lounge	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-08 to 13 & 16-3996-04 to 06	None Detected	N/A	N/A	
2-044	Lounge	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-08 to 13 & 16-3996-04 to 06	None Detected	N/A	N/A	
2-045	Office	Floor	Vinyl Sheet Flooring 11	Asbestos	Not Sampled	ACM Assumed	110 SF	Good	Brown Mosaic
2-045	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-08 to 13 & 16-3996-04 to 06	None Detected	N/A	N/A	
2-045	Office	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
2-046	Lobby	Floor	Vinyl Sheet Flooring 11	Asbestos	Not Sampled	ACM Assumed	130 SF	Good	Brown Mosaic
2-046	Lobby	Walls	Drywall (DJC)	Asbestos	17-7152-12*	None Detected	N/A	N/A	*From Fisher Project No.17-8428, dated Sept. 2017
2-046	Lobby	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
2-047	Corridor	Floor	Vinyl Sheet Flooring 20	Asbestos	Not Sampled	ACM Assumed	1750 SF	Good	Beige with White & Brown Specks
2-047	Corridor	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-08 to 13 & 16-3996-04 to 06	None Detected	N/A	N/A	
2-047	Corridor	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
2-048	Nurse's Station	Floor	Vinyl Sheet Flooring 21	Asbestos	Homogeneous w/ 18-1053-01 to 03	None Detected	N/A	N/A	Grey Wood Laminate like Pattern
2-048	Nurse's Station	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-08 to 13 & 16-3996-04 to 06	None Detected	N/A	N/A	
2-048	Nurse's Station	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
2-049	Med. Room	Floor	Vinyl Sheet Flooring 21	Asbestos	18-1053-01 to 03*	None Detected	N/A	N/A	Grey Wood Laminate like Pattern * From Fisher Project No. 18-9072, dated Oct. 2018

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
2-049	Med. Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-08 to 13 & 16-3996-04 to 06	None Detected	N/A	N/A	
2-049	Med. Room	Walls	Paint	Lead	18-1053-11*	8822 ppm	240 SF	Good	Green *From Fisher Project No. 18-9072, dated Oct. 2018
2-049	Med. Room	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
2-050	Activity Room	Floor	Vinyl Sheet Flooring 21	Asbestos	Homogeneous w/ 18-1053-01 to 03	None Detected	N/A	N/A	Grey Wood Laminate like Pattern
2-050	Activity Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-08 to 13 & 16-3996-04 to 06	None Detected	N/A	N/A	
2-050	Activity Room	Ceiling	Ceiling Tile 8	Asbestos	Not Sampled	ACM Assumed	1250 SF	Good	2' x 2' Pinhole Fissure
2-051	Lounge	Floor	Vinyl Sheet Flooring 21	Asbestos	Homogeneous w/ 18-1053-01 to 03	None Detected	N/A	N/A	Grey Wood Laminate like Pattern
2-051	Lounge	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-08 to 13 & 16-3996-04 to 06	None Detected	N/A	N/A	
2-051	Lounge	Ceiling	Ceiling Tile 8	Asbestos	Not Sampled	ACM Assumed	255 SF	Good	2' x 2' Pinhole Fissure
2-052	Room 201C	Floor	Vinyl Sheet Flooring 21	Asbestos	Homogeneous w/ 18-1053-01 to 03	None Detected	N/A	N/A	Grey Wood Laminate like Pattern
2-052	Room 201C	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-08 to 13 & 16-3996-04 to 06	None Detected	N/A	N/A	
2-052	Room 201C	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
2-053	Room 202C	Floor	Vinyl Sheet Flooring 21	Asbestos	Homogeneous w/ 18-1053-01 to 03	None Detected	N/A	N/A	Grey Wood Laminate like Pattern
2-053	Room 202C	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-08 to 13 & 16-3996-04 to 06	None Detected	N/A	N/A	
2-053	Room 202C	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
2-054	Room 203C	Floor	Vinyl Sheet Flooring 21	Asbestos	Homogeneous w/ 18-1053-01 to 03	None Detected	N/A	N/A	Grey Wood Laminate like Pattern
2-054	Room 203C	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-08 to 13 & 16-3996-04 to 06	None Detected	N/A	N/A	
2-054	Room 203C	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
2-055	Room 204C	Floor	Vinyl Sheet Flooring 21	Asbestos	Homogeneous w/ 18-1053-01 to 03	None Detected	N/A	N/A	Grey Wood Laminate like Pattern
2-055	Room 204C	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-08 to 13 & 16-3996-04 to 06	None Detected	N/A	N/A	
2-055	Room 204C	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
2-056	Room 205C	Floor	Vinyl Sheet Flooring 21	Asbestos	Homogeneous w/ 18-1053-01 to 03	None Detected	N/A	N/A	Grey Wood Laminate like Pattern
2-056	Room 205C	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-08 to 13 & 16-3996-04 to 06	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
2-056	Room 205C	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
2-057	Room 206C	Floor	Vinyl Sheet Flooring 21	Asbestos	Homogeneous w/ 18-1053-01 to 03	None Detected	N/A	N/A	Grey Wood Laminate like Pattern
2-057	Room 206C	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-08 to 13 & 16-3996-04 to 06	None Detected	N/A	N/A	
2-057	Room 206C	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
2-058	Room 207C	Floor	Vinyl Sheet Flooring 21	Asbestos	Homogeneous w/ 18-1053-01 to 03	None Detected	N/A	N/A	Grey Wood Laminate like Pattern
2-058	Room 207C	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-08 to 13 & 16-3996-04 to 06	None Detected	N/A	N/A	
2-058	Room 207C	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
2-059	Room 208C	Floor	Vinyl Sheet Flooring 21	Asbestos	Homogeneous w/ 18-1053-01 to 03	None Detected	N/A	N/A	Grey Wood Laminate like Pattern
2-059	Room 208C	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-08 to 13 & 16-3996-04 to 06	None Detected	N/A	N/A	
2-059	Room 208C	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
2-060	Room 209C	Floor	Vinyl Sheet Flooring 21	Asbestos	Homogeneous w/ 18-1053-01 to 03	None Detected	N/A	N/A	Grey Wood Laminate like Pattern
2-060	Room 209C	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-08 to 13 & 16-3996-04 to 06	None Detected	N/A	N/A	
2-060	Room 209C	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
2-061	Room 210C	Floor	Vinyl Sheet Flooring 21	Asbestos	Homogeneous w/ 18-1053-01 to 03	None Detected	N/A	N/A	Grey Wood Laminate like Pattern
2-061	Room 210C	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-08 to 13 & 16-3996-04 to 06	None Detected	N/A	N/A	
2-061	Room 210C	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
2-062	Storage	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	<b>NO ACCESS</b>
2-062	Storage	Walls	Block	N/A	N/A	N/A	N/A	N/A	
2-062	Storage	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
2-063	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
2-063	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-08 to 13 & 16-3996-04 to 06	None Detected	N/A	N/A	
2-063	Office	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
2-064	Conference Room	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
2-064	Conference Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-08 to 13 & 16-3996-04 to 06	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
2-064	Conference Room	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
2-065	Office	Floor	Vinyl Sheet Flooring 29	Asbestos	Not Sampled	ACM Assumed	280 SF	Good	Parquet Design
2-065	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-08 to 13 & 16-3996-04 to 06	None Detected	N/A	N/A	
2-065	Office	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
2-066	Room 219C	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	ACM Assumed	300 SF	Good	Square Mosaic Design
2-066	Room 219C	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-08 to 13 & 16-3996-04 to 06	None Detected	N/A	N/A	
2-066	Room 219C	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
2-067	Room 220C	Floor	Vinyl Sheet Flooring 4	Asbestos	Homogeneous w/ 16-3996-22 to 24	None Detected	N/A	N/A	Off white with Blue and White Dots
2-067	Room 220C	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-08 to 13 & 16-3996-04 to 06	None Detected	N/A	N/A	
2-067	Room 220C	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
2-068	Laundry Room	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
2-068	Laundry Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-08 to 13 & 16-3996-04 to 06	None Detected	N/A	N/A	
2-068	Laundry Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-08 to 13 & 16-3996-04 to 06	None Detected	N/A	N/A	
2-069	Washroom	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
2-069	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-08 to 13 & 16-3996-04 to 06	None Detected	N/A	N/A	
2-069	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-08 to 13 & 16-3996-04 to 06	None Detected	N/A	N/A	
2-070	Washroom	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
2-070	Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-08 to 13 & 16-3996-04 to 06	None Detected	N/A	N/A	
2-070	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-08 to 13 & 16-3996-04 to 06	None Detected	N/A	N/A	
2-071	Washroom	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
2-071	Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-08 to 13 & 16-3996-04 to 06	None Detected	N/A	N/A	
2-071	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-08 to 13 & 16-3996-04 to 06	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
2-072	Washroom	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
2-072	Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-08 to 13 & 16-3996-04 to 06	None Detected	N/A	N/A	
2-072	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-08 to 13 & 16-3996-04 to 06	None Detected	N/A	N/A	
2-073	Treatment Room	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
2-073	Treatment Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-08 to 13 & 16-3996-04 to 06	None Detected	N/A	N/A	
2-073	Treatment Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-08 to 13 & 16-3996-04 to 06	None Detected	N/A	N/A	
2-074	Soiled Utility	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
2-074	Soiled Utility	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-08 to 13 & 16-3996-04 to 06	None Detected	N/A	N/A	
2-074	Soiled Utility	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-08 to 13 & 16-3996-04 to 06	None Detected	N/A	N/A	
2-075	Washroom	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
2-075	Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-08 to 13 & 16-3996-04 to 06	None Detected	N/A	N/A	
2-075	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-08 to 13 & 16-3996-04 to 06	None Detected	N/A	N/A	
2-076	Shower Room	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
2-076	Shower Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-08 to 13 & 16-3996-04 to 06	None Detected	N/A	N/A	
2-076	Shower Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-08 to 13 & 16-3996-04 to 06	None Detected	N/A	N/A	
2-077	Washroom	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
2-077	Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-08 to 13 & 16-3996-04 to 06	None Detected	N/A	N/A	
2-077	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-08 to 13 & 16-3996-04 to 06	None Detected	N/A	N/A	
2-078	Washroom	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
2-078	Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-08 to 13 & 16-3996-04 to 06	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
2-078	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-08 to 13 & 16-3996-04 to 06	None Detected	N/A	N/A	
2-079	Shower Room	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
2-079	Shower Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-08 to 13 & 16-3996-04 to 06	None Detected	N/A	N/A	
2-079	Shower Room	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
2-080	Shower & Tub Room	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
2-080	Shower & Tub Room	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
2-080	Shower & Tub Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-08 to 13 & 16-3996-04 to 06	None Detected	N/A	N/A	
2-081	Housekeeping	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
2-081	Housekeeping	Walls	Block	N/A	N/A	N/A	N/A	N/A	
2-081	Housekeeping	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A	
2-082	Storage	Floor	Vinyl Floor Tile 15	Asbestos	Not Sampled	ACM Assumed	110 SF	Good	12" x 12" Beige with Brown Specks
2-082	Storage	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-08 to 13 & 16-3996-04 to 06	None Detected	N/A	N/A	
2-082	Storage	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
2-083	Washroom	Floor	Vinyl Sheet Flooring 11	Asbestos	Not Sampled	ACM Assumed	100 SF	Good	<b>NO ACCESS</b> Brown Mosaic
2-083	Washroom	Floor	Vinyl Sheet Flooring 10	Asbestos	16-3996-25 to 27*	None Detected	N/A	N/A	Taupe with Beige Swirls *From Fisher Project No. 16-7778, dated May 2016 NOT OBSERVED
2-083	Washroom	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
2-083	Washroom	Ceiling	Drywall (DJC)	Asbestos	16-3996-04 to 06*	None Detected	N/A	N/A	*From Fisher Project No. 16-7778, dated May 2016
2-084	Lounge	Floor	Vinyl Sheet Flooring 11	Asbestos	Not Sampled	ACM Assumed	300 SF	Good	Brown Mosaic
2-084	Lounge	Walls	Drywall (DJC)	Asbestos	17-7152-13*	None Detected	N/A	N/A	*From Fisher Project No.17-8428, dated Sept. 2017
2-084	Lounge	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
2-085	Chapel	Floor	Vinyl Sheet Flooring 11	Asbestos	Not Sampled	ACM Assumed	400 SF	Good	Brown Mosaic
2-085	Chapel	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-08 to 13 & 16-3996-04 to 06	None Detected	N/A	N/A	
2-085	Chapel	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
2-086	Storage	Floor	Vinyl Sheet Flooring 10	Asbestos	Homogeneous w/ 16-3996-25 to 27	None Detected	N/A	N/A	Taupe with Beige Swirls



APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
2-086	Storage	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7152-08 to 13 & 16-3996-04 to 06	None Detected	N/A	N/A	
2-086	Storage	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
3-001	Lobby	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
3-001	Lobby	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 16-4653-10 to 12	0.5-5% Chrysotile	55 SF	Good	12" x 12" Tan with Rust Streaks Under VSF 6
3-001	Lobby	Walls	Drywall (DJC)	Asbestos	17-7152-14*	None Detected	N/A	N/A	*From Fisher Project No.17-8428, dated Sept. 2017
3-001	Lobby	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-07 to 09 & 17-7152-14 to 17	None Detected	N/A	N/A	
3-001	Lobby	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
3-002	Corridor	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
3-002	Corridor	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-07 to 09 & 17-7152-14 to 17	None Detected	N/A	N/A	
3-002	Corridor	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
3-003	Room 301W	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
3-003	Room 301W	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-07 to 09 & 17-7152-14 to 17	None Detected	N/A	N/A	
3-003	Room 301W	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
3-004	Room 302W	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
3-004	Room 302W	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-07 to 09 & 17-7152-14 to 17	None Detected	N/A	N/A	
3-004	Room 302W	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
3-005	Room 303W	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
3-005	Room 303W	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-07 to 09 & 17-7152-14 to 17	None Detected	N/A	N/A	
3-005	Room 303W	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
3-006	Room 304W	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
3-006	Room 304W	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-07 to 09 & 17-7152-14 to 17	None Detected	N/A	N/A	
3-006	Room 304W	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
3-007	Room 305W	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots



APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
3-007	Room 305W	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-07 to 09 & 17-7152-14 to 17	None Detected	N/A	N/A	
3-007	Room 305W	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
3-008	Lounge	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
3-008	Lounge	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-07 to 09 & 17-7152-14 to 17	None Detected	N/A	N/A	
3-008	Lounge	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
3-009	Room 306W	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
3-009	Room 306W	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-07 to 09 & 17-7152-14 to 17	None Detected	N/A	N/A	
3-009	Room 306W	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
3-010	Room 307W	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
3-010	Room 307W	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-07 to 09 & 17-7152-14 to 17	None Detected	N/A	N/A	
3-010	Room 307W	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
3-011	Room 308W	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
3-011	Room 308W	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-07 to 09 & 17-7152-14 to 17	None Detected	N/A	N/A	
3-011	Room 308W	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
3-012	Room 309W	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
3-012	Room 309W	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-07 to 09 & 17-7152-14 to 17	None Detected	N/A	N/A	
3-012	Room 309W	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
3-013	Room 310W	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
3-013	Room 310W	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-07 to 09 & 17-7152-14 to 17	None Detected	N/A	N/A	
3-013	Room 310W	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
3-014	Room 311W	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
3-014	Room 311W	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-07 to 09 & 17-7152-14 to 17	None Detected	N/A	N/A	
3-014	Room 311W	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
3-015	Room 312W	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
3-015	Room 312W	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-07 to 09 & 17-7152-14 to 17	None Detected	N/A	N/A	
3-015	Room 312W	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
3-016	Room 313W	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
3-016	Room 313W	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-07 to 09 & 17-7152-14 to 17	None Detected	N/A	N/A	
3-016	Room 313W	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
3-017	Room 314W	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
3-017	Room 314W	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-07 to 09 & 17-7152-14 to 17	None Detected	N/A	N/A	
3-017	Room 314W	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
3-018	Room 315W	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
3-018	Room 315W	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-07 to 09 & 17-7152-14 to 17	None Detected	N/A	N/A	
3-018	Room 315W	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
3-019	Lounge	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
3-019	Lounge	Walls	Drywall (DJC)	Asbestos	17-7152-15*	None Detected	N/A	N/A	*From Fisher Project No.17-8428, dated Sept. 2017
3-019	Lounge	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
3-020	Room 316W	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
3-020	Room 316W	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-07 to 09 & 17-7152-14 to 17	None Detected	N/A	N/A	
3-020	Room 316W	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
3-021	Room 317W	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
3-021	Room 317W	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-07 to 09 & 17-7152-14 to 17	None Detected	N/A	N/A	
3-021	Room 317W	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
3-022	Room 318W	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
3-022	Room 318W	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-07 to 09 & 17-7152-14 to 17	None Detected	N/A	N/A	
3-022	Room 318W	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
3-023	Room 319W	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
3-023	Room 319W	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-07 to 09 & 17-7152-14 to 17	None Detected	N/A	N/A	
3-023	Room 319W	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
3-024	Room 320W	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
3-024	Room 320W	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-07 to 09 & 17-7152-14 to 17	None Detected	N/A	N/A	
3-024	Room 320W	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
3-025	Washroom	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
3-025	Washroom	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
3-025	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-07 to 09 & 17-7152-14 to 17	None Detected	N/A	N/A	
3-026	Washroom	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
3-026	Washroom	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
3-026	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-07 to 09 & 17-7152-14 to 17	None Detected	N/A	N/A	
3-027	Washroom	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
3-027	Washroom	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
3-027	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-07 to 09 & 17-7152-14 to 17	None Detected	N/A	N/A	
3-028	Washroom	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
3-028	Washroom	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
3-028	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-07 to 09 & 17-7152-14 to 17	None Detected	N/A	N/A	
3-029	Utility	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
3-029	Utility	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
3-029	Utility	Ceiling	Drywall (DJC)	Asbestos	17-7152-16*	None Detected	N/A	N/A	*From Fisher Project No.17-8428, dated Sept. 2017
3-030	Housekeeping	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
3-030	Housekeeping	Walls	Block	N/A	N/A	N/A	N/A	N/A	
3-030	Housekeeping	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-07 to 09 & 17-7152-14 to 17	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
3-031	Office	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 16-4653-10 to 12	0.5-5% Chrysotile	55 SF	Good	12" x 12" Tan with Rust Streaks
3-031	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-07 to 09 & 17-7152-14 to 17	None Detected	N/A	N/A	
3-031	Office	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-07 to 09 & 17-7152-14 to 17	None Detected	N/A	N/A	
3-032	Disposal Chute	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
3-032	Disposal Chute	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-07 to 09 & 17-7152-14 to 17	None Detected	N/A	N/A	
3-032	Disposal Chute	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-07 to 09 & 17-7152-14 to 17	None Detected	N/A	N/A	
3-033	Storage	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
3-033	Storage	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-07 to 09 & 17-7152-14 to 17	None Detected	N/A	N/A	
3-033	Storage	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-07 to 09 & 17-7152-14 to 17	None Detected	N/A	N/A	
3-034	Lounge	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
3-034	Lounge	Walls	Brick/Glass	N/A	N/A	N/A	N/A	N/A	
3-034	Lounge	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-07 to 09 & 17-7152-14 to 17	None Detected	N/A	N/A	
3-035	Dining Room	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
3-035	Dining Room	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 16-4653-10 to 12	0.5-5% Chrysotile	55 SF	Good	12" x 12" Tan with Rust Streaks Under VSF 6
3-035	Dining Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-07 to 09 & 17-7152-14 to 17	None Detected	N/A	N/A	
3-035	Dining Room	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
3-036	Servery	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3996-28 to 30	None Detected	N/A	N/A	Tan with Black and White Dots
3-036	Servery	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-07 to 09 & 17-7152-14 to 17	None Detected	N/A	N/A	
3-036	Servery	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-07 to 09 & 17-7152-14 to 17	None Detected	N/A	N/A	
3-037	Lounge	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
3-037	Lounge	Walls	Brick/Glass	N/A	N/A	N/A	N/A	N/A	
3-037	Lounge	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-07 to 09 & 17-7152-14 to 17	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
3-038	Corridor	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
3-038	Corridor	Walls	Drywall (DJC)	Asbestos	17-7152-17*	None Detected	N/A	N/A	*From Fisher Project No.17-8428, dated Sept. 2017
3-038	Corridor	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
3-039	Room 301C	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
3-039	Room 301C	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-07 to 09 & 17-7152-14 to 17	None Detected	N/A	N/A	
3-039	Room 301C	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
3-040	Room 302C	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
3-040	Room 302C	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-07 to 09 & 17-7152-14 to 17	None Detected	N/A	N/A	
3-040	Room 302C	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
3-041	Room 303C	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
3-041	Room 303C	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-07 to 09 & 17-7152-14 to 17	None Detected	N/A	N/A	
3-041	Room 303C	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
3-042	Room 304C	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
3-042	Room 304C	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-07 to 09 & 17-7152-14 to 17	None Detected	N/A	N/A	
3-042	Room 304C	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
3-043	Room 305C	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
3-043	Room 305C	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-07 to 09 & 17-7152-14 to 17	None Detected	N/A	N/A	
3-043	Room 305C	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
3-044	Lounge	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
3-044	Lounge	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-07 to 09 & 17-7152-14 to 17	None Detected	N/A	N/A	
3-044	Lounge	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
3-045	Room 306C	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
3-045	Room 306C	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-07 to 09 & 17-7152-14 to 17	None Detected	N/A	N/A	
3-045	Room 306C	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
3-046	Room 307C	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
3-046	Room 307C	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-07 to 09 & 17-7152-14 to 17	None Detected	N/A	N/A	
3-046	Room 307C	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
3-047	Room 308C	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
3-047	Room 308C	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-07 to 09 & 17-7152-14 to 17	None Detected	N/A	N/A	
3-047	Room 308C	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
3-048	Room 309C	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
3-048	Room 309C	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-07 to 09 & 17-7152-14 to 17	None Detected	N/A	N/A	
3-048	Room 309C	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
3-049	Room 310C	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
3-049	Room 310C	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-07 to 09 & 17-7152-14 to 17	None Detected	N/A	N/A	
3-049	Room 310C	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
3-050	Room 311C	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
3-050	Room 311C	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-07 to 09 & 17-7152-14 to 17	None Detected	N/A	N/A	
3-050	Room 311C	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
3-051	Room 312C	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
3-051	Room 312C	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-07 to 09 & 17-7152-14 to 17	None Detected	N/A	N/A	
3-051	Room 312C	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
3-052	Room 313C	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
3-052	Room 313C	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-07 to 09 & 17-7152-14 to 17	None Detected	N/A	N/A	
3-052	Room 313C	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
3-053	Room 314C	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
3-053	Room 314C	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-07 to 09 & 17-7152-14 to 17	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
3-053	Room 314C	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
3-054	Room 315C	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
3-054	Room 315C	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-07 to 09 & 17-7152-14 to 17	None Detected	N/A	N/A	
3-054	Room 315C	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
3-055	Lounge	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
3-055	Lounge	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-07 to 09 & 17-7152-14 to 17	None Detected	N/A	N/A	
3-055	Lounge	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
3-056	Room 316C	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
3-056	Room 316C	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-07 to 09 & 17-7152-14 to 17	None Detected	N/A	N/A	
3-056	Room 316C	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
3-057	Room 317C	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
3-057	Room 317C	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-07 to 09 & 17-7152-14 to 17	None Detected	N/A	N/A	
3-057	Room 317C	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
3-058	Room 318C	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
3-058	Room 318C	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-07 to 09 & 17-7152-14 to 17	None Detected	N/A	N/A	
3-058	Room 318C	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
3-059	Room 319C	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
3-059	Room 319C	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-07 to 09 & 17-7152-14 to 17	None Detected	N/A	N/A	
3-059	Room 319C	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
3-060	Room 320C	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
3-060	Room 320C	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-07 to 09 & 17-7152-14 to 17	None Detected	N/A	N/A	
3-060	Room 320C	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
3-061	Washroom	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
3-061	Washroom	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	



APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
3-062	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-07 to 09 & 17-7152-14 to 17	None Detected	N/A	N/A	
3-062	Washroom	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
3-062	Washroom	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
3-062	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-07 to 09 & 17-7152-14 to 17	None Detected	N/A	N/A	
3-063	Washroom	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
3-063	Washroom	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
3-063	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-07 to 09 & 17-7152-14 to 17	None Detected	N/A	N/A	
3-064	Washroom	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
3-064	Washroom	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
3-064	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-07 to 09 & 17-7152-14 to 17	None Detected	N/A	N/A	
3-065	Utility	Floor	Vinyl Sheet Flooring 25	Asbestos	Not Sampled	ACM Assumed	81 SF	Good	Grey with Dark & Light Grey Specks
3-065	Utility	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
3-065	Utility	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-07 to 09 & 17-7152-14 to 17	None Detected	N/A	N/A	
3-066	Housekeeping	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
3-066	Housekeeping	Walls	Block	N/A	N/A	N/A	N/A	N/A	
3-066	Housekeeping	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-07 to 09 & 17-7152-14 to 17	None Detected	N/A	N/A	
3-067	Laundry Room	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 17-7557-01 to 03	0.5-5% Chrysotile	55 SF	Good	12" x 12" Beige with Black Streaks
3-067	Laundry Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-07 to 09 & 17-7152-14 to 17	None Detected	N/A	N/A	
3-067	Laundry Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-07 to 09 & 17-7152-14 to 17	None Detected	N/A	N/A	
3-068	Fire Panel Room	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
3-068	Fire Panel Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-07 to 09 & 17-7152-14 to 17	None Detected	N/A	N/A	
3-068	Fire Panel Room	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
3-069	Corridor	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots



APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
3-069	Corridor	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-07 to 09 & 17-7152-14 to 17	None Detected	N/A	N/A	
3-069	Corridor	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
3-070	Washroom	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
3-070	Washroom	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
3-070	Washroom	Ceiling	Drywall (DJC)	Asbestos	16-3996-07, 08*	None Detected	N/A	N/A	*From Fisher Project No. 16-7778, dated May 2016
3-071	Washroom	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
3-071	Washroom	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
3-071	Washroom	Ceiling	Drywall (DJC)	Asbestos	16-3996-09*	None Detected	N/A	N/A	*From Fisher Project No. 16-7778, dated May 2016
3-072	Room 300	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
3-072	Room 300	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-07 to 09 & 17-7152-14 to 17	None Detected	N/A	N/A	
3-072	Room 300	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
3-073	Office	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
3-073	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-07 to 09 & 17-7152-14 to 17	None Detected	N/A	N/A	
3-073	Office	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
3-074	Med. Room	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
3-074	Med. Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-07 to 09 & 17-7152-14 to 17	None Detected	N/A	N/A	
3-074	Med. Room	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
3-075	Meeting Room	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
3-075	Meeting Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-07 to 09 & 17-7152-14 to 17	None Detected	N/A	N/A	
3-075	Meeting Room	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
3-076	Housekeeping	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
3-076	Housekeeping	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-07 to 09 & 17-7152-14 to 17	None Detected	N/A	N/A	
3-076	Housekeeping	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-07 to 09 & 17-7152-14 to 17	None Detected	N/A	N/A	
3-077	Treatment Room	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
3-077	Treatment Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-07 to 09 & 17-7152-14 to 17	None Detected	N/A	N/A	
3-077	Treatment Room	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
3-078	Nurse's Station	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
3-078	Nurse's Station	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-07 to 09 & 17-7152-14 to 17	None Detected	N/A	N/A	
3-078	Nurse's Station	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
4-001	Lobby	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
4-001	Lobby	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-10 to 12 & 17-7151-18 to 21	None Detected	N/A	N/A	
4-001	Lobby	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-10 to 12 & 17-7151-18 to 21	None Detected	N/A	N/A	
4-001	Lobby	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
4-002	Corridor	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
4-002	Corridor	Walls	Drywall (DJC)	Asbestos	17-7152-18*	None Detected	N/A	N/A	*From Fisher Project No.17-8428, dated Sept. 2017
4-002	Corridor	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
4-003	Room 401W	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
4-003	Room 401W	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-10 to 12 & 17-7151-18 to 21	None Detected	N/A	N/A	
4-003	Room 401W	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
4-004	Room 402W	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
4-004	Room 402W	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-10 to 12 & 17-7151-18 to 21	None Detected	N/A	N/A	
4-004	Room 402W	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
4-005	Room 403W	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
4-005	Room 403W	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-10 to 12 & 17-7151-18 to 21	None Detected	N/A	N/A	
4-005	Room 403W	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
4-006	Room 404W	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
4-006	Room 404W	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-10 to 12 & 17-7151-18 to 21	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
4-006	Room 404W	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
4-007	Room 405W	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
4-007	Room 405W	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-10 to 12 & 17-7151-18 to 21	None Detected	N/A	N/A	
4-007	Room 405W	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
4-008	Lounge	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
4-008	Lounge	Walls	Drywall (DJC)	Asbestos	17-7152-19*	None Detected	N/A	N/A	*From Fisher Project No.17-8428, dated Sept. 2017
4-008	Lounge	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
4-009	Room 406W	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
4-009	Room 406W	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-10 to 12 & 17-7151-18 to 21	None Detected	N/A	N/A	
4-009	Room 406W	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
4-010	Room 407W	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
4-010	Room 407W	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-10 to 12 & 17-7151-18 to 21	None Detected	N/A	N/A	
4-010	Room 407W	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
4-011	Room 408W	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
4-011	Room 408W	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-10 to 12 & 17-7151-18 to 21	None Detected	N/A	N/A	
4-011	Room 408W	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
4-012	Room 409W	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
4-012	Room 409W	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-10 to 12 & 17-7151-18 to 21	None Detected	N/A	N/A	
4-012	Room 409W	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
4-013	Room 410W	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
4-013	Room 410W	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-10 to 12 & 17-7151-18 to 21	None Detected	N/A	N/A	
4-013	Room 410W	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
4-014	Room 411W	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
4-014	Room 411W	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-10 to 12 & 17-7151-18 to 21	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
4-014	Room 411W	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
4-015	Room 412W	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
4-015	Room 412W	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-10 to 12 & 17-7151-18 to 21	None Detected	N/A	N/A	
4-015	Room 412W	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
4-016	Room 413W	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
4-016	Room 413W	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-10 to 12 & 17-7151-18 to 21	None Detected	N/A	N/A	
4-016	Room 413W	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
4-017	Room 414W	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
4-017	Room 414W	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-10 to 12 & 17-7151-18 to 21	None Detected	N/A	N/A	
4-017	Room 414W	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
4-018	Room 415W	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
4-018	Room 415W	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-10 to 12 & 17-7151-18 to 21	None Detected	N/A	N/A	
4-018	Room 415W	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
4-019	Lounge	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
4-019	Lounge	Walls	Drywall (DJC)	Asbestos	17-7152-20*	None Detected	N/A	N/A	*From Fisher Project No.17-8428, dated Sept. 2017
4-019	Lounge	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
4-020	Room 416W	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
4-020	Room 416W	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-10 to 12 & 17-7151-18 to 21	None Detected	N/A	N/A	
4-020	Room 416W	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
4-021	Room 417W	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
4-021	Room 417W	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-10 to 12 & 17-7151-18 to 21	None Detected	N/A	N/A	
4-021	Room 417W	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
4-022	Room 418W	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
4-022	Room 418W	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-10 to 12 & 17-7151-18 to 21	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
4-022	Room 418W	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
4-023	Room 419W	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
4-023	Room 419W	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-10 to 12 & 17-7151-18 to 21	None Detected	N/A	N/A	
4-023	Room 419W	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
4-024	Room 420W	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
4-024	Room 420W	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-10 to 12 & 17-7151-18 to 21	None Detected	N/A	N/A	
4-024	Room 420W	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
4-025	Washroom	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
4-025	Washroom	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
4-025	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-10 to 12 & 17-7151-18 to 21	None Detected	N/A	N/A	
4-026	Washroom	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
4-026	Washroom	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
4-026	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-10 to 12 & 17-7151-18 to 21	None Detected	N/A	N/A	
4-027	Washroom	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
4-027	Washroom	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
4-027	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-10 to 12 & 17-7151-18 to 21	None Detected	N/A	N/A	
4-028	Washroom	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
4-028	Washroom	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
4-028	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-10 to 12 & 17-7151-18 to 21	None Detected	N/A	N/A	
4-029	Utility	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
4-029	Utility	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
4-029	Utility	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-10 to 12 & 17-7151-18 to 21	None Detected	N/A	N/A	
4-030	Housekeeping	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
4-030	Housekeeping	Walls	Block	N/A	N/A	N/A	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
4-030	Housekeeping	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-10 to 12 & 17-7151-18 to 21	None Detected	N/A	N/A	
4-031	Office	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 16-4653-10 to 12	0.5-5% Chrysotile	55 SF	Good	12" x 12" Tan with Rust Streaks
4-031	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-10 to 12 & 17-7151-18 to 21	None Detected	N/A	N/A	
4-031	Office	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-10 to 12 & 17-7151-18 to 21	None Detected	N/A	N/A	
4-032	Disposal Chute	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
4-032	Disposal Chute	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-10 to 12 & 17-7151-18 to 21	None Detected	N/A	N/A	
4-032	Disposal Chute	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-10 to 12 & 17-7151-18 to 21	None Detected	N/A	N/A	
4-033	Storage	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
4-033	Storage	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-10 to 12 & 17-7151-18 to 21	None Detected	N/A	N/A	
4-033	Storage	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-10 to 12 & 17-7151-18 to 21	None Detected	N/A	N/A	
4-034	Lounge	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
4-034	Lounge	Walls	Brick/Glass	N/A	N/A	N/A	N/A	N/A	
4-034	Lounge	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-10 to 12 & 17-7151-18 to 21	None Detected	N/A	N/A	
4-035	Dining Room	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
4-035	Dining Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-10 to 12 & 17-7151-18 to 21	None Detected	N/A	N/A	
4-035	Dining Room	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
4-036	Servery	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3996-28 to 30	None Detected	N/A	N/A	Tan with Black and White Dots
4-036	Servery	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-10 to 12 & 17-7151-18 to 21	None Detected	N/A	N/A	
4-036	Servery	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-10 to 12 & 17-7151-18 to 21	None Detected	N/A	N/A	
4-037	Lounge	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
4-037	Lounge	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots NOT OBSERVED
4-037	Lounge	Walls	Brick/Glass	N/A	N/A	N/A	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
4-037	Lounge	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-10 to 12 & 17-7151-18 to 21	None Detected	N/A	N/A	
4-038	Corridor	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
4-038	Corridor	Walls	Drywall (DJC)	Asbestos	17-7152-21*	None Detected	N/A	N/A	*From Fisher Project No.17-8428, dated Sept. 2017
4-038	Corridor	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
4-039	Room 401C	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
4-039	Room 401C	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-10 to 12 & 17-7151-18 to 21	None Detected	N/A	N/A	
4-039	Room 401C	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
4-040	Room 402C	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
4-040	Room 402C	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-10 to 12 & 17-7151-18 to 21	None Detected	N/A	N/A	
4-040	Room 402C	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
4-041	Room 403C	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
4-041	Room 403C	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-10 to 12 & 17-7151-18 to 21	None Detected	N/A	N/A	
4-041	Room 403C	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
4-042	Room 404C	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
4-042	Room 404C	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-10 to 12 & 17-7151-18 to 21	None Detected	N/A	N/A	
4-042	Room 404C	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
4-043	Room 405C	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
4-043	Room 405C	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-10 to 12 & 17-7151-18 to 21	None Detected	N/A	N/A	
4-043	Room 405C	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
4-044	Lounge	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
4-044	Lounge	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-10 to 12 & 17-7151-18 to 21	None Detected	N/A	N/A	
4-044	Lounge	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
4-045	Room 406C	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots



APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
4-045	Room 406C	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-10 to 12 & 17-7151-18 to 21	None Detected	N/A	N/A	
4-045	Room 406C	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
4-046	Room 407C	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
4-046	Room 407C	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-10 to 12 & 17-7151-18 to 21	None Detected	N/A	N/A	
4-046	Room 407C	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
4-047	Room 408C	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
4-047	Room 408C	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-10 to 12 & 17-7151-18 to 21	None Detected	N/A	N/A	
4-047	Room 408C	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
4-048	Room 409C	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
4-048	Room 409C	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-10 to 12 & 17-7151-18 to 21	None Detected	N/A	N/A	
4-048	Room 409C	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
4-049	Room 410C	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
4-049	Room 410C	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-10 to 12 & 17-7151-18 to 21	None Detected	N/A	N/A	
4-049	Room 410C	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
4-050	Room 411C	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
4-050	Room 411C	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-10 to 12 & 17-7151-18 to 21	None Detected	N/A	N/A	
4-050	Room 411C	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
4-051	Room 412C	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
4-051	Room 412C	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-10 to 12 & 17-7151-18 to 21	None Detected	N/A	N/A	
4-051	Room 412C	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
4-052	Room 413C	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
4-052	Room 413C	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-10 to 12 & 17-7151-18 to 21	None Detected	N/A	N/A	
4-052	Room 413C	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure



APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
4-053	Room 414C	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
4-053	Room 414C	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-10 to 12 & 17-7151-18 to 21	None Detected	N/A	N/A	
4-053	Room 414C	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
4-054	Room 415C	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
4-054	Room 415C	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-10 to 12 & 17-7151-18 to 21	None Detected	N/A	N/A	
4-054	Room 415C	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
4-055	Lounge	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
4-055	Lounge	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-10 to 12 & 17-7151-18 to 21	None Detected	N/A	N/A	
4-055	Lounge	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
4-056	Room 416C	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
4-056	Room 416C	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-10 to 12 & 17-7151-18 to 21	None Detected	N/A	N/A	
4-056	Room 416C	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
4-057	Room 417C	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
4-057	Room 417C	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-10 to 12 & 17-7151-18 to 21	None Detected	N/A	N/A	
4-057	Room 417C	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
4-058	Room 418C	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
4-058	Room 418C	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-10 to 12 & 17-7151-18 to 21	None Detected	N/A	N/A	
4-058	Room 418C	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
4-059	Room 419C	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
4-059	Room 419C	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-10 to 12 & 17-7151-18 to 21	None Detected	N/A	N/A	
4-059	Room 419C	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
4-060	Room 420C	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
4-060	Room 420C	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-10 to 12 & 17-7151-18 to 21	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
4-060	Room 420C	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
4-061	Washroom	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
4-061	Washroom	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
4-061	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-10 to 12 & 17-7151-18 to 21	None Detected	N/A	N/A	
4-062	Washroom	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
4-062	Washroom	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
4-062	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-10 to 12 & 17-7151-18 to 21	None Detected	N/A	N/A	
4-063	Washroom	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
4-063	Washroom	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
4-063	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-10 to 12 & 17-7151-18 to 21	None Detected	N/A	N/A	
4-064	Washroom	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
4-064	Washroom	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
4-064	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-10 to 12 & 17-7151-18 to 21	None Detected	N/A	N/A	
4-065	Utility	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
4-065	Utility	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
4-065	Utility	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-10 to 12 & 17-7151-18 to 21	None Detected	N/A	N/A	
4-066	Housekeeping	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
4-066	Housekeeping	Walls	Block	N/A	N/A	N/A	N/A	N/A	
4-066	Housekeeping	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-10 to 12 & 17-7151-18 to 21	None Detected	N/A	N/A	
4-067	Laundry Room	Floor	Vinyl Floor Tile 9	Asbestos	Not Sampled	ACM Assumed	55 SF	Good	12" x 12" Light Brown with White Streaks
4-067	Laundry Room	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 16-4653-10 to 12	0.5-5% Chrysotile	N/A	N/A	12" x 12" Tan with Rust Streaks NOT OBSERVED
4-067	Laundry Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-10 to 12 & 17-7151-18 to 21	None Detected	N/A	N/A	
4-067	Laundry Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-10 to 12 & 17-7151-18 to 21	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
4-067	Laundry Room	Pipe	Parging Cement	Asbestos	Homogeneous w/ 082407-15 to 17	70% Chrysotile	1 Fitting	Good	
4-068	Fire Panel Room	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
4-068	Fire Panel Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-10 to 12 & 17-7151-18 to 21	None Detected	N/A	N/A	
4-068	Fire Panel Room	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
4-069	Corridor	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
4-069	Corridor	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-10 to 12 & 17-7151-18 to 21	None Detected	N/A	N/A	
4-069	Corridor	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
4-070	Washroom	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
4-070	Washroom	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
4-070	Washroom	Ceiling	Drywall (DJC)	Asbestos	16-3996-10, 11*	None Detected	N/A	N/A	*From Fisher Project No. 16-7778, dated May 2016
4-071	Washroom	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
4-071	Washroom	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
4-071	Washroom	Ceiling	Drywall (DJC)	Asbestos	16-3996-12*	None Detected	N/A	N/A	*From Fisher Project No. 16-7778, dated May 2016
4-072	Room 400	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
4-072	Room 400	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-10 to 12 & 17-7151-18 to 21	None Detected	N/A	N/A	
4-072	Room 400	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
4-073	Office	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
4-073	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-10 to 12 & 17-7151-18 to 21	None Detected	N/A	N/A	
4-073	Office	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
4-074	Med. Room	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	<b>NO ACCESS</b> Beige with Black and Brown Dots
4-074	Med. Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-10 to 12 & 17-7151-18 to 21	None Detected	N/A	N/A	
4-074	Med. Room	Walls	Paint	Lead	18-1053-10*	250 ppm	N/A	N/A	Off-white *From Fisher Project No. 18-9072, dated Oct. 2018
4-074	Med. Room	Ceiling	Ceiling Tile 1	Asbestos	18-1053-07 to 09*	None Detected	N/A	N/A	2' x 4' Pinhole Fissure * From Fisher Project No. 18-9072, dated Oct. 2018
4-075	Meeting Room	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
4-075	Meeting Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-10 to 12 & 17-7151-18 to 21	None Detected	N/A	N/A	
4-075	Meeting Room	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
4-076	Housekeeping	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
4-076	Housekeeping	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-10 to 12 & 17-7151-18 to 21	None Detected	N/A	N/A	
4-076	Housekeeping	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-10 to 12 & 17-7151-18 to 21	None Detected	N/A	N/A	
4-077	Treatment Room	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
4-077	Treatment Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-10 to 12 & 17-7151-18 to 21	None Detected	N/A	N/A	
4-077	Treatment Room	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
4-078	Nurse's Station	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
4-078	Nurse's Station	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-10 to 12 & 17-7151-18 to 21	None Detected	N/A	N/A	
4-078	Nurse's Station	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
5-001	Lobby	Floor	Vinyl Sheet Flooring 21	Asbestos	Homogeneous w/ 18-1053-01 to 03	None Detected	N/A	N/A	Grey Wood Laminate like Pattern
5-001	Lobby	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
5-001	Lobby	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 16-4653-10 to 12	0.5-5% Chrysotile	100 SF	Good	12" x 12" Tan with Rust Streaks Under VSF 6
5-001	Lobby	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-13 to 15 & 17-7152-22 to 25	None Detected	N/A	N/A	
5-001	Lobby	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-13 to 15 & 17-7152-22 to 25	None Detected	N/A	N/A	
5-001	Lobby	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
5-002	Corridor	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
5-002	Corridor	Walls	Drywall (DJC)	Asbestos	17-7152-22*	None Detected	N/A	N/A	*From Fisher Project No.17-8428, dated Sept. 2017
5-002	Corridor	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
5-003	Room 501W	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
5-003	Room 501W	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-13 to 15 & 17-7152-22 to 25	None Detected	N/A	N/A	
5-003	Room 501W	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
5-004	Room 502W	Floor	Vinyl Sheet Flooring 7	Asbestos	Not Sampled	ACM Assumed	220 SF	Good	Grey with White Specks
5-004	Room 502W	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots NOT OBSERVED
5-004	Room 502W	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-13 to 15 & 17-7152-22 to 25	None Detected	N/A	N/A	
5-004	Room 502W	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
5-005	Room 503W	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
5-005	Room 503W	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-13 to 15 & 17-7152-22 to 25	None Detected	N/A	N/A	
5-005	Room 503W	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
5-006	Room 504W	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
5-006	Room 504W	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-13 to 15 & 17-7152-22 to 25	None Detected	N/A	N/A	
5-006	Room 504W	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
5-007	Room 505W	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
5-007	Room 505W	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-13 to 15 & 17-7152-22 to 25	None Detected	N/A	N/A	
5-007	Room 505W	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
5-008	Lounge	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
5-008	Lounge	Walls	Drywall (DJC)	Asbestos	17-7152-23*	None Detected	N/A	N/A	*From Fisher Project No.17-8428, dated Sept. 2017
5-008	Lounge	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
5-009	Room 506W	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
5-009	Room 506W	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-13 to 15 & 17-7152-22 to 25	None Detected	N/A	N/A	
5-009	Room 506W	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
5-010	Room 507W	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
5-010	Room 507W	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-13 to 15 & 17-7152-22 to 25	None Detected	N/A	N/A	
5-010	Room 507W	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
5-011	Room 508W	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
5-011	Room 508W	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-13 to 15 & 17-7152-22 to 25	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
5-011	Room 508W	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
5-012	Room 509W	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
5-012	Room 509W	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-13 to 15 & 17-7152-22 to 25	None Detected	N/A	N/A	
5-012	Room 509W	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
5-013	Room 510W	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
5-013	Room 510W	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-13 to 15 & 17-7152-22 to 25	None Detected	N/A	N/A	
5-013	Room 510W	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
5-014	Room 511W	Floor	Vinyl Sheet Flooring 7	Asbestos	Not Sampled	ACM Assumed	220 SF	Good	Grey with White Specks
5-014	Room 511W	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots NOT OBSERVED
5-014	Room 511W	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-13 to 15 & 17-7152-22 to 25	None Detected	N/A	N/A	
5-014	Room 511W	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
5-015	Room 512W	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
5-015	Room 512W	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-13 to 15 & 17-7152-22 to 25	None Detected	N/A	N/A	
5-015	Room 512W	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
5-016	Room 513W	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
5-016	Room 513W	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-13 to 15 & 17-7152-22 to 25	None Detected	N/A	N/A	
5-016	Room 513W	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
5-017	Room 514W	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
5-017	Room 514W	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-13 to 15 & 17-7152-22 to 25	None Detected	N/A	N/A	
5-017	Room 514W	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
5-018	Room 515W	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
5-018	Room 515W	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-13 to 15 & 17-7152-22 to 25	None Detected	N/A	N/A	
5-018	Room 515W	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
5-019	Lounge	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
5-019	Lounge	Walls	Drywall (DJC)	Asbestos	17-7152-24*	None Detected	N/A	N/A	*From Fisher Project No.17-8428, dated Sept. 2017
5-019	Lounge	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
5-020	Room 516W	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
5-020	Room 516W	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-13 to 15 & 17-7152-22 to 25	None Detected	N/A	N/A	
5-020	Room 516W	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
5-021	Room 517W	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
5-021	Room 517W	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-13 to 15 & 17-7152-22 to 25	None Detected	N/A	N/A	
5-021	Room 517W	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
5-022	Room 518W	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
5-022	Room 518W	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-13 to 15 & 17-7152-22 to 25	None Detected	N/A	N/A	
5-022	Room 518W	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
5-023	Room 519W	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
5-023	Room 519W	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-13 to 15 & 17-7152-22 to 25	None Detected	N/A	N/A	
5-023	Room 519W	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
5-024	Room 520W	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
5-024	Room 520W	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-13 to 15 & 17-7152-22 to 25	None Detected	N/A	N/A	
5-024	Room 520W	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
5-025	Washroom	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
5-025	Washroom	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
5-025	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-13 to 15 & 17-7152-22 to 25	None Detected	N/A	N/A	
5-026	Washroom	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
5-026	Washroom	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
5-026	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-13 to 15 & 17-7152-22 to 25	None Detected	N/A	N/A	
5-027	Washroom	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	



APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
5-027	Washroom	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
5-027	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-13 to 15 & 17-7152-22 to 25	None Detected	N/A	N/A	
5-028	Washroom	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
5-028	Washroom	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
5-028	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-13 to 15 & 17-7152-22 to 25	None Detected	N/A	N/A	
5-029	Utility	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
5-029	Utility	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-13 to 15 & 17-7152-22 to 25	None Detected	N/A	N/A	
5-030	Housekeeping	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
5-030	Housekeeping	Walls	Block	N/A	N/A	N/A	N/A	N/A	
5-030	Housekeeping	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-13 to 15 & 17-7152-22 to 25	None Detected	N/A	N/A	
5-031	Office	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
5-031	Office	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 16-4653-10 to 12	0.5-5% Chrysotile	N/A	N/A	12" x 12" Tan with Rust Streaks NOT OBSERVED
5-031	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-13 to 15 & 17-7152-22 to 25	None Detected	N/A	N/A	
5-031	Office	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-13 to 15 & 17-7152-22 to 25	None Detected	N/A	N/A	
5-032	Disposal Chute	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
5-032	Disposal Chute	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-13 to 15 & 17-7152-22 to 25	None Detected	N/A	N/A	
5-032	Disposal Chute	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-13 to 15 & 17-7152-22 to 25	None Detected	N/A	N/A	
5-033	Storage	Floor	Vinyl Floor Tile 15	Asbestos	Not Sampled	ACM Assumed	20 SF	Good	12" x 12" Beige with Brown Specks
5-033	Storage	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots NOT OBSERVED
5-033	Storage	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-13 to 15 & 17-7152-22 to 25	None Detected	N/A	N/A	
5-033	Storage	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-13 to 15 & 17-7152-22 to 25	None Detected	N/A	N/A	
5-034	Lounge	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots



APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
5-034	Lounge	Walls	Brick/Glass	N/A	N/A	N/A	N/A	N/A	
5-034	Lounge	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-13 to 15 & 17-7152-22 to 25	None Detected	N/A	N/A	
5-035	Dining Room	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
5-035	Dining Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-13 to 15 & 17-7152-22 to 25	None Detected	N/A	N/A	
5-035	Dining Room	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
5-036	Servery	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3996-28 to 30	None Detected	N/A	N/A	Tan with Black and White Dots
5-036	Servery	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-13 to 15 & 17-7152-22 to 25	None Detected	N/A	N/A	
5-036	Servery	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-13 to 15 & 17-7152-22 to 25	None Detected	N/A	N/A	
5-037	Lounge	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
5-037	Lounge	Walls	Brick/Glass	N/A	N/A	N/A	N/A	N/A	
5-037	Lounge	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-13 to 15 & 17-7152-22 to 25	None Detected	N/A	N/A	
5-038	Corridor	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
5-038	Corridor	Walls	Drywall (DJC)	Asbestos	17-7152-25*	None Detected	N/A	N/A	*From Fisher Project No.17-8428, dated Sept. 2017
5-038	Corridor	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
5-039	Room 501C	Floor	Vinyl Sheet Flooring 7	Asbestos	Not Sampled	ACM Assumed	220 SF	Good	Grey with White Specks
5-039	Room 501C	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots NOT OBSERVED
5-039	Room 501C	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-13 to 15 & 17-7152-22 to 25	None Detected	N/A	N/A	
5-039	Room 501C	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
5-040	Room 502C	Floor	Vinyl Sheet Flooring 7	Asbestos	Not Sampled	ACM Assumed	220 SF	Good	Grey with White Specks
5-040	Room 502C	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots NOT OBSERVED
5-040	Room 502C	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-13 to 15 & 17-7152-22 to 25	None Detected	N/A	N/A	
5-040	Room 502C	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
5-041	Room 503C	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
5-041	Room 503C	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-13 to 15 & 17-7152-22 to 25	None Detected	N/A	N/A	
5-041	Room 503C	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
5-042	Room 504C	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
5-042	Room 504C	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-13 to 15 & 17-7152-22 to 25	None Detected	N/A	N/A	
5-042	Room 504C	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
5-043	Room 505C	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
5-043	Room 505C	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-13 to 15 & 17-7152-22 to 25	None Detected	N/A	N/A	
5-043	Room 505C	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
5-044	Lounge	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
5-044	Lounge	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-13 to 15 & 17-7152-22 to 25	None Detected	N/A	N/A	
5-044	Lounge	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
5-045	Room 506C	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
5-045	Room 506C	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-13 to 15 & 17-7152-22 to 25	None Detected	N/A	N/A	
5-045	Room 506C	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
5-046	Room 507C	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
5-046	Room 507C	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-13 to 15 & 17-7152-22 to 25	None Detected	N/A	N/A	
5-046	Room 507C	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
5-047	Room 508C	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
5-047	Room 508C	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-13 to 15 & 17-7152-22 to 25	None Detected	N/A	N/A	
5-047	Room 508C	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
5-048	Room 509C	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
5-048	Room 509C	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-13 to 15 & 17-7152-22 to 25	None Detected	N/A	N/A	
5-048	Room 509C	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
5-049	Room 510C	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
5-049	Room 510C	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-13 to 15 & 17-7152-22 to 25	None Detected	N/A	N/A	
5-049	Room 510C	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
5-050	Room 511C	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
5-050	Room 511C	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-13 to 15 & 17-7152-22 to 25	None Detected	N/A	N/A	
5-050	Room 511C	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
5-051	Room 512C	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
5-051	Room 512C	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-13 to 15 & 17-7152-22 to 25	None Detected	N/A	N/A	
5-051	Room 512C	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
5-052	Room 513C	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
5-052	Room 513C	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-13 to 15 & 17-7152-22 to 25	None Detected	N/A	N/A	
5-052	Room 513C	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
5-053	Room 514C	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
5-053	Room 514C	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-13 to 15 & 17-7152-22 to 25	None Detected	N/A	N/A	
5-053	Room 514C	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
5-054	Room 515C	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
5-054	Room 515C	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-13 to 15 & 17-7152-22 to 25	None Detected	N/A	N/A	
5-054	Room 515C	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
5-055	Lounge	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
5-055	Lounge	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-13 to 15 & 17-7152-22 to 25	None Detected	N/A	N/A	
5-055	Lounge	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
5-056	Room 516C	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
5-056	Room 516C	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-13 to 15 & 17-7152-22 to 25	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
5-056	Room 516C	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
5-057	Room 517C	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
5-057	Room 517C	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-13 to 15 & 17-7152-22 to 25	None Detected	N/A	N/A	
5-057	Room 517C	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
5-058	Room 518C	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
5-058	Room 518C	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-13 to 15 & 17-7152-22 to 25	None Detected	N/A	N/A	
5-058	Room 518C	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
5-059	Room 519C	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
5-059	Room 519C	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-13 to 15 & 17-7152-22 to 25	None Detected	N/A	N/A	
5-059	Room 519C	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
5-060	Room 520C	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
5-060	Room 520C	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-13 to 15 & 17-7152-22 to 25	None Detected	N/A	N/A	
5-060	Room 520C	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
5-061	Washroom	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
5-061	Washroom	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
5-061	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-13 to 15 & 17-7152-22 to 25	None Detected	N/A	N/A	
5-062	Washroom	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
5-062	Washroom	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
5-062	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-13 to 15 & 17-7152-22 to 25	None Detected	N/A	N/A	
5-063	Washroom	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
5-063	Washroom	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
5-063	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-13 to 15 & 17-7152-22 to 25	None Detected	N/A	N/A	
5-064	Washroom	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
5-064	Washroom	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
5-064	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-13 to 15 & 17-7152-22 to 25	None Detected	N/A	N/A	
5-065	Utility	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
5-065	Utility	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
5-065	Utility	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-13 to 15 & 17-7152-22 to 25	None Detected	N/A	N/A	
5-066	Housekeeping	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
5-066	Housekeeping	Walls	Block	N/A	N/A	N/A	N/A	N/A	
5-066	Housekeeping	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-13 to 15 & 17-7152-22 to 25	None Detected	N/A	N/A	
5-067	Storage	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
5-067	Storage	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 16-4653-10 to 12	0.5-5% Chrysotile	N/A	N/A	12" x 12" Tan with Rust Streaks NOT OBSERVED
5-067	Storage	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-13 to 15 & 17-7152-22 to 25	None Detected	N/A	N/A	
5-067	Storage	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-13 to 15 & 17-7152-22 to 25	None Detected	N/A	N/A	
5-067	Storage	Pipe	Parging Cement	Asbestos	Homogeneous w/ 082407-15 to 17	70% Chrysotile	8 Fittings	Good	
5-068	Fire Panel Room	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
5-068	Fire Panel Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-13 to 15 & 17-7152-22 to 25	None Detected	N/A	N/A	
5-068	Fire Panel Room	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
5-069	Corridor	Floor	Vinyl Sheet Flooring 21	Asbestos	Homogeneous w/ 18-1053-01 to 03	None Detected	N/A	N/A	Grey Wood Laminate like Pattern
5-069	Corridor	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots NOT OBSERVED
5-069	Corridor	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-13 to 15 & 17-7152-22 to 25	None Detected	N/A	N/A	
5-069	Corridor	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
5-070	Washroom	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
5-070	Washroom	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
5-070	Washroom	Ceiling	Drywall (DJC)	Asbestos	16-3996-13, 14*	None Detected	N/A	N/A	*From Fisher Project No. 16-7778, dated May 2016
5-071	Washroom	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
5-071	Washroom	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
5-071	Washroom	Ceiling	Drywall (DJC)	Asbestos	16-3996-15*	None Detected	N/A	N/A	*From Fisher Project No. 16-7778, dated May 2016
5-072	Room 500	Floor	Vinyl Sheet Flooring 21	Asbestos	Homogeneous w/ 18-1053-01 to 03	None Detected	N/A	N/A	Grey Wood Laminate like Pattern
5-072	Room 500	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots NOT OBSERVED
5-072	Room 500	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-13 to 15 & 17-7152-22 to 25	None Detected	N/A	N/A	
5-072	Room 500	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
5-073	Office	Floor	Vinyl Sheet Flooring 21	Asbestos	Homogeneous w/ 18-1053-01 to 03	None Detected	N/A	N/A	Grey Wood Laminate like Pattern
5-073	Office	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots NOT OBSERVED
5-073	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-13 to 15 & 17-7152-22 to 25	None Detected	N/A	N/A	
5-073	Office	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
5-074	Med. Room	Floor	Vinyl Sheet Flooring 21	Asbestos	Homogeneous w/ 18-1053-01 to 03	None Detected	N/A	N/A	Grey Wood Laminate like Pattern
5-074	Med. Room	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots NOT OBSERVED
5-074	Med. Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-13 to 15 & 17-7152-22 to 25	None Detected	N/A	N/A	
5-074	Med. Room	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
5-075	Meeting Room	Floor	Vinyl Sheet Flooring 21	Asbestos	Homogeneous w/ 18-1053-01 to 03	None Detected	N/A	N/A	Grey Wood Laminate like Pattern
5-075	Meeting Room	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots NOT OBSERVED
5-075	Meeting Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-13 to 15 & 17-7152-22 to 25	None Detected	N/A	N/A	
5-075	Meeting Room	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
5-076	Housekeeping	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
5-076	Housekeeping	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-13 to 15 & 17-7152-22 to 25	None Detected	N/A	N/A	
5-076	Housekeeping	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-13 to 15 & 17-7152-22 to 25	None Detected	N/A	N/A	
5-077	Treatment Room	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
5-077	Treatment Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-13 to 15 & 17-7152-22 to 25	None Detected	N/A	N/A	
5-077	Treatment Room	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
5-078	Nurse's Station	Floor	Vinyl Sheet Flooring 21	Asbestos	Homogeneous w/ 18-1053-01 to 03	None Detected	N/A	N/A	Grey Wood Laminate like Pattern

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
5-078	Nurse's Station	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots NOT OBSERVED
5-078	Nurse's Station	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-13 to 15 & 17-7152-22 to 25	None Detected	N/A	N/A	
5-078	Nurse's Station	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
6-001	Lobby	Floor	Vinyl Sheet Flooring 21	Asbestos	Homogeneous w/ 18-1053-01 to 03	None Detected	N/A	N/A	Grey Wood Laminate like Pattern
6-001	Lobby	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots NOT OBSERVED
6-001	Lobby	Walls	Drywall (DJC)	Asbestos	17-7152-26*	None Detected	N/A	N/A	*From Fisher Project No.17-8428, dated Sept. 2017
6-001	Lobby	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-16 to 18 & 17-7152-26 to 29	None Detected	N/A	N/A	
6-001	Lobby	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
6-002	Corridor	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
6-002	Corridor	Walls	Drywall (DJC)	Asbestos	17-7152-27*	None Detected	N/A	N/A	*From Fisher Project No.17-8428, dated Sept. 2017
6-002	Corridor	Ceiling	Ceiling Tile 1	Asbestos	16-4653-03*	None Detected	N/A	N/A	2' x 4' Pinhole Fissure *From Fisher Project No. 16-7715, dated Aug. 2016
6-003	Room 601W	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
6-003	Room 601W	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-16 to 18 & 17-7152-26 to 29	None Detected	N/A	N/A	
6-003	Room 601W	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
6-004	Room 602W	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
6-004	Room 602W	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-16 to 18 & 17-7152-26 to 29	None Detected	N/A	N/A	
6-004	Room 602W	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
6-005	Room 603W	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
6-005	Room 603W	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-16 to 18 & 17-7152-26 to 29	None Detected	N/A	N/A	
6-005	Room 603W	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
6-006	Room 604W	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
6-006	Room 604W	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-16 to 18 & 17-7152-26 to 29	None Detected	N/A	N/A	
6-006	Room 604W	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
6-007	Room 605W	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots



APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
6-007	Room 605W	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-16 to 18 & 17-7152-26 to 29	None Detected	N/A	N/A	
6-007	Room 605W	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
6-008	Lounge	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
6-008	Lounge	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-16 to 18 & 17-7152-26 to 29	None Detected	N/A	N/A	
6-008	Lounge	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
6-009	Room 606W	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
6-009	Room 606W	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-16 to 18 & 17-7152-26 to 29	None Detected	N/A	N/A	
6-009	Room 606W	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
6-010	Room 607W	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
6-010	Room 607W	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-16 to 18 & 17-7152-26 to 29	None Detected	N/A	N/A	
6-010	Room 607W	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
6-011	Room 608W	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
6-011	Room 608W	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-16 to 18 & 17-7152-26 to 29	None Detected	N/A	N/A	
6-011	Room 608W	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
6-012	Room 609W	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
6-012	Room 609W	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-16 to 18 & 17-7152-26 to 29	None Detected	N/A	N/A	
6-012	Room 609W	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
6-013	Room 610W	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
6-013	Room 610W	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-16 to 18 & 17-7152-26 to 29	None Detected	N/A	N/A	
6-013	Room 610W	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
6-014	Room 611W	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
6-014	Room 611W	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-16 to 18 & 17-7152-26 to 29	None Detected	N/A	N/A	
6-014	Room 611W	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure



APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
6-015	Room 612W	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
6-015	Room 612W	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-16 to 18 & 17-7152-26 to 29	None Detected	N/A	N/A	
6-015	Room 612W	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
6-016	Room 613W	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
6-016	Room 613W	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-16 to 18 & 17-7152-26 to 29	None Detected	N/A	N/A	
6-016	Room 613W	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
6-017	Room 614W	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
6-017	Room 614W	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-16 to 18 & 17-7152-26 to 29	None Detected	N/A	N/A	
6-017	Room 614W	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
6-018	Room 615W	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
6-018	Room 615W	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-16 to 18 & 17-7152-26 to 29	None Detected	N/A	N/A	
6-018	Room 615W	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
6-019	Lounge	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
6-019	Lounge	Walls	Drywall (DJC)	Asbestos	17-7152-28*	None Detected	N/A	N/A	*From Fisher Project No.17-8428, dated Sept. 2017
6-019	Lounge	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
6-020	Room 616W	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
6-020	Room 616W	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-16 to 18 & 17-7152-26 to 29	None Detected	N/A	N/A	
6-020	Room 616W	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
6-021	Room 617W	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
6-021	Room 617W	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-16 to 18 & 17-7152-26 to 29	None Detected	N/A	N/A	
6-021	Room 617W	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
6-022	Room 618W	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
6-022	Room 618W	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-16 to 18 & 17-7152-26 to 29	None Detected	N/A	N/A	
6-022	Room 618W	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
6-023	Room 619W	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
6-023	Room 619W	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-16 to 18 & 17-7152-26 to 29	None Detected	N/A	N/A	
6-023	Room 619W	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
6-024	Room 620W	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
6-024	Room 620W	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-16 to 18 & 17-7152-26 to 29	None Detected	N/A	N/A	
6-024	Room 620W	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
6-025	Washroom	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
6-025	Washroom	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
6-025	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-16 to 18 & 17-7152-26 to 29	None Detected	N/A	N/A	
6-026	Washroom	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
6-026	Washroom	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
6-026	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-16 to 18 & 17-7152-26 to 29	None Detected	N/A	N/A	
6-027	Washroom	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
6-027	Washroom	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
6-027	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-16 to 18 & 17-7152-26 to 29	None Detected	N/A	N/A	
6-028	Washroom	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
6-028	Washroom	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
6-028	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-16 to 18 & 17-7152-26 to 29	None Detected	N/A	N/A	
6-029	Utility	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
6-029	Utility	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
6-029	Utility	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-16 to 18 & 17-7152-26 to 29	None Detected	N/A	N/A	
6-030	Housekeeping	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
6-030	Housekeeping	Walls	Block	N/A	N/A	N/A	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
6-030	Housekeeping	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-16 to 18 & 17-7152-26 to 29	None Detected	N/A	N/A	
6-031	Office	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
6-031	Office	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 16-4653-10 to 12	0.5-5% Chrysotile	N/A	N/A	12" x 12" Tan with Rust Streaks NOT OBSERVED
6-031	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-16 to 18 & 17-7152-26 to 29	None Detected	N/A	N/A	
6-031	Office	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-16 to 18 & 17-7152-26 to 29	None Detected	N/A	N/A	
6-032	Disposal Chute	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
6-032	Disposal Chute	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-16 to 18 & 17-7152-26 to 29	None Detected	N/A	N/A	
6-032	Disposal Chute	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-16 to 18 & 17-7152-26 to 29	None Detected	N/A	N/A	
6-033	Storage	Floor	Vinyl Floor Tile 15	Asbestos	Not Sampled	ACM Assumed	20 SF	Good	12" x 12" Beige with Brown Specks
6-033	Storage	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots NOT OBSERVED
6-033	Storage	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-16 to 18 & 17-7152-26 to 29	None Detected	N/A	N/A	
6-033	Storage	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-16 to 18 & 17-7152-26 to 29	None Detected	N/A	N/A	
6-034	Lounge	Floor	Vinyl Sheet Flooring 13	Asbestos	Not Sampled	ACM Assumed	300 SF	Good	Beige with Multicolor Mosaic
6-034	Lounge	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots NOT OBSERVED
6-034	Lounge	Walls	Brick/Glass	N/A	N/A	N/A	N/A	N/A	
6-034	Lounge	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-16 to 18 & 17-7152-26 to 29	None Detected	N/A	N/A	
6-035	Dining Room	Floor	Vinyl Sheet Flooring 21	Asbestos	Homogeneous w/ 18-1053-01 to 03	None Detected	N/A	N/A	Grey Wood Laminate like Pattern
6-035	Dining Room	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots NOT OBSERVED
6-035	Dining Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-16 to 18 & 17-7152-26 to 29	None Detected	N/A	N/A	
6-035	Dining Room	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
6-036	Servery	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3996-28 to 30	None Detected	N/A	N/A	Tan with Black and White Dots
6-036	Servery	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-16 to 18 & 17-7152-26 to 29	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
6-036	Servery	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-16 to 18 & 17-7152-26 to 29	None Detected	N/A	N/A	
6-037	Lounge	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
6-037	Lounge	Walls	Brick/Glass	N/A	N/A	N/A	N/A	N/A	
6-037	Lounge	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-16 to 18 & 17-7152-26 to 29	None Detected	N/A	N/A	
6-038	Corridor	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
6-038	Corridor	Walls	Drywall (DJC)	Asbestos	17-7152-29*	None Detected	N/A	N/A	*From Fisher Project No.17-8428, dated Sept. 2017
6-038	Corridor	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
6-039	Room 601C	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
6-039	Room 601C	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-16 to 18 & 17-7152-26 to 29	None Detected	N/A	N/A	
6-039	Room 601C	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
6-040	Room 602C	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
6-040	Room 602C	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-16 to 18 & 17-7152-26 to 29	None Detected	N/A	N/A	
6-040	Room 602C	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
6-041	Room 603C	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
6-041	Room 603C	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-16 to 18 & 17-7152-26 to 29	None Detected	N/A	N/A	
6-041	Room 603C	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
6-042	Room 604C	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
6-042	Room 604C	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-16 to 18 & 17-7152-26 to 29	None Detected	N/A	N/A	
6-042	Room 604C	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
6-043	Room 605C	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
6-043	Room 605C	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-16 to 18 & 17-7152-26 to 29	None Detected	N/A	N/A	
6-043	Room 605C	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
6-044	Lounge	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
6-044	Lounge	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-16 to 18 & 17-7152-26 to 29	None Detected	N/A	N/A	
6-044	Lounge	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
6-045	Room 606C	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
6-045	Room 606C	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-16 to 18 & 17-7152-26 to 29	None Detected	N/A	N/A	
6-045	Room 606C	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
6-046	Room 607C	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
6-046	Room 607C	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-16 to 18 & 17-7152-26 to 29	None Detected	N/A	N/A	
6-046	Room 607C	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
6-047	Room 608C	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
6-047	Room 608C	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-16 to 18 & 17-7152-26 to 29	None Detected	N/A	N/A	
6-047	Room 608C	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
6-048	Room 609C	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
6-048	Room 609C	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-16 to 18 & 17-7152-26 to 29	None Detected	N/A	N/A	
6-048	Room 609C	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
6-049	Room 610C	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
6-049	Room 610C	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-16 to 18 & 17-7152-26 to 29	None Detected	N/A	N/A	
6-049	Room 610C	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
6-050	Room 611C	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
6-050	Room 611C	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-16 to 18 & 17-7152-26 to 29	None Detected	N/A	N/A	
6-050	Room 611C	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
6-051	Room 612C	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
6-051	Room 612C	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-16 to 18 & 17-7152-26 to 29	None Detected	N/A	N/A	
6-051	Room 612C	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
6-052	Room 613C	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
6-052	Room 613C	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-16 to 18 & 17-7152-26 to 29	None Detected	N/A	N/A	
6-052	Room 613C	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
6-053	Room 614C	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
6-053	Room 614C	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-16 to 18 & 17-7152-26 to 29	None Detected	N/A	N/A	
6-053	Room 614C	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
6-054	Room 615C	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
6-054	Room 615C	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-16 to 18 & 17-7152-26 to 29	None Detected	N/A	N/A	
6-054	Room 615C	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
6-055	Lounge	Floor	Vinyl Sheet Flooring 9	Asbestos	Not Sampled	ACM Assumed	360 SF	Good	Tan with Black Dots
6-055	Lounge	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots NOT OBSERVED
6-055	Lounge	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-16 to 18 & 17-7152-26 to 29	None Detected	N/A	N/A	
6-055	Lounge	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
6-056	Room 616C	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
6-056	Room 616C	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-16 to 18 & 17-7152-26 to 29	None Detected	N/A	N/A	
6-056	Room 616C	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
6-057	Room 617C	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
6-057	Room 617C	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-16 to 18 & 17-7152-26 to 29	None Detected	N/A	N/A	
6-057	Room 617C	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
6-058	Room 618C	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
6-058	Room 618C	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-16 to 18 & 17-7152-26 to 29	None Detected	N/A	N/A	
6-058	Room 618C	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
6-059	Room 619C	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
6-059	Room 619C	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-16 to 18 & 17-7152-26 to 29	None Detected	N/A	N/A	
6-059	Room 619C	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
6-060	Room 620C	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
6-060	Room 620C	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-16 to 18 & 17-7152-26 to 29	None Detected	N/A	N/A	
6-060	Room 620C	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
6-061	Washroom	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
6-061	Washroom	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
6-061	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-16 to 18 & 17-7152-26 to 29	None Detected	N/A	N/A	
6-062	Washroom	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
6-062	Washroom	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
6-062	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-16 to 18 & 17-7152-26 to 29	None Detected	N/A	N/A	
6-063	Washroom	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
6-063	Washroom	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
6-063	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-16 to 18 & 17-7152-26 to 29	None Detected	N/A	N/A	
6-064	Washroom	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
6-064	Washroom	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
6-064	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-16 to 18 & 17-7152-26 to 29	None Detected	N/A	N/A	
6-065	Utility	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
6-065	Utility	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
6-065	Utility	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-16 to 18 & 17-7152-26 to 29	None Detected	N/A	N/A	
6-066	Housekeeping	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
6-066	Housekeeping	Walls	Block	N/A	N/A	N/A	N/A	N/A	
6-066	Housekeeping	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-16 to 18 & 17-7152-26 to 29	None Detected	N/A	N/A	



APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
6-067	Laundry Room	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
6-067	Laundry Room	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 16-4653-10 to 12	0.5-5% Chrysotile	N/A	N/A	12" x 12" Tan with Rust Streaks NOT OBSERVED
6-067	Laundry Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-16 to 18 & 17-7152-26 to 29	None Detected	N/A	N/A	
6-067	Laundry Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-16 to 18 & 17-7152-26 to 29	None Detected	N/A	N/A	
6-067	Laundry Room	Pipe	Parging Cement	Asbestos	Homogeneous w/ 082407-15 to 17	70% Chrysotile	5 Fittings	Good	
6-068	Fire Panel Room	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
6-068	Fire Panel Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-16 to 18 & 17-7152-26 to 29	None Detected	N/A	N/A	
6-068	Fire Panel Room	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
6-069	Corridor	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
6-069	Corridor	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-16 to 18 & 17-7152-26 to 29	None Detected	N/A	N/A	
6-069	Corridor	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
6-070	Washroom	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
6-070	Washroom	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
6-070	Washroom	Ceiling	Drywall (DJC)	Asbestos	16-3996-16, 17*	None Detected	N/A	N/A	*From Fisher Project No. 16-7778, dated May 2016
6-071	Washroom	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
6-071	Washroom	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
6-071	Washroom	Ceiling	Drywall (DJC)	Asbestos	16-3996-18*	None Detected	N/A	N/A	*From Fisher Project No. 16-7778, dated May 2016
6-072	Room 600	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
6-072	Room 600	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-16 to 18 & 17-7152-26 to 29	None Detected	N/A	N/A	
6-072	Room 600	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
6-073	Office	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
6-073	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-16 to 18 & 17-7152-26 to 29	None Detected	N/A	N/A	
6-073	Office	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
6-074	Med. Room	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	<b>NO ACCESS</b> Beige with Black and Brown Dots

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
6-074	Med. Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-16 to 18 & 17-7152-26 to 29	None Detected	N/A	N/A	
6-074	Med. Room	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
6-075	Meeting Room	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
6-075	Meeting Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-16 to 18 & 17-7152-26 to 29	None Detected	N/A	N/A	
6-075	Meeting Room	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
6-076	Housekeeping	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
6-076	Housekeeping	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-16 to 18 & 17-7152-26 to 29	None Detected	N/A	N/A	
6-076	Housekeeping	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-16 to 18 & 17-7152-26 to 29	None Detected	N/A	N/A	
6-077	Treatment Room	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
6-077	Treatment Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-16 to 18 & 17-7152-26 to 29	None Detected	N/A	N/A	
6-077	Treatment Room	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
6-078	Nurse's Station	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
6-078	Nurse's Station	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-16 to 18 & 17-7152-26 to 29	None Detected	N/A	N/A	
6-078	Nurse's Station	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
7-001	Lobby	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
7-001	Lobby	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-19 to 21 & 17-7152-30 to 33	None Detected	N/A	N/A	
7-001	Lobby	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-19 to 21 & 17-7152-30 to 33	None Detected	N/A	N/A	
7-001	Lobby	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
7-002	Corridor	Floor	Vinyl Sheet Flooring 6	Asbestos	16-4653-04 to 06*	None Detected	N/A	N/A	Beige with Black and Brown Dots *From Fisher Project No. 16-7715, dated Aug. 2016
7-002	Corridor	Floor	Vinyl Floor Tile 8	Asbestos	16-4653-07 to 09*	0.5-5% Chrysotile	1750 SF	Good	12" x 12" Beige (underneath VSF 6) *From Fisher Project No. 16-7715, dated Aug. 2016
7-002	Corridor	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-19 to 21 & 17-7152-30 to 33	None Detected	N/A	N/A	
7-002	Corridor	Ceiling	Ceiling Tile 1	Asbestos	16-4653-01, 02*	None Detected	N/A	N/A	2' x 4' Pinhole Fissure *From Fisher Project No. 16-7715, dated Aug. 2016
7-003	Room 701W	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
7-003	Room 701W	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-19 to 21 & 17-7152-30 to 33	None Detected	N/A	N/A	
7-003	Room 701W	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
7-004	Room 702W	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
7-004	Room 702W	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-19 to 21 & 17-7152-30 to 33	None Detected	N/A	N/A	
7-004	Room 702W	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
7-005	Room 703W	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
7-005	Room 703W	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-19 to 21 & 17-7152-30 to 33	None Detected	N/A	N/A	
7-005	Room 703W	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
7-006	Room 704W	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
7-006	Room 704W	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-19 to 21 & 17-7152-30 to 33	None Detected	N/A	N/A	
7-006	Room 704W	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
7-007	Room 705W	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
7-007	Room 705W	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-19 to 21 & 17-7152-30 to 33	None Detected	N/A	N/A	
7-007	Room 705W	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
7-008	Lounge	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
7-008	Lounge	Walls	Drywall (DJC)	Asbestos	17-7152-30*	None Detected	N/A	N/A	*From Fisher Project No.17-8428, dated Sept. 2017
7-008	Lounge	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
7-009	Room 706W	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
7-009	Room 706W	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-19 to 21 & 17-7152-30 to 33	None Detected	N/A	N/A	
7-009	Room 706W	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
7-010	Room 707W	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
7-010	Room 707W	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-19 to 21 & 17-7152-30 to 33	None Detected	N/A	N/A	
7-010	Room 707W	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
7-011	Room 708W	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
7-011	Room 708W	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-19 to 21 & 17-7152-30 to 33	None Detected	N/A	N/A	
7-011	Room 708W	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
7-012	Room 709W	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
7-012	Room 709W	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-19 to 21 & 17-7152-30 to 33	None Detected	N/A	N/A	
7-012	Room 709W	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
7-013	Room 710W	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
7-013	Room 710W	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-19 to 21 & 17-7152-30 to 33	None Detected	N/A	N/A	
7-013	Room 710W	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
7-014	Room 711W	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
7-014	Room 711W	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-19 to 21 & 17-7152-30 to 33	None Detected	N/A	N/A	
7-014	Room 711W	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
7-015	Room 712W	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
7-015	Room 712W	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-19 to 21 & 17-7152-30 to 33	None Detected	N/A	N/A	
7-015	Room 712W	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
7-016	Room 713W	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
7-016	Room 713W	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-19 to 21 & 17-7152-30 to 33	None Detected	N/A	N/A	
7-016	Room 713W	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
7-017	Room 714W	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
7-017	Room 714W	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-19 to 21 & 17-7152-30 to 33	None Detected	N/A	N/A	
7-017	Room 714W	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
7-018	Room 715W	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
7-018	Room 715W	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-19 to 21 & 17-7152-30 to 33	None Detected	N/A	N/A	
7-018	Room 715W	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
7-019	Lounge	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
7-019	Lounge	Walls	Drywall (DJC)	Asbestos	17-7152-31*	None Detected	N/A	N/A	*From Fisher Project No.17-8428, dated Sept. 2017
7-019	Lounge	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
7-020	Room 716W	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
7-020	Room 716W	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-19 to 21 & 17-7152-30 to 33	None Detected	N/A	N/A	
7-020	Room 716W	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
7-021	Room 717W	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
7-021	Room 717W	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-19 to 21 & 17-7152-30 to 33	None Detected	N/A	N/A	
7-021	Room 717W	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
7-022	Room 718W	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
7-022	Room 718W	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-19 to 21 & 17-7152-30 to 33	None Detected	N/A	N/A	
7-022	Room 718W	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
7-023	Room 719W	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
7-023	Room 719W	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-19 to 21 & 17-7152-30 to 33	None Detected	N/A	N/A	
7-023	Room 719W	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
7-024	Room 720W	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
7-024	Room 720W	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-19 to 21 & 17-7152-30 to 33	None Detected	N/A	N/A	
7-024	Room 720W	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
7-025	Washroom	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
7-025	Washroom	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
7-025	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-19 to 21 & 17-7152-30 to 33	None Detected	N/A	N/A	
7-026	Washroom	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
7-026	Washroom	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
7-026	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-19 to 21 & 17-7152-30 to 33	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
7-027	Washroom	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
7-027	Washroom	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
7-027	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-19 to 21 & 17-7152-30 to 33	None Detected	N/A	N/A	
7-028	Washroom	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
7-028	Washroom	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
7-028	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-19 to 21 & 17-7152-30 to 33	None Detected	N/A	N/A	
7-029	Utility	Floor	Vinyl Sheet Flooring 9	Asbestos	Not Sampled	ACM Assumed	80 SF	Good	Tan with Black Dots
7-029	Utility	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
7-029	Utility	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-19 to 21 & 17-7152-30 to 33	None Detected	N/A	N/A	
7-030	Housekeeping	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
7-030	Housekeeping	Walls	Block	N/A	N/A	N/A	N/A	N/A	
7-030	Housekeeping	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-19 to 21 & 17-7152-30 to 33	None Detected	N/A	N/A	
7-031	Office	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 16-4653-10 to 12	0.5-5% Chrysotile	55 SF	Good	12" x 12" Tan with Rust Streaks
7-031	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-19 to 21 & 17-7152-30 to 33	None Detected	N/A	N/A	
7-031	Office	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-19 to 21 & 17-7152-30 to 33	None Detected	N/A	N/A	
7-032	Disposal Chute	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
7-032	Disposal Chute	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-19 to 21 & 17-7152-30 to 33	None Detected	N/A	N/A	
7-032	Disposal Chute	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-19 to 21 & 17-7152-30 to 33	None Detected	N/A	N/A	
7-033	Storage	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
7-033	Storage	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-19 to 21 & 17-7152-30 to 33	None Detected	N/A	N/A	
7-033	Storage	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-19 to 21 & 17-7152-30 to 33	None Detected	N/A	N/A	
7-034	Lounge	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
7-034	Lounge	Walls	Brick/Glass	N/A	N/A	N/A	N/A	N/A	
7-034	Lounge	Ceiling	Drywall (DJC)	Asbestos	17-7152-32*	None Detected	N/A	N/A	*From Fisher Project No.17-8428, dated Sept. 2017
7-035	Dining Room	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
7-035	Dining Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-19 to 21 & 17-7152-30 to 33	None Detected	N/A	N/A	
7-035	Dining Room	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
7-036	Servery	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3996-28 to 30	None Detected	N/A	N/A	Tan with Black and White Dots
7-036	Servery	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-19 to 21 & 17-7152-30 to 33	None Detected	N/A	N/A	
7-036	Servery	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-19 to 21 & 17-7152-30 to 33	None Detected	N/A	N/A	
7-037	Lounge	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	300 SF	Good	Grey Mosaic
7-037	Lounge	Walls	Brick/Glass	N/A	N/A	N/A	N/A	N/A	
7-037	Lounge	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-19 to 21 & 17-7152-30 to 33	None Detected	N/A	N/A	
7-038	Corridor	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
7-038	Corridor	Walls	Drywall (DJC)	Asbestos	17-7152-33*	None Detected	N/A	N/A	*From Fisher Project No.17-8428, dated Sept. 2017
7-038	Corridor	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
7-039	Room 701C	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
7-039	Room 701C	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-19 to 21 & 17-7152-30 to 33	None Detected	N/A	N/A	
7-039	Room 701C	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
7-040	Room 702C	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
7-040	Room 702C	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-19 to 21 & 17-7152-30 to 33	None Detected	N/A	N/A	
7-040	Room 702C	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
7-041	Room 703C	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
7-041	Room 703C	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-19 to 21 & 17-7152-30 to 33	None Detected	N/A	N/A	
7-041	Room 703C	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
7-042	Room 704C	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots



APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
7-042	Room 704C	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-19 to 21 & 17-7152-30 to 33	None Detected	N/A	N/A	
7-042	Room 704C	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
7-043	Room 705C	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
7-043	Room 705C	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-19 to 21 & 17-7152-30 to 33	None Detected	N/A	N/A	
7-043	Room 705C	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
7-044	Lounge	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
7-044	Lounge	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-19 to 21 & 17-7152-30 to 33	None Detected	N/A	N/A	
7-044	Lounge	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
7-045	Room 706C	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
7-045	Room 706C	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-19 to 21 & 17-7152-30 to 33	None Detected	N/A	N/A	
7-045	Room 706C	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
7-046	Room 707C	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
7-046	Room 707C	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-19 to 21 & 17-7152-30 to 33	None Detected	N/A	N/A	
7-046	Room 707C	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
7-047	Room 708C	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
7-047	Room 708C	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-19 to 21 & 17-7152-30 to 33	None Detected	N/A	N/A	
7-047	Room 708C	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
7-048	Room 709C	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
7-048	Room 709C	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-19 to 21 & 17-7152-30 to 33	None Detected	N/A	N/A	
7-048	Room 709C	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
7-049	Room 710C	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
7-049	Room 710C	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-19 to 21 & 17-7152-30 to 33	None Detected	N/A	N/A	
7-049	Room 710C	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
7-050	Room 711C	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
7-050	Room 711C	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-19 to 21 & 17-7152-30 to 33	None Detected	N/A	N/A	
7-050	Room 711C	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
7-051	Room 712C	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
7-051	Room 712C	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-19 to 21 & 17-7152-30 to 33	None Detected	N/A	N/A	
7-051	Room 712C	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
7-052	Room 713C	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
7-052	Room 713C	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-19 to 21 & 17-7152-30 to 33	None Detected	N/A	N/A	
7-052	Room 713C	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
7-053	Room 714C	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
7-053	Room 714C	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-19 to 21 & 17-7152-30 to 33	None Detected	N/A	N/A	
7-053	Room 714C	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
7-054	Room 715C	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
7-054	Room 715C	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-19 to 21 & 17-7152-30 to 33	None Detected	N/A	N/A	
7-054	Room 715C	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
7-055	Lounge	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
7-055	Lounge	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-19 to 21 & 17-7152-30 to 33	None Detected	N/A	N/A	
7-055	Lounge	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
7-056	Room 716C	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
7-056	Room 716C	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-19 to 21 & 17-7152-30 to 33	None Detected	N/A	N/A	
7-056	Room 716C	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
7-057	Room 717C	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
7-057	Room 717C	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-19 to 21 & 17-7152-30 to 33	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
7-057	Room 717C	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
7-058	Room 718C	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
7-058	Room 718C	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-19 to 21 & 17-7152-30 to 33	None Detected	N/A	N/A	
7-058	Room 718C	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
7-059	Room 719C	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
7-059	Room 719C	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-19 to 21 & 17-7152-30 to 33	None Detected	N/A	N/A	
7-059	Room 719C	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
7-060	Room 720C	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
7-060	Room 720C	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-19 to 21 & 17-7152-30 to 33	None Detected	N/A	N/A	
7-060	Room 720C	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
7-061	Washroom	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
7-061	Washroom	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
7-061	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-19 to 21 & 17-7152-30 to 33	None Detected	N/A	N/A	
7-062	Washroom	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
7-062	Washroom	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
7-062	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-19 to 21 & 17-7152-30 to 33	None Detected	N/A	N/A	
7-063	Washroom	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
7-063	Washroom	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
7-063	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-19 to 21 & 17-7152-30 to 33	None Detected	N/A	N/A	
7-064	Washroom	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
7-064	Washroom	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
7-064	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-19 to 21 & 17-7152-30 to 33	None Detected	N/A	N/A	
7-065	Utility	Floor	Vinyl Sheet Flooring 8	Asbestos	Not Sampled	ACM Assumed	80SF	Good	Tan with Black and Brown Dots
7-065	Utility	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
7-065	Utility	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-19 to 21 & 17-7152-30 to 33	None Detected	N/A	N/A	
7-066	Housekeeping	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
7-066	Housekeeping	Walls	Block	N/A	N/A	N/A	N/A	N/A	
7-066	Housekeeping	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-19 to 21 & 17-7152-30 to 33	None Detected	N/A	N/A	
7-067	Laundry Room	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 16-4653-10 to 12	0.5-5% Chrysotile	55 SF	Good	12" x 12" Tan with Rust Streaks
7-067	Laundry Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-19 to 21 & 17-7152-30 to 33	None Detected	N/A	N/A	
7-067	Laundry Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-19 to 21 & 17-7152-30 to 33	None Detected	N/A	N/A	
7-067	Laundry Room	Pipe	Parging Cement	Asbestos	Homogeneous w/ 082407-15 to 17	70% Chrysotile	8 Fittings	Good	
7-068	Fire Panel Room	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
7-068	Fire Panel Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-19 to 21 & 17-7152-30 to 33	None Detected	N/A	N/A	
7-068	Fire Panel Room	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
7-069	Corridor	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
7-069	Corridor	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-19 to 21 & 17-7152-30 to 33	None Detected	N/A	N/A	
7-069	Corridor	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
7-070	Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	16-3996-28 to 30*	None Detected	N/A	N/A	Tan with Black and White Dots *From Fisher Project No. 16-7778, dated May 2016
7-070	Washroom	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
7-070	Washroom	Ceiling	Drywall (DJC)	Asbestos	16-3996-19, 20*	None Detected	N/A	N/A	*From Fisher Project No. 16-7778, dated May 2016
7-071	Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3996-28 to 30	None Detected	N/A	N/A	Tan with Black and White Dots
7-071	Washroom	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
7-071	Washroom	Ceiling	Drywall (DJC)	Asbestos	16-3996-21*	None Detected	N/A	N/A	*From Fisher Project No. 16-7778, dated May 2016
7-072	Room 700	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
7-072	Room 700	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-19 to 21 & 17-7152-30 to 33	None Detected	N/A	N/A	
7-072	Room 700	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
7-073	Office	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
7-073	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-19 to 21 & 17-7152-30 to 33	None Detected	N/A	N/A	
7-073	Office	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
7-074	Med. Room	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
7-074	Med. Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-19 to 21 & 17-7152-30 to 33	None Detected	N/A	N/A	
7-074	Med. Room	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
7-075	Office	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
7-075	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-19 to 21 & 17-7152-30 to 33	None Detected	N/A	N/A	
7-075	Office	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
7-076	Housekeeping	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
7-076	Housekeeping	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-19 to 21 & 17-7152-30 to 33	None Detected	N/A	N/A	
7-076	Housekeeping	Ceiling	Drywall (DJC)	Asbestos	16-3996-19, 20*	None Detected	N/A	N/A	*From Fisher Project No. 16-7778, dated May 2016
7-077	Treatment Room	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
7-077	Treatment Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-19 to 21 & 17-7152-30 to 33	None Detected	N/A	N/A	
7-077	Treatment Room	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
7-078	Nurse's Station	Floor	Vinyl Sheet Flooring 6	Asbestos	Homogeneous w/ 16-4653-04 to 06	None Detected	N/A	N/A	Beige with Black and Brown Dots
7-078	Nurse's Station	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3996-19 to 21 & 17-7152-30 to 33	None Detected	N/A	N/A	
7-078	Nurse's Station	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-4653-01 to 03	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
PH-001	Penthouse - Center Mechanical Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
PH-001	Penthouse - Center Mechanical Room	Walls	Block/Metal	N/A	N/A	N/A	N/A	N/A	
PH-001	Penthouse - Center Mechanical Room	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A	
PH-001	Penthouse - Center Mechanical Room	Pipe	Parging Cement	Asbestos	082407-01 to 06*	40-70% Chrysotile	30 Fittings	Good	*From Building Asbestos Survey Report, dated 2007
PH-002	Penthouse -East Mechanical Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
PH-002	Penthouse -East Mechanical Room	Walls	Metal	N/A	N/A	N/A	N/A	N/A	
PH-002	Penthouse -East Mechanical Room	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A	

## APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
PH-002	Penthouse -East Mechanical Room	Pipe	Parging Cement	Asbestos	Homogeneous w/ 082407-01 to 06	40-70% Chrysotile	15 Fittings	Good	
PH-003	Penthouse -West Mechanical Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
PH-003	Penthouse -West Mechanical Room	Walls	Metal	N/A	N/A	N/A	N/A	N/A	
PH-003	Penthouse -West Mechanical Room	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A	
PH-003	Penthouse -West Mechanical Room	Pipe	Parging Cement	Asbestos	Homogeneous w/ 082407-01 to 06	40-70% Chrysotile	5 Fittings	Good	
Surveyor's Field Notes									

## **APPENDIX II**


### **RESULTS OF BULK SAMPLE ANALYSIS**

**(NO INFORMATION TO REPORT)**



## **APPENDIX III**

### **SITE DRAWINGS**



## Legend



Asbestos-Containing Material

1-01

Location Number

NAR

No Access to Room

The drawing does not illustrate locations of drywall joint compound, plaster, window caulking or roofing materials, for reasons discussed in Section 6 of the Standard Operating Procedure for Designated Substance Surveys. Please refer to the Designated Substance Survey Form in Appendix I for information regarding the locations and asbestos or lead-content of these materials.

### Figure 1

**LOCATION:**  
351 Christie Street  
Toronto, Ontario

**BUILDING NAME:**  
Castleview-Wychwood Tower


**Basement Floor Plan**  
**Asbestos-Containing Material Locations**

**CLIENT:** City of Toronto


**PROJECT NUMBER:** FE 24-13855 **DATE:** June 2024 **DRW BY:** T.L.

**CAD FILE:** FIG1 **SCALE:** Not to Scale **CHK BY:** I.F.







### Legend



Asbestos-Containing Material



Location Number



No Access to Room

The drawing does not illustrate locations of drywall joint compound, plaster, window caulking or roofing materials, for reasons discussed in Section 6 of the Standard Operating Procedure for Designated Substance Surveys. Please refer to the Designated Substance Survey Form in Appendix I for information regarding the locations and asbestos or lead-content of these materials.

## Figure 2

LOCATION:

351 Christie Street  
Toronto, Ontario

BUILDING NAME:

Castlevew-Wychwood Tower

First Floor Plan  
Asbestos-Containing Material Locations

CLIENT:

City of Toronto

PROJECT NUMBER:

FE 24-13855

DATE:

June 2024

DRW BY:

T.L.

CAD FILE:


FIG2

SCALE:


Not to Scale

CHK BY:

I.F.







Location Number

The drawing does not illustrate locations of drywall joint compound, plaster, window caulking or roofing materials, for reasons discussed in Section 6 of the Standard Operating Procedure for Designated Substance Surveys. Please refer to the Designated Substance Survey Form in Appendix I for information regarding the locations and asbestos or lead-content of these materials.

**LOCATION:** 351 Christie Street  
Toronto, Ontario


351 Christie Street  
Toronto, Ontario

## Castleview-Wychwood Tower


AGENT: City of Toronto		
PROJECT NUMBER: FE 24-13855	DATE: June 2024	DRW BY: T.L.
ID FILE: FIG4	SCALE: Not to Scale	CHK BY: I.F.

CAD FILE:	FIG4	SCALE:	Not to Scale	CHK BY:	I.F.
-----------	------	--------	--------------	---------	------





## Legend



Asbestos-Containing Material

1-01

Location Number

NAR

No Access to Room

The drawing does not illustrate locations of drywall joint compound, plaster, window caulking or roofing materials, for reasons discussed in Section 6 of the Standard Operating Procedure for Designated Substance Surveys. Please refer to the Designated Substance Survey Form in Appendix I for information regarding the locations and asbestos or lead-content of these materials.

### Figure 5

**LOCATION:**  
351 Christie Street  
Toronto, Ontario

**BUILDING NAME:**  
Castlerview-Wychwood Tower


**Fourth Floor Plan**  
**Asbestos-Containing Material Locations**

**CLIENT:** City of Toronto

**PROJECT NUMBER:** FE 24-13855 **DATE:** June 2024 **DRW BY:** T.L.

**CAD FILE:** FIG5 **SCALE:** Not to Scale **CHK BY:** I.F.





## Legend

The drawing does not illustrate locations of drywall joint compound, plaster, window caulking or roofing materials, for reasons discussed in Section 6 of the Standard Operating Procedure for Designated Substance Surveys. Please refer to the Designated Substance Survey Form in Appendix I for information regarding the locations and asbestos or lead-content of these materials.


**LOCATION:** 351 Christie Street  
Toronto, Ontario

### Fifth Floor Plan Asbestos-Containing Material Locations


PROJECT: City of Toronto		
PROJECT NUMBER: FE 24-13855	DATE: June 2024	DRW BY: T.L.
ID FILE: FIG6	SCALE: Not to Scale	CHK BY: I.F.







## Legend



Asbestos-Containing Material

1-01

Location Number

NAR

No Access to Room

The drawing does not illustrate locations of drywall joint compound, plaster, window caulking or roofing materials, for reasons discussed in Section 6 of the Standard Operating Procedure for Designated Substance Surveys. Please refer to the Designated Substance Survey Form in Appendix I for information regarding the locations and asbestos or lead-content of these materials.

### Figure 7

**LOCATION:**  
351 Christie Street  
Toronto, Ontario

**BUILDING NAME:**  
Castleview-Wychwood Tower


**Sixth Floor Plan**  
**Asbestos-Containing Material Locations**

**CLIENT:** City of Toronto

**PROJECT NUMBER:** FE 24-13855 **DATE:** June 2024 **DRW BY:** T.L.

**CAD FILE:** FIG7 **SCALE:** Not to Scale **CHK BY:** I.F.





---

351 Christie Street  
Toronto, Ontario


### Castleview-Wychwood Tower

PROJECT NUMBER:	FE 24-13855	DATE:	June 2024	DRW BY:	T.L.
-----------------	-------------	-------	-----------	---------	------


D FILE:	FIG8	SCALE:	Not to Scale	CHK BY:	I.F.
---------	------	--------	--------------	---------	------

\_\_\_\_\_





## Legend



Asbestos-Containing Material

1-01

Location Number

NAR

No Access to Room

The drawing does not illustrate locations of drywall joint compound, plaster, window caulking or roofing materials, for reasons discussed in Section 6 of the Standard Operating Procedure for Designated Substance Surveys. Please refer to the Designated Substance Survey Form in Appendix I for information regarding the locations and asbestos or lead-content of these materials.

### Figure 9

**LOCATION:**  
351 Christie Street  
Toronto, Ontario

**BUILDING NAME:**  
Castleview-Wychwood Tower

**Roof Floor Plan**  
**Asbestos-Containing Material Locations**

**CLIENT:** City of Toronto

**PROJECT NUMBER:** FE 24-13855 **DATE:** June 2024 **DRW BY:** T.L.

**CAD FILE:** FIG9 **SCALE:** Not to Scale **CHK BY:** I.F.



## **APPENDIX IV**

### **SITE PHOTOGRAPHS**

**(NO INFORMATION TO REPORT)**

## **APPENDIX V**

### **CORRECTIVE ACTIONS INSPECTION REPORT**



August 30, 2024

Corporate Real Estate Management  
City of Toronto  
Metro Hall, 55 John Street  
Toronto, ON M5V 3C6

Inder Bhamra, EP, PMP, CSM  
Environmental Coordinator -Project Management Office

**Re: Level 1 Mould Abatement & Type 2 Glove Bag Asbestos Abatement at the  
Castlevue-Wychwood Tower LTCH, 351 Christie Street, Toronto, ON**

As requested, Fisher Engineering Limited (Fisher) has provided environmental monitoring services with respect to mould and asbestos abatement activities recently undertaken in the Castlevue-Wychwood Tower LTCH building, located at 351 Christie Street, Toronto, Ontario (the "Site"). The project involving Fisher's environmental health and safety consulting services were provided on August 22 and 26, 2024.

**Background**

Mould and asbestos abatement were initiated following the discovery of mould on two (2) pipe fittings in the East Mechanical Room (B-053), and one damaged pipe fitting with asbestos-containing parging in the Laundry Room (B-007), during the annual re-assessment survey 2024.

The current abatement scope of work included the following:

- Clean mould-impacted surfaces with Concrobium, apply new canvas and lagging in the East Mechanical Room, B-053.
- Repair/Remove the damaged fitting following Type 2 Glove Bag Operations in the Laundry Room, B-007.
- Clean up the Work Area.

The location name and number where the current work was conducted are referenced from the most recent annual survey report (under separate cover).

The City of Toronto retained Fisher as the environmental health and safety consultant to provide project monitoring. Fisher retained Furcon Environmental Inc. (Furcon) as the environmental abatement contractor to undertake the specified abatement work.

Mould abatement followed Level 1 Mould Abatement Procedures as per the EACC Mould Abatement Guidelines, Edition 3 (2015). Asbestos removal operations followed Type 2 Glove Bag asbestos abatement procedures as outlined in Ontario Regulation 278/05, "Asbestos on Construction Projects and in Building Repairs and Repair Operations" made under the Occupational Health and Safety Act (O. Reg. 278/05).

## **Level 1 Mould Abatement in the East Mechanical Room (B-053) – August 22, 2024**

### **Preparation Phase Inspection**

The representative from Fisher arrived on-site to conduct the preparation phase inspection of the Level 1 mould abatement procedures and met with the Site Supervisor of Furcon. There was one (1) additional Furcon worker on-site to conduct the specified scope of work.

During the mould abatement, it was observed that the mould growth was only on the surface of the canvas, the pipe insulation was not impacted. Therefore, no insulation was removed during the mould abatement on the pipe fittings. However, as one of the pipe fittings was insulated with asbestos-containing parging cement, Fisher decided to collect an ambient air sample within the work area, to ensure that the air quality was not impacted.

Prior to the removal work, Fisher performed a pre-contamination assessment of Furcon's Work Area preparations. The following observations were noted during the preparation phase inspection:

- Asbestos and mould warning signs were posted at the entrance to the Work Area.
- Rip-proof poly was placed under the mould-impacted pipe fittings.
- Prohibitions were adhered to within the Work Area (i.e., no eating, drinking, or smoking was observed).
- Removal equipment was present in the Work Area, including airless misting sprayers, HEPA vacuum, waste bags, clean sponges/rags for clean-up, disinfectant, etc.
- The contractor had the required equipment and Personal Protective Equipment (PPE) on site including Half-Face Air Purifying Respirators equipped with P-100 filters, Tyvek suits, safety boots, and disposable gloves.
- A waste bin was not present during the inspection. The contractor will transport waste to an off-site bin and have the proper Certificate of Approval for transporting the waste.
- The contractor waited for authorization before commencing removal activities.

Fisher observed no deficiencies regarding Furcon's Level 1 mould abatement Work Area preparations. The abatement contractor was advised that the contaminated work phase may commence.

### **Contaminated Work Phase Inspection**

The following observations were noted during the contaminated phase inspection:

- Safety measures were observed to be satisfactory during the inspection.
- Asbestos and mould warning signs remain posted at the entrance to the Work Area.
- The contractor had the required equipment and PPE on site.
- Appropriate waste bags were noted to be present on-site. Waste was double-bagged and properly decontaminated prior to being removed from the Work Area.



- After cleaning all the surfaces of the straight pipe and fittings, the lagging was applied all over the surfaces.
- The floor and concrete pad under the pipe fittings were cleaned using a HEPA-filtered vacuum, wiped with a wet rag, and treated with disinfectant.
- Contractor personnel were observed to be following the proper exiting and decontaminating procedures when leaving the Work Area.

### **Final Visual Inspection**

The following observations were noted during the final visual inspection:

- Review of the Work Area revealed that mould-impacted insulation cover on pipe fittings was cleaned, treated, and encapsulated following Level 1 mould abatement procedure.
- Waste and equipment were removed from the Work Area.
- Floor surfaces were noted to be clean and dry.
- The contractor waited for authorization prior to applying disinfectant (Concrobium). Additionally, the contractor applied encapsulation on the pipe fittings and associated fiberglass-insulated straight pipes, according to the scope of work.
- Fisher found the work quality and the condition of the Work Area to be satisfactory.
- The contractor was given the authorization to dismantle the Work Area.

While on-site, Fisher collected one (1) ambient air sample for asbestos fibres from inside the Mechanical Room, adjacent to the Work Area. The sample was submitted to Fisher Environmental Laboratories for phase contrast microscopy (PCM) analysis, as outlined in NIOSH method 7400. The analysis determined the air sample (Sample ID 24-3423-1) to be within the allowable Time-Weighted Average Exposure limit of 0.1 fibres per cubic centimetres of air for an 8-hour work shift, as outlined in O. Reg. 278/05.

Please refer to the laboratory analysis report, included in Attachment A.

### **Type 2 Glove Bag Asbestos Abatement in Laundry Room (B-007) – August 26, 2024**

#### **Preparation Phase Inspection**

The representative from Fisher arrived on-site to conduct the preparation phase inspections of the Type 2 asbestos abatement procedures and met with the Site Supervisor of Furcon. There was one (1) additional Furcon worker on-site to conduct the specified scope of work. The following observations were noted during the preparation phase inspection:

- Prior to the setup of the glove bag, Furcon cleaned the Work Area using a HEPA filtered vacuum cleaner.
- The perimeter of the Work Area was marked with yellow tape, and asbestos warning signs were posted at all entrances to Work Area.

- Prohibitions were adhered to within the Work Areas (i.e., no eating, drinking, or smoking was observed).
- Removal equipment was present within the Work Area including HEPA-filtered vacuum, glove bags, airless misting sprayers, hand tools, ladders, clean rags for clean-up, etc.
- The glove bags were securely attached around the pipes and pipe fittings.
- The contractor had the required equipment and Personal Protective Equipment (PPE) on site including Half-face Air Purifying Respirators equipped with P100 filters, Tyvek suits, safety boots, and disposable gloves.
- A waste bin was not present during the inspection. The contractor will transport waste to an off-site bin and has proper Certificate of Approval for transporting the waste.
- The contractor waited for authorization before commencing abatement activities.

The Work Area isolation measures were observed to be adequate and intact. No deficiencies regarding Furcon Type 2 Glove Bag preparation were observed by Fisher, and the abatement contractor was advised that the contaminated work phase may commence.

### **Asbestos Removal Phase Inspections**

The following observations were noted during the removal phase inspections:

- Asbestos warning sign remain posted at the entrances to the Work Area.
- Work Area was isolated from the rest of the building using yellow tape.
- The contractor had the required equipment and PPE.
- Wetting procedures were noted; pipe insulation scheduled for removal was regularly wetted during the removal operations using airless sprayers and amended water.
- Appropriate waste bags were noted to be present. Waste was double bagged and waste bags were properly decontaminated prior to being removed from the Work Area.
- Contractor personnel was observed to be following the proper exiting and decontaminating procedures when leaving the Work Area.

### **Clearance Visual Inspection**

The following observations were noted during the final clearance visual inspection.

- Specified asbestos-containing damaged pipe insulation on a pipe fitting was removed.
- The contractor waited for authorization prior to applying lock-down agent.
- The exposed edges of the remaining insulation were sealed with canvas and lagging.
- Waste and equipment were removed from the Work Area.
- Surrounding surfaces were noted to be clean and dry.
- Fisher found the work quality and the condition of the Work Area to be satisfactory.
- The contractor was given the authorization to dismantle the Work Area.

While on-site, Fisher collected one (1) ambient air sample for asbestos fibres from inside the Laundry Room, adjacent to the Work Area. The sample was submitted to Fisher Environmental Laboratories for phase contrast microscopy (PCM) analysis, as outlined in NIOSH method 7400. The analysis determined the air sample (Sample ID 24-3435-1) to be within the allowable Time-Weighted Average Exposure limit of 0.1 fibres per cubic centimetres of air for an 8-hour work shift, as outlined in O. Reg. 278/05.

Please refer to the laboratory analysis report, included in Attachment A.

Site photos are presented in Attachment B.

Based on the air sampling results and observed work results, the cleaning and applying the encapsulation of the specified mould-impacted pipe fittings in the East Mechanical Room and the removal of the specified damaged pipe-fitting with asbestos-containing parging cement was completed as per the scope of work.

Should you have any questions or concerns please do not hesitate to contact the undersigned.

Prepared by:

Reviewed by:



Iqbal Fattah, M.Sc.  
Project Manager



Dave Fisher, P.Eng. C.Chem.  
Principal

Attachments: Attachment A - Laboratory Analysis Report  
Attachment B - Site Photos

## **Attachment A - Laboratory Analysis Reports**



# FISHER ENVIRONMENTAL LABORATORIES

FULL RANGE ANALYTICAL SERVICES • SOIL/WATER/AIR TESTING • ENVIRONMENTAL  
COMPLIANCE PACKAGES • 24 HOUR EMERGENCY RESPONSE • CALA ACCREDITED

400 ESNA PARK DRIVE #15  
MARKHAM, ONT. L3R 3K2  
TEL: 905 475-7755  
FAX: 905 475-7718  
www.fisherenvironmental.com

**Client:** City of Toronto  
Facilities Management  
**Address:** 2nd Floor, Metro Hall  
55 John Street, Toronto, ON  
M5V 3C6  
**Tel.:**  
**Attn:**

**F.E. Job #:** 24-3423  
**Project Name:** Asbestos Abatement  
**Project ID:** FM 24-14158  
**Date Sampled:** 22-Aug-2024  
**Date Received:** 23-Aug-2024  
**Date Reported:** 23-Aug-2024  
**Location:** 351 Christie Street

## Certificate of Analysis

<b>Analysis Requested:</b>	Total Fibre Count by Phase Contrast Microscopy
<b>Sample Description:</b>	1 PCM Cassette Samples ( <i>Same Day</i> )

Client Sample ID	Lab Sample ID	Purpose	Total Volume (L)	Result* (fibres/ml)	Comments
PCM 1 - Ambient, East Mechanical Rm, adjacent to Work Area	24-3423-1	Ambient	930	<0.0036	

\* Results reported for total fibres are inclusive of any fibre with specific length to width ratios and are not specific to asbestos. They may include fibres from many sources including but not limited to carpets, clothing, wood, fiberglass, and asbestos. Elevated total fibre levels may be commonly encountered during interior renovation and/or demolition works.

Occupational Health and Safety Act, Ontario regulation 278/05 requires that the work area inside the enclosure passes the clearance air test only if every air sample collected has a concentration of fibres that does not exceed 0.01 fibres per cubic centimeters of air.

The Ontario ministry of labour mandates that employers shall take all necessary measures and procedures to ensure that the time-weighted average exposure of a worker to airborne asbestos shall not exceed a criterion of 0.1 fibres/ml.


Fisher Engineering utilizes and recommends a criterion action level for asbestos of 0.04 fibres/ml, above which an immediate shut down of any building works will occur until such time as a cause for the elevated fibre levels can be determined.

### ANALYTICAL METHOD:

PCM - Method #F-10, Rev.2.2, standard operating procedure for the determination of asbestos and other fibers by Phase Contrast Microscopy.

Authorized by:

  
Roger Lin, Ph. D., C. Chem.  
Laboratory Manager





# FISHER ENVIRONMENTAL LABORATORIES

FULL RANGE ANALYTICAL SERVICES • SOIL/WATER/AIR TESTING • ENVIRONMENTAL  
COMPLIANCE PACKAGES • 24 HOUR EMERGENCY RESPONSE • CALA ACCREDITED

400 ESNA PARK DRIVE #15  
MARKHAM, ONT. L3R 3K2  
TEL: 905 475-7755  
FAX: 905 475-7718  
www.fisherenvironmental.com

**Client:** City of Toronto  
Facilities Management  
**Address:** 2nd Floor, Metro Hall  
55 John Street, Toronto, ON  
M5V 3C6  
**Tel.:**  
**Attn:**

**F.E. Job #:** 24-3435  
**Project Name:** Asbestos Abatement  
**Project ID:** FE 24-14158  
**Date Sampled:** 26-Aug-2024  
**Date Received:** 27-Aug-2024  
**Date Reported:** 27-Aug-2024  
**Location:** 351 Christie Street

## Certificate of Analysis

<b>Analysis Requested:</b>	Total Fibre Count by Phase Contrast Microscopy
<b>Sample Description:</b>	1 PCM Cassette Samples ( <i>Same Day</i> )

Client Sample ID	Lab Sample ID	Purpose	Total Volume (L)	Result* (fibres/ml)	Comments
PCM 1 - Ambient, Basement, Laundry Rm (B007), adjacent to Work Area	24-3435-1	Ambient	930	<0.0029	

\* Results reported for total fibres are inclusive of any fibre with specific length to width ratios and are not specific to asbestos. They may include fibres from many sources including but not limited to carpets, clothing, wood, fiberglass, and asbestos. Elevated total fibre levels may be commonly encountered during interior renovation and or demolition works

Occupational Health and Safety Act, Ontario regulation 278/05 requires that the work area inside the enclosure passes the clearance air test only if every air sample collected has a concentration of fibres that does not exceed 0.01 fibres per cubic centimeters of air.

The Ontario ministry of labour mandates that employers shall take all necessary measures and procedures to ensure that the time-weighted average exposure of a worker to airborne asbestos shall not exceed a criterion of 0.1 fibres/ml.


Fisher Engineering utilizes and recommends a criterion action level for asbestos of 0.04 fibres/ml, above which an immediate shut down of any building works will occur until such time as a cause for the elevated fibre levels can be determined.

### ANALYTICAL METHOD:

PCM - Method #F-10, Rev.2.2, standard operating procedure for the determination of asbestos and other fibers by Phase Contrast Microscopy.

Authorized by:

  
Roger Lin, Ph. D., C. Chem.  
Laboratory Manager



## **Attachment B – Site Photos**





**Photos 1 and 2** – View of the Level 1 Work Area preparation in the East Mechanical Room (B-053).



**Photos 3 and 4:** View of the mould-impacted fittings before the abatement work.




**Photos 5 and 6:** Post abatement view of the pipe fittings in the East Mechanical Room (B-053).





**Photo 7:** View of the Work Area after completion of the abatement work.



**Photo 8:** View of the Type 2 Glove Bag Work Area Preparation in the Laundry Room (B-007).



**Photo 9:** View of the damaged fitting prior to the abatement.



**Photo 10:** Post-abatement view of the fitting in the Laundry Room (B-007).