

February 11, 2025

Kawartha Pine Ridge District School Board 1994 Fisher Drive Peterborough, Ontario, K9J 7A1

#### Re: Hazardous Building Materials Assessment (Pre-Construction) Enniskillen Public School, 8145 Old Scugog Road, Enniskillen, Ontario Pinchin File: 349417.020

Kawartha Pine Ridge District School Board (Client) retained Pinchin Ltd. (Pinchin) to conduct a hazardous building materials assessment at Enniskillen Public School located at 8145 Old Scugog Road, Enniskillen, Ontario.

Pinchin performed the assessment on December 17, 2024. The assessor was unaccompanied during the assessment. The assessed area was unoccupied at the time of the assessment.

The objective of the assessment was to identify specified hazardous building materials in preparation for an upcoming building renovation. The proposed work is detailed in the drawings, provided by the Client, titled "Enniskillen Public School Renovation, 8145 Old Scugog Road, Hampton, ON", prepared by Salterpilon architecture, dated January 2025.

The results of this assessment are intended for use with a properly developed performance specification.

The **assessed area** is limited to the portions of the building to be renovated, detailed in the abovementioned drawing and as identified in the drawing included in Appendix I.

#### 1.0 SUMMARY OF FINDINGS

Asbestos was detected in the following building materials present in the assessed area:

- Plaster on walls and ceilings.
- Parging cement on pipe fittings.
- Drywall joint compound on drywall walls and ceilings.
- Paint on block masonry walls.
- Adhesive associated with vinyl trim.
- Expansion joint caulking.
- Cement (Transite) pipes and panels.
- Adhesive associated with blackboard and tackboard (presumed asbestos).



Elevated lead content was detected in the following paints, finishes, and items:

- White paint on masonry block walls.
- Beige paint on masonry walls.
- Blue paint on wooden cabinets.
- Blue paint on radiators and door frames (presumed elevated).
- Red paint on joists (presumed elevated).
- Beige paint on drywall and masonry block walls (presumed elevated).

#### Other findings:

- Crystalline silica is present in concrete and other materials such as masonry, and ceramic tiles.
- Mercury vapour is present in lamp tubes.
- PCBs may be present in light ballasts.
- Mould impacted or water damaged building materials were not observed at the time of the site visit.

#### 2.0 RECOMMENDATIONS

#### 2.1 General

Prepare performance specifications for hazardous material removal required for the planned work. The specifications should include safe work practices, personal protective equipment, respiratory protection, and disposal of waste materials.

If suspected hazardous building materials are discovered during the planned work, which are not identified in this report, do not disturb, and arrange for further testing and evaluation.

Provide this report to the contractor(s) prior to bidding or commencing work.

Retain a qualified consultant to specify, observe and document the successful removal of hazardous materials.

Update the asbestos inventory upon completion of the abatement and removal of asbestos-containing materials and any other relevant findings.

#### 2.2 Remedial Work

Remedial work is not required.



#### 2.3 Project Work

The following recommendations are made regarding renovations involving the hazardous materials identified:

#### 2.3.1 Asbestos

Remove asbestos-containing materials (ACM) prior to renovation activities if ACM may be disturbed by the work, following safe work procedures.

If the identified ACM will not be removed prior to commencement of the work, any potential disturbance of ACM must follow asbestos precautions appropriate for the type of work being performed.

Asbestos-containing materials must be disposed of at a landfill approved to accept asbestos waste.

#### 2.3.2 Lead

For lead-containing (i.e., greater than the EACC guideline of 0.1% (1,000 mg/kg)), construction disturbance may result in over-exposure to lead dust or fumes. The need for work procedures, engineering controls and personal protective equipment should be assessed on a site-specific basis to comply with applicable regulations, and/or guidelines.

For paints identified as having low levels of lead (i.e., equal to or above 0.009% (90 mg/kg) but less than or equal to the EACC guideline of 0.1% (1,000 mg/kg) for lead-containing paints) special precautions are not recommended unless aggressive disturbance (grinding, blasting, torching) is planned.

Exposure from construction disturbance of paints containing lead less than 0.009% (90 mg/kg) is assumed to be insignificant.

Dispose of painted materials exceeding the criteria for leachable lead as hazardous waste.

#### 2.3.3 Silica

Construction disturbance of silica-containing products may result in excessive exposures to airborne silica, especially if performed indoors and dry. Cutting, grinding, drilling or demolition of materials containing silica should be completed only with proper respiratory protection and other worker safety precautions that comply with applicable regulations and guidelines.

#### 2.3.4 Mercury

Do not break lamps. Recycle and reclaim mercury from fluorescent lamps when taken out of service. Mercury is classified as a hazardous waste and must be disposed of in accordance with applicable regulations.



#### 2.3.5 PCBs

As light fixtures are removed from service, examine light ballasts for PCB content. If ballasts are not clearly labelled as "non-PCB" or are suspected to contain PCBs, package, and ship ballasts for destruction at a federally permitted facility. As per the PCB Regulation (SOR/2008-273), all PCB light ballasts must be removed from service and properly disposed of by December 31, 2025.

#### 3.0 BACKGROUND INFORMATION

#### 3.1 Assessed Area Description Summary

Description Item	Details
Building Use	Elementary School
Floors Above Grade	1
Floors Below Grade	1
Total Area (square feet)	~ 14,300
Year of Construction	1926
Additions	1968 and 1972
Structure	Poured concrete foundation, wood framed, structural steel
Exterior Cladding	Brick
HVAC	Boiler with radiators
Roof	Not assessed (outside of scope)
Flooring	Vinyl floor tile, carpet/carpet tile, hardwood, terrazzo
Wall and Ceiling Finishes	Drywall, plaster, ceramic, wood, concrete block, lay-in ceiling tiles, wallboard, and cement boards (Transite)

#### 3.2 Existing Reports

#### 3.2.1 Review of Previous Reports

Pinchin reviewed the following reports and included relevant results as appropriate:

- "Asbestos Assessment, Kawartha Pine Ridge District School Board, Enniskillen Public School, 8145 Old Scugog Road, Enniskillen, Ontario", dated January 21, 2011, Pinchin File 59723.
- "Asbestos-Containing Materials Reassessment, Enniskillen Public School, 8145 Old Scugog Road, Enniskillen, Ontario", dated August 31, 2023, Pinchin File 315813.
- "Hazardous Building Materials Assessment, Classroom, Washroom, Staff Room, and Changeroom Refresh Project, Enniskillen Public School, 8145 Old Scugog Road, Enniskillen, Ontario", dated May 7, 2024, Pinchin File 335324.027.



• "Asbestos-Containing Materials Reassessment, Enniskillen Public School, 8145 Old Scugog Road, Enniskillen, Ontario", dated July 26, 2024, Pinchin File 335324.027.

#### 4.0 FINDINGS

Any quantities listed in this report or data tables are estimated based on visual approximations only and are subject to variation.

#### 4.1 Asbestos

The following table summarizes the materials evaluated for asbestos in the assessed area. For details on approximate quantities, condition, friability, accessibility, and locations of hazardous building materials; refer to the Hazardous Material Summary / Sample Log and All Data Report in Appendices V and VI.

Sample Number	Material Description	Type of Asbestos	Confirmed Hazard	Total Quantity Present	Material Specific Notes
V0002	Plaster on walls & ceilings applied to concrete block masonry	Chrysotile	Yes	3,600 SF	In the 1926 Phase
V0003	Parging cement on pipe fittings	Chrysotile	Yes	21 EA	In the 1968 & 1972 Phases
V0004	Drywall joint compound on drywall walls & ceilings	Chrysotile	Yes	552 SF	In the 1968 & 1972 Phases
S0006	12" x 12" Vinyl floor tile (off white with gray spots) and mastic	None Detected	No	5,735 SF	-
V0020	Brown window caulking	None Detected	No	280 LF	1926 Phase
S0021	Beige paint on exterior masonry block wall	None Detected	No	2,720 SF	1968 Phase
S0022	Grey sink mastic	None Detected	No	6 EA	-
S0023	Black adhesive associated with vinyl trim	None Detected	No	290 LF	1968 Phase
S0024	Primer paint on interior masonry block wall	None Detected	No	3,200 SF	1968 Phase
S0025	Brown caulking on window frame	None Detected	No	280 LF	1968 & 1972 Phase



#### Hazardous Building Materials Assessment (Pre-Construction)

Enniskillen Public School, 8145 Old Scugog Road, Enniskillen, Ontario Kawartha Pine Ridge District School Board

S0027	Carpet mastic	Chrysotile (Trace <0.5%)	No	6,150 SF	Refer to Material Specific Note #1
S0029	Paint on exterior masonry wall	Chrysotile	Yes	1,620 SF	1972 Phase
S0031	Paint on interior block walls	Chrysotile	Yes	560 SF	1972 Phase
S0032	Brown adhesive associated with vinyl trim	Chrysotile	Yes	40 LF	1972 Phase
S0035	Black caulking on window frame	None Detected	No	40 LF	-
S0036	White caulking on door frame	None Detected	No	34 LF	-
S0038	Brown adhesive associated with tackboards	Chrysotile (Trace <0.5%)	No	25 EA	Refer to Material Specific Note #1
V0039	Terrazzo flooring	None Detected	No	1,100 SF	-
S0041	Grey expansion joint caulking	Chrysotile	Yes	30 SF	-
S0042	Concrete floor	None Detected	No	800 SF	-
S0043	Paint on block wall	Chrysotile	Yes	100 SF	1972 Phase
S0044	Mastic beneath rubber baseboards	None Detected	No	80 SF	-
V9500	Mastic beneath vinyl floor tiles	Presumed Asbestos	Yes	1,600 SF	Original Mastic - 1972 Phase
V9000	Cement (Transite) pipe	Confirmed Asbestos	Yes	Refer to Material Specific Note #2	Below concrete slab
V9000	Cement (Transite) panel	Confirmed Asbestos	Yes	10 SF	On walls
V9500	Adhesive associated with tackboards	Presumed Asbestos	Yes	10 EA	-
V0000	Caulking on door frame	None	No	200 LF	Installed 2024



V0000	Ceiling Tiles (lay-in)   Various Patterns	None	No	4,662 SF	Date code 2004 and 2024.
V0000	Thin-set beneath ceramic tile	None	No	410 SF	Installed post- 2023.
V0000	Vermiculite Investigation	None	No	8 EA	None Found

#### Specific Notes:

- Chrysotile asbestos was found in trace concentrations (<0.5%) in the carpet mastic sample set 0027A-C, and the tackboard mastic sample set S0038A-C. As per Ontario Regulation 278/05, an asbestos-containing material is defined as any material that contains 0.5% or more asbestos by dry weight. As such, the carpet mastic and tack board mastic are considered non-asbestos.
- 2. Material inaccessible for quantification.

#### **General Notes:**

Materials identified as Sample Number V9500 were either observed to be present or based on the construction of the building/equipment are likely present in concealed locations. These materials have not been sampled and are presumed to contain asbestos based on historical known use of asbestos. Sampling of these materials may be completed prior to disturbance.

Materials identified as Sample Number V9000 were observed to be present and were determined to contain asbestos based on previous analytical results, or labelling (e.g., Transite clearly labelled by the manufacturer).

Materials identified as Sample Number V0000 were determined to be non-asbestos based on the manufacture date and known end of use of asbestos in these products.

#### 4.1.1 Excluded Asbestos Materials

The following is a list of materials which may contain asbestos and were excluded from the assessment. These materials are presumed to contain asbestos until otherwise proven to be non-asbestos by sampling and analysis:

- Floor levelling compound
- Electrical components
- Ropes and gaskets in cast-iron bell and spigot joints
- Sealants on pipe threads
- Paper products



#### 4.2 Lead

Refer to the Hazardous Material Summary / Sample Log and All Data Report in Appendices V and VI for details on locations, condition and approximate quantities on paints sampled and their locations.

The following table summarizes the analytical results of paints sampled:

Sample Number	Material Description	Concentration	Confirmed Hazard	Total Quantity Present	Material Specific Notes
L0004	Blue paint on wood window frames	0.12%	Yes	380 SF	-
L0005	Beige paint on interior and exterior block walls	0.052%	Yes	8,200 SF	-
V0006	Blue paint on wood doors	0.045%	Yes	68 SF	-
V0007	Beige paint on drywall walls	0.0057%	No	810 SF	-
L0009	White paint on masonry walls	0.083%	Yes	100 SF	-
V9500	Blue paint on metal radiator covers	Presumed lead containing.	Yes	1,210 SF	-
V9500	Blue paint on metal door frames	Presumed lead containing.	Yes	11 EA	-
V9500	White paint on plaster walls	Presumed lead containing.	Yes	1,800 SF	-
V9500	Red primer on steel joists and beams	Presumed lead containing.	Yes	12,440 SF	-

#### **General Notes:**

Results above 0.1% (1,000 mg/kg) are considered lead-containing.

Results less than or equal to 0.1% (1,000 mg/kg), but equal to or greater than 0.009% (90 mg/kg), are considered low-level lead paints or surface coatings in accordance with the EACC guideline.

Paints containing lead less than 0.009% (90 mg/kg) are assumed to be insignificant relating to potential exposure from construction disturbance.

Paints identified as Sample Number V9500 were observed to be present and have not been sampled and based on the construction of the building/equipment are assumed to contain lead. Sampling of these materials may be completed prior to disturbance.



#### 4.2.1 Lead Products and Applications

Lead containing products and applications were not found during the assessment.

#### 4.2.2 Excluded Lead Materials

Lead may be present in a number of materials which were not assessed and/or sampled. The following materials, where found, should be considered to contain lead:

- Electrical components, including wiring connectors, grounding conductors, and solder
- Solder on pipe connections
- Glazing on ceramic tiles

#### 4.3 Silica

Crystalline silica is a presumed component of the following materials:

- Poured and pre-cast concrete
- Masonry and mortar
- Ceramic tiles and grout
- Terrazzo

#### 4.4 Mercury

Refer to the Hazardous Material Summary / Sample Log and All Data Report in Appendices V and VI for details on mercury-containing products including their locations and quantities.

Sample	Material	Confirmed	Total Quantity	Material Specific
Number	Description	Hazard	Present	Notes
V9000	Light Fixture	Yes	464 EA	-

#### **General Notes:**

Items identified as Sample Number V9000 were observed to be present and were determined to contain mercury based on visual observation (e.g., labelled lamps and ampules in thermostats).



#### 4.5 Polychlorinated Biphenyls

Refer to the Hazardous Material Summary / Sample Log and All Data Report in Appendices V and VI for details on PCB-products including their locations and quantities.

Sample Number	Material Description	Concentration	Confirmed Hazard	Total Quantity Present	Material Specific Notes
P0001	Caulking   1926 Brown Bottom Window Caulking	<0.2mg/kg	No	200 LF	-
P0002	Caulking   1926 Brown Upper Window Caulking	<0.2mg/kg	No	80 LF	-
V9500	Light Ballasts	Presumed PCB Containing	Yes	59 EA	-
V0000	Caulking   Black Window Caulking	None	No	240 LF	Installed 2002

#### **General Notes:**

PCBs were banned in 1980; however, are found to be present in caulking and sealants until 1985.

Materials identified as Sample Number V9500 were either observed to be present or based on the construction of the building/equipment are likely present in concealed locations. These materials have not been sampled and are presumed to contain PCBs based on historical known use (e.g. concealed ballasts of fluorescent fixtures with T12 tubes). Assessment these items may be completed prior to disturbance.

#### 4.5.1 Excluded PCB Materials

PCBs are known to be present in several materials and equipment which were not assessed or sampled. The following materials, where found, should be presumed to contain PCBs until sampling proves otherwise:

- Capacitors within or associated with electrical equipment
- Paints



#### 4.6 Mould and Water Damage

Visible mould growth and water damage was not observed during the assessment.

#### 5.0 METHODOLOGY

For the purpose of the assessment and this report, hazardous building materials are defined as follows:

- Asbestos
- Lead
- Silica
- Mercury
- Polychlorinated Biphenyls (PCBs)
- Mould and Water Damage

Arsenic, acrylonitrile, benzene, coke oven emissions, ethylene oxide, isocyanates and vinyl chloride monomer are not typically found in building materials in a composition/state that is hazardous and were not included in this assessment.

Pinchin conducted a room-by-room assessment to identify the hazardous building materials as defined in the scope.

The assessment was performed to establish the type of specified hazardous building materials, locations and approximate quantities incorporated in the structure(s) and its finishes.

The assessment included limited demolition of wall and ceiling finishes (drywall or plaster) to view concealed conditions at representative areas as permitted by the current building use. Limited destructive testing of flooring was conducted where possible (under ceramic tiles, carpets, or multiple layers of flooring). Demolition of exterior building finishes, masonry walls (chases, shafts etc.), and structural surrounds was not conducted.

Limited demolition of masonry block walls (core holes) was conducted to investigate for loose fill vermiculite insulation. Sampling of roofing materials was not conducted.

For further details on the methodology including test methods and evaluation criteria, refer to Appendix III.



#### 6.0 **REFERENCES**

The following legislation and documents were referenced in completing the assessment and this report:

- 1. Asbestos on Construction Projects and in Buildings and Repair Operations, Ontario Regulation 278/05.
- 2. Designated Substances, Ontario Regulation 490/09.
- 3. Lead on Construction Projects, Ministry of Labour Guidance Document.
- 4. The Environmental Abatement Council of Canada (EACC) Lead Guideline for Construction, Renovation, Maintenance or Repair.
- 5. Ministry of the Environment Regulation, R.R.O. 1990 Reg. 347 as amended.
- 6. Ministry of the Environment Regulation, R.R.O. 1990 Reg. 362 as amended.
- 7. Silica on Construction Projects, Ministry of Labour Guidance Document.
- 8. Alert Mould in Workplace Buildings, Ontario Ministry of Labour.
- 9. PCB Regulations, SOR/2008-273, Canadian Environmental Protection Act.
- Surface Coating Materials Regulations, SOR/2016-193, Canada Consumer Product Safety Act.
- 11. Consolidated Transportation of Dangerous Goods Regulations, including Amendment SOR/2019-101, Transportation of Dangerous Goods Act.
- Mould Guidelines for the Canadian Construction Industry, Standard Construction Document CCA 82 – 2004 (Revised 2018), Canadian Construction Association.

#### 7.0 LIMITATIONS

This work was performed subject to the Terms and Limitations presented or referenced in the Master Service Agreement.

Information provided by Pinchin is intended for Client use only. Pinchin will not provide results or information to any party unless disclosure by Pinchin is required by law. Any use by a third party of reports or documents authored by Pinchin or any reliance by a third party on or decisions made by a third party based on the findings described in said documents, is the sole responsibility of such third parties. Pinchin accepts no responsibility for damages suffered by any third party as a result of decisions made or actions conducted. No other warranties are implied or expressed.



#### 8.0 CLOSURE

The data presented in the appendices is prepared by Pinchin's Hazardous Materials Inventory System (HMIS). The information contained within this report was current at the time of this report issue, and is provided as a summary; however, HMIS should be accessed for the most current data.

Contact the Project Manager, Cal Cathcart at 705.772.7933 or <u>ccathcart@pinchin.com</u> should you have any questions.

Sincerely,

#### Pinchin Ltd.

Prepared by:

Reviewed by:

Project Managed by:


Spencer Yeo, B.Sc. Senior Project Technologist Calvin Cathcart, B.A.Sc., C.I.H. Senior Project Manager

Tanya Stanisic, BSc Hons, Dip EMA Operations Manager – GTA Hazardous Materials

Encl:	APPENDIX I	Drawings
	APPENDIX II-A	Asbestos Analytical Certificates
	APPENDIX II-B	Lead Analytical Certificates
	APPENDIX II-C	PCB Analytical Certificates
	APPENDIX III	Methodology
	APPENDIX IV	Location Summary Report
	APPENDIX V	Hazardous Materials Summary Report / Sample Log
	APPENDIX VI	All Data Report
	APPENDIX VII	Photographs

\\pinchin.com\pet\Job\349000s\0349417.000 KPRDSB,VariousSchools,Upgrades,ASB,CONS\0349417.020 KPRDSB,EnniskillenPS,Upgrades,ASB,CONS\Deliverables\HBMA\349417.020 HBMA EPS 8145 Old Scugog Enniskillen KPRDSB Feb 11 2025.docx Template: Master Template HBMA PreConstruction, HMIS, HAZ, August 15, 2024

APPENDIX I Drawings




APPENDIX II-A Asbestos Analytical Certificates



By Polarized Light Microscopy EPA Method: 600/R-93/116 and 600/M4-82-020



Customer: Pinchin Environmental Ltd 380 Armour Rd Suite 101 Peterborough, ON K9H 7L7 Attn: Tiffany Smith



Project: KPRDSB-Enniskillen

Sample ID Description		Asbestos	Fibrous	Non-Fibrous	Attributes
Lab Sample ID	Lab Notes	Aspestos	Components	Components	Treatment
S001A	Drywall - B01	3% Chrysotile		97% Other	Tan Non Fibrous Homogeneous
1013336PLM_1					Crushed
S001B	Drywall - B06	Not Analyzed			
1013336PLM_2	-				
S001C	Drywall - B06	Not Analyzed			
1013336PLM_3	-				
S002A - A	Plaster - B01	None Detected		100% Other	White Non Fibrous Homogeneous
1013336PLM_4	finish				Crushed
S002A - B	Plaster - B01	None Detected	2% Cellulose	98% Other	Gray Non Fibrous Heterogeneous
1013336PLM_32	base				Crushed
S002B - A	Plaster - B03	3% Chrysotile		97% Other	White Non Fibrous Homogeneous
1013336PLM_5	finish				Crushed
S002B - B	Plaster - B03	None Detected	2% Cellulose	98% Other	Pink Non Fibrous Heterogeneous
1013336PLM_33	base				Crushed
S002C - A	Plaster - B03	Not Analyzed			
1013336PLM_6	finish				

Disclaimer: Due to the nature of the EPA 600 method, asbestos may not be detected in samples containing low levels of asbestos. We strongly recommended that analysis of floor tiles, vermiculite, and/or heterogeneous soil samples be conducted by TEM for confirmation of "None Detected" by PLM. This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAI. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the US, government. Estimated MDL is 0.5%.

Bart Huber (47)

Analyst


Nathaniel Durham, MS or Approved Signatory



By Polarized Light Microscopy EPA Method: 600/R-93/116 and 600/M4-82-020



Customer: Pinchin Environmental Ltd 380 Armour Rd Suite 101 Peterborough, ON K9H 7L7 Attn: Tiffany Smith



Project: KPRDSB-Enniskillen

Sample ID	Description	Asbestos		Fibrous		n-Fibrous	Attributes
Lab Sample ID	Lab Notes	ASUESIUS	C	Components		mponents	Treatment
S002C - B	Plaster - B03	None Detected	2%	Cellulose	98%	Other	Pink Non Fibrous Heterogeneous
1013336PLM_34	base						Crushed
S002D	Plaster - B01	None Detected	3%	Hair	97%	Other	Gray Non Fibrous Heterogeneous
1013336PLM_7	single layer plaster						Crushed
S002E - A	Plaster - B02	Not Analyzed					
1013336PLM_8	finish						
S002E - B	Plaster - B02	None Detected	2%	Cellulose	98%	Other	Gray Non Fibrous Heterogeneous
1013336PLM_35	base						Crushed
S002F	Plaster - B05	None Detected	3%	Hair	97%	Other	Gray Non Fibrous Heterogeneous
1013336PLM_9	single layer plaster						Crushed
S002G	Plaster - B05	None Detected	3%	Hair	97%	Other	Gray Non Fibrous Heterogeneous
1013336PLM_10	single layer plaster						Crushed
S003A	Parging cement - B01	15% Chrysotile			85%	Other	White Non Fibrous Homogeneous
1013336PLM_11	1						Crushed
S003B	Parging cement - B01	Not Analyzed					
1013336PLM_12	-						<u> </u>

Disclaimer: Due to the nature of the EPA 600 method, asbestos may not be detected in samples containing low levels of asbestos. We strongly recommended that analysis of floor tiles, vermiculite, and/or heterogeneous soil samples be conducted by TEM for confirmation of "None Detected" by PLM. This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAI. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the US, government. Estimated MDL is 0.5%.

Bart Huber (47)

Analyst


Nathaniel Durham, MS or Approved Signatory



By Polarized Light Microscopy EPA Method: 600/R-93/116 and 600/M4-82-020



Customer: Pinchin Environmental Ltd 380 Armour Rd Suite 101 Peterborough, ON K9H 7L7 Attn: Tiffany Smith



**Date Reported:** 11/16/2010

Project: KPRDSB-Enniskillen

Sample ID         Description           Lab Sample ID         Lab Notes	Asbestos	Fibrous	Non-Fibrous	Attributes	
	Aspestos	Components	Components	Treatment	
S003C	Parging cement - B01	Not Analyzed			
1013336PLM_13					
S004A	Drywall - 1st Floor - Corridor 150	3% Chrysotile		97% Other	Tan Non Fibrous Homogeneous
1013336PLM_14	-				Crushed
S004B	Drywall - 1st Floor - Corridor 150	Not Analyzed			
1013336PLM_15					
S004C	Drywall - 1st Floor - Corridor 150	Not Analyzed			
1013336PLM_16	-				
S006A - A	Vinyl floor tile - 12 x 12 Off white with grey spots - Loc 9 Classroom 02	None Detected		100% Other	White Non Fibrous Homogeneous
1013336PLM_17	tile				Dissolved
S006A - B	Vinyl floor tile - 12 x 12 Off white with grey spots - Loc 9 Classroom 02	None Detected		100% Other	Black Non Fibrous Homogeneous
1013336PLM_36	mastic				Dissolved
S006B - A	Vinyl floor tile - 12 x 12 Off white with grey spots - Loc 9 Classroom 02	None Detected		100% Other	White Non Fibrous Homogeneous
1013336PLM_18	tile tile				Dissolved
S006B - B	Vinyl floor tile - 12 x 12 Off white with grey spots - Loc 9 Classroom 02	None Detected		100% Other	Black Non Fibrous Homogeneous
1013336PLM_37	mastic				Dissolved

Disclaimer: Due to the nature of the EPA 600 method, asbestos may not be detected in samples containing low levels of asbestos. We strongly recommended that analysis of floor tiles, vermiculite, and/or heterogeneous soil samples be conducted by TEM for confirmation of "None Detected" by PLM. This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAI. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the US, government. Estimated MDL is 0.5%.

Bart Huber (47)

Analyst


Nathaniel Durham, MS or Approved Signatory



By Polarized Light Microscopy EPA Method: 600/R-93/116 and 600/M4-82-020



Customer: Pinchin Environmental Ltd 380 Armour Rd Suite 101 Peterborough, ON K9H 7L7 Attn: Tiffany Smith



Project: KPRDSB-Enniskillen

Sample ID	Description	Asbestos	Fibrous	Non-Fibrous	Attributes Treatment
Lab Sample ID	Lab Notes	Aspestos	Components	Components	
S006C - A	Vinyl floor tile - 12 x 12 Off white with grey spots - Loc 9 Classroom 02	None Detected		100% Other	White Non Fibrous Homogeneous
1013336PLM_19	tile				Dissolved
S006C - B	Vinyl floor tile - 12 x 12 Off white with grey spots - Loc 9 Classroom 02	None Detected		100% Other	Black Non Fibrous Homogeneous
1013336PLM_38	mastic				Dissolved
S007A	AT07 - Textured no pattern - Vestibule - Loc 12	2% Amosite	95% Fiber Glass	3% Other	White Non Fibrous Homogeneous
1013336PLM_20	-				Teased
S007B	AT07 - Textured no pattern - Vestibule - Loc 12	Not Analyzed			
1013336PLM_21	-				
S007C	AT07 - Textured no pattern - Vestibule - Loc 12	Not Analyzed			
1013336PLM_22	-				
S008A - A	Vinyl floor tile - 12 x 12 Beige with brown striations Loc 14 - Room 155	3% Chrysotile		97% Other	Beige Non Fibrous Homogeneous
1013336PLM_23	tile				Dissolved
S008A - B	Vinyl floor tile - 12 x 12 Beige with brown striations Loc 14 - Room 155	None Detected		100% Other	Black Non Fibrous Homogeneous
1013336PLM_39	- mastic				Dissolved
S008B - A	Vinyl floor tile - 12 x 12 Beige with brown striations Loc 14 - Room 155	Not Analyzed			
1013336PLM_24	tile				

Disclaimer: Due to the nature of the EPA 600 method, asbestos may not be detected in samples containing low levels of asbestos. We strongly recommended that analysis of floor tiles, vermiculite, and/or heterogeneous soil samples be conducted by TEM for confirmation of "None Detected" by PLM. This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAI. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the US, government. Estimated MDL is 0.5%.

Bart Huber (47)

Analyst


Nathaniel Durham, MS or Approved Signatory



By Polarized Light Microscopy EPA Method: 600/R-93/116 and 600/M4-82-020



Customer: Pinchin Environmental Ltd 380 Armour Rd Suite 101 Peterborough, ON K9H 7L7 Attn: Tiffany Smith



Project: KPRDSB-Enniskillen

Sample ID	Description	Asbestos	Fibrous		-Fibrous	Attributes
Lab Sample ID Lab Notes		Aspestos	Components	Con	nponents	Treatment
S008B - B	Vinyl floor tile - 12 x 12 Beige with brown striations Loc 14 - Room 155 mastic	None Detected		100%	Other	Black Non Fibrous Homogeneous
1013336PLM_40	mastic					Dissolved
S008C - A	Vinyl floor tile - 12 x 12 Beige with brown striations Loc 14 - Room 155	Not Analyzed				
1013336PLM_25	tile					
S008C - B	Vinyl floor tile - 12 x 12 Beige with brown striations Loc 14 - Room 155	None Detected		100%	Other	Black Non Fibrous Homogeneous
1013336PLM_41	mastic					Dissolved
S009A - A	Vinyl floor tile - 12 x 12 Off white with thin brown striations - Loc 18 - Room 144	3% Chrysotile		97%	Other	White Non Fibrous Homogeneous
1013336PLM_26	tile tile					Dissolved
S009A - B	Vinyl floor tile - 12 x 12 Off white with thin brown striations - Loc 18 - Room 144	None Detected		100%	Other	Black Non Fibrous Homogeneous
1013336PLM_42	mastic					Dissolved
S009B - A	Vinyl floor tile - 12 x 12 Off white with thin brown striations - Loc 18 - Room 144 tile	Not Analyzed				
1013336PLM_27	me					
S009B - B	Vinyl floor tile - 12 x 12 Off white with thin brown striations - Loc 18 - Room 144	None Detected		100%	Other	Black Non Fibrous Homogeneous
1013336PLM_43	mastic					Dissolved
S009C - A	Vinyl floor tile - 12 x 12 Off white with thin brown striations - Loc 18 - Room 144	Not Analyzed				
1013336PLM_28	tile					

Disclaimer: Due to the nature of the EPA 600 method, asbestos may not be detected in samples containing low levels of asbestos. We strongly recommended that analysis of floor tiles, vermiculite, and/or heterogeneous soil samples be conducted by TEM for confirmation of "None Detected" by PLM. This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAI. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the US, government. Estimated MDL is 0.5%.

Bart Huber (47)

Analyst


Nathaniel Durham, MS or Approved Signatory



By Polarized Light Microscopy EPA Method: 600/R-93/116 and 600/M4-82-020



Customer: Pinchin Environmental Ltd 380 Armour Rd Suite 101 Peterborough, ON K9H 7L7 Attn: Tiffany Smith



Project: KPRDSB-Enniskillen

Sample ID	Description	Description Asbestos	Fibrous	Non-Fibrous	Attributes
Lab Sample ID	Lab Notes	ASDESLUS	Components	Components	Treatment
S009C - B	Vinyl floor tile - 12 x 12 Off white with thin brown striations - Loc 18 - Room 144	None Detected		100% Other	Black Non Fibrous Homogeneous
1013336PLM_44	mastic				Dissolved
S010A - A	Vinyl sheet flooring - White 9 x 9 square pattern - Room 152	None Detected	30% Cellulose	70% Other	White Non Fibrous Homogeneous
1013336PLM_29	– linoleum				Dissolved, Teased
S010A - B	Vinyl sheet flooring - White 9 x 9 square pattern - Room 152	None Detected		100% Other	Yellow Non Fibrous Homogeneous
1013336PLM_45	mastic				Dissolved
S010B - A	Vinyl sheet flooring - White 9 x 9 square pattern - Room 152	None Detected	30% Cellulose	70% Other	White Non Fibrous Homogeneous
1013336PLM_30	– linoleum				Dissolved, Teased
S010B - B	Vinyl sheet flooring - White 9 x 9 square pattern - Room 152	None Detected		100% Other	Yellow Non Fibrous Homogeneous
1013336PLM_46	mastic				Dissolved
S010C - A	Vinyl sheet flooring - White 9 x 9 square pattern - Room 152	None Detected	30% Cellulose	70% Other	White Non Fibrous Homogeneous
1013336PLM_31	linoleum				Dissolved, Teased
S010C - B	Vinyl sheet flooring - White 9 x 9 square pattern - Room 152	None Detected		100% Other	Yellow Non Fibrous Homogeneous
1013336PLM_47	mastic				Dissolved

Disclaimer: Due to the nature of the EPA 600 method, asbestos may not be detected in samples containing low levels of asbestos. We strongly recommended that analysis of floor tiles, verniculite, and/or heterogeneous soil samples be conducted by TEM for confirmation of "None Detected" by PLM. This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAI. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the US, government. Estimated MDL is 0.5%.

Bart Huber (47)

Analyst

Nathaniel Durham, MS or Approved Signatory

1013336

Client: Martine	Pinchin Environmental Ltd.	and the second	Instructions:	
Contact: Address:	Tiffany Smith 380 Armour Rd., Suite 101	Use Colur	a "B" for your contact info	Scientific Analytical
Phone:	(7050 748-4627	To Se	n Example Click the	Institute, Inc.
Fax:	(705) 748-6927		om Example Tab.	
Email:	tsmith@pinchin.com	and the second second		302-L Pomona Dr.
Project:	KPRDSB - Enniskillen	Begin Samples wi	to between "<<" and ">>" th a "<< "above the first sample >>" below the last sample.	Greensboro, NC 27407 Phone: 336.292.3888 Fax: 336.292.3313
Client Notes:	Stop on positive		data on the first sheet "Sheet1"	Email: lab@sallab.com
P.O. #.	59723	Note: Data	and Data 2 are optional	
Date Submitted;	11/5/2010 0:00		hot show up on the official	
Analysis:	Asbestos analysis	in the elect	ever they will be included	
TurnAroundTime:	144 Hours	to facilitate your	reintegration of the report data.	

ţ

Sample N	umber Data 1	Sample Description Data 2	ALC: NO DECEMBER OF
<<			
S001A		Drywall - B01	
S001B		Drywall - B06	
S001C		Drywall - B06	
S002A		Plaster - B01	
S002B		Plaster - B03	
S002C		Plaster - B03	
S002D		Plaster - B01	
S002E		Plaster - B02	
S002F		Plaster - B05	
S002G		Plaster - B05	
S003A		Parging cement - B01	
S003B		Parging cement - B01	un de la construcción de la constru
S003C		Parging cement - B01	
S004A		Drywall - 1st Floor - Corridor 150	Accepted
S004B		Drywall - 1st Floor - Corridor 150	Accepted
S004C		Drywall - 1st Floor - Corridor 150	Rejected
S006A		Vinyl floor tile - 12 x 12 Off white with grey spots - Loc 9 Classroom 02	NGJECIEN
S006B		Vinyl floor tile - 12 x 12 Off white with grey spots - Loc 9 Classroom 02	

7:30 Alla 11-8

S006C	Vinyl floor tile - $12 \times 12$ Off white with grey spots - Loc 9 Classroom 02
S007A	AT07 - Textured no pattern - Vestibule - Loc 12
S007B	AT07 - Textured no pattern - Vestibule - Loc 12
S007C	AT07 - Textured no pattern - Vestibule - Loc 12
S008A	Vinyl floor tile - 12 x 12 Beige with brown striations Loc 14 - Room 155
S008B	Vinyl floor tile - 12 x 12 Beige with brown striations Loc 14 - Room 155
S008C	Vinyl floor tile - 12 x 12 Beige with brown striations Loc 14 - Room 155
S009A	Vinyl floor tile - 12 x 12 Off white with thin brown striations - Loc 18 - Room 144
S009B	Vinyl floor tile - 12 x 12 Off white with thin brown striations - Loc 18 - Room 144
S009C	Vinyl floor tile - 12 x 12 Off white with thin brown striations - Loc 18 - Room 144
S010A	Vinyl sheet flooring - White 9 x 9 square pattern - Room 152
S010B	Vinyl sheet flooring - White 9 x 9 square pattern - Room 152
S010C	Vinyl sheet flooring - White 9 x 9 square pattern - Room 152

ć





## Pinchin Environmental Asbestos Laboratory Certificate of Analysis

Project Name:	Kawartha Pine Ridge District School Board,		
	Enniskillen Public Sch	nool, 8145 Old Scugog Ro	bad
Project No.:	88682		
Prepared For:	R. Northey/M. Wilson	Date Received:	January 6, 2014
Lab Reference No.:	b105022	Date Analyzed:	January 17, 2014
Analyst(s):	S. Capsuyen	# Samples submitted:	3
		# Phases analyzed:	3

#### Method of Analysis:

#### EPA 600/R-93/116 - Method for the Determination of Asbestos in Bulk Building Materials dated July, 1993

Bulk samples are checked visually and scanned under a stereomicroscope. Slides are prepared and observed under a Polarized Light Microscope (PLM) at magnifications of 40X, 100X or 400X as appropriate. Asbestos fibres are identified by a combination of morphology, colour, refractive index, extinction, sign of elongation, birefringence and dispersion staining colours. A visual estimate is made of the percentage of asbestos present. A reported concentration of less than (<) the regulatory threshold (see chart below) indicates the presence of confirmed asbestos in trace quantities, limited to only a few fibres or fibre bundles in an entire sample. This method complies with all provincial regulatory requirements (NIOSH 9002, I.R.S.S.T. 244-3). Multiple phases within a sample are analyzed and reported separately.

Provincial Jurisdiction	Regulatory Threshold	Provincial Jurisdiction	Regulatory Threshold
Ontario, British Columbia,			
Nova Scotia	0.5%	Manitoba	0.1% friable 1% non-friable
Quebec	0.1%	Saskatchewan	0.1% friable 1% non-friable
Alberta, NWT, Yukon,		Newfoundland and Labrador,	
Nunavut	1%	PEI and New Brunswick	1%

All bulk samples submitted to this laboratory for asbestos analysis are retained for a minimum of three months. Samples may be retrieved, upon request, for re-examination at any time during that period.

Pinchin Environmental Ltd. is accredited by the National Institute of Standards and Technology, National Voluntary Laboratory Accreditation Program (NVLAP Lab Code 101270-0) for the 'EPA-600/M4-82-020: Interim Method for the Determination of Asbestos in Bulk Insulation Samples' and meets all requirements of ISO/IEC 17025:2005.

This report relates only to the items tested.

NOTE: This test report may not be reproduced, except in full, without the written approval of the laboratory. The client may not use this report to claim product endorsement by NVLAP or any agency of the U.S. Government. This report is valid only when signed in blue ink by the analyst. Vinyl asbestos floor tiles contain very fine fibres of asbestos and may be missed by some laboratories using the PLM method. Internal verification studies performed by Pinchin indicate that the chance of missing asbestos in floor tiles is no higher than about 2%. The vinyl tile study and laboratory documentation on measurement uncertainty is available upon request. The analysis of dust samples by PLM cannot be used as an indicator of past or present airborne asbestos fibre levels.





## Pinchin Environmental Asbestos Laboratory Certificate of Analysis

Project Name:	Kawartha Pine Ridge District School Board, Enniskillen Public School, 8145 Old Scugog Road
Project No.:	88682
Prepared For:	R. Northey/M. Wilson

Lab Reference No.:b105022Date Analyzed:January 17, 2014

### **BULK SAMPLE ANALYSIS**

SAMPLE	SAMPLE	% COMPOSITION	(VISUAL ESTIMATE)	
IDENTIFICATION	DESCRIPTION	ASBESTOS	OTHER	
Plaster from exterior soffit,	Non-homogeneous, grey, hard, cementitious, plaster material.	None Detected	Non-Fibrous Material > 7	75%
	Non-homogeneous, grey, hard, cementitious, plaster material.	None Detected	Non-Fibrous Material > 7	75%
	Non-homogeneous, grey, hard, cementitious, plaster material.	None Detected	Non-Fibrous Material > 7	75%







Project Name:	Kawartha Pine Ridge I 8145 Old Scugog Road	District School Board, En	niskillen Public School,
Project No.:	101081		
Prepared For:	R. Northey / M. Wilson	Date Received:	January 6, 2015
Lab Reference No.:	b115397	Date Analyzed:	January 12, 2015
Analyst(s):	S. Capsuyen	# Samples submitted:	3
		# Phases analyzed:	5

#### Method of Analysis:

#### EPA 600/R-93/116 - Method for the Determination of Asbestos in Bulk Building Materials dated July, 1993

Bulk samples are checked visually and scanned under a stereomicroscope. Slides are prepared and observed under a Polarized Light Microscope (PLM) at magnifications of 40X, 100X or 400X as appropriate. Asbestos fibres are identified by a combination of morphology, colour, refractive index, extinction, sign of elongation, birefringence and dispersion staining colours. A visual estimate is made of the percentage of asbestos present. A reported concentration of less than (<) the regulatory threshold (see chart below) indicates the presence of confirmed asbestos in trace quantities, limited to only a few fibres or fibre bundles in an entire sample. This method complies with provincial regulatory requirements where applicable. Multiple phases within a sample are analyzed and reported separately.

Provincial Jurisdiction	Regulatory Threshold	Provincial Jurisdiction	Regulatory Threshold
Ontario, British Columbia, Nova Scotia	0.5%	Manitoba	0.1% friable 1% non-friable
Quebec	0.1%	Saskatchewan	0.5% friable 1% non-friable
Alberta, NWT, Yukon, Nunavut	1%	Newfoundland and Labrador, PEI and New Brunswick	1%

All bulk samples submitted to this laboratory for asbestos analysis are retained for a minimum of three months. Samples may be retrieved, upon request, for re-examination at any time during that period.

Pinchin Ltd. is accredited by the National Institute of Standards and Technology, National Voluntary Laboratory Accreditation Program (NVLAP Lab Code 101270-0) for the 'EPA-600/M4-82-020: Interim Method for the Determination of Asbestos in Bulk Insulation Samples' and meets all requirements of ISO/IEC 17025:2005.

This report relates only to the items tested.

NOTE: This test report may not be reproduced, except in full, without the written approval of the laboratory. The client may not use this report to claim product endorsement by NVLAP or any agency of the U.S. Government. This report is valid only when signed in blue ink by the analyst. Vinyl asbestos floor tiles contain very fine fibres of asbestos and may be missed by some laboratories using the PLM method. Internal verification studies performed by Pinchin indicate that the chance of missing asbestos in floor tiles is no higher than about 2%. The vinyl tile study and laboratory documentation on measurement uncertainty is available upon request. The analysis of dust samples by PLM cannot be used as an indicator of past or present airborne asbestos fibre levels.





Project Name:	Kawartha Pine Ridge District School Board, Enniskillen Public School,
	8145 Old Scugog Road
Project No.:	101081
Prepared For:	R. Northey / M. Wilson

Lab Reference No.:b115397Date Analyzed:January 12, 2015

### **BULK SAMPLE ANALYSIS**

SAMPLE	SAMPLE	% COMPOSITION (	VISUAL ESTIMATE)
IDENTIFICATION	DESCRIPTION	ASBESTOS	OTHER
0012A Mortar on basement wall in old school house	Homogeneous, grey, hard, cementitious material.	None Detected	Non-Fibrous Material > 75%
0012B Mortar on basement wall in old school house	2 Phases: a) Homogeneous, light grey, hard, cementitious material.	None Detected	Non-Fibrous Material > 75%
	b) Homogeneous, dark grey, hard, cementitious material.	None Detected	Non-Fibrous Material > 75%
0012C Mortar on basement wall in old school house	2 Phases: a) Homogeneous, ligjt grey, hard, cementitious material.	None Detected	Non-Fibrous Material > 75%
	b) Homogeneous, dark grey, hard, cementitious material.	None Detected	Non-Fibrous Material > 75%

**REVIEWED BY** 





Project No.:	0317322.004				
Prepared For:	M. Barnett / R. Northey				
Lab Reference No.: Analyst(s):	b281937 T. Ly				
Date Received:	November 1, 2022	Samples Submitted:	9		
Date Analyzed:	November 8, 2022	Phases Analyzed:	9		

The Pinchin Ltd. Mississauga asbestos laboratory is accredited by the National Institute of Standards and Technology, National Voluntary Laboratory Accreditation Program (NVLAP Lab Code 101270-0) for the 'EPA – 40 CFR Appendix E to Subpart E of Part 763, Interim Method of the Determination of Asbestos in Bulk Insulation Samples,' and the 'EPA 600/R-93/116: Method for the Determination of Asbestos in Bulk Building Materials'; and meets all requirements of ISO/IEC 17025:2017. The Pinchin asbestos laboratory uses the aforementioned methods of analysis.

Bulk samples are checked visually and scanned under a stereomicroscope. Slides are prepared and observed under a Polarized Light Microscope (PLM) at magnifications of 40X, 100X or 400X as appropriate. Asbestos fibres are identified by a combination of morphology, colour, refractive index, extinction, sign of elongation, birefringence and dispersion staining colours. A visual estimate is made of the percentage of asbestos present. A reported concentration of less than (<) the regulatory threshold indicates the presence of confirmed asbestos in trace quantities, limited to only a few fibres or fibre bundles in an entire sample. This method complies with provincial regulatory requirements where applicable. Multiple phases within a sample are analyzed and reported separately.

All bulk samples submitted to this laboratory for asbestos analysis are retained for a minimum of three months. Samples may be retrieved, upon request, for re-examination at any time during that period.

This report relates only to the items tested.

This report relates only to the items tested and is valid only when signed with a protected, authorized, electronic signature. This report may not be reproduced, except in full, without the written approval of Pinchin Ltd. The client may not use this report to claim product endorsement by NVLAP or any agency of the U.S. Government. Internal verification studies, quality assurance / control data and laboratory documentation on measurement uncertainty are available upon request.



Project No.:0317322.004Prepared For:M. Barnett / R. Northey

Lab Reference No.:b281937Date Analyzed:November 8, 2022

### **BULK SAMPLE ANALYSIS**

SAMPLE	SAMPLE	% COMPOSITI	ON (VISUAL ESTIMATE)	
IDENTIFICATION	DESCRIPTION	ASBESTOS	OTHER	
S0013A Caulking, Brown Caulking On Vents - Roof C, Loc:72, ROOF	Homogeneous, brown, caulking material.	None Detected	Non-Fibrous Material	> 75%
S0013B Caulking, Brown Caulking On Vents - Roof D, Loc:72, ROOF	Homogeneous, brown, caulking material.	None Detected	Non-Fibrous Material	> 75%
S0013C Caulking, Brown Caulking On Vents - Roof B, Loc:72, ROOF	Homogeneous, brown, caulking material.	None Detected	Non-Fibrous Material	> 75%
S0014A Tar, Black Tar On Vents - Roof C, Loc:72, ROOF	Homogeneous, black, tar material.	None Detected	Tar and other Non- Fibrous Material	> 75%
S0014B Tar, Black Tar On Vents - Roof D, Loc:72, ROOF	Homogeneous, black, tar material.	None Detected	Tar and other Non- Fibrous Material	> 75%
S0014C Tar, Black Tar On Vents - Roof E, Loc:72, ROOF	Homogeneous, black, tar material.	None Detected	Tar and other Non- Fibrous Material	> 75%
S0015A Caulking, Brown Caulking On Roof Flashing - Roof D, Loc:72, ROOF	Homogeneous, brown, caulking material.	None Detected	Non-Fibrous Material	> 75%
S0015B Caulking, Brown Caulking On Roof Flashing - Roof B, Loc:72, ROOF	Homogeneous, brown, caulking material.	None Detected	Non-Fibrous Material	> 75%



Project No.:0317322.004Prepared For:M. Barnett / R. Northey

Lab Reference No.:b281937Date Analyzed:November 8, 2022

### **BULK SAMPLE ANALYSIS**

SAMPLE	SAMPLE	% COMPOSITION (VISUAL ESTIMATE)				
IDENTIFICATION	DESCRIPTION	ASBESTOS	OTHER			
S0015C Caulking, Brown Caulking On Roof Flashing - Roof E, Loc:72, ROOF	caulking material.	None Detected	Non-Fibrous Material > 75%			

Reviewed by:



Digitally signed by Elizabeth DeCurtis Date: 2022.11.08 14:16:37-05'00'



Reporting Analyst: Digitally signed by Elizabeth DeCurtis Date: 2022.11.08 14:16:17-05'00'

Page 3 of 3

NOTACTIVE 11/2/2022 Wrong PN.



### Pinchin Ltd. - Asbestos Laboratory Internal Asbestos Bulk Sample Chain of Custody

Client Name	<b>):</b>	1		Project Address:			
Portfolio/Bi	uilding No:			Pinchin File:	317322.0	54	1000
Submitted I	by:	Matt Barnett		Email:	mbarnett@pir	hchin.com	
CC Results	to:	Rachel North	теу	CC Email:	rnorthey@pin	chin.com	
Date Submi	tted:	October	30 2022	Required by:	Month	Day	2020
# of Sample	s:	9		Priority:		Select	
Year of Buil	ding Constru	ction (Manda	atory, Years ONLY):	1991		3 19 11	1.11
Do NOT Sto	p on Positive	e (Sample Nu	mbers):				
Pinchin Gro	up Company	(Mandatory	Field ):	1	Pinchin		
HMIS2 Build	ding Reference	:e #:	6281922	412312/202292875	530752		
To be Comp	leted by Lab			1	Section of	Selling P	17
Lab Referer	nce #:	NOV 0 1	2022	Time:	24 1	nour clock	MRD GAL
Received by	/:	1101 0		Date:	Month	Day	Year
Name(s) of	Analyst(s):		il		A STATISTICS	8	22
Sample	Sample	Commission	NAME AND ADDRESS OF TAXABLE PARTY.				
Prefix	No.	Sample Suffix	Samp	le Description/Lo	cation (Manda	atory)	
	the second second second	and the second		le Description/Lo			Ð
Prefix	No.	Suffix	Caulking,Brown Cau		f C,Loc:72,ROC	DF	1D
Prefix S	No. 0013	Suffix A	Caulking,Brown Cau Caulking,Brown Cau	Iking On Vents - Roo	f C,Loc:72,ROC f D,Loc:72,ROC	DF	ちり
Prefix S S	No. 0013 0013	Suffix A B	Caulking,Brown Cau Caulking,Brown Cau Caulking,Brown Cau	Iking On Vents - Roo Iking On Vents - Roo	f C,Loc:72,ROC f D,Loc:72,ROC f B,Loc:72,ROO	DF	5 1 1 1 1 1 1 1 1 1 1 1 1 1
Prefix S S S	No. 0013 0013 0013	Suffix A B C	Caulking,Brown Cau Caulking,Brown Cau Caulking,Brown Cau Tar,Black Tar On Ve	Iking On Vents - Roo Iking On Vents - Roo Iking On Vents - Roo	f C,Loc:72,ROC f D,Loc:72,ROC f B,Loc:72,ROO ROOF	DF	で し し
Prefix S S S	No. 0013 0013 0013 0014	Suffix A B C A	Caulking,Brown Cau Caulking,Brown Cau Caulking,Brown Cau Tar,Black Tar On Ve Tar,Black Tar On Ve	Iking On Vents - Roo Iking On Vents - Roo Iking On Vents - Roo nts - Roof C,Loc:72,F	f C,Loc:72,ROC f D,Loc:72,ROC f B,Loc:72,ROO ROOF	DF	ち し し し し

Sample Prefix	Sample No.	Sample Suffix	Sample Description/Location (Mandatory)			
S	0015	В	Caulking,Brown Caulking On Roof Flashing - Roof B,Loc:72,ROOF	MD		
S	0015	с	Caulking,Brown Caulking On Roof Flashing - Roof E,Loc:72,ROOF	ND		



Project No.: Prepared For:	0317322.004 R. Northey		
Lab Reference No.: Analyst(s):	b282072 T. Tran		
Date Received: Date Analyzed:	November 3, 2022 November 16, 2022	Samples Submitted: Phases Analyzed:	1 6

The Pinchin Ltd. Mississauga asbestos laboratory is accredited by the National Institute of Standards and Technology, National Voluntary Laboratory Accreditation Program (NVLAP Lab Code 101270-0) for the 'EPA – 40 CFR Appendix E to Subpart E of Part 763, Interim Method of the Determination of Asbestos in Bulk Insulation Samples,' and the 'EPA 600/R-93/116: Method for the Determination of Asbestos in Bulk Building Materials'; and meets all requirements of ISO/IEC 17025:2017. The Pinchin asbestos laboratory uses the aforementioned methods of analysis.

Bulk samples are checked visually and scanned under a stereomicroscope. Slides are prepared and observed under a Polarized Light Microscope (PLM) at magnifications of 40X, 100X or 400X as appropriate. Asbestos fibres are identified by a combination of morphology, colour, refractive index, extinction, sign of elongation, birefringence and dispersion staining colours. A visual estimate is made of the percentage of asbestos present. A reported concentration of less than (<) the regulatory threshold indicates the presence of confirmed asbestos in trace quantities, limited to only a few fibres or fibre bundles in an entire sample. This method complies with provincial regulatory requirements where applicable. Multiple phases within a sample are analyzed and reported separately.

All bulk samples submitted to this laboratory for asbestos analysis are retained for a minimum of three months. Samples may be retrieved, upon request, for re-examination at any time during that period.

This report relates only to the items tested.

This report relates only to the items tested and is valid only when signed with a protected, authorized, electronic signature. This report may not be reproduced, except in full, without the written approval of Pinchin Ltd. The client may not use this report to claim product endorsement by NVLAP or any agency of the U.S. Government. Internal verification studies, quality assurance / control data and laboratory documentation on measurement uncertainty are available upon request.



0317322.004
R. Northey

Lab Reference No.:b282072Date Analyzed:November 16, 2022

### **BULK SAMPLE ANALYSIS**

SAMPLE	SAMPLE	% COMPOSITION (	VISUAL ESTIMATE)
IDENTIFICATION	DESCRIPTION	ASBESTOS	OTHER
S0016A Roofing Material, Roof Section E, Loc:72,ROOF	6 Phases: a) Homogeneous, black, layered, tar material on bottom of roofing.	None Detected	Tar and other Non- > 75% Fibrous Material
	b) Homogeneous, black, layered, tar-impregnated, compressed, fibrous material.	None Detected	Cellulose 50-75% Tar and other Non- 25-50% Fibrous Material
	c) Homogeneous, black, layered, tar material in middle of roofing.	None Detected	Man-Made Vitreous 5-10% Fibres Tar and other Non- > 75% Fibrous Material
	d) Homogeneous, black, tar paper in middle roofing.	None Detected	Cellulose > 75% Tar and other Non- 10-25% Fibrous Material
	e) Homogeneous, black, layered, tar material on top of roofing.	None Detected	Tar and other Non- > 75% Fibrous Material
	f) Homogeneous, black, layered, tar material with fibres on top of roofing.	None Detected	Tar and other Non- > 75% Fibrous Material
Comments:	Man-made vitreous fibres, c	ellulose and drywall are present on	the surface of this sample.

Reviewed by:



Digitally signed by Cheryl Hendsbee Date: 2022.11.16 11:36:08-05'00' Page 2 of 2

**Reporting Analyst:** 

Digitally signed by Cheryl Hendsbee Date: 2022.11.16 11:35:56-05'00'



### Pinchin Ltd. - Asbestos Laboratory Internal Asbestos Bulk Sample Chain of Custody

Client Name	91				Project Address:			
Portfolio/Bu	ilding No:		-11.4		Pinchin File:	317322.004		
Submitted b	y:	2 .1 .	1	and the second	Email:		1	11 1221
CC Results	to:	Nor	heir	2. 监合	CC Email:	网络信心的	-	Sec.
Date Submit	tted:	November	02	2022	Required by:	Month	Day	2020
# of Sample	s:	1	U		Priority:	5 Da	ay Tumaroi	und
Year of Built	ding Constru	uction (Manda	tory, Yea	rs ONLY):			TOTAL ST	1. 1.
Do NOT Sto	p on Positive	e (Sample Nu	mbers):		A MARINE SALES	Martin Ker		
Pinchin Gro	up Company	(Mandatory	Field):			Pinchin	116 201	
HMIS2 Build	ling Referen	ce #:		1	112312/20229287	530752		
To be Comp	leted by Lab	Personnel O	nly:	- ca	Silling Silling			
Lab Referen	ice #:	628	201	L	Time:	- 24	4 hour cloci	K
Received by	<i>r</i> :	020	NOV 0 3	2022	Date:	Month	Day	Year
Name(s) of	Analyst(s):	The	Ton			NOV	14/	22
Sample Prefix	Sample No.	Sample Suffix	and canadianas	Samp	le Description/Lo	cation (Man	datory)	
S	0016	A	Roofing M	laterial,Loc	72,ROOF	20	20 52	12 Jul



Project Name:	KPRDSB, Enniskillen		
Project No.:	0317322.004		
Prepared For:	B. Guindon / R. Northey		
Lab Reference No.:	b285087		
Analyst(s):	J. Raisch-Berkoff		
Date Received:	January 10, 2023	Samples Submitted:	2
Date Analyzed:	January 25, 2023	Phases Analyzed:	16

The Pinchin Ltd. Mississauga asbestos laboratory is accredited by the National Institute of Standards and Technology, National Voluntary Laboratory Accreditation Program (NVLAP Lab Code 101270-0) for the 'EPA – 40 CFR Appendix E to Subpart E of Part 763, Interim Method of the Determination of Asbestos in Bulk Insulation Samples,' and the 'EPA 600/R-93/116: Method for the Determination of Asbestos in Bulk Building Materials'; and meets all requirements of ISO/IEC 17025:2017. The Pinchin asbestos laboratory uses the aforementioned methods of analysis.

Bulk samples are checked visually and scanned under a stereomicroscope. Slides are prepared and observed under a Polarized Light Microscope (PLM) at magnifications of 40X, 100X or 400X as appropriate. Asbestos fibres are identified by a combination of morphology, colour, refractive index, extinction, sign of elongation, birefringence and dispersion staining colours. A visual estimate is made of the percentage of asbestos present. A reported concentration of less than (<) the regulatory threshold indicates the presence of confirmed asbestos in trace quantities, limited to only a few fibres or fibre bundles in an entire sample. This method complies with provincial regulatory requirements where applicable. Multiple phases within a sample are analyzed and reported separately.

All bulk samples submitted to this laboratory for asbestos analysis are retained for a minimum of three months. Samples may be retrieved, upon request, for re-examination at any time during that period.

This report relates only to the items tested.

This report relates only to the items tested and is valid only when signed with a protected, authorized, electronic signature. This report may not be reproduced, except in full, without the written approval of Pinchin Ltd. The client may not use this report to claim product endorsement by NVLAP or any agency of the U.S. Government. Internal verification studies, quality assurance / control data and laboratory documentation on measurement uncertainty are available upon request.



Project Name:	KPRDSB, Enniskillen
Project No.:	0317322.004
Prepared For:	B. Guindon / R. Northey

Lab Reference No.:b285087Date Analyzed:January 25, 2023

SAMPLE	SAMPLE	SAMPLE % COMPOSITION (VISUAL ESTIMAT		
IDENTIFICATION	DESCRIPTION	ASBESTOS	OTHER	
S0016B Roofing Material, Roof Section E Sample B, Loc:72, ROOF	8 Phases: a) Homogeneous, black, layered, tar material on drywall (bottom of sample).	None Detected	Tar and other non-fibrous	> 75%
	b) Homogeneous, black, layered, tar-impregnated, compressed, fibrous material on drywall.	None Detected	Cellulose Tar and other non-fibrous	> 75% 10-25%
	c) Non-homogeneous, brown, paper material with black tar and colourless fibres on man-made vitreous fibres.	None Detected	Cellulose Man-Made Vitreous Fibres Tar and other non-fibrous	50-75% 5-10% 25-50%
	d) Homogeneous, black, tar material between phase c) and cellulose.	None Detected	Tar and other non-fibrous	> 75%
	e) Non-homogeneous, black, tar material between cellulose layers.	None Detected	Cellulose Tar and other non-fibrous	5-10% > 75%
	f) Homogeneous, black, layered, tar material on cellulose.	None Detected	Tar and other non-fibrous	> 75%
	g) Homogeneous, black, layered, tar-impregnated, compressed, fibrous material.	None Detected	Man-Made Vitreous Fibres Tar and other non-fibrous	25-50% 50-75%
	h) Homogeneous, black, textured, tar material (top of sample).	None Detected	Tar and other non-fibrous	> 75%
Comments:	Cellulose and man-made vitreous	fibres are present on the surface	of this sample.	



Project Name:	KPRDSB, Enniskillen
Project No.:	0317322.004
Prepared For:	B. Guindon / R. Northey

Lab Reference No.:b285087Date Analyzed:January 25, 2023

### **BULK SAMPLE ANALYSIS**

SAMPLE	SAMPLE	% COMPOSITI	ON (VISUAL ESTIMATE)	
IDENTIFICATION	DESCRIPTION	ASBESTOS	OTHER	
S0016C Roofing Material, Roof Section E Sample C, Loc:72, ROOF	8 Phases: a) Homogeneous, black, layered, tar material on drywall (bottom of sample).	None Detected	Tar and other non-fibrous >	> 75%
	b) Homogeneous, black, layered, tar-impregnated, compressed, fibrous material on drywall.	None Detected		> 75% )-25%
	c) Non-homogeneous, black, tar material between cellulose layers.	None Detected		5-10% > 75%
	d) Non-homogeneous, black, layered, tar material on cellulose.	None Detected	Tar and other non-fibrous >	> 75%
	e) Homogeneous, black, tar- impregnated, compressed, fibrous material.	None Detected		5-50% )-75%
	f) Homogeneous, black, tar- impregnated, compressed, fibrous material.	None Detected		)-75% 5-50%
	g) Homogeneous, black, layered, tar-impregnated, compressed, fibrous material.	None Detected		5-50% )-75%
	h) Homogeneous, black, textured, tar material (top of sample).	None Detected	Tar and other non-fibrous >	> 75%
Comments:	Cellulose and man-made vitreous f	ibres are present on the surface	of this sample.	


#### **Reviewed by:**

Digitally signed by Elizabeth DeCurtis Date: 2023.01.25 16:06:24-05'00'

Tow Be

#### Reporting Analyst:

Digitally signed by Elizabeth DeCurtis Date: 2023.01.25 16:05:56-05'00'



# Pinchin Ltd. - Asbestos Laboratory Internal Asbestos Bulk Sample Chain of Custody

Client Name	:	KPRDSB			Project Address:	Enniskillen	no hos	Really
Portfolio/Bui	ilding No:		The Astr		Pinchin File:	0317322.004	THE .	
Submitted b	y:	Bryan Guind	on	1	Email:	bguindon@pi	inchin.com	
CC Results t		rnorthey@p	inchin.com		CC Email:			
Date Submit	ted:	January	09	2023	Required by:	January	17	2023
# of Samples	s:	2	- 22 F	11 - T	Priority:	5 Da	y Turnarou	nd
Year of Build	ding Constr	uction (Manda	atory, Year	s ONLY):	A state of the second		123.112.0	- 10-0
Do NOT Stop	p on Positiv	e (Sample Nu	mbers):					1445
Pinchin Gro	up Compan	y (Mandatory	Field ):			Pinchin		
HMIS2 Build					115646/20221129	97065728		
the second se	and the second se	Personnel C	nly:		in the second se			
		5087 JE			Time:	24	hour clock	
Received by					Date:	Month	Day	Year
Name(s) of A	Analyst(s):	- war are	the tests		enter the state			
Sample Prefix	Sample No.	Sample Suffix		Samp	ble Description/Lo	ocation (Man	datory)	
S	0016	В	Roofing M a) ND		of Section E Sample ()ND ()ND			HND
S	0016	с	Roofing M		of Section E Sample	C,Loc:72,ROO	F	hint



Project Name: Project No.: Prepared For:	Kawartha Pine Ridge Di 0332605.017 C. Snarr / R. Northey	istrict School Board, Ennis	killen Public School Roof, ON
Lab Reference No.: Analyst(s):	b301642 A. Williams		
Date Received: Date Analyzed:	October 5, 2023 October 13, 2023	Samples Submitted: Phases Analyzed:	7 7

The Pinchin Ltd. Mississauga asbestos laboratory is accredited by the National Institute of Standards and Technology, National Voluntary Laboratory Accreditation Program (NVLAP Lab Code 101270-0) for the 'EPA – 40 CFR Appendix E to Subpart E of Part 763, Interim Method of the Determination of Asbestos in Bulk Insulation Samples,' and the 'EPA 600/R-93/116: Method for the Determination of Asbestos in Bulk Building Materials'; and meets all requirements of ISO/IEC 17025:2017. The Pinchin asbestos laboratory uses the aforementioned methods of analysis.

Bulk samples are checked visually and scanned under a stereomicroscope. Slides are prepared and observed under a Polarized Light Microscope (PLM) at magnifications of 40X, 100X or 400X as appropriate. Asbestos fibres are identified by a combination of morphology, colour, refractive index, extinction, sign of elongation, birefringence and dispersion staining colours. A visual estimate is made of the percentage of asbestos present. A reported concentration of less than (<) the regulatory threshold indicates the presence of confirmed asbestos in trace quantities, limited to only a few fibres or fibre bundles in an entire sample. This method complies with provincial regulatory requirements where applicable. Multiple phases within a sample are analyzed and reported separately.

All bulk samples submitted to this laboratory for asbestos analysis are retained for a minimum of three months. Samples may be retrieved, upon request, for re-examination at any time during that period.

This report relates only to the items tested.

This report relates only to the items tested and is valid only when signed with a protected, authorized, electronic signature. This report may not be reproduced, except in full, without the written approval of Pinchin Ltd. The client may not use this report to claim product endorsement by NVLAP or any agency of the U.S. Government. Internal verification studies, quality assurance / control data and laboratory documentation on measurement uncertainty are available upon request.



Project Name: Project No.:	Kawartha Pine Ridge District School Board, Enniskillen Public School Roof, ON 0332605.017
Prepared For:	C. Snarr / R. Northey

Lab Reference No.: Date Analyzed: b301642 October 13, 2023

#### **BULK SAMPLE ANALYSIS**

SAMPLE	SAMPLE	% COMPOSIT	ION (VISUAL ESTIMATE)	
IDENTIFICATION	DESCRIPTION	ASBESTOS	OTHER	
S0014D Tar,Black Tar On Vents - Roof E,Loc:75,Roof Section E	Homogeneous, black, tar material.	None Detected	Tar and other Non- Fibrous Material	> 75%
S0014E Tar,Black Tar On Vents - Roof E,Loc:75,Roof Section E	Homogeneous, black, tar material.	None Detected	Tar and other Non- Fibrous Material	> 75%
S0015D Caulking,Brown Caulking On Roof Flashing - Roof E,Loc:75,Roof Section E	Homogeneous, brown, caulking material.	None Detected	Non-Fibrous Material	> 75%
S0015E Caulking,Brown Caulking On Roof Flashing - Roof E,Loc:75,Roof Section E	Homogeneous, brown, caulking material.	None Detected	Non-Fibrous Material	> 75%
S0017A Caulking,Grey Caulking On Skylights,Loc:75,Roof Section E	Homogeneous, grey, caulking material.	None Detected	Non-Fibrous Material	> 75%
S0017B Caulking,Grey Caulking On Skylights,Loc:75,Roof Section E	Homogeneous, grey, caulking material.	None Detected	Non-Fibrous Material	> 75%
S0017C Caulking,Grey Caulking On Skylights,Loc:75,Roof Section E	Homogeneous, grey, caulking material.	None Detected	Non-Fibrous Material	> 75%

Reviewed by:



Digitally signed by Kendra Bertuzzi Date: 2023.10.13 15:36:03-04'00' Digitally signed by Kendra Bertuzzi Date: 2023.10.13 15:36:18-04'00'

Reporting Analyst:



## Pinchin Ltd. - Asbestos Laboratory Internal Asbestos Bulk Sample Chain of Custody

Client Name	9:	Kawartha Pine Ridge District School Board		Project Address:	ON		
Portfolio/Bu	ulding No:	Enniskillen P	Public School Roof	Pinchin File:	Pinchin File: 332605.017		
Submitted b	by:	Caitlin Snarr	Margarian San	Email:	csnarr@pinct	hin.com	
CC Results	to:	Rachel North	hey	CC Email:	rnorthey@pin	nchin.com	
Date Submi	tted:	October	03 2023	Required by:	October	11	2023
# of Sample	s:	7		Priority:	5 Da	y Tumarour	nd
Year of Buil	ding Constru	uction (Manda	atory, Years ONLY):	1926			
Do NOT Sto	p on Positive	e (Sample Nu	mbers):				10 25
Pinchin Gro	up Company	(Mandatory	Field ):		Pinchin		
	ling Reference			125670/20239288	571147	STILL!	Stable
And and a second se		Personnel O	only:	COLOR BALL	SU- 3 7 19	and the second	m.S.
Lab Referer	and the second se	030164	1220	Time:	24	hour clock	
Received by	<i>I</i> :	0 TOO	5 2023	Date:	Month	Day	Year
Name(s) of		in the second	ALW OCH 13	ELIS	the stand with		
Sample Prefix	Sample No.	Sample Suffix		ele Description/Lo	cation (Mano	datory)	
S	0014	D	Tar,Black Tar On Ve	ents - Roof E,Loc:75,	Roof Section E		ND
S	0014	E	Tar,Black Tar On Ve	ents - Roof E,Loc:75,	Roof Section E		ND
S	0015	D	Caulking,Brown Cau	Iking On Roof Flashi	ng - Roof E,Loo	c:75,Roof S	ection F
							ND
S	0015	E	Caulking,Brown Cau	lking On Roof Flashi	ng - Roof E,Lo	c:75,Roof S	ND
S S	0015	E	Caulking,Brown Cau Caulking,Grey Caulk				ND
				ing On Skylights,Loc	:75,Roof Section	on E	ND ection E



Project Name: Project No.:	KPRDSB, Enniskillen, ON 0335495.018	I	
•			
Prepared For:	B. Guindon / R. Northey		
Lab Reference No.:	b306613		
Analyst(s):	A. Wells		
Date Received:	January 9, 2024	Samples Submitted:	35
Date Analyzed:	January 16, 2024	Phases Analyzed:	37

The Pinchin Ltd. Mississauga asbestos laboratory is accredited by the National Institute of Standards and Technology, National Voluntary Laboratory Accreditation Program (NVLAP Lab Code 101270-0) for the 'EPA – 40 CFR Appendix E to Subpart E of Part 763, Interim Method of the Determination of Asbestos in Bulk Insulation Samples,' and the 'EPA 600/R-93/116: Method for the Determination of Asbestos in Bulk Building Materials'; and meets all requirements of ISO/IEC 17025:2017. The Pinchin asbestos laboratory uses the aforementioned methods of analysis.

Bulk samples are checked visually and scanned under a stereomicroscope. Slides are prepared and observed under a Polarized Light Microscope (PLM) at magnifications of 40X, 100X or 400X as appropriate. Asbestos fibres are identified by a combination of morphology, colour, refractive index, extinction, sign of elongation, birefringence and dispersion staining colours. A visual estimate is made of the percentage of asbestos present. A reported concentration of less than (<) the regulatory threshold indicates the presence of confirmed asbestos in trace quantities, limited to only a few fibres or fibre bundles in an entire sample. This method complies with provincial regulatory requirements where applicable. Multiple phases within a sample are analyzed and reported separately.

All bulk samples submitted to this laboratory for asbestos analysis are retained for a minimum of three months. Samples may be retrieved, upon request, for re-examination at any time during that period.

This report relates only to the items tested.

This report relates only to the items tested and is valid only when signed with a protected, authorized, electronic signature. This report may not be reproduced, except in full, without the written approval of Pinchin Ltd. The client may not use this report to claim product endorsement by NVLAP or any agency of the U.S. Government. Internal verification studies, quality assurance / control data and laboratory documentation on measurement uncertainty are available upon request.



Project Name:	KPRDSB, Enniskillen, ON
Project No.:	0335495.018
Prepared For:	B. Guindon / R. Northey

Lab Reference No.: b306613 Date Analyzed: January

# January 16, 2024

SAMPLE	SAMPLE	% COMPO	SITION (	VISUAL ESTIMATE)	
IDENTIFICATION	DESCRIPTION	ASBESTOS		OTHER	
S0018A	Homogeneous, grey,	Chrysotile	10-25%	Non-Fibrous Material	50-75%
Wall,Cement	compressed, fibrous	Crocidolite	10-25%		
Product,Brown Painted	material.	Amosite	0.5-5%		
Cement Fascia					
Board,Loc:71,EXTERIOR					
S0018B				Not Analyzed	
Wall,Cement					
Product,Brown Painted					
Cement Product					
Fascia,Loc:71,EXTERIOR					
Comments:	Analysis was stopped due to	a previous positive result.			
S0018C				Not Analyzed	
Wall,Fascia,Cement					
Product,Brown Painted					
Cement Product On					
Fascia,Loc:71,EXTERIOR					
Comments:	Analysis was stopped due to	a previous positive result.			
S0019A	2 Phases:				
Window,Caulking,Brown	a) Homogeneous, grey-	None Detected		Non-Fibrous Material	> 75%
Caulking On Lower Portion	brown, caulking material.				
Of Window Frame Old					
Windows,Loc:71,EXTERIO	b) Homogeneous, red-	None Detected		Non-Fibrous Material	> 75%
R	brown, caulking material.				
S0019B	2 Phases:				
Window,Caulking,Brown	a) Homogeneous, grey-	None Detected		Non-Fibrous Material	> 75%
Caulking On Lower Portion	brown, caulking material.				
Of Window Frame Old	-				
Windows,Loc:71,EXTERIO	b) Homogeneous, red-	None Detected		Non-Fibrous Material	> 75%
R	brown, caulking material.				



Project Name:	KPRDSB, Enniskillen, ON
Project No.:	0335495.018
Prepared For:	B. Guindon / R. Northey

Lab Reference No.:b306613Date Analyzed:January 16, 2024

SAMPLE	SAMPLE	% COMPOSITION (	VISUAL ESTIMATE)
IDENTIFICATION	DESCRIPTION	ASBESTOS	OTHER
S0019C Window,Caulking,Brown Caulking On Lower Portion Of Window Frame Old	2 Phases: a) Homogeneous, grey- brown, caulking material.	None Detected	Non-Fibrous Material > 75%
Windows,Loc:71,EXTERIO R	b) Homogeneous, red- brown, caulking material.	None Detected	Non-Fibrous Material > 75%
S0020A Window,Caulking,Soft Brown Vertical And Upper Window Caulking,Loc:71,EXTERIO R	Homogeneous, grey-brown, caulking material.	None Detected	Non-Fibrous Material > 75%
S0020B Window,Caulking,Soft Brown Vertical And Upper Window Caulking,Loc:71,EXTERIO R	Homogeneous, grey-brown, caulking material.	None Detected	Non-Fibrous Material > 75%
S0020C Window,Caulking,Soft Brown Vertical And Upper Window Caulking,Loc:71,EXTERIO R	Homogeneous, grey-brown, caulking material.	None Detected	Non-Fibrous Material > 75%
S0021A Wall,Paint,Beige Painted Exterior Masonry Block Wall 1968 Yoc,Loc:13,CLASSROOM	Homogeneous, off-white, coating material.	None Detected	Non-Fibrous Material > 75%



Project Name:	KPRDSB, Enniskillen, ON
Project No.:	0335495.018
Prepared For:	B. Guindon / R. Northey

Lab Reference No.:b306613Date Analyzed:January 16, 2024

SAMPLE	SAMPLE	% COMPOSITIO	ON (VISUAL ESTIMATE)
IDENTIFICATION	DESCRIPTION	ASBESTOS	OTHER
S0021B Wall,Paint,Beige Painted Exterior Masonry Block Wall 1968 Yoc,Loc:13,CLASSROOM	Homogeneous, off-white, coating material.	None Detected	Non-Fibrous Material > 75%
S0021C Wall,Paint,Masonry Block Wall Paint Exterior Wall,Loc:27,CLASSROOM	Homogeneous, off-white, coating material.	None Detected	Non-Fibrous Material > 75%
S0021D Wall,Paint,Exterior Block Wall Paint,Loc:27,CLASSROOM	Homogeneous, off-white, coating material.	None Detected	Non-Fibrous Material > 75%
S0021E Wall,Paint,Exterior Block Wall Paint,Loc:28,CLASSROOM	Homogeneous, off-white, coating material.	None Detected	Non-Fibrous Material > 75%
S0021F Wall,Paint,Exterior Block Wall Paint By Chalkboards,Loc:28,CLAS SROOM	Homogeneous, multicoloured, coating material.	None Detected	Non-Fibrous Material > 75%
S0021G Wall,Paint,Exterior Paint Block Walls,Loc:18,CLASSROO M	Homogeneous, multicoloured, coating material.	None Detected	Non-Fibrous Material > 75%



Project Name:	KPRDSB, Enniskillen, ON
Project No.:	0335495.018
Prepared For:	B. Guindon / R. Northey

Lab Reference No.:b306613Date Analyzed:January 16, 2024

SAMPLE	SAMPLE	% COMPOSITIO	N (VISUAL ESTIMATE)	
IDENTIFICATION	DESCRIPTION	ASBESTOS	OTHER	
S0022A Sink,Mastic, Grey,Grey Sink Mastic,Loc:13,CLASSROO	Homogeneous, off-white, mastic material.	None Detected		5-10% > 75%
S0022B Sink,Mastic, Grey,Grey Sink Mastic,Loc:27,CLASSROO	Homogeneous, white, mastic material.	None Detected		5-10% > 75%
S0022C Sink,Mastic, Grey,Grey Sink Mastic,Loc:28,CLASSROO	Homogeneous, white, mastic material.	None Detected		5-10% > 75%
S0023A Wall,Base,Adhesive/mastic, Black Vinyl Trim Adhesive,Loc:27,CLASSR	adhesive material.	None Detected		> 75%
OOM	b) Homogeneous, brown, adhesive material.	None Detected	Non-Fibrous Material	> 75%
S0023B Wall,Adhesive/mastic,Black Vinyl Trim Adhesive,Loc:14,CUSTODI	2 Phases: a) Homogeneous, yellow, adhesive material.	None Detected	Non-Fibrous Material	> 75%
AN ROOM	b) Homogeneous, brown, adhesive material.	None Detected	Non-Fibrous Material	> 75%
S0023C Wall,Adhesive/mastic,Vinyl Trim Adhesive On Block Wall,Loc:28,CLASSROOM	2 Phases: a) Homogeneous, yellow, adhesive material.	None Detected	Non-Fibrous Material	> 75%
······,,	b) Homogeneous, brown, adhesive material.	None Detected	Non-Fibrous Material	> 75%



Project Name:	KPRDSB, Enniskillen, ON
Project No.:	0335495.018
Prepared For:	B. Guindon / R. Northey

Lab Reference No.:b306613Date Analyzed:January 16, 2024

SAMPLE	SAMPLE SAMPLE % COMPOSITION (VISUAL ESTIM/		ION (VISUAL ESTIMATE)	
IDENTIFICATION	DESCRIPTION	ASBESTOS	OTHER	
S0024A Wall,Paint,Interior Masonry Block Wall Paint,Loc:14,CUSTODIAN ROOM	Homogeneous, beige, coating material.	None Detected	Non-Fibrous Material	> 75%
S0024B Wall,Paint,Interior Beige Block Wall Paint,Loc:15,CORRIDOR	Homogeneous, beige, coating material.	None Detected	Non-Fibrous Material	> 75%
S0024C Wall,Paint,Beige Interior Block Wall Paint,Loc:16,WASHROOM	Homogeneous, multicoloured, coating material.	None Detected	Non-Fibrous Material	> 75%
S0024D	Homogeneous, multicoloured, coating material.	None Detected	Non-Fibrous Material	> 75%
S0024E Wall,Paint,Interior Masonry Block Paint,Loc:22,GIRLS WASHROOM	Homogeneous, multicoloured, coating material.	None Detected	Non-Fibrous Material	> 75%
S0024F Wall,Paint,Interior Block Wall Paint,Loc:26,BOYS WASHROOM	Homogeneous, multicoloured, coating material.	None Detected	Non-Fibrous Material	> 75%



Project Name:	KPRDSB, Enniskillen, ON
Project No.:	0335495.018
Prepared For:	B. Guindon / R. Northey

Lab Reference No.:b306613Date Analyzed:January 16, 2024

SAMPLE	SAMPLE	% COMPOSITION	I (VISUAL ESTIMATE)
IDENTIFICATION	DESCRIPTION	ASBESTOS	OTHER
S0024G Wall,Paint,Interior Block Wall Paint Corridor Wall,Loc:26,BOYS WASHROOM	Homogeneous, multicoloured, coating material.	None Detected	Non-Fibrous Material > 75%
S0025A Window,Caulking,Brown Window Frame Caulking 2002 Date Stamp,Loc:14,CUSTODIAN ROOM	Homogeneous, brown, caulking material.	None Detected	Non-Fibrous Material > 75%
S0025B Window,Caulking,Brown Window Frame Caulking, Loc:20,Coat Room	Homogeneous, brown, caulking material.	None Detected	Non-Fibrous Material > 75%
S0025C Window,Caulking,Brown Window Frame Caulking Exterior Windows,Loc:18,CLASSR OOM	Homogeneous, brown, caulking material.	None Detected	Non-Fibrous Material > 75%
S0026A DoorMetal Shelf Frame Caulking,Loc:15,CORRIDO R	Homogeneous, grey, caulking material.	Chrysotile 0.5-5	% Non-Fibrous Material > 75%
Comments:	Another phase is present t	but there was insufficient material su	ubmitted to analyze.



Project Name:	KPRDSB, Enniskillen, ON
Project No.:	0335495.018
Prepared For:	B. Guindon / R. Northey

Lab Reference No.:b306613Date Analyzed:January 16, 2024

#### **BULK SAMPLE ANALYSIS**

SAMPLE	SAMPLE	% COMPOSITION (VISUAL ESTIMATE)		
IDENTIFICATION	DESCRIPTION	ASBESTOS	OTHER	
S0026B Door,Caulking,Door Frame Caulking,Loc:16,WASHRO OM			Not Analyzed	
Comments:	Analysis was stopped due to a previous positive result.			
S0026C Door,Caulking,Door Frame Caulking,Loc:26,BOYS WASHROOM			Not Analyzed	
Comments:	Analysis was stopped due to a previous positive result.			

**Reviewed by:** 



Digitally signed by Elizabeth DeCurtis Date: 2024.01.16 14:38:11-05'00'

Page 8 of 8

**Reporting Analyst:** 

Digitally signed by Elizabeth DeCurtis Date: 2024.01.16 14:38:28-05'00'



#### Pinchin Ltd. - Asbestos Laboratory Internal Asbestos Bulk Sample Chain of Custody ON KPRDSB Project Address: Client Name: Portfolio/Building No: Enniskillen **Pinchin File:** 335495.018 bguindon@pinchin.com Bryan Guindon Email: Submitted by: CC Email: rnorthey@pinchin.com CC Results to: **Rachel Northey** Date Submitted: 06 2024 Required by: January 13 2024 January 5 Day Turnaround # of Samples: 64 35 File 1/2 Priority: Year of Building Construction (Mandatory, Years ONLY): 1926 21, 24, 29, 31 Do NOT Stop on Positive (Sample Numbers): Pinchin Pinchin Group Company (Mandatory Field): 128807/20240398103632 HMIS2 Building Reference #: To be Completed by Lab Personnel Only: b306613 CH 24 hour clock Lab Reference #: Time: Jan 9 2023 CH Date: Month Dav Year Received by: New 2401.16 Name(s) of Analyst(s): Sample Sample Sample Sample Description/Location (Mandatory) Prefix No. Suffix Wall Cement Product Brown Painted Cement Fascia Board Loc: 71, EXTERIOR CH 10-757. CR 10.257 AMO.5-57. s 0018 A Wall,Cement Product,Brown Painted Cement Product s 0018 В Fascia,Loc:71,EXTERIOR Ne Wall, Fascia, Cement Product, Brown Painted Cement Product On S С 0018 Fascia,Loc:71,EXTERIOR no Window, Caulking, Brown Caulking On Lower Portion Of Window Frame Old s 0019 A Windows,Loc 71,EXTERIOR JUDDU Window, Caulking, Brown Caulking On Lower Portion Of Window Frame Old s 0019 в Windows,Loc:71,EXTERIOR Window, Caulking, Brown Caulking On Lower Portion Of Window Frame Old S 0019 С Windows,Loc:71,EXTERIOR Window, Caulking, Soft Brown Vertical And Upper Window S 0020 A Caulking,Loc:71,EXTERIOR Window, Caulking, Soft Brown Vertical And Upper Window S 0020 в Caulking,Loc:71,EXTERIOR Window, Caulking, Soft Brown Vertical And Upper Window s 0020 С Caulking,Loc:71,EXTERIOR Wall, Paint, Beige Painted Exterior Masonry Block Wall 1968 A S 0021 Yoc,Loc:13,CLASSROOM

Sample Prefix	Sample No.	Sample Suffix	Sample Description/Location (Mandatory)
S	0021	B	Wall,Paint,Beige Painted Exterior Masonry Block Wall 1968 Yoc,Loc:13,CLASSROOM
s	0021	0	Wall,Paint,Masonry Block Wall Paint Exterior Wall,Loc:27,CLASSROOM
S	0021	D	Wall,Paint,Exterior Block Wall Paint,Loc:27,CLASSROOM
s	0021	E	Wall,Paint,Exterior Block Wall Paint,Loc:28,CLASSROOM
S	0021	F	Wall,Paint,Exterior Block Wall Paint By Chalkboards,Loc 28,CLASSROOM
s	0021	G	Wall, Paint, Exterior Paint Block Walls, Loc: 18, CLASSROOM
s	0022	A	Sink,Mastic, Grey,Grey Sink Mastic,Loc:13,CLASSROOM
s	0022	в	Sink,Mastic, Grey,Grey Sink Mastic,Loc:27,CLASSROOM
S	0022	с	Sink,Mastic, Grey,Grey Sink Mastic,Loc:28,CLASSROOM
5	0023	A	Wall,Base,Adhesive/mastic,Black Vinyl Trim Adhesive,Loc:27,CLASSROOM
s	0023	В	Wall,Adhesive/mastic,Black Vinyl Trim Adhesive,Loc:14,CUSTODIAN
s	0023	с	Wall,Adhesive/mastic,Vinyl Trim Adhesive On Block Wall,Loc:28,CLASSROOM
s	0024	A	Wall,Paint,Interior Masonry Block Wall Paint,Loc:14,CUSTODIAN ROOM
S	0024	в	Wall,Paint,Interior Beige Block Wall Paint,Loc:15,CORRIDOR
s	0024	с	Wall,Paint,Beige Interior Block Wall Paint,Loc:16,WASHROOM
S	0024	D	Wall,Paint,Interior Masonry Wall Paint,Loc:21,WASHROOM
s	0024	E	Wall,Paint,Interior Masonry Block Paint,Loc:22,GIRLS WASHROOM

20

Sample Prefix	Sample No.	Sample Suffix	Sample Description/Location (Mandatory)	
S	0024	F	Wall,Paint,Interior Block Wall Paint,Loc:26,BOYS WASHROOM	
S	0024	G	Wall,Paint,Interior Block Wall Paint Corridor Wall,Loc:26,BOYS WASHROOM	
S	0025	A	Window,Caulking,Brown Window Frame Caulking 2002 Date Stamp,Loc:14,CUSTODIAN ROOM	
S	0025	в	Window,Caulking,Brown Window Frame Caulking, Loc:20,Coat Room	
S	0025	с	Window,Caulking,Brown Window Frame Caulking Exterior Windows,Loc:18,CLASSROOM	
S	0026	A	DoorMetal Shelf Frame Caulking,Loc:15,CORRIDOR	
S	0026	в	Door,Caulking,Door Frame Caulking,Loc:16,WASHROOM	
s	0026	с	Door,Caulking,Door Frame Caulking,Loc:26,BOYS WASHROOM	

Ģ



Project Name:	KPRDSB, Enniskillen, ON		
Project No.:	0335495.018		
Prepared For:	B. Guindon / R. Northey		
Lab Reference No.: Analyst(s):	b306614 C. Luong / M. Tipgos		
Date Received:	January 9, 2024	Samples Submitted:	30
Date Analyzed:	January 16, 2024	Phases Analyzed:	48

The Pinchin Ltd. Mississauga asbestos laboratory is accredited by the National Institute of Standards and Technology, National Voluntary Laboratory Accreditation Program (NVLAP Lab Code 101270-0) for the 'EPA – 40 CFR Appendix E to Subpart E of Part 763, Interim Method of the Determination of Asbestos in Bulk Insulation Samples,' and the 'EPA 600/R-93/116: Method for the Determination of Asbestos in Bulk Building Materials'; and meets all requirements of ISO/IEC 17025:2017. The Pinchin asbestos laboratory uses the aforementioned methods of analysis.

Bulk samples are checked visually and scanned under a stereomicroscope. Slides are prepared and observed under a Polarized Light Microscope (PLM) at magnifications of 40X, 100X or 400X as appropriate. Asbestos fibres are identified by a combination of morphology, colour, refractive index, extinction, sign of elongation, birefringence and dispersion staining colours. A visual estimate is made of the percentage of asbestos present. A reported concentration of less than (<) the regulatory threshold indicates the presence of confirmed asbestos in trace quantities, limited to only a few fibres or fibre bundles in an entire sample. This method complies with provincial regulatory requirements where applicable. Multiple phases within a sample are analyzed and reported separately.

All bulk samples submitted to this laboratory for asbestos analysis are retained for a minimum of three months. Samples may be retrieved, upon request, for re-examination at any time during that period.

This report relates only to the items tested.

This report relates only to the items tested and is valid only when signed with a protected, authorized, electronic signature. This report may not be reproduced, except in full, without the written approval of Pinchin Ltd. The client may not use this report to claim product endorsement by NVLAP or any agency of the U.S. Government. Internal verification studies, quality assurance / control data and laboratory documentation on measurement uncertainty are available upon request.



Project Name:	KPRDSB, Enniskillen, ON
Project No.:	0335495.018
Prepared For:	B. Guindon / R. Northey

Lab Reference No.:b306614Date Analyzed:January 16, 2024

SAMPLE	SAMPLE	% COMPOSITION (VISUAL ESTIMATE)		
IDENTIFICATION	DESCRIPTION	ASBESTOS	OTHER	
S0027A Floor, Adhesive/mastic, Carpet Adhesive Burgundy Brown Streak Carpet Adhesive, Loc:27, CLASSROOM	Non-homogeneous, yellow and black, mastic material.	None Detected	Tar Material 0.5- Other Non-Fibrous > 7	-5% '5%
S0027B Floor, Adhesive/mastic, Carpet Adhesive By Floor Tiles, Loc:27, CLASSROOM	Non-homogeneous, yellow and black, mastic material.	Chrysotile < 0.5%	Tar Material < 0. Other Non-Fibrous > 7	.5% '5%
S0027C Floor, Adhesive/mastic, Carpet Adhesive By Windows, Loc:27, CLASSROOM	Non-homogeneous, yellow and black, mastic material.	None Detected	Tar Material < 0. Other Non-Fibrous > 7	.5% '5%
S0028A Sink, Adhesive/mastic, Gold Sink Mastic In Closet, Loc:27, CLASSROOM	Homogeneous, gold, mastic material.	Chrysotile 0.5-5%	Tar and other non-fibrous > 7	′5%
S0028B Sink, Adhesive/mastic, Gold Sink Mastic In Closet, Loc:27, CLASSROOM			Not Analyzed	
Comments:	Analysis was stopped due to a p	revious positive result.		



Project Name:	KPRDSB, Enniskillen, ON
Project No.:	0335495.018
Prepared For:	B. Guindon / R. Northey

Lab Reference No.:b306614Date Analyzed:January 16, 2024

SAMPLE	SAMPLE	% COMPOSITIO	ON (VISUAL ESTIMATE)	
IDENTIFICATION	DESCRIPTION	ASBESTOS	OTHER	
S0028C Sink, Adhesive/mastic, Gold Sink Mastic In Closet, Loc:27, CLASSROOM			Not Analyzed	
Comments:	Analysis was stopped due to a p	revious positive result.		
S0029A Wall, Paint, Exterior Masonry Brick Paint On Masonry, Loc:30,	2 Phases: a) Homogeneous, off-white, coating material.		Non-Fibrous Material > 75%	
CLASSROOM	b) Non-homogeneous, multicoloured, coating material.	None Detected	Non-Fibrous Material > 75%	
Comments:	Phase a) is small in size.			
S0029B Wall, Paint, Beige Exterior Block Wall Paint, Loc:31, CLASSROOM	2 Phases: a) Non-homogeneous, white and off-white, coating material.	Chrysotile < 0.5%	Non-Fibrous Material > 75%	
	b) Non-homogeneous, multicoloured, coating material.	None Detected	Non-Fibrous Material > 75%	
Comments:	Phase a) is very small in size. Fo	or more reliable results, a larg	er sample is required.	
S0029C Wall, Paint, Exterior Block Wall Paint, Loc:38, STAFF ROOM	2 Phases: a) Homogeneous, white, soft, cementitious, coating material.	None Detected	Non-Fibrous Material > 75%	
	b) Non-homogeneous, multicoloured, coating material.	None Detected	Non-Fibrous Material > 75%	



Project Name:	KPRDSB, Enniskillen, ON
Project No.:	0335495.018
Prepared For:	B. Guindon / R. Northey

Lab Reference No.:b306614Date Analyzed:January 16, 2024

SAMPLE	SAMPLE	SAMPLE % COMPOSITION		
IDENTIFICATION	DESCRIPTION	ASBESTOS	OTHER	
S0029D Wall, Paint, Beige Masonry Paint Exterior Wall, Loc:40, COPIER ROOM	2 Phases: a) Homogeneous, white, soft, cementitious, coating material.	Chrysotile < 0.5%	Non-Fibrous Material > 75%	
	b) Non-homogeneous, multicoloured, coating material.	None Detected	Non-Fibrous Material > 75%	
S0029E Wall, Paint, Exterior Block Wall Paint, Loc:32, CLASSROOM	3 Phases: a) Homogeneous, off-white, coating material.	Chrysotile < 0.5%	Non-Fibrous Material > 75%	
	b) Homogeneous, white, soft, cementitious, coating material.	None Detected	Non-Fibrous Material > 75%	
	c) Non-homogeneous, multicoloured, coating material.	None Detected	Non-Fibrous Material > 75%	
Comments:	Phase a) is very small in size. Fo	or more reliable results, a larg	er sample is required.	
S0029F Wall, Paint, Exterior Beige Block Walls, Loc:33, CLASSROOM	3 Phases: a) Homogeneous, white, soft, cementitious, coating material.	Chrysotile < 0.5%	Non-Fibrous Material > 75%	
	b) Non-homogeneous, multicoloured, coating material.	None Detected	Non-Fibrous Material > 75%	
S0029G Wall, Paint, Beige Block Wall Paint, Loc:47, Special Education	2 Phases: a) Homogeneous, white, soft, cementitious, coating material.	Chrysotile < 0.5%	Non-Fibrous Material > 75%	
	b) Non-homogeneous, multicoloured, coating material.	None Detected	Non-Fibrous Material > 75%	



Project Name:	KPRDSB, Enniskillen, ON
Project No.:	0335495.018
Prepared For:	B. Guindon / R. Northey

Lab Reference No.:b306614Date Analyzed:January 16, 2024

SAMPLE	SAMPLE	% COMPOSITION (VISUAL ESTIMATE)			
IDENTIFICATION	DESCRIPTION	ASBESTOS	OTHER		
S0030A Wall, Adhesive/mastic, Beige Adhesive On Black Trim Demountable Walls, Loc:36, WASHROOM	Homogeneous, beige, mastic material.	None Detected	Non-Fibrous Material > 75%		
Comments:	Cellulose is present on the surfa	ce of this sample.			
S0030B Wall, Adhesive/mastic, Beige Adhesive On Black Trim Demountable Walls, Loc:36, WASHROOM	Homogeneous, beige, mastic material.	None Detected	Non-Fibrous Material > 75%		
S0030C Wall, Adhesive/mastic, Beige Adhesive Black Trim On Demountable Drywall Walls, Loc:37, VESTIBULE	Homogeneous, beige, mastic material.	None Detected	Non-Fibrous Material > 75%		
S0031A Wall, Paint, Interior Block Wall Paint, Loc:52, LOBBY	2 Phases: a) Homogeneous, off-white, soft, cementitious coating material.	Chrysotile 0.5-5%	Non-Fibrous Material > 75%		
	b) Homogeneous, beige, coating material.	None Detected	Non-Fibrous Material > 75%		



Project Name:	KPRDSB, Enniskillen, ON
Project No.:	0335495.018
Prepared For:	B. Guindon / R. Northey

Lab Reference No.:b306614Date Analyzed:January 16, 2024

SAMPLE	SAMPLE	% COMPOSITION (VISUAL ESTIMATE)			
IDENTIFICATION	DESCRIPTION	ASBESTOS	OTHER		
S0031B Wall, Paint, Interior Block Wall Paint, Loc:53, GIRLS WASHROOM	2 Phases: a) Homogeneous, off-white, soft, cementitious coating material.	None Detected	Talc 0.5-5% Non-Fibrous Material > 75%		
	b) Homogeneous, beige, coating material.	None Detected	Non-Fibrous Material > 75%		
S0031C Wall, Paint, Interior Block Wall Paint, Loc:53, GIRLS WASHROOM	2 Phases: a) Homogeneous, off-white, soft, cementitious coating material.	Chrysotile < 0.5%	Non-Fibrous Material > 75%		
	b) Homogeneous, beige, coating material.	None Detected	Non-Fibrous Material > 75%		
S0031D Wall, Paint, Beige Interior Block Wall Paint, Loc:55, Girls Changeroom	2 Phases: a) Homogeneous, off-white, soft, cementitious coating material.	Chrysotile < 0.5%	Non-Fibrous Material > 75%		
	b) Homogeneous, beige, coating material.	None Detected	Non-Fibrous Material > 75%		
S0031E Wall, Paint, Beige Block Walls, Loc:64, BOYS WASHROOM	2 Phases: a) Homogeneous, off-white, soft, cementitious coating material.	Chrysotile 0.5-5%	Non-Fibrous Material > 75%		
	b) Homogeneous, beige, coating material.	None Detected	Non-Fibrous Material > 75%		



Project Name:	KPRDSB, Enniskillen, ON
Project No.:	0335495.018
Prepared For:	B. Guindon / R. Northey

Lab Reference No.:b306614Date Analyzed:January 16, 2024

SAMPLE	SAMPLE	% COMPOSITION (VISUAL ESTIMATE)			
IDENTIFICATION	DESCRIPTION	ASBESTOS	OTHER		
S0031F Wall, Paint, Interior Beige Block Wall Paint, Loc:66, STORAGE	Homogeneous, beige, coating material.	None Detected	Non-Fibrous Material > 75%		
S0031G Wall, Paint, Interior Beige Block Wall Paint, Loc:67, Closet	2 Phases: a) Homogeneous, off-white, soft, cementitious coating material.	Chrysotile 0.5-5%	Non-Fibrous Material > 75%		
Closet	b) Homogeneous, beige, coating material.	None Detected	Non-Fibrous Material > 75%		
S0032A Wall, Adhesive/mastic, Brown Adhesive Black Vinyl Trim, Loc:53, GIRLS	, , , ,	None Detected	Non-Fibrous Material > 75%		
WASHROOM	b) Homogeneous, yellow, soft, mastic material.	None Detected	Non-Fibrous Material > 75%		
S0032B Wall, Adhesive/mastic, Brown Adhesive Black Vinyl Trim By Toilet, Loc:53,	, , , ,	None Detected	Non-Fibrous Material > 75%		
GIRLS WASHROOM	b) Homogeneous, yellow, soft, mastic material.	None Detected	Non-Fibrous Material > 75%		



Project Name:	KPRDSB, Enniskillen, ON
Project No.:	0335495.018
Prepared For:	B. Guindon / R. Northey

Lab Reference No.:b306614Date Analyzed:January 16, 2024

#### **BULK SAMPLE ANALYSIS**

SAMPLE	SAMPLE	% COMPOSITION (VISUAL ESTIMATE)			
IDENTIFICATION	DESCRIPTION	ASBESTOS	OTHER		
S0032C Wall, Adhesive/mastic, Brown Wall Adhesive On Vinyl Trim, Loc:55, Girls	3 Phases: a) Homogeneous, brown, hard, adhesive material.	None Detected	Non-Fibrous Material > 75%		
Changeroom	b) Homogeneous, yellow, soft, mastic material.	None Detected	Non-Fibrous Material > 75%		
	c) Homogeneous, off-white, soft, cementitious coating material.	Chrysotile 0.5-5%	Non-Fibrous Material > 75%		
S0033A Stairs, Adhesive/mastic, Staircase Green Rubber Tread Adhesive Beige And	2 Phases: a) Homogeneous, brown, hard, adhesive material.	None Detected	Non-Fibrous Material > 75%		
Brown, Loc:62, GYMNASIUM	b) Homogeneous, beige, hard, adhesive material.	None Detected	Non-Fibrous Material > 75%		
S0033B Stairs, Adhesive/mastic, Staircase Green Rubber Tread Adhesive Beige And	2 Phases: a) Homogeneous, brown, hard, adhesive material.	None Detected	Non-Fibrous Material > 75%		
Brown, Loc:62, GYMNASIUM	b) Homogeneous, beige, hard, adhesive material.	None Detected	Non-Fibrous Material > 75%		
S0033C Stairs, Adhesive/mastic, Staircase Green Rubber Tread Adhesive Beige And	2 Phases: a) Homogeneous, brown, hard, adhesive material.	None Detected	Non-Fibrous Material > 75%		
Brown, Loc:62, GYMNASIUM	b) Homogeneous, beige, hard, adhesive material.	None Detected	Non-Fibrous Material > 75%		

Reviewed by:

Digitally signed by John Raisch-Berkoff Date: 2024.01.16 17:20:28-05'00'

M. H

**Reporting Analyst:** Digitally signed by John Raisch-Berkoff Date: 2024.01.16 17:20:53-05'00'

Analyzed by Mr 2014/1/16 Reviewed by ORB Report Sent by ORB

#### Pinchin Ltd. - Asbestos Laboratory Internal Asbestos Bulk Sample Chain of Custody Project Address: ON **KPRDSB** Client Name: 335495.018 Portfolio/Building No: Enniskillen Pinchin File: bguindon@pinchin.com Email: Submitted by: **Bryan Guindon** rnorthey@pinchin.com CC Email: **Rachel Northey** CC Results to: 2024 January 13 Required by: Date Submitted: January 06 2024 5 Day Turnaround Priority: 30 # of Samples: Year of Building Construction (Mandatory, Years ONLY): 1926 21, 24, 29, 31 Do NOT Stop on Positive (Sample Numbers): Pinchin Pinchin Group Company (Mandatory Field): 128807/20240398103632 HMIS2 Building Reference #: To be Completed by Lab Personnel Only: Time: 24 hour clock Lab Reference #: JAN 0 9 2024 Year Date: Month Day Received by: rely Name(s) of Analyst(s): Sample Sample Sample Sample Description/Location (Mandatory) Prefix No. Suffix Floor, Adhesive/mastic, Carpet Adhesive Burgundy Brown Streak Carpet 0027 A S Adhesive, Loc: 27, CLASSROOM NĎ Floor, Adhesive/mastic, Carpet Adhesive By Floor Tiles, Loc: 27, CLASSROOM 0027 S В CH<0.57. Floor, Adhesive/mastic, Carpet Adhesive By Windows, Loc: 27, CLASSROOM C \$ 0027 ND Sink,Adhesive/mastic,Gold Sink Mastlc In Closet,Loc:27,CLASSROOM 0028 А S CH0.6-57. Sink,Adhesive/mastic,Gold Sink Mastic In Closet,Loc:27,CLASSROOM S 0028 в - NA -Sink,Adhesive/mastic,Gold Sink Mastic In Closet,Loc:27,CLASSROOM С S 0028 -NA-Wall, Paint, Exterior Masonry Brick Paint On Masonry, Loc: 30, CLASSROOM S 0029 А a) CHO.5-57. b) ND Wall, Paint, Beige Exterior Block Wall Paint, Loc: 31, CLASSROOM S 0029 В A) CH<0.57. 6) NO Wall, Paint, Exterior Block Wall Paint, Loc: 38, STAFF ROOM S 0029 С 9 ND 6) ND

	Sample Prefix	Sample No.	Sample Suffix	Sample Description/Location (Mandatory)
	s	0029	D	Wall,Paint,Beige Masonry Paint Exterior Wall,Loc:40,COPIER ROOM <u> A) CH &lt; 0.57. b) NC</u>
•	s	0029	E	Wall,Paint,Exterior Block Wall Paint,Loc:32,CLASSROOM
•	S	0029	F	Wall,Paint,Exterior Beige Block Walls,Loc:33.CLASSROOM A) CH < 0.5 7。 b) ND
	s	0029	G	Wall,Paint,Beige Block Wall Paint,Loc:47,Special Education
	s	0030	A	Wall,Adhesive/mastic,Beige Adhesive On Black Trim Demountable Walls,Loc:36,WASHROOM
	S	0030	В	Wall, Adhesive/mastic, Beige Adhesive On Black Trim Demountable Walls, Loc: 36, WASHROOM NO
U 1	S	0030	c	Wall,Adhesive/mastic,Beige Adhesive Black Trim On Demountable Drywall Walls,Loc:37,VESTIBULE
ht	S	0031	A	Wall, Paint, Interior Block Wall Paint, Lpa: 52, LOBBY
ſ	s	0031	В	Wall,Paint,Interior Block Wall Paint,Lod:53,GIRLS WASHROOM
•	s	0031	С	Wall,Paint,Interior Block Wall Paint,Lot:53 GIRLS WASHROOM
•	s	0031	D	Wall,Paint,Beige Interior Block Wall Paint,Loc:55,Girls Changeroom
	s	0031	Е	Wall,Paint,Beige Block Walls,Loc:64,BOYS WASHROOM
•	s	0031	F	Wall,Paint,Interior Beige Block Wall Paint,Loc:66,STORAGE
•	S	0031	G	Wall, Paint, Interior Block Wall Paint, Loc:67, CLOSET
	S	0032	А	Wall, Adhesive/mastic, Brown Adhesive Black Vinyl, Tinh, voc:53, G!RLS WASHROOM
	S	0032	в	Wall,Adhesive/mastic,Brown Adhesive Black Vinyl, Trim By Toilet,Loc:53,GIRLS WASHROOM
X	s	0032	с	Wall,Adhesive/mastic,Brown Adhesive Black Vinyl Trim By Sink Basin,Loc:53,GIRLS WASHROOM

\* The F

24

1	Sample Prefix	Sample No.	Sample Suffix	Sample Description/Location (Mandatory)
15	S	0032	с	Wall,Adhesive/mastic,Brown Wall Adhesive On Vinyl Trim, Loc:55, Girls Changeroom
(	S	0033	A	Stairs, Adhesive/mastic, Staircase Green Rubber Tread Adhesive Beige And Brown, Loc: 62, GYMNASIUM
	s	0033	В	Stairs, Adhesive/mastic, Staircase Green Rubber Tread Adhesive Beige And Brown, Loc: 62, GYMNASIUM
4	s	0033	с	Stairs, Adhesive/mastic, Staircase Green Rubber Tread Adhesive Beige And Brown, Loc: 62, GYMNASIUM
			C	1.9
				10
				21 GI
				70
				v



Project No.: Prepared For:	0335495.018 N. Robinson		
Lab Reference No.: Analyst(s):	b311537 C. Luong		
Date Received: Date Analyzed:	April 10, 2024 April 16, 2024	Samples Submitted: Phases Analyzed:	6 6

The Pinchin Ltd. Mississauga asbestos laboratory is accredited by the National Institute of Standards and Technology, National Voluntary Laboratory Accreditation Program (NVLAP Lab Code 101270-0) for the 'EPA – 40 CFR Appendix E to Subpart E of Part 763, Interim Method of the Determination of Asbestos in Bulk Insulation Samples,' and the 'EPA 600/R-93/116: Method for the Determination of Asbestos in Bulk Building Materials'; and meets all requirements of ISO/IEC 17025:2017. The Pinchin asbestos laboratory uses the aforementioned methods of analysis.

Bulk samples are checked visually and scanned under a stereomicroscope. Slides are prepared and observed under a Polarized Light Microscope (PLM) at magnifications of 40X, 100X or 400X as appropriate. Asbestos fibres are identified by a combination of morphology, colour, refractive index, extinction, sign of elongation, birefringence and dispersion staining colours. A visual estimate is made of the percentage of asbestos present. A reported concentration of less than (<) the regulatory threshold indicates the presence of confirmed asbestos in trace quantities, limited to only a few fibres or fibre bundles in an entire sample. This method complies with provincial regulatory requirements where applicable. Multiple phases within a sample are analyzed and reported separately.

All bulk samples submitted to this laboratory for asbestos analysis are retained for a minimum of three months. Samples may be retrieved, upon request, for re-examination at any time during that period.

This report relates only to the items tested.

This report relates only to the items tested and is valid only when signed with a protected, authorized, electronic signature. This report may not be reproduced, except in full, without the written approval of Pinchin Ltd. The client may not use this report to claim product endorsement by NVLAP or any agency of the U.S. Government. Internal verification studies, quality assurance / control data and laboratory documentation on measurement uncertainty are available upon request.



0335495.018
N. Robinsor

Lab Reference No.:b311537Date Analyzed:April 16, 2024

#### **BULK SAMPLE ANALYSIS**

SAMPLE SAMPLE % COMPOSITION (VISUAL ESTIMATE			N (VISUAL ESTIMATE)		
IDENTIFICATION	DESCRIPTION	ASBESTOS	OTHER	OTHER	
S0034A Ceiling, Ceiling Tiles (lay- in), 2ft By 4ft Pinhole, Fissure, And Crater,	Homogeneous, beige, layered, compressed, acoustic ceiling tile.	None Detected	Cellulose Man-Made Vitreous Fibres Perlite	25-50% 25-50% 10-25%	
Loc:44, COAT ROOM			Other Non-Fibrous	0.5-5%	
S0034B Ceiling, Ceiling Tiles (lay- in), 2ft By 4ft Pinhole, Fissure, And Crater, Loc:44, COAT ROOM	Homogeneous, beige, layered, compressed, acoustic ceiling tile.	None Detected	Cellulose Man-Made Vitreous Fibres Perlite Other Non-Fibrous	25-50% 25-50% 10-25% 0.5-5%	
S0034C Ceiling, Ceiling Tiles (lay- in), 2ft By 4ft Pinhole, Fissure, And Crater, Loc:44, COAT ROOM	Homogeneous, beige, layered, compressed, acoustic ceiling tile.	None Detected	Cellulose Man-Made Vitreous Fibres Perlite Other Non-Fibrous	25-50% 25-50% 10-25% 0.5-5%	
S0035A Wall, Caulking, Black Caulking Around Windows Frames, Loc:13, CLASSROOM	Homogeneous, dark brown, caulking material.	None Detected	Non-Fibrous Material	> 75%	
S0035B Wall, Caulking, Black Caulking Around Windows Frames, Loc:13, CLASSROOM	Homogeneous, dark brown, caulking material.	None Detected	Non-Fibrous Material	> 75%	
S0035C Wall, Caulking, Black Caulking Around Windows Frames, Loc:13, CLASSROOM	Homogeneous, dark brown, caulking material.	None Detected	Non-Fibrous Material	> 75%	

**Reviewed by:** 

**Digitally signed** by Pinchin Ltd. Date: 2024.04.17 10:23:35-04'00'

C.L Page 2 of 2

Reporting Analyst:

Digitally signed by Pinchin Ltd. Date: 2024.04.17 10:23:44-04'00'



# Pinchin Ltd. - Asbestos Laboratory Internal Asbestos Bulk Sample Chain of Custody

Client Name	:			Project Address:	ON		
Portfolio/Bu	ilding No:			Pinchin File:	335495.018		
Submitted b	y:	Nicholas Rol	oinson	Email:	nrobinson@p	inchin.com	
CC Results		Rachel North	ney	CC Email:	rnorthey@pinchin.com		
Date Submit	ted:	April	08 2024	Required by:	April	15	2024
# of Sample	s:	6		Priority:	5 Da	y Turnarour	ıd
Year of Buik	ding Constru	ction (Manda	atory, Years ONLY):	1926	31 21 53		
Do NOT Sto	p on Positive	(Sample Nu	mbers):		a denter of	-	_
Pinchin Gro	up Company	(Mandatory	Field ):		Pinchin		1.12
HMIS2 Build	ing Reference	:e #:		132288/202435646	523315	10	
THE R. LEWIS CO., NAMES OF TAXABLE PARTY.	leted by Lab	States and states and states and states and	nly: CH	A DAM A DAME	A STATE OF THE STATE OF		
Lab Referen	ce #:	631	1537	Time:	24	hour clock	
Descined here		0 2024	Date:	Month	Day	Year	
Name(s) of Analyst(s):		U KURO		April	16	2024	
Sample Prefix	Sample No.	Sample Suffix	Sam	ple Description/Lo	cation (Man	datory)	
S	0034	A	Ceiling,Ceiling Tiles Crater,Loc:44,COA	(lay-in),2ft By 4ft Pinl T ROOM ND	hole, Fissure, A	nd	
S	0034	В	Ceiling,Ceiling Tiles (lay-ln),2ft By 4ft Pinhole, Fissure, And Crater,Loc:44,COAT ROOM				
S	0034	с	Ceiling,Ceiling Tiles Crater,Loc:44,COA	: (lay-in),2ft By 4ft Pin T ROOM <mark>NЮ</mark>	hole, Fissure, A	And	
S	0035	A	Wall,Caulking,Black Frames,Loc:13,CL4	Caulking Around Wi	ndows		
S	0035	в	Wall,Caulking,Black Frames,Loc:13,CLA	Caulking Around Wi	ndows		
s	0035	с	Wall,Caulking,Black Frames,Loc:13,CL4	Caulking Around Wi	ndows		



Project Name:	KPRDSB, ON		
Project No.:	0335495.018		
Prepared For:	C. Reynolds / A. Brett		
Lab Reference No.:	b317386		
Analyst(s):	E. Cianni / K. Cockburn		
Date Received:	July 3, 2024	Samples Submitted:	9
Date Analyzed:	July 4, 2024	Phases Analyzed:	19

The Pinchin Ltd. Mississauga asbestos laboratory is accredited by the National Institute of Standards and Technology, National Voluntary Laboratory Accreditation Program (NVLAP Lab Code 101270-0) for the 'EPA – 40 CFR Appendix E to Subpart E of Part 763, Interim Method of the Determination of Asbestos in Bulk Insulation Samples,' and the 'EPA 600/R-93/116: Method for the Determination of Asbestos in Bulk Building Materials'; and meets all requirements of ISO/IEC 17025:2017. The Pinchin asbestos laboratory uses the aforementioned methods of analysis for all bulk materials. Please be advised that bulk materials do not include debris, dust, and tape-lift samples, and the analysis and reporting of these materials does not conform with Pinchin Ltd.'s NVLAP accreditation.

Bulk samples are checked visually and scanned under a stereomicroscope. Slides are prepared and observed under a Polarized Light Microscope (PLM) at magnifications of 40X, 100X or 400X as appropriate. Asbestos fibres are identified by a combination of morphology, colour, refractive index, extinction, sign of elongation, birefringence and dispersion staining colours. A visual estimate is made of the percentage of asbestos present. A reported concentration of less than (<) the regulatory threshold indicates the presence of confirmed asbestos in trace quantities, limited to only a few fibres or fibre bundles in an entire sample. This method complies with provincial regulatory requirements where applicable. Multiple phases within a sample are analyzed and reported separately.

All bulk samples submitted to this laboratory for asbestos analysis are retained for a minimum of three months. Samples may be retrieved, upon request, for re-examination at any time during that period.

This report relates only to the items tested.

This report relates only to the items tested and is valid only when signed with a protected, authorized, electronic signature. This report may not be reproduced, except in full, without the written approval of Pinchin Ltd. The client may not use this report to claim product endorsement by NVLAP or any agency of the U.S. Government. Internal verification studies, quality assurance / control data and laboratory documentation on measurement uncertainty are available upon request.



Project Name:	KPRDSB, ON
Project No.:	0335495.018
Prepared For:	C. Reynolds / A. Brett

Lab Reference No.:b317386Date Analyzed:July 4, 2024

SAMPLE SAMPLE % COMPOSITIO		% COMPOSITION (	I (VISUAL ESTIMATE)	
IDENTIFICATION	DESCRIPTION	ASBESTOS	OTHER	
S0036A Door,Caulking,White Caulking On Door Frame,Loc:64,BOYS WASHROOM	Homogeneous, grey, caulking material.	None Detected	Non-Fibrous Material > 75%	
S0036B Door,Caulking,White Caulking On Door Frame,Loc:64,BOYS WASHROOM	Homogeneous, grey, caulking material.	None Detected	Non-Fibrous Material > 75%	
S0036C Door,Caulking,White Caulking On Door Frame,Loc:53,GIRLS WASHROOM	Homogeneous, grey, caulking material.	None Detected	Non-Fibrous Material > 75%	
S0037A Wall,Thin-set,Thinset Behind 2" X 2" Ceramic Tiles,Loc:15,CORRIDOR	3 Phases: a) Homogeneous, grey, hard, cementitious material.	None Detected	Non-Fibrous Material > 75%	
	b) Homogeneous, white, hard, cementitious material.	None Detected	Non-Fibrous Material > 75%	
	c) Homogeneous, off-white, soft, cementitious material.	None Detected	Non-Fibrous Material > 75%	
Comments:	Phase c) is small in size. Ceramic tile is present on the surface of this sample.			



Project Name:	KPRDSB, ON
Project No.:	0335495.018
Prepared For:	C. Reynolds / A. Brett

Lab Reference No.:b317386Date Analyzed:July 4, 2024

SAMPLE	SAMPLE	% COMPOSITION (VISUAL ESTIMATE)	
IDENTIFICATION	DESCRIPTION	ASBESTOS	OTHER
S0037B Wall,Thin-set,Thinset Behind 2" X 2" Ceramic Tiles,Loc:15,CORRIDOR	3 Phases: a) Homogeneous, grey, hard, cementitious material.	None Detected	Non-Fibrous Material > 75
Thes, Loc. 13, CORRIDOR	b) Homogeneous, white, hard, cementitious material.	None Detected	Non-Fibrous Material > 75
	c) Homogeneous, off-white, soft, cementitious material.	None Detected	Non-Fibrous Material > 75
Comments:	Phase c) is small in size. Ce	ramic tile is present on the surface of	I fhis sample.
S0037C Wall,Thin-set,Thinset Behind 2" X 2" Ceramic Tiles,Loc:15,CORRIDOR	3 Phases: a) Homogeneous, grey, hard, cementitious material.	None Detected	Non-Fibrous Material > 75
Thes, Loc. 13, CORRIDOR	b) Homogeneous, white, hard, cementitious material.	None Detected	Non-Fibrous Material > 75
	c) Homogeneous, off-white, soft, cementitious material.	None Detected	Non-Fibrous Material > 75
Comments:	Phase c) is small in size. Ce	ramic tile is present on the surface of	of this sample.
S0038A Bulletin Board,Adhesive /mastic, Brown Mastic Adhesive On Wall For	3 Phases: a) Homogeneous, brown, adhesive material.	None Detected	Non-Fibrous Material > 75
Tackboards, Loc:13, CLASSROOM	b) Homogeneous, light grey, soft, cementitious material.	Chrysotile < 0.5%	Non-Fibrous Material > 75
	c) Homogeneous, brown, soft, cementitious material.	None Detected	Non-Fibrous Material > 75
Comments:	Phase b) is small in size. Fo	r more reliable results, a larger sam	ple is required.



Project Name:	KPRDSB, ON
Project No.:	0335495.018
Prepared For:	C. Reynolds / A. Brett

Lab Reference No.:b317386Date Analyzed:July 4, 2024

### **BULK SAMPLE ANALYSIS**

SAMPLE	SAMPLE	% COMPOSITION (VISUAL ESTIMATE)	
IDENTIFICATION	DESCRIPTION	ASBESTOS	OTHER
S0038B	2 Phases:		
Bulletin Board,Adhesive		None Detected	Non-Fibrous Material > 75%
/mastic,Brown Mastic	adhesive material.		
Adhesive On Wall For			
Tackboards,Loc:13,	b) Homogeneous, light	Chrysotile < 0.5%	Non-Fibrous Material > 75%
CLASSROOM	grey, soft, cementitious		
	material.		
Comments:	Phase b) is small in size. For	r more reliable results, a larger san	nple is required.
S0038C	2 Phases:		
Bulletin Board,Adhesive	a) Homogeneous, brown,	None Detected	Non-Fibrous Material > 75%
/mastic,Brown Mastic	adhesive material.		
Adhesive On Wall For			
Tackboards,Loc:18,	b) Homogeneous, light	Chrysotile < 0.5%	Non-Fibrous Material > 75%
CLASSROOM	grey, soft, cementitious		
	material.		

Reviewed by:

Digitally signed by Pinchin Ltd. Date: 2024.07.04 13:07:00-04'00'

Digitally signed by Pinchin Ltd. Date: 2024.07.04 13:07:17-04'00'

**Reporting Analyst:** 



# Pinchin Ltd. - Asbestos Laboratory Internal Asbestos Bulk Sample Chain of Custody

\$

Client Nam	e:	KPRDSB		Project Address:	ON			
Portfolio/B	uilding No:			Pinchin File: 0335495.018				
Submitted	bmitted by:		olds	Email:	nail: ccreynolds@pinchin.com			
CC Results	to:	Alex Brett	The second	CC Email:	abrett@pind	the of the state of the state of the state of the	283	
Date Subm	itted:	July	3 2024	Required by:	July	4	2024	
# of Sample	es:	9	- Savin Ballery	Priority:		sh Turnarour	nd	
Year of Bui	Iding Constru	uction (Mana	datory, Years ONLY):	1926	100	TE Date	1	
Do NOT Sto	op on Positive	e (Sample N	umbers):	ES ELSELLES	20		1970-	
Pinchin Gro	oup Company	(Mandatory	/ Field ):		Pinchin		1000	
HMIS2 Buil	ding Referen	ce #:	1	135959/202452871	194037		R TE	
To be Com	pleted by Lab		Constant and the second s	86 04	Mere Street	19- 8- 11-	1-12	
Lab Referen		JUL	0 3 2024	Time:	A second s	4 hour clock		
Received by	-	A search and a second second		Date: July 7,202	4 Month	Day	Year	
A DESCRIPTION OF THE OWNER	Analyst(s):	ECI	K.C					
Sample Prefix	Sample No.	Sample Suffix	Sampl	e Description/Loo	cation (Man	datory)		
S	0036	A	Door,Caulking,White	Caulking On Door F	rame,Loc:64,	BOYS WAS	HROOM	
S	0036	В	Door,Caulking,White Caulking On Door Frame,Loc:64,BOYS WASHR				HROOM	
S	0036	с	Door,Caulking,White	Caulking On Door F	rame,Loc:53,		HROOM	
S	0037	A	Wall, Thin-set, Thinset	Behind 2" X 2" Cera		- Ale	DOR	
S	0037	В	Wall,Thin-set,Thinset	Behind 2" X 2" Cera	mic Tiles,Loc		OOR	
S	0037	С	Wall, Thin-set, Thinset	Behind 2" X 2" Cera	mic Tiles, Loc	15 CORRIE	DOR	
S	0038	A	Bulletin Board, Adhesive/mastic, Brown Mastic Adhesive On Wall For Tackboards, Loc: 13, CLASSROOMa) ND b) CH < 0, 5% c) ND					
S	0038	В	Bulletin Board, Adhesive/mastic, Brown Mastic Adhesive On Wall For Tackboards, Loc: 13, CLASSROOM a) ND b) CH<0.5%					
S	0038	С	Bulletin Board,Adhesiv Tackboards,Loc:18,Cl	ve/mastic,Brown Ma _ASSROOM (a) \	stic Adhesive	On Wall Fo	r	



# Pinchin Ltd. Asbestos Laboratory Certificate of Analysis

Project Name: Project No.: Prepared For:	Kawartha Pine Ridge Dis 0335495.018 C. Reynolds / A. Brett	trict School Board, ON	
Lab Reference No.: Analyst(s):	b318083 C. Luong		
Date Received: Date Analyzed:	July 11, 2024 July 11, 2024	Samples Submitted: Phases Analyzed:	3 3

The Pinchin Ltd. Mississauga asbestos laboratory is accredited by the National Institute of Standards and Technology, National Voluntary Laboratory Accreditation Program (NVLAP Lab Code 101270-0) for the 'EPA – 40 CFR Appendix E to Subpart E of Part 763, Interim Method of the Determination of Asbestos in Bulk Insulation Samples,' and the 'EPA 600/R-93/116: Method for the Determination of Asbestos in Bulk Building Materials'; and meets all requirements of ISO/IEC 17025:2017. The Pinchin asbestos laboratory uses the aforementioned methods of analysis for all bulk materials. Please be advised that bulk materials do not include debris, dust, and tape-lift samples, and the analysis and reporting of these materials does not conform with Pinchin Ltd.'s NVLAP accreditation.

Bulk samples are checked visually and scanned under a stereomicroscope. Slides are prepared and observed under a Polarized Light Microscope (PLM) at magnifications of 40X, 100X or 400X as appropriate. Asbestos fibres are identified by a combination of morphology, colour, refractive index, extinction, sign of elongation, birefringence and dispersion staining colours. A visual estimate is made of the percentage of asbestos present. A reported concentration of less than (<) the regulatory threshold indicates the presence of confirmed asbestos in trace quantities, limited to only a few fibres or fibre bundles in an entire sample. This method complies with provincial regulatory requirements where applicable. Multiple phases within a sample are analyzed and reported separately.

All bulk samples submitted to this laboratory for asbestos analysis are retained for a minimum of three months. Samples may be retrieved, upon request, for re-examination at any time during that period.

This report relates only to the items tested.

This report relates only to the items tested and is valid only when signed with a protected, authorized, electronic signature. This report may not be reproduced, except in full, without the written approval of Pinchin Ltd. The client may not use this report to claim product endorsement by NVLAP or any agency of the U.S. Government. Internal verification studies, quality assurance / control data and laboratory documentation on measurement uncertainty are available upon request.



# Pinchin Ltd. Asbestos Laboratory Certificate of Analysis

Project Name:Kawartha Pine Ridge District School Board, ONProject No.:0335495.018Prepared For:C. Reynolds / A. Brett

Lab Reference No.:b318083Date Analyzed:July 11, 2024

## **BULK SAMPLE ANALYSIS**

SAMPLE	SAMPLE	% COMPOSITION (VISUAL ESTIMATE)				
IDENTIFICATION	DESCRIPTION	ASBESTOS	OTHER			
Floor,Terrazzo,Loc:15,COR	J , J,	None Detected	Non-Fibrous Material > 75%			
Floor,Terrazzo,Loc:15,COR	5,57	None Detected	Non-Fibrous Material > 75%			
S0039C Floor,Terrazzo,Loc:15,COR RIDOR	J , J,	None Detected	Non-Fibrous Material > 75%			

Reviewed by:

Digitally signed by Pinchin Ltd. Date: 2024.07.11 16:01:11-04'00'

Digitally signed by Pinchin Ltd. Date: 2024.07.11 16:01:27-04'00' C.L

**Reporting Analyst:** 



# Pinchin Ltd. - Asbestos Laboratory Internal Asbestos Bulk Sample Chain of Custody

Client Name	:	Kawartha Pin School Boar		istrict	Project Address:	ON			
Portfolio/Bu	ilding No:				Pinchin File:	0335495.018			
Submitted b	y:	Cole Reynol	ds		Email:	ccreynolds@p	inchin.co	m	
CC Results	to:	Alex Brett	11/12.2	1223	CC Email:	abrett@pinch	in.com		
Date Submit	ted:	July	9	2024	Required by:	July	11	2024	
# of Sample:	s:	3			Priority:	Rush	Turnarou	und	
Year of Build	ding Constru	iction (Manda	atory, Year	s ONLY):	1927	III		6	
Do NOT Sto	p on Positive	e (Sample Nu	mbers):		Contraction of the second		1 Parto	_	
Pinchin Gro	ир Сотрапу	(Mandatory	Field):			Pinchin	2		
HMIS2 Build	ing Reference	ce #:			135959/20245287	1194037		-	
To be Comp	leted by Lab	Personnel C	inly:	A State					
Lab Referen	ce #:	<b>13180</b>	832	2	Time:	24	hour cloc	k	
Received by			1 2026	0.0	Date:	Month	Day	Year	
Name(s) of /	Analyst(s):	JUL I	LUCS	01		puls		200	
Sample Prefix	Sample No.	Sample Suffix		Samp	le Description/Lo	cation (Mand	atory)	, care	
s	0039	A	Floor,Terr	azzo,Loc:1	5,CORRIDOR NC	}			
s	0039	в	Floor,Terr	razzo,Loc:1	5,CORRIDOR NC	)			
S	0039	с	Eloor Terr	azzo Loc:1	5,CORRIDOR				



# Pinchin Ltd. Asbestos Laboratory Certificate of Analysis

Project Name: Project No.: Prepared For:	Kawartha Pine Ridge Dis 0335495.018 C. Reynolds / A. Brett	trict School Board, ON	
Lab Reference No.: Analyst(s):	b319303 N. Barinque		
Date Received: Date Analyzed:	July 25, 2024 July 25, 2024	Samples Submitted: Phases Analyzed:	3 3

The Pinchin Ltd. Mississauga asbestos laboratory is accredited by the National Institute of Standards and Technology, National Voluntary Laboratory Accreditation Program (NVLAP Lab Code 101270-0) for the 'EPA – 40 CFR Appendix E to Subpart E of Part 763, Interim Method of the Determination of Asbestos in Bulk Insulation Samples,' and the 'EPA 600/R-93/116: Method for the Determination of Asbestos in Bulk Building Materials'; and meets all requirements of ISO/IEC 17025:2017. The Pinchin asbestos laboratory uses the aforementioned methods of analysis for all bulk materials. Please be advised that bulk materials do not include debris, dust, and tape-lift samples, and the analysis and reporting of these materials does not conform with Pinchin Ltd.'s NVLAP accreditation.

Bulk samples are checked visually and scanned under a stereomicroscope. Slides are prepared and observed under a Polarized Light Microscope (PLM) at magnifications of 40X, 100X or 400X as appropriate. Asbestos fibres are identified by a combination of morphology, colour, refractive index, extinction, sign of elongation, birefringence and dispersion staining colours. A visual estimate is made of the percentage of asbestos present. A reported concentration of less than (<) the regulatory threshold indicates the presence of confirmed asbestos in trace quantities, limited to only a few fibres or fibre bundles in an entire sample. This method complies with provincial regulatory requirements where applicable. Multiple phases within a sample are analyzed and reported separately.

All bulk samples submitted to this laboratory for asbestos analysis are retained for a minimum of three months. Samples may be retrieved, upon request, for re-examination at any time during that period.

This report relates only to the items tested.

This report relates only to the items tested and is valid only when signed with a protected, authorized, electronic signature. This report may not be reproduced, except in full, without the written approval of Pinchin Ltd. The client may not use this report to claim product endorsement by NVLAP or any agency of the U.S. Government. Internal verification studies, quality assurance / control data and laboratory documentation on measurement uncertainty are available upon request.



# Pinchin Ltd. Asbestos Laboratory Certificate of Analysis

Project Name:Kawartha Pine Ridge District School Board, ONProject No.:0335495.018Prepared For:C. Reynolds / A. Brett

Lab Reference No.:b319303Date Analyzed:July 25, 2024

# **BULK SAMPLE ANALYSIS**

SAMPLE	SAMPLE	% COMPOSIT	ION (VISUAL ESTIMATE)	
IDENTIFICATION	DESCRIPTION	ASBESTOS	OTHER	
S0040A Door, Caulking, Grey Caulking Along Door Frames In 1968 Phase Of Construction, Loc:71, EXTERIOR	Homogeneous, beige, caulking material.	None Detected	Non-Fibrous Material	> 75%
S0040B Door, Caulking, Grey Caulking Along Door Frames In 1968 Phase Of Construction, Loc:71, EXTERIOR	Homogeneous, beige, caulking material.	None Detected	Non-Fibrous Material	> 75%
S0040C Door, Caulking, Grey Caulking Along Door Frames In 1968 Phase Of Construction, Loc:71, EXTERIOR	Homogeneous, beige, caulking material.	None Detected	Non-Fibrous Material	> 75%

Reviewed by:



Digitally signed by Pinchin Ltd. Date: 2024.07.25 15:49:50-04'00' Page 2 of 2

**Reporting Analyst:** 

Digitally signed by Pinchin Ltd. Date: 2024.07.25 15:49:29-04'00'



# Pinchin Ltd. - Asbestos Laboratory Internal Asbestos Bulk Sample Chain of Custody

Client Name:			Kawartha Pine Ridge District School Board		Project Address:	ON		in
Portfolio/Bui	Iding No:	5.6 B B			Pinchin File:	0335495.018		
Submitted by	y:	Cole Reynold	cole Reynolds		Email:	ccreynolds@	pinchin.com	n
CC Results t	:0:	Alex Brett			CC Email:	abrett@pincl	nin.com	
Date Submit	ted:	July	10	2024	Required by:	July	12	2024
# of Samples	3:	3			Priority:	Rus	h Turnarou	nd
Year of Build	ling Constr	uction (Manda	atory, Yea	rs ONLY):	1927		188 E	11.5
Do NOT Stop	o on Positiv	e (Sample Nu	mbers):					
Pinchin Group Company (Mandatory Field):			Pinchin					
HMIS2 Building Reference #:			135959/20245287	1194037	12 - 4.1	11		
To be Comp	leted by Lat	Personnel O	nly:		and the second second second			
Lab Referen	CONTRACTOR OF A CONTRACTOR OF A DATE	631930	3 20		Time:	24	hour clock	•
Received by	:		JUL	L 2 5 2024	Date:	Month	Day	Year
Name(s) of A	Analyst(s):	and the second						
Sample Prefix	Sample No.	Sample Suffix	1941-12-1	Samp	le Description/Lo	cation (Man	datory)	
s	0040	A			Caulking Along Doo EXTERIOR	r Frames In 19	68 Phase	Of
s	0040	В			Caulking Along Doo EXTERIOR	r Frames In 19	68 Phase	Of
s	0040	с			Caulking Along Doo EXTERIOR	r Frames In 19	68 Phase	Of



# Pinchin Ltd. Asbestos Laboratory Certificate of Analysis

0335495.018		
N. Robinson / A. Brett		
b318328 A. Wells		
July 12, 2024 July 15, 2024	Samples Submitted: Phases Analyzed:	3 3
	N. Robinson / A. Brett b318328 A. Wells July 12, 2024	N. Robinson / A. Brett b318328 A. Wells July 12, 2024 Samples Submitted:

The Pinchin Ltd. Mississauga asbestos laboratory is accredited by the National Institute of Standards and Technology, National Voluntary Laboratory Accreditation Program (NVLAP Lab Code 101270-0) for the 'EPA – 40 CFR Appendix E to Subpart E of Part 763, Interim Method of the Determination of Asbestos in Bulk Insulation Samples,' and the 'EPA 600/R-93/116: Method for the Determination of Asbestos in Bulk Building Materials'; and meets all requirements of ISO/IEC 17025:2017. The Pinchin asbestos laboratory uses the aforementioned methods of analysis for all bulk materials. Please be advised that bulk materials do not include debris, dust, and tape-lift samples, and the analysis and reporting of these materials does not conform with Pinchin Ltd.'s NVLAP accreditation.

Bulk samples are checked visually and scanned under a stereomicroscope. Slides are prepared and observed under a Polarized Light Microscope (PLM) at magnifications of 40X, 100X or 400X as appropriate. Asbestos fibres are identified by a combination of morphology, colour, refractive index, extinction, sign of elongation, birefringence and dispersion staining colours. A visual estimate is made of the percentage of asbestos present. A reported concentration of less than (<) the regulatory threshold indicates the presence of confirmed asbestos in trace quantities, limited to only a few fibres or fibre bundles in an entire sample. This method complies with provincial regulatory requirements where applicable. Multiple phases within a sample are analyzed and reported separately.

All bulk samples submitted to this laboratory for asbestos analysis are retained for a minimum of three months. Samples may be retrieved, upon request, for re-examination at any time during that period.

This report relates only to the items tested.

This report relates only to the items tested and is valid only when signed with a protected, authorized, electronic signature. This report may not be reproduced, except in full, without the written approval of Pinchin Ltd. The client may not use this report to claim product endorsement by NVLAP or any agency of the U.S. Government. Internal verification studies, quality assurance / control data and laboratory documentation on measurement uncertainty are available upon request.



# Pinchin Ltd. Asbestos Laboratory Certificate of Analysis

Project No.:0335495.018Prepared For:N. Robinson / A. Brett

Lab Reference No.:b318328Date Analyzed:July 15, 2024

# **BULK SAMPLE ANALYSIS**

SAMPLE	SAMPLE	% COMPOSI	TION (	VISUAL ESTIMATE)		
IDENTIFICATION	DESCRIPTION	ASBESTOS		OTHER		
S0041A Wall,Expansion Joint, Caulking, Grey,Loc:13, CLASSROOM	2 Phases: a) Homogeneous, beige, caulking material.	None Detected		Non-Fibrous Material	> 75%	
	b) Homogeneous, grey, caulking material.	Chrysotile (	0.5-5%	Non-Fibrous Material	> 75%	
Comments:	Man-made vitreous fibres ar	e present on the surface of th	his sam	ple.		
S0041B Wall,Expansion Joint, Caulking, Grey,Loc:13, CLASSROOM	2 Phases: a) Homogeneous, grey, soft, caulking material. b) Homogeneous, grey, caulking material.	Chrysotile (		Non-Fibrous Material Not Analyzed	> 75%	
Comments:	Another phase is present bu Analysis of phase b) was sto	It there was insufficient mater opped due to a previous posit re present on the surface of th	ive resu	ult.		
S0041C Wall,Expansion Joint, Caulking, Grey,Loc:27, CLASSROOM				Not Analyzed		
Comments:	Analysis was stopped due to	a previous positive result.				

**Reviewed by:** 

Digitally signed by Pinchin Ltd. Date: 2024.07.15 10:28:39-04'00'

Reporting Analyst: Digitally signed by Pinchin Ltd. Date: 2024.07.15 10:28:54-04'00'



# reid 2:50 Jul 12

# Pinchin Ltd. - Asbestos Laboratory Internal Asbestos Bulk Sample Chain of Custody

Client Name	:	102102			Project Address:	ON			
Portfolio/Bu	uilding No:	11.14	and and	1.3.3	Pinchin File:	0335495.018			
Submitted b	by:	Nicholas Ro	binson		Email:	nrobinson@	pinchin.con	m	
CC Results	to:	Alex Brett	San La se	Co. CHERRY	CC Email:	abrett@pinc	hin.com		
Date Submit	tted:	July	12	2024	Required by:	July	15	2024	
# of Sample	s:	3	and the state		Priority:	Rus	h Tumarou	nd	
Year of Buil	ding Constru	uction ( <i>Mano</i>	latory, Year	s ONLY):	1900	A DE LE		12.57	
Do NOT Sto	p on Positiv	e (Sample Ni	umbers):			W I STANK		Car a	
Pinchin Gro	up Company	(Mandatory	Field):			Pinchin	Call Alvert	3114	
HMIS2 Build	HMIS2 Building Reference #:				135959/202452871194037				
NAMES OF TAXABLE PARTY.	of the local division of the local divisiono	Personnel (	Only:	1		the second second	Charles .	TRACT	
Lab Referen	the second s	JUL 1 2 2	0.11	8378	Time:	24	hour clock		
Received by	':			uno	Date:	Month	Day	Year	
Name(s) of <i>I</i>	Analyst(s):	Al 2	4015		100 100 100 1 100 100 100 100 100 100 1	AC A DING TO A DI	1.11		
Sample Prefix	Sample No.	Sample Suffix		Samp	le Description/Lo	cation (Man	datory)		
S	0041	A	Wall,Expa	nsion Joint	,Caulking, Grey,Loc: あんりあ <i>(針の</i> )	13 CLASSRO	ом		
S	0041	В	Wall,Expa	insion Joint	Caulking, Grey, Loc:	13,CLASSRO	ОМ		
s	0041	с	Wall,Expa	insion Joint	,Caulking, Grey,Loc:	27,CLASSRO	ОМ		



Your Project #: 350929 Site Location: ON Your C.O.C. #: 1014908

**Attention: Pinchin Asbestos Lab** 

Pinchin Ltd 2360 Meadowpine Blvd Unit # 2 Mississauga, ON CANADA L5N 6S2

> Report Date: 2024/12/20 Report #: R8455001 Version: 1 - Final

### **CERTIFICATE OF ANALYSIS**

### BUREAU VERITAS JOB #: C4BM688

Received: 2024/12/16, 15:17

Sample Matrix: Solid # Samples Received: 6

		Date	Date		
Analyses	Quantity	y Extracted	Analyzed	Laboratory Method	Analytical Method
Asbestos by PLM - 0.5 RDL (1)	6	N/A	2024/12/20	) COR3SOP-00002	EPA 600R-93/116

#### Remarks:

Bureau Veritas is accredited to ISO/IEC 17025 for specific parameters on scopes of accreditation. Unless otherwise noted, procedures used by Bureau Veritas are based upon recognized Provincial, Federal or US method compendia such as CCME, EPA, APHA or the Quebec Ministry of Environment.

All work recorded herein has been done in accordance with procedures and practices ordinarily exercised by professionals in Bureau Veritas' profession using accepted testing methodologies, quality assurance and quality control procedures (except where otherwise agreed by the client and Bureau Veritas in writing). All data is in statistical control and has met quality control and method performance criteria unless otherwise noted. All method blanks are reported; unless indicated otherwise, associated sample data are not blank corrected. Where applicable, unless otherwise noted, Measurement Uncertainty has not been accounted for when stating conformity to the referenced standard.

Bureau Veritas liability is limited to the actual cost of the requested analyses, unless otherwise agreed in writing. There is no other warranty expressed or implied. Bureau Veritas has been retained to provide analysis of samples provided by the Client using the testing methodology referenced in this report. Interpretation and use of test results are the sole responsibility of the Client and are not within the scope of services provided by Bureau Veritas, unless otherwise agreed in writing. Bureau Veritas is not responsible for the accuracy or any data impacts, that result from the information provided by the customer or their agent.

Solid sample results, except biota, are based on dry weight unless otherwise indicated. Organic analyses are not recovery corrected except for isotope dilution methods.

Results relate to samples tested. When sampling is not conducted by Bureau Veritas, results relate to the supplied samples tested. This Certificate shall not be reproduced except in full, without the written approval of the laboratory.

Bureau Veritas' Asbestos Laboratory is accredited by NVLAP for bulk asbestos analysis by polarized light microscopy, NVLAP Code 600136-0.

This report may not be reproduced, except in full, without the written approval of Bureau Veritas. This report may not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any other agency of the U.S. Government.

Bureau Veritas' scope of accreditation includes EPA -- 40 CFR Appendix E to Subpart E of Part 763, "Interim Method for the Determination of Asbestos in Bulk Insulation Samples" and EPA-600/R-93/116: "Method for the Determination of Asbestos in Bulk Building Materials".

Reference Method suffix "m" indicates test methods incorporate validated modifications from specific reference methods to improve performance.

\* RPDs calculated using raw data. The rounding of final results may result in the apparent difference.

(1) P.O.B. - Percent of Bulk

#### Page 1 of 8

Bureau Veritas 6740 Campobello Road, Mississauga, Ontario, L5N 2L8 Tel: (905) 817-5700 Toll-Free: 800-563-6266 Fax: (905) 817-5777 www.bvna.com



Your Project #: 350929 Site Location: ON Your C.O.C. #: 1014908

#### **Attention: Pinchin Asbestos Lab**

Pinchin Ltd 2360 Meadowpine Blvd Unit # 2 Mississauga, ON CANADA L5N 6S2

> Report Date: 2024/12/20 Report #: R8455001 Version: 1 - Final

## **CERTIFICATE OF ANALYSIS**

#### BUREAU VERITAS JOB #: C4BM688

Received: 2024/12/16, 15:17

When Asbestos data is reported with other data, this report contains data that are not covered by the NVLAP accreditation.

**Encryption Key** 



Bureau Veritas 20 Dec 2024 16:16:56

Please direct all questions regarding this Certificate of Analysis to: Nilushi Mahathantila, Project Manager Email: Nilushi.Mahathantila@bureauveritas.com Phone# (905) 817-5700

This report has been generated and distributed using a secure automated process.

Bureau Veritas has procedures in place to guard against improper use of the electronic signature and have the required "signatories", as per ISO/IEC 17025, signing the reports. For Service Group specific validation, please refer to the Validation Signatures page if included, otherwise available by request. For Department specific Analyst/Supervisor validation names, please refer to the Test Summary section if included, otherwise available by request. This report is authorized by Rodney Major, General Manager responsible for Ontario Environmental laboratory operations.

Bureau Veritas 6740 Campobello Road, Mississauga, Ontario, L5N 2L8 Tel: (905) 817-5700 Toll-Free: 800-563-6266 Fax: (905) 817-5777 www.bvna.com



### **Asbestos Analytical Results**

EPA/600R-93/116 by Polarized Light Microscopy

Bureau Veritas ID:	AMES54	4,CUSTODIAN CLOSET			I	Date Analyzed:	2024/12/20
	P.O.B	Sample Morphology	Asbestos		Other Fibres		Particulate
Layer 1	100	Non-homogeneous white/grey paint/cementitious material	Chrysotile	1%			Non-Fibrous

S0043B,Wall,P	aint,Loc:65	,CUSTODIAN CLOSET				
Bureau Veritas ID:	AMES55				Date Analyzed:	2024/12/20
	P.O.B	Sample Morphology	Asbestos	Other Fibres		Particulate
Layer 1			N/A			
	Comment:	Not Analyzed - Positive Stop				

S0043C,Wall,P	aint,Loc:65	CUSTODIAN CLOSET				
Bureau Veritas ID:	AMES56				Date Analyzed:	2024/12/20
	P.O.B	Sample Morphology	Asbestos	Other Fibres		Particulate
Layer 1			N/A			
	Comment:	Not Analyzed - Positive Stop				

e Analyzed: 202	24/12/20
Par	ticulate
Nor	n-Fibrous
-	

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%) Date Format : yyyy/mm/dd



### **Asbestos Analytical Results**

EPA/600R-93/116 by Polarized Light Microscopy

D:				Date Analyzed:	2024/12/20
	P.O.B	Sample Morphology	Asbestos	Other Fibres	Particulate
Layer 1	100	Homogeneous brown mastic	Not Detected		Non-Fibrous

Bureau Veritas ID:	AMES59			Date Analyzed:	2024/12/20
	P.O.B	Sample Morphology	Asbestos	Other Fibres	Particulate
Layer 1	100	Homogeneous brown mastic	Not Detected		Non-Fibrous

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%) Date Format : yyyy/mm/dd



### **TEST SUMMARY**

Bureau Veritas ID: Sample ID: Matrix:	S0043A,Wall,Paint,L	oc:54,CUSTODIAN CL	OSET			Collected: Shipped: Received:	
Test Description		Instrumentation	Batch	Extracted	Date Analyzed	Analyst	
Asbestos by PLM - 0.5 RD	-	MIC 9839546 N/A Jon			Jon Delos	Santos	
Bureau Veritas ID: Sample ID: Matrix:	S0043B,Wall,Paint,L	oc:65,CUSTODIAN CLO	DSET			Collected: Shipped: Received:	2024/12/13 2024/12/16
Test Description		Instrumentation	Batch	Extracted	Date Analyzed	Analyst	
Asbestos by PLM - 0.5 RD	-	MIC	9839546	N/A		Jon Delos	Santos
Bureau Veritas ID: Sample ID: Matrix:		oc:65,CUSTODIAN CLO	DSET			Collected: Shipped: Received:	2024/12/13 2024/12/16
Test Description		Instrumentation	Batch	Extracted	Date Analyzed	Analyst	
Asbestos by PLM - 0.5 RD	_	MIC	9839546	N/A		Jon Delos	Santos
Bureau Veritas ID: Sample ID: Matrix:	S0044A,Wall,Mastic	,Loc:19,VESTIBULE				Collected: Shipped: Received:	2024/12/13 2024/12/16
Test Description		Instrumentation	Batch	Extracted	Date Analyzed	Analyst	
Asbestos by PLM - 0.5 RD	-	MIC	9839546	N/A	•	Jon Delos	Santos
Bureau Veritas ID: Sample ID: Matrix:	S0044B,Wall,Mastic	Loc:20,COAT ROOM				Collected: Shipped: Received:	2024/12/13 2024/12/16
Test Description		Instrumentation	Batch	Extracted	Date Analyzed	Analyst	
Asbestos by PLM - 0.5 RD		MIC	9839546	N/A	-	Jon Delos	Santos
Bureau Veritas ID: Sample ID: Matrix:	S0044C,Wall,Mastic	Loc:21,WASHROOM				Collected: Shipped: Received:	2024/12/13 2024/12/16
Test Description		Instrumentation	Batch	Extracted	Date Analyzed	Analyst	
Asbestos by PLM - 0.5 RD	_	MIC	9839546	N/A		Jon Delos	Santos

Microbiology testing is conducted at 6660 Campobello Rd. Chemistry testing is conducted at 6740 Campobello Rd.



## **GENERAL COMMENTS**

Results relate only to the items tested.

Bureau Veritas 6740 Campobello Road, Mississauga, Ontario, LSN 2L8 Tel: (905) 817-5700 Toll-Free: 800-563-6266 Fax: (905) 817-5777 www.bvna.com

Microbiology testing is conducted at 6660 Campobello Rd. Chemistry testing is conducted at 6740 Campobello Rd.

Page 6 of 8



### VALIDATION SIGNATURE PAGE

The analytical data and all QC contained in this report were reviewed and validated by:

Cinenti

Dina Yousif, Analyst 2

Bureau Veritas has procedures in place to guard against improper use of the electronic signature and have the required "signatories", as per ISO/IEC 17025, signing the reports. For Service Group specific validation, please refer to the Validation Signatures page if included, otherwise available by request. For Department specific Analyst/Supervisor validation names, please refer to the Test Summary section if included, otherwise available by request. This report is authorized by Rodney Major, General Manager responsible for Ontario Environmental laboratory operations.

Page 7 of 8 Bureau Veritas 6740 Campobello Road, Mississauga, Ontario, L5N 2L8 Tel: (905) 817-5700 Toll-Free: 800-563-6266 Fax: (905) 817-5777 www.bvna.com

71014908

Analyzed by

Report Sent by:\_\_\_\_\_

Radmind by:

# Pinchin Ltd. - Asbestos Laboratory Internal Asbestos Bulk Sample Chain of Custody

**Special Instructions:** 

Client Name	:			Project Address:	ON		
Portfolio/Bu	ilding No:	1-1-1-1-1-		Pinchin File:	350929		
Submitted b	v:	Nicholas Rol	binson	Email:	nrobinson@p	inchin.com	10-1
CC Results t		Cal Cathcart		CC Email:	ccathcart@p	inchin.com	
Date Submit	ted:	December	13 2024	Required by:	December	20	2024
# of Samples	s:	6	1 1 1 1 1 1 1 1 1 1	Priority:	5 Da	y Turnaroun	d
Year of Build	ting Constru	ction (Manda	atory, Years ONLY):	1960	Sector Sector		
Do NOT Stop	o on Positive	(Sample Nu	mbers):				
Pinchin Grou	up Company	(Mandatory	Field ):		Pinchin		
	ing Reference			143637/202411127	77434548	and the second second	
the second se	and the second se	Personnel O	)nly:				
Lab Referen	Contraction of the local division of the loc		THE REAL PROPERTY OF	Time:	24	hour clock	
		A CONTRACTOR OF THE OWNER		Dates	Month	Day	Yea
Received by	: :	A Second Street of Street Stre	Sector Party and a sector	Date:	A A A A A A A A A A A A A A A A A A A	of the new party of the local division of the local division of the local division of the local division of the	
Received by Name(s) of A		DEC 1	6 2024	Date:	Wicklin	Chester And	
		DEC 1 Sample Suffix		Date: ble Description/Lo		Concession of the	
Name(s) of A Sample	Analyst(s): Sample	Sample	Samj		cation (Man	Concession of the	
Name(s) of A Sample Prefix	nalyst(s): Sample No.	Sample Suffix	Samj Wall,Paint,Loc:54,C	ole Description/Lo	cation (Man	Concession of the	
Name(s) of A Sample Prefix S	Analyst(s): Sample No. 0043	Sample Suffix A	Samp Wall,Paint,Loc:54,C Wall,Paint,Loc:65,C	Die Description/Lo	cation (Man	datory)	
Name(s) of A Sample Prefix S S	Analyst(s): Sample No. 0043 0043	Sample Suffix A B	Samp Wall,Paint,Loc:54,C Wall,Paint,Loc:65,C	USTODIAN CLOSET	cation (Man	datory)	
Name(s) of A Sample Prefix S S S	Analyst(s): Sample No. 0043 0043 0043	Sample Suffix A B C	Samj Wall,Paint,Loc:54,C Wall,Paint,Loc:65,C Wall,Paint,Loc:65,C	DIE DESCRIPTION/LO USTODIAN CLOSET USTODIAN CLOSET	cation (Man	Concession of the	FNV-777

116 my POL (SVア Page 1 of 1

APPENDIX II-B Lead Analytical Certificates



**Project:** 


# Analysis for Lead Concentration in Paint Chips

by Flame Atomic Absorption Spectroscopy EPA SW-846 3050B/6010C/7000B



Customer: Pinchin Ltd. 191 Bloor Street East Oshawa, ON L1H 3M3

350929



Sample ID	Description	Mass	Reporting	Concentration	Concentration
Lab Sample ID	Lab Notes	(g)	Limit (ppm)	(ppm)	(% by weight)
L0009	Wall, Masonry, White Paint,Loc:54,CUSTODIAN CLOSET	0.1130	35	830	0.083%
10070949_0001					

Disclaimer: Unless otherwise noted blank sample correction was not performed on analytical results. Scientific Analytical Institute participates in the AIHA ELPAT program. ELPAT Laboratory ID: 173190. This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAI. Analytical uncertainty available upon request. The quality control samples run with the samples in this report have passed all EPA required specifications unless otherwise noted. RL: (Report Limit for an undiluted 50ml sample is 4µg Total Pb). All sample dried before preparation and analysis.

L-F-021 r17 2/13/2027

Mark Doki (1)

Analyst Approved Signatory Scientific Analytical Institute, Inc. 4604 Dundas Dr. Greensboro, NC 27407 (336) 292-3888

10070949

Client:	Pinchin Ltd.	*Instructions:	Version 1-15-20
Contact:	Nicholas Robinson	Use Column "B" for your contact info	
Address:	191 Bloor St E, Oshawa, ON, L1H	3M3	
Phone:	365.822.1361	To See an Example Click the	
Fax:		bottom Example Tab.	
Email:	nrobinson@pinchin.com		
	ccathcart@pinchin.com		
	1	1	
Project:	35092	Begin Samples with a "<< "above the first sample	Scientific
		and end with a ">>" below the last sample.	Analytical
Client Notes:		Only Enter your data on the first sheet "Sheet1"	Institute
P.O. #.	350929.000	Note: Data 1 and Data 2 are optional	4604 Dundas Dr.
Date Submitted:	12-13-2024	fields that do not show up on the official	Greensboro, NC 27407
		report, however they will be included	Phone: 336.292.3888
Analysis:	Paint Chips Flame AA	in the electronic data returned to you	Fax: 336.292.3313
TurnAroundTime:	Regular 5 Day TAT	to facilitate your reintegration of the report data.	Email: lab@sailab.com

<<

L0009

>>

Wall, Masonry, White Paint, Loc: 54, CUSTODIAN CLOSET

J92 12:17 10:20 am

Accepted V

Rejected



Your Project #: 335495.018 Your C.O.C. #: n/a

#### **Attention: Rachel Northey**

Pinchin Ltd 160 Charlotte Street Suite 204 Peterborough, ON CANADA K9J 2T8

> Report Date: 2024/01/11 Report #: R7985886 Version: 1 - Final

### **CERTIFICATE OF ANALYSIS**

#### BUREAU VERITAS JOB #: C407677

Received: 2024/01/09, 09:10

Sample Matrix: Bulk # Samples Received: 6

	Date	Date		
Analyses	Quantity Extracted	Analyzed	Laboratory Method	Analytical Method
Metals in Paint	6 2024/01/1	.1 2024/01/1	1 CAM SOP-00408	EPA 6010D m

#### Remarks:

Bureau Veritas is accredited to ISO/IEC 17025 for specific parameters on scopes of accreditation. Unless otherwise noted, procedures used by Bureau Veritas are based upon recognized Provincial, Federal or US method compendia such as CCME, MELCCFP, EPA, APHA.

All work recorded herein has been done in accordance with procedures and practices ordinarily exercised by professionals in Bureau Veritas' profession using accepted testing methodologies, quality assurance and quality control procedures (except where otherwise agreed by the client and Bureau Veritas in writing). All data is in statistical control and has met quality control and method performance criteria unless otherwise noted. All method blanks are reported; unless indicated otherwise, associated sample data are not blank corrected. Where applicable, unless otherwise noted, Measurement Uncertainty has not been accounted for when stating conformity to the referenced standard.

Bureau Veritas liability is limited to the actual cost of the requested analyses, unless otherwise agreed in writing. There is no other warranty expressed or implied. Bureau Veritas has been retained to provide analysis of samples provided by the Client using the testing methodology referenced in this report. Interpretation and use of test results are the sole responsibility of the Client and are not within the scope of services provided by Bureau Veritas, unless otherwise agreed in writing. Bureau Veritas is not responsible for the accuracy or any data impacts, that result from the information provided by the customer or their agent.

Solid sample results, except biota, are based on dry weight unless otherwise indicated. Organic analyses are not recovery corrected except for isotope dilution methods.

Results relate to samples tested. When sampling is not conducted by Bureau Veritas, results relate to the supplied samples tested.

This Certificate shall not be reproduced except in full, without the written approval of the laboratory.

Reference Method suffix "m" indicates test methods incorporate validated modifications from specific reference methods to improve performance.

\* RPDs calculated using raw data. The rounding of final results may result in the apparent difference.



Your Project #: 335495.018 Your C.O.C. #: n/a

#### **Attention: Rachel Northey**

Pinchin Ltd 160 Charlotte Street Suite 204 Peterborough, ON CANADA K9J 2T8

> Report Date: 2024/01/11 Report #: R7985886 Version: 1 - Final

### **CERTIFICATE OF ANALYSIS**

BUREAU VERITAS JOB #: C407677 Received: 2024/01/09, 09:10

Encryption Key

Please direct all questions regarding this Certificate of Analysis to: Nilushi Mahathantila, Project Manager Email: Nilushi.Mahathantila@bureauveritas.com Phone# (905) 817-5700

This report has been generated and distributed using a secure automated process.

Bureau Veritas has procedures in place to guard against improper use of the electronic signature and have the required "signatories", as per ISO/IEC 17025, signing the reports. For Service Group specific validation, please refer to the Validation Signatures page if included, otherwise available by request. For Department specific Analyst/Supervisor validation names, please refer to the Test Summary section if included, otherwise available by request. This report is authorized by Rodney Major, General Manager responsible for Ontario Environmental laboratory operations.

> Total Cover Pages : 2 Page 2 of 8 Bureau Veritas 6740 Campobello Road, Mississauga, Ontario, L5N 2L8 Tel: (905) 817-5700 Toll-Free: 800-563-6266 Fax: (905) 817-5777 www.bvna.com



### **ELEMENTS BY ATOMIC SPECTROSCOPY (BULK)**

Bureau Veritas ID		YBN409			YBN410		
Sampling Date			ĺ				
COC Number		n/a	ĺ		n/a		
	UNITS	L0003, BROWN PAINT ON WINDOW LINTEL 1926,LOC:71,EXTERIO R		QC Batch	L0004, BLUE WOOEN WINDOW FRAME,LOC:9,CLASSR OOM	RDL	QC Batch
Metals							
Lead (Pb)	%	0.0044	0.00036	9155693	0.12	0.00019	9156160
RDL = Reportable Detection L	imit						

QC Batch = Quality Control Batch

Bureau Veritas ID		YBN411			YBN412		
Sampling Date							
COC Number		n/a			n/a		
	UNITS	L0005, BEIGE MASONRY BLOCK PAINT,LOC:13,CLASSR OOM	RDL	QC Batch	L0006, BLUE WOODEN DOORS,LOC:14,CUSTO DIAN ROOM	RDL	QC Batch
Metals							
Lead (Pb)	%	0.052	0.00042	9156160	0.045	0.00064	9155693
RDL = Reportable Detection L	imit						

QC Batch = Quality Control Batch

Bureau Veritas ID		YBN413		YBN414		
Sampling Date						
COC Number		n/a		n/a		
	UNITS	L0007, BEIGE PAINT ON DRYWALL WALLS,LOC:15,CORRI DOR	RDL	L0008, BEIGE PAINT ON WOODEN SHELVES,LOC:15,CORR IDOR	RDL	QC Batch
Metals						
Lead (Pb)	%	0.0057	0.00076	0.028	0.0015	9155693
RDL = Reportable Detection L QC Batch = Quality Control Ba		·				



### **TEST SUMMARY**

Bureau Veritas ID: Sample ID: Matrix:		Collected: Shipped: Received:	2024/01/09				
Test Description		Instrumentation	Batch	Extracted	Date Analyzed	Analyst	
Metals in Paint		ICP	9155693	2024/01/11	2024/01/11	Japneet Gill	
Bureau Veritas ID: Sample ID: Matrix:	Sample ID: L0004, BLUE WOOEN WINDOW FRAME,LOC:9,CLASSROOM						2024/01/09
Test Description		Instrumentation	Batch	Extracted	Date Analyzed	Analyst	
Metals in Paint		ICP	9156160	2024/01/11	2024/01/11	Indira Harry	/Paul
Bureau Veritas ID: Sample ID: Matrix:	YBN411 L0005, BEIGE MAS Bulk	ONRY BLOCK PAINT,L	OC:13,CLASSRO	МОС		Collected: Shipped: Received:	2024/01/09
Test Description		Instrumentation	Batch	Extracted	Date Analyzed	Analyst	
Metals in Paint		ICP	9156160	2024/01/11	2024/01/11	Indira Harry	/Paul
Bureau Veritas ID: Sample ID: Matrix:	YBN412 L0006, BLUE WOO Bulk	DEN DOORS,LOC:14,C	USTODIAN RO	ЮМ		Collected: Shipped: Received:	2024/01/09
Test Description		Instrumentation	Batch	Extracted	Date Analyzed	Analyst	
Metals in Paint		ICP	9155693	2024/01/11	2024/01/11	Japneet Gil	
Bureau Veritas ID: Sample ID: Matrix:	-	T ON DRYWALL WALL	S,LOC:15,COR	RIDOR		Collected: Shipped: Received:	2024/01/09
Test Description		Instrumentation	Batch	Extracted	Date Analyzed	Analyst	
Metals in Paint		ICP	9155693	2024/01/11	2024/01/11	Japneet Gil	
Bureau Veritas ID:	Collected: Shipped:						
Sample ID: Matrix:	L0008, BEIGE PAIN Bulk	T ON WOODEN SHELV	ves,loc.15,co			Received:	2024/01/09
•	,	T ON WOODEN SHELV	Batch	Extracted	Date Analyzed	Received: Analyst	2024/01/09

Page 4 of 8 Bureau Veritas 6740 Campobello Road, Mississauga, Ontario, LSN 2L8 Tel: (905) 817-5700 Toll-Free: 800-563-6266 Fax: (905) 817-5777 www.bvna.com



### **GENERAL COMMENTS**

Metal Analysis: Due to limited amount of sample available for analysis, a smaller than usual portion of the sample was used. Detection limits were adjusted accordingly.

Sample YBN410 [L0004, BLUE WOOEN WINDOW FRAME,LOC:9,CLASSROOM] : Metals Analysis: Due to limited amount of sample available for analysis, a smaller than usual portion of the sample was used. Detection limits were adjusted accordingly.

Sample YBN411 [L0005, BEIGE MASONRY BLOCK PAINT,LOC:13,CLASSROOM] : Metals Analysis: Due to limited amount of sample available for analysis, a smaller than usual portion of the sample was used. Detection limits were adjusted accordingly.

#### Results relate only to the items tested.



#### **QUALITY ASSURANCE REPORT**

QA/QC								
Batch	Init	QC Type	Parameter	Date Analyzed	Value	Recovery	UNITS	QC Limits
9155693	JGC	Matrix Spike	Lead (Pb)	2024/01/11		NC	%	75 - 125
9155693	JGC	QC Standard	Lead (Pb)	2024/01/11		100	%	75 - 125
9155693	JGC	Method Blank	Lead (Pb)	2024/01/11	<0.00010		%	
9155693	JGC	RPD	Lead (Pb)	2024/01/11	26		%	35
9156160	IHP	Matrix Spike	Lead (Pb)	2024/01/11		NC	%	75 - 125
9156160	IHP	QC Standard	Lead (Pb)	2024/01/11		99	%	75 - 125
9156160	IHP	Method Blank	Lead (Pb)	2024/01/11	<0.00010		%	
9156160	IHP	RPD	Lead (Pb)	2024/01/11	1.5		%	35

Duplicate: Paired analysis of a separate portion of the same sample. Used to evaluate the variance in the measurement.

Matrix Spike: A sample to which a known amount of the analyte of interest has been added. Used to evaluate sample matrix interference.

QC Standard: A sample of known concentration prepared by an external agency under stringent conditions. Used as an independent check of method accuracy.

Method Blank: A blank matrix containing all reagents used in the analytical procedure. Used to identify laboratory contamination.

NC (Matrix Spike): The recovery in the matrix spike was not calculated. The relative difference between the concentration in the parent sample and the spike amount was too small to permit a reliable recovery calculation (matrix spike concentration was less than the native sample concentration)



### VALIDATION SIGNATURE PAGE

The analytical data and all QC contained in this report were reviewed and validated by:

austin Camere

Cristina Carriere, Senior Scientific Specialist

Bureau Veritas has procedures in place to guard against improper use of the electronic signature and have the required "signatories", as per ISO/IEC 17025, signing the reports. For Service Group specific validation, please refer to the Validation Signatures page if included, otherwise available by request. For Department specific Analyst/Supervisor validation names, please refer to the Test Summary section if included, otherwise available by request. This report is authorized by Rodney Major, General Manager responsible for Ontario Environmental laboratory operations.

	/it	宮	2.	<u>à</u> .	
1	9	33	а	3	
- 3	E.	14	3	7	
	13	с:	۲.	/	
1	1	Ŗ	3./	0	2
80	212	x	æ	57	ε.

#### 6740 Campobello Road, Mississauga, Ontario LSN 218 Phone: 905-817-5700 Fax: 905-817-5779 Toll Free: 800-563-6266

CAM PCD-01191/5

	Invoice Information		Rep	ort information (	if diff	ers fre	om im	volce	1	-		1	Proi	ect inf	format	tion (w	here a	oplicat	(ele	T	-	Turnarow	Page 1 of 1 nd Time (TAT) Required
Company Name	Pinchin Ltd.	Comp	Report Information (If differs from invoice) Project Information (where applicable) mpany Name: Quotation II:							X Regular TAT (5-7 days) Most analyses													
Contact Name:	Bryan Guindon	Contac	1 Name:	Rachel Northey					1			P.O. #/A									LEASE	ROVIDE AD	VANCE NOTICE FOR BUSH PROJECT
Address:		Addres	IS;								Ĩ	Project #		-				33549	5.018		R	ush TAT (S	urcharges will be applied)
	2 dian all all a	100							1			Site Loca	tion:		Ennis	killen					1	Day	2 Days 3-4 Days
Phone:	Fax.	Phone				Fax:		1.			1	Site #:									_	-	
Email: bgundont	@pinchin.com	Email:	ш	orthey@pind	chin.	com						Site Loca	tion (	Provin	cet	0	N			De	te Req	uired:	CONTRACTOR OF MAN
MOR NEOLEATED DH	INANG WATER OR WATER INTENDED FOR HUM	AN CONSUMPTION MUST	NE BLOWTIES	ON THE BUREAU VER	tiato	etectio	i RATI	in de	enor		0×	Sampled	Br		Bryar	Guind	-			-	ish Con	firmation i	
	Regulation 153	Othe	r Regulation	5			-				-	Analysis	-	ested	-	A CONTRACTOR		-	-			LABO	RATORY USE ONLY
teres 1	hand hand h		Sanitary Se										Г	Г			Т					ODY SEAL	
	Lond Lond L	JARSA C	Storm Sew Region	er Bylaw		-						100								H	Y	/ N Intact	COOLER TEMPERATURES
Table			Other (Specify)														Ľ	1000					
FOR RSC (PLEA	ASE CIRCLE) Y / N	REG SSR (MIN. )	DAY TAT REC	WIRED)	1	whi / H				5		1						H			H	H	
	i i i i i i i i i i i i i i i i i i i	REG 406 Tabl		10 10 1	ATTEL	Met				<b>NGAN</b>		C. HW					1			. [			THE OV R
nclude Criteria on i	Certificate of Analysis: Y / M		10.000	A	Study 1	DICLE				6110	ELALS	Metal								-	-	-	
AMPLES MUST BE	KEPT COOL ( < 10 °C ) FROM TIME OF	SAMPLING UNTIL D	ELIVERY TO I	UREAU VERITAS	UNER	NED (C				CTALS	IN SWI	CTALS OTMS	Paint				I.	H		NUL			
	AMPLE IDENTIFICATION	DATE SAMPLED	TIME	MATRO	CONT	Partie	SH.	1-12		53 MI	13410	SS MI	101					Ħ		8 00	OLINGN	HEDIA PRESI	NTI Y / (H)
		(VYYY/MM/DD)	(HHHMM)	MATHIA	101	FRIT	BTEK	ST.	NOC.	NEG	10314	Pre.	1	PCB.						1004	2	- X	COMMENTS
0003, Brown Paint	On Window Lintel 1926,Loc.71,EXTERN	0		BULK									x							1			
0004, Blue Wooen	Window Frame.Loc.9.CLASSROOM			BULK									x									09-1	an-24 09:10
0005, Beige Mason	ary Block Paint.Loc: 13,CLASSROOM			BULK									x							<b>n</b> i	Anto	mella 1	an-24 09:10 Brasil 
0006, Blue Wooder	n Doors,Loc:14,CUSTODIAN ROOM		-	BULK									x								C	4076	77
0007, Beige Paint C	On Drywall Walls.Loc:15,CORRIDOR			BULK									x							UR	E		V-580
0008, Beige Paint O	On Wooden Shelves.Loc:15.CORRIDOR			BULK									x										
ILUNQUISHED BY: CHE	mature/Print) DA	TE (YYYY/MM/DD)	TIME PHEM	M) RECEIVED BY	r: (Sign	ature/	Print)						DATE	m	/MM/0	(0)	TIM	D (HH)	AM)	ev:	06#		
Bryan Guindon		2024-01-06		91	-		50	. CA	m	s.	+u	(April	74	24	101	100	0	1:	10				

CULANI OF CUCTORY OF

Unless otherwise agreed to in writing, work submitted on this Chain of Custody is subject to Bureau Veritas' standard Terms and Conditions. Signing of this Chain of Custody document is acknowledgment and acceptance of our terms available at https://www.bvna.com/coc-terms-and-conditions

APPENDIX II-C PCB Analytical Certificates





Date of Issue: Jan 16, 2024

# **Certificate of Analysis**

Bryan Guindon

Pinchin Ltd. (Peterborough - Charlotte St.) 204-160 Charlotte Street, Peterborough, ON K9J 2T8

Report Description: 3 solid samples were submitted for the following chemical analysis

Project Name:	Enniskillen	Date Sampled:	Jan 06, 2024
Project No.:	335495.018	Date Tested:	Jan 15, 2024
Site Location:		Sampled by:	

	Report Number: 24-0034											
No.	Analyte	Result	Units	MDL	Comments	Technique / Test Method						
<u>1</u>	Sample ID.: P001, Exterior dark brown	window caulkir	ng Loc 71, 1	926 yoc								
	PCBs in Solid	<0.2	mg/kg	0.2		LAB-M06 (EPA 3550C/8082A modified)						
<u>2</u>	Sample ID.: P002, Soft brown upper wi	ndow frame ca	ulking Loc, 7	71								
	PCBs in Solid	<0.2	mg/kg	0.2		LAB-M06 (EPA 3550C/8082A modified)						
<u>3</u>	Sample ID.: P003, Interior door and she	elf frame caulki	ng, Loc, 16									
	PCBs in Solid	<0.2	mg/kg	0.2		LAB-M06 (EPA 3550C/8082A modified)						

Results apply to the sample as received.

Approved By:

Son C.H. Le, (Chem.) Lab Manager Phone: (519) 740-1333 Ext.: 1030 Fax: (519) 740-2320 Email: SonLe@aevitas.ca

The Analytical Chemistry Laboratory of Aevitas Inc. (Ayr) is accredited for specific tests in accordance with the recognized International Standard ISO/IEC 17025:2017, by the Canadian Association for Laboratory Accreditation (CALA) Inc. This accreditation demonstrates technical competence for a defined scope and the operation of a laboratory quality management system (refer to joint ISO-ILAC-IAF Communiqué dated April 2017). The laboratory quality management system of Aevitas Inc. (Ayr) also operates in accordance with the principles of ISO 9001.

All Analytical data is subject to uncertainty which, may vary with sample matrices, sample preparation techniques and instrumental parameters. As a general guideline, uncertainty may be expressed as approximately +/- 50% of the reported value at or near the Method Detection Limit (MDL) and +/-10% or less, of the reported result that is greater than 10 times the MDL. Method Detection Limits are defined as approximately 3 times the standard deviation value (at 99% confidence level), which is obtained from replicate analysis of a low-level standard as per the Ontario MOE - MISA Protocol for the Sampling and Analysis of Industrial / Municipal Wastewater (2016). MDL determination is based on undiluted samples with relatively low matrix interferences. Where dilutions are required, the reported MDL value will be scaled proportionally.

All testing procedures follow strict guidelines and quality assurance / quality control (QA/QC) protocols. QA/QC data is available for review at any time upon client's request.

APPENDIX III Methodology



### 1.0 GENERAL

An investigation was conducted to identify the type of Hazardous Building Materials incorporated in the structure and its finishes.

Information regarding the location and condition of hazardous building materials encountered and visually estimated quantities were recorded. The locations of any samples collected were recorded on small-scale plans. As-built drawings and previous reports were referenced where provided.

Sample collection was conducted in accordance with our Standard Operating Procedures.

### 1.1 Asbestos

The investigation for asbestos included friable and non-friable asbestos-containing materials (ACM). A friable material is a material that when dry can be crumbled, pulverized or powdered by hand pressure, or a material that has already become crushed, pulverized, or powdered.

A separate set of samples was collected of each type of homogenous material suspected to contain asbestos. A homogenous material is defined by the US EPA as material that is uniform in texture and appearance, was installed at one time, and is unlikely to consist of more than one type or formulation of material. The homogeneous materials were determined by visual examination and available information on the phases of construction and prior renovations.

Samples were collected at a rate that is in compliance with the requirements of local regulations and guidelines. The sampling strategy was also based on known ban dates and phase out dates of the use of asbestos; sampling of certain building materials is not conducted after specific construction dates. In addition, to be conservative, several years past these dates are added to account for some uncertainty in the exact start / finish date of construction and associated usage of ACM. In some cases, manufactured products such as asbestos cement pipe were visually identified without sample confirmation.

The asbestos analysis of select materials was completed using a stop-positive approach. Only one result meeting the regulated criteria was required to determine that a material is asbestos containing, but all samples must be analyzed to conclusively determine that a material is non-asbestos. The laboratory stopped analyzing samples from a homogeneous material once a result equal to or greater than the regulated criteria is detected in any of the samples of that material. All samples of a homogeneous material were analyzed if no asbestos is detected. In some cases, all samples were analyzed in the sample set regardless of result.

The analysis was performed in accordance with Test Method EPA/600/R-93/116: Method for the Determination of Asbestos in Bulk Building Materials, July 1993.



Analytical results were compared to the following criteria:

Jurisdiction*	Friable	Non-Friable
Ontario	0.5%	0.5%
Federal	1%	1%

\* If there is a conflict between federal and provincial criteria, the more stringent will apply.

Where building materials are described in the report as "non-asbestos" or "does not contain asbestos", this means that either no asbestos was detected by the analytical method utilized in any of the multiple samples or, if detected, it is below the lower limit of an asbestos-containing material in the applicable regulation. Additionally, these terms are used for materials which historically are known to not include asbestos in their manufacturing.

Asbestos materials were evaluated in order to make recommendations regarding any remedial work. The priority for remedial action was based on several factors:

- Friability (friable or non-friable)
- Condition (good, fair, poor, debris)
- Accessibility (ranking from accessible to all building users to inaccessible)
- Visibility (whether the material is obscured by other building components)
- Efficiency of the work (for example, if damaged ACM is being removed in an area, it may be most practical to remove all ACM in the area even if it is in good condition)

### 1.2 Lead

Samples of distinctive paint finishes, and surface coatings present in more than a limited application, where removal of the paint is possible were collected. The samples were collected by scraping the painted finish to include base and covering applications.

Analysis for lead in paints or surface coatings was performed in accordance with EPA Method No. 3050B/Method No. 7420; flame atomic absorption and EPA Method No. 601D; Inductively Couple Plasma – Atomic Emission Spectrometry.

Analytical results were compared to the following criteria:

Jurisdiction*	Units (%)	Units (ppm) / (mg/kg)
Ontario	0.009	90
Federal	0.009	90

\* If there is a conflict between federal and provincial criteria, the more stringent will apply.

Other lead building products (e.g. batteries, lead sheeting, flashing) were identified by visual observation only.

Pinchin reviewed the bulk samples results for elevated concentrations of lead. Where elevated concentrations are present, paint samples including the substrate (e.g., wood, concrete, plaster) were submitted for waste characterization analysis following CGSB 164-GP-IMP.

## 1.3 Silica

Building materials known to contain crystalline silica (e.g. concrete, cement, tile, brick, masonry, mortar) were identified by visual inspection only. Pinchin did not perform sampling of these materials for laboratory analysis of crystalline silica content.

### 1.4 Mercury

Building materials, products or equipment (e.g. thermostats, barometers, pressure gauges, lamp tubes), suspected to contain mercury were identified by visual inspection only. Dismantling of equipment suspected of containing mercury was not performed. Sampling of these materials for laboratory analysis of mercury content was not performed.

### 1.5 Polychlorinated Biphenyls

The potential for light ballast and oil filled transformers to contain PCBs was based on the age of the building, a review of maintenance records, and examination of labels or nameplates on equipment, where present and accessible. The information was compared to known ban dates of PCBs and Environment Canada publications.

### 1.6 Visible Mould

The presence of mould or water damage was determined by visual inspection of exposed building surfaces. If any mould growth or water damage was concealed within building cavities it was not addressed in this assessment.

Template: Methodology for Hazardous Building Materials Assessment, HAZ, November 13 2024

APPENDIX IV Location Summary Report



Survey Date:

Building Phases: A: 1926



#### Client:Kawartha Pine Ridge District School Board Building Name: Enniskillen

#### Site: 8145 Old Scugog Road, Enniskillen, ON

Last Re-Assessment: 2024-12-13

Location No.	Name or Description	Area ft <sup>2</sup>	Floor No.	Bldg. Phase	Notes
9	CLASSROOM, room no. 2	900	1	А	Attic access. Limited assessment of attic in 2015
10	CLASSROOM, room no. 1	900	1	А	
13	CLASSROOM, room no. 06	800	1	А	
18	CLASSROOM, room no. 144	800	1	А	
19	VESTIBULE, room no. 151	200	1	А	
20	COAT ROOM, room no. 147	275	1	А	
21	WASHROOM, room no. 152	50	1	А	
25	CORRIDOR, room no. 150	5165	1	А	HMIS sticker at location 43 door
27	CLASSROOM, room no. 7	800	1	А	
28	CLASSROOM, room no. 143	800	1	А	
30	CLASSROOM, room no. 114D	800	1	А	
31	CLASSROOM, room no. 114C	800	1	А	
32	CLASSROOM, room no. 114B	800	1	А	
33	CLASSROOM, room no. 114A	800	1	А	
53	GIRLS WASHROOM, room no. 106	200	1	A	
54	CUSTODIAN CLOSET	20	1	A	
64	BOYS WASHROOM, room no. 105	150	1	A	
65	CUSTODIAN CLOSET	40	1	А	

APPENDIX V Hazardous Materials Summary Report / Sample Log





Board	rtha Pine Ridge Di	Site: 8145 Old Scugog Road, En	niskillen, ON Building Name: Enniskillen						Survey Date:		
HAZMAT	Sample No	System/Component/Material/Sample Description	Locations	Bldg. Phase	LF	SF	EA	%	Туре	Positive	Friability
Asbestos	V0002	Ceiling, Wall     Plaster   Plaster, Wall, Loc. 1	9,10	A	0	3600	0	0	Chrysotile	Yes	PF
Asbestos	V0003	Piping   Hot Water Heating   Parging Cement   Parging Cement, Loc. 1	25,54,65	А	0	0	21	0	Chrysotile	Yes	F
Asbestos	V0004	Ceiling, Wall   Bulkhead   Drywall And Joint Compound   Drywall Joint Compound, Wall, Loc. 15	18,25,28,32	А	0	552	0	0	Chrysotile	Yes	NF
Asbestos	S0006	Floor    Vinyl Floor Tile And Mastic   Vft 12x12 Off White With Gray Spots, Loc. 9	9,10,13,18,19,20,21,25,27,30,31,32,33,64	А	0	5735	0	0	None Detected	No	
Asbestos	V0020	Other   Window   Caulking   Soft Brown Vertical And Upper Window Caulking	9,10	А	280	0	0	0	None Detected	No	
Asbestos	S0021 ABCDEFG	Wall     Paint   Beige Painted Exterior Masonry Block Wall 1968 Yoc	13,18,20,27,28	А	0	2720	0	0	None Detected	No	
Asbestos	S0022 BC	Other   Sink   Mastic, Grey   Grey Sink Mastic	18,27,28,31,32,33	А	0	0	6	0	None Detected	No	
Asbestos	S0023 AC	Wall   Base   Adhesive/mastic   Black Vinyl Trim Adhesive	13,18,27,28	А	290	0	0	0	None Detected	No	
Asbestos	S0024 D	Wall, Other, Wall    Paint   Interior Masonry Block Wall Paint	18,19,20,21,25	А	0	3200	0	0	None Detected	No	
Asbestos	S0025 BC	Other   Window   Caulking   Brown Window Frame Caulking 2002 Date Stamp	18,20,30,31,32,33	А	320	0	0	0	None Detected	No	
Asbestos	S0027 ABC	Floor    Adhesive/mastic   Carpet Adhesive Burgundy Brown Streak Carpet Adhesive	25,27,30,31	А	0	5375	0	0	Chrysotile	No	
Asbestos	S0029 ABEF	Wall    Paint   Exterior Masonry Brick Paint On Masonry	30,31,32,33	А	0	1620	0	0	Chrysotile	Yes	NF
Asbestos	S0031 BCE	Wall     Paint   Interior Block Wall Paint	53,64	А	0	560	0	0	Chrysotile	Yes	NF
Asbestos	S0032	Wall     Adhesive/mastic   Brown Adhesive Black Vinyl Trim	64	А	40	0	0	0	Chrysotile	Yes	NF
Asbestos	S0035 ABC	Wall    Caulking   Black Caulking Around Windows Frames	13	А	40	0	0	0	None Detected	No	
Asbestos	S0036 C	Other   Door   Caulking   White Caulking On Door Frame	53,64	А	34	0	0	0	None Detected	No	
Asbestos	S0038 C	Other   Bulletin Board   Adhesive/mastic   Brown Mastic Adhesive On Wall For Tackboards	18,27,33	А	0	0	25	0	Chrysotile	No	
Asbestos	V0039	Floor    Terrazzo   Terrazzo In The 1968 Phase	25	А	0	1100	0	0	None Detected	No	
Asbestos	S0041 C	Wall   Expansion Joint   Caulking, Grey   Grey Expansion Joint Caulking	27,30,31	А	30	0	0	0	Chrysotile	Yes	NF
Asbestos	S0042 ABC	Floor     Concrete (poured)   Concrete Slab	13	А	0	800	0	0	None Detected	No	
Asbestos	S0043 ABC	Wall     Paint	54,65	А	0	100	0	0	Chrysotile	Yes	NF
Asbestos	S0044 ABC	Wall     Mastic	18,19,20,21	А	0	80	0	0	None Detected	No	
Asbestos	V9000	Piping     Cement Product	30	A	0	0	0	100	Confirmed	Yes	NF

Quantities shown above are based on visual approximations only and may be subject to variation. Copyright Pinchin Ltd. 2025





HAZMAT	Sample No	System/Component/Material/Sample Description	Locations	Bldg. Phase	LF	SF	EA	%	Туре	Positive	Friability
									Asbestos		
Asbestos	V9000	Wall    Cement Product	28	А	0	10	0	0	Confirmed Asbestos	Yes	NF
Asbestos	V9500	Floor     Mastic   Original Mastic	32,33	А	0	1600	0	0	Presumed Asbestos	Yes	NF
Asbestos	V9500	Other   Blackboard   Adhesive/mastic   Mastic Behind Tackboards	9,10	А	0	0	10	0	Presumed Asbestos	Yes	NF
Asbestos	V0000	Ceiling     Ceiling Tiles (lay-in)	27,28,30,31,32,33,53,64	А	0	4362	0	0	Non Asbestos	No	
Asbestos	V0000	Ceiling     Ceiling Tiles (lay-in)   2ft By 4ft Pinhole And Fissure	25	А	0	300	0	0	Non Asbestos	No	
Asbestos	V0000	Floor     Carpet	25	A	0	3300	0	0	Non Asbestos	No	
Asbestos	V0000	Floor     Thin-set	53,54,64,65	А	0	410	0	0	Non Asbestos	No	
Asbestos	V0000	Floor     Vinyl Floor Tile And Mastic   12 X 12 Blue Splotches	54,65	А	0	20	0	0	Non Asbestos	No	
Asbestos	V0000	Other   Bulletin Board   Particle Board	30,31	A	0	0	12	0	Non Asbestos	No	
Asbestos	V0000	Other   Blackboard   Wood	13,27,30,31	Α	0	0	16	0	Non Asbestos	No	
Asbestos	V0000	Piping   Hot Water Heating, All   Fibreglass	28,33,54,65	А	0	0	0	0	Non Asbestos	No	
Asbestos	V0000	Wall   Door Frame   Caulking	30,31	Α	200	0	0	0	Non Asbestos	No	
Asbestos	V0000	Wall     Vermiculite Investigation	9,10,28,33	А	0	0	8	0	Non Asbestos	No	
Paint	L0004	Other   Wood   Blue Wooden Window Frame	9,10	A	0	380	0	0	Lead (High)	Yes	-
Paint	L0005	Structure   Masonry   Beige Masonry Block Paint	13,18,19,20,21,25,27,28,30,31,32,33,53,64	A	0	8200	0	0	Lead (Low)	Yes	-
Paint	V0006	Other   Wood   Blue Wooden Doors	18,28	Α	0	68	0	0	Lead (Low)	Yes	-
Paint	V0007	Wall   Drywall And Joint Compound   Beige Paint On Drywall	25,27,28,30,32	А	0	810	0	0		No	-
Paint	L0009	Wall   Masonry   White Paint	54,65	А	0	100	0	0	Lead (Low)	Yes	-
Paint	V9500	Mechanical Equipment   Metal   Blue metal radiator covers, Blue metal radiator covers, Blue rad enclosures, Blue radiator enclosures	13,18,27,28,30,31,32,33,53,64	А	0	1210	0	0	Presumed Lead	Yes	-
Paint	V9500	Other   Metal   Blue metal door frames, blue painted metal door frames, blue metal door frame.	18,21,25,27	А	0	0	11	0	Presumed Lead	Yes	-
Paint	V9500	Other   Plaster   White plaster asbestos-containing wall, presumed with lead paint.	9,10	А	0	1800	0	0	Presumed Lead	Yes	-
Paint	V9500	Structure   Steel   Red primer paint joists and beams, Primer on joists, Red primer joists and beams, Primer paint on beams and joists, Primer paint on joists and beam, red primer paint on joists., red primer paint on structural steel joists., red primer on joists, red primer paint on steel joist., red primer steel, red primer steel joist, red primer steel joists	13,18,19,20,21,25,27,28,30,31,32,33,53,64	A	0	12440	0	0	Presumed Lead	Yes	-
PCB	V0001	Caulking   1926 Brown Bottom Window Caulking	9,10	A	200	0	0	0	-	No	-





HAZMAT	Sample No	System/Component/Material/Sample Description	Locations	Bldg. Phase	LF	SF	EA	%	Туре	Positive	Friability
PCB	V0002	Caulking   1926 Brown Upper Window Caulking	9,10	А	80	0	0	0	-	No	-
РСВ	V9500	Light Ballasts	13,25	А	0	0	59	0	Presumed PCB	Yes	-
PCB	V0000	Caulking	13,18,20,28,30,31,32,33	А	240	0	0	0	-	No	-
Hg	V9000	Light Fixture	9,10,13,18,19,20,21,25,27,28,30,31,32,33,53 64	А	0	0	464	0	Hg	Yes	-





# Legend:

#### Sample number

- S#### Asbestos sample collected
- L#### Paint sample collected
- P#### PCB sample collected
- M#### Mould sample collected
- V#### Material visually similar to numbered sample collected
- V0000 Known non Hazardous Material

V9000 Material is visually identified as Hazardous Material

V9500 Material is presumed to be Hazardous Material

[Loc. No.] Abated Material

#### Units SF

LF

%

Square feet Linear feet EA Each

Percentage

NF Non Friable material.

F Friable material

PF Potentially Friable material

APPENDIX VI All Data Report





	9 : CLASSRO e: 2024-12-12	OM Floor:	1							ent: 2024-12	-13		Area (sqft): 900			
System	Component	Material	Item	Covering	A*	V*	AS AP*	BESTOS Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friabl
System Ceiling	Component	Plaster	Surface	Covering	C	Y	AF	900	Faii	P001	SF	V0002	Chrysotile	0.5-5%	Confirmed	PF
Duct		None Found														
Floor		Wood														
Floor		Vinyl Floor Tile and Mastic	Surface		А	Y		900			SF	S0006	None Detected	N.D.	None	
Mechanical Equipment		None Found														
Other	Blackboard	Adhesive/mastic, Mastic behind tackboards			A	N		5			EA	V9500	Presumed Asbestos		Presumed Asbestos	NF
Other	Window	Caulking, Soft brown interior window caulking			А	Y		140			LF	V0020	None Detected	N.D.	None	
Piping		None Found														
Structure	Not Accessible	N/A														
Wall		Plaster	Surface	Wood	A	Y		900			SF	V0002	Chrysotile	0.5-5%	Confirmed Asbestos	PF
Wall <sup>1</sup>		Vermiculite Investigation			D	Ν		2			EA	V0000	Non-Asbestos		None	
tic access - None Fo l <b>ient: Kaw</b>	und artha Pine Rid	ssment of attic in 2015		g Road, Enni	skille	n, ON		-	y Name: En	niskillen						
ttic access - None Fo <b>lient: Kaw</b> ocation: #	und	dge District School Board Site: 8		g Road, Enni	skille	n, ON		Room #	: 2	niskillen ent: 2024-12	-13		Area (sqft): 900			
ttic access - None Fo lient: Kaw ocation: #	und artha Pine Rid 9 : CLASSRO e: 2024-12-12	dge District School Board Site: 8					P	Room # Last Re-	: 2 -Assessme							
ttic access - None Fo <b>lient: Kaw</b> ocation: #	und artha Pine Rid 9 : CLASSRO e: 2024-12-12 System	dge District School Board Site: 8: OM Floor:	1 tem		Good			Room # Last Re AINT Unit	: 2 -Assessme Sample		S	ample Descri	otion			Hazard
ttic access - None Fo <b>lient: Kaw</b> ocation: #	und artha Pine Rid 9 : CLASSRO e: 2024-12-12 System Other	dge District School Board Site: 8: OM Floor:	1 tem /ood		<b>Good</b> 160		P	Room # Last Re- AINT Unit SF	2 -Assessme Sample L0004	ent: 2024-12	SBlue	wooden windo	ption w frame		0.12 % L	ead (High)
ttic access - None Fo Client: Kaw ocation: #	artha Pine Rid 9 : CLASSRO e: 2024-12-12 System Other Other	dge District School Board Site: 8: OM Floor:	1 tem		Good		P	Room # Last Re AINT Unit	: 2 -Assessme Sample	ent: 2024-12	SBlue	wooden windo	otion		0.12 % L	ead (High)
ttic access - None Fo Client: Kaw ocation: # Survey Dat ttic access Client: Kaw ocation: #	und artha Pine Rid 9 : CLASSRO e: 2024-12-12 System Other Other . Limited asses	dge District School Board Site: 8: OM Floor: In W Ssment of attic in 2015 dge District School Board Site: 8:	tem /ood aster 145 Old Scugo		<b>Good</b> 160 900	Po	P, DOOT	Room # Last Re- AINT Unit SF SF Building Room # Last Re-	2 Assessme Sample L0004 V9500 V9500	ent: 2024-12 White plaste	S Blue r asbestos-	wooden windo	ption w frame		0.12 % L	ead (High)
ttic access - None Fo Client: Kaw ocation: # Survey Dat ttic access Client: Kaw ocation: #	und artha Pine Rid 9 : CLASSRO e: 2024-12-12 System Other Other . Limited assess artha Pine Rid 9 : CLASSRO	dge District School Board Site: 8 OM Floor: 1 M Ssment of attic in 2015 dge District School Board Site: 8 OM Floor: 1	tem /ood aster 145 Old Scugo		<b>Good</b> 160 900	Po	P, DOOT	Room # Last Re- AINT Unit SF SF Building Room # Last Re- RCURY	2 Assessme L0004 V9500 Name: En 2 Assessme	ent: 2024-12 White plaste	S Blue r asbestos-	wooden windc containing wal	ption w frame , presumed with lead paint. Area (sqft): 900	Pb: (	0.12 % Li Pre	ead (High) sumed Lead
ttic access - None Fo Client: Kaw ocation: # Survey Dat ttic access Client: Kaw ocation: #	und artha Pine Rid 9 : CLASSRO e: 2024-12-12 System Other Other . Limited assess artha Pine Rid 9 : CLASSRO	dge District School Board Site: 8 OM Floor: Floor: 1 M Ssment of attic in 2015 dge District School Board Site: 8 OM Floor: 1 Component	tem /ood aster 145 Old Scugo		<b>Good</b> 160 900	Po	P, DOOT	Room # Last Re- AINT Unit SF SF Building Room # Last Re- RCURY Quan	2 Assessme L0004 V9500 S Name: En 2 Assessme	ent: 2024-12 White plaste	S Blue r asbestos-	wooden windc containing wal	ption w frame , presumed with lead paint. Area (sqft): 900 Jnit	Pb: (	0.12 % Li Pre	ead (High) sumed Lead Hazard
ttic access - None Fo Client: Kaw .ocation: # Survey Data .ttic access Client: Kaw .ocation: # Survey Data	artha Pine Rid 9 : CLASSRO e: 2024-12-12 System Other Other . Limited asses artha Pine Rid 9 : CLASSRO e: 2024-12-12	dge District School Board Site: 8 OM Floor: 1 M Ssment of attic in 2015 dge District School Board Site: 8 OM Floor: 1	tem /ood aster 145 Old Scugo		<b>Good</b> 160 900	Po	P, DOOT	Room # Last Re- AINT Unit SF SF Building Room # Last Re- RCURY	2 Assessme L0004 V9500 S Name: En 2 Assessme	ent: 2024-12 White plaste	S Blue r asbestos-	wooden windc containing wal	ption w frame , presumed with lead paint. Area (sqft): 900	Pb: (	0.12 % Li Pre	ead (High) sumed Lea





				PCB			
Component	Good	Poor	Unit	Sample	Sample Description	Amount	PCB
Caulking	100		LF	V0001		<0.2 mg/kg	No
Caulking	40		LF	V0002		<0.2 mg/kg	No

Attic access. Limited assessment of attic in 2015





	10 : CLASSRO e: 2024-12-12	DOM Floor:	1				Last Re-Assessment: 2024-12-13 ASBESTOS /* AP* Good Fair Poor Unit Sample Asbestos Type Amount									
System	Component	Material	Item	Covering	A*	V*	AS AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friak
Ceiling	Component	Plaster	Surface	Covering	С	Y		900	- Tun	1 001	SF	V0002	Chrysotile	0.5-5%	Confirmed	PF
Duct		None Found														
Floor		Vinyl Floor Tile and Mastic	Surface		Α	Y		900			SF	S0006	None Detected	N.D.	None	
Mechanical Equipment		None Found														
Other	Blackboard	Adhesive/mastic, Mastic behind tackboards			А	N		5			EA	V9500	Presumed Asbestos		Presumed Asbestos	N
Other	Window	Caulking, Soft brown interior window frame caulking			А	Y		140			LF	V0020	None Detected	N.D.	None	
Piping		None Found														
Structure	Not Accessible	N/A														
Wall		Plaster	Surface	Wood	А	Y		900			SF	V0002	Chrysotile	0.5-5%	Confirmed Asbestos	PI
Wall <sup>1</sup>		Vermiculite Investigation			D	Ν		2			EA	V0000	Non-Asbestos		None	
ent: Kaw cation: #		dge District School Board Site: 8 DOM Floor:	-	og Road, Enni	skille	n, ON	I	Room #:		niskillen nt: 2024-12	-13		Area (sqft): 900			
cation: #	vartha Pine Rid 10 : CLASSR( e: 2024-12-12	DOM Floor:	1				P	Room #: Last Re-/	1 Assessme							Henry
ient: Kaw cation: #	artha Pine Rid 10 : CLASSRO e: 2024-12-12 System	DOM Floor:	1 Item		Good			Room #: Last Re-/	1 Assessme Sample	nt: 2024-12	9	Sample Descri	ption		ount	Hazard
ient: Kaw cation: #	vartha Pine Rid 10 : CLASSR( e: 2024-12-12	DOM Floor:	1				P	Room #: Last Re-/	1 Assessme	nt: 2024-12 Blue	s wooden wii	ndow frame an			).12 % I	_ead (High
ient: Kaw ocation: #: irvey Date ient: Kaw ocation: #:	vartha Pine Rid 10 : CLASSRO e: 2024-12-12 System Other Other	DOM Floor:	1 Item Vood laster 145 Old Scug		<b>Good</b> 220 900	P	Poor P	Room #: Last Re-/ AINT Unit SF SF Building Room #: Last Re-/	1 Assessme Sample V0004 V9500 Name: En 1	nt: 2024-12 Blue White plaste	s wooden win er asbestos	ndow frame an	ption d wood wall covering		).12 % I	_ead (High
ient: Kaw ocation: #: irvey Date ient: Kaw ocation: #:	vartha Pine Rid 10 : CLASSRO e: 2024-12-12 System Other Other vartha Pine Rid 10 : CLASSRO	DOM Floor:	1 Item Vood laster 145 Old Scug		<b>Good</b> 220 900	P	Poor P	Room #: Last Re-/ AINT Unit SF SF Building Room #: Last Re-/ RCURY	1 Assessme Sample V0004 V9500 Name: En 1 Assessme	nt: 2024-12 Blue White plaste niskillen	s wooden win er asbestos	ndow frame and	ption d wood wall covering l, presumed with lead paint. Area (sqft): 900	Pb: C	).12 % I Pri	Lead (High esumed Le
ent: Kaw cation: # rvey Date ent: Kaw cation: #	vartha Pine Rid 10 : CLASSRO e: 2024-12-12 System Other Other vartha Pine Rid 10 : CLASSRO	DOM Floor:	1 Item Vood laster 145 Old Scug		<b>Good</b> 220 900	P	Poor P	Room #: Last Re-/ AINT Unit SF SF Building Room #: Last Re-/	1 Assessme Sample V0004 V9500 Name: En 1 Assessme	nt: 2024-12 Blue White plaste niskillen	s wooden win er asbestos	ndow frame and containing wal	ption d wood wall covering I, presumed with lead paint.		).12 % I Pri	_ead (High
ient: Kaw ocation: # irvey Date ient: Kaw ocation: # ient: Kaw ocation: #	vartha Pine Rid 10 : CLASSRO e: 2024-12-12 System Other Other other artha Pine Rid 10 : CLASSRO e: 2024-12-12	DOM Floor:	1 Item Vood laster 145 Old Scug 145 Old Scug	og Road, Enni	Good 220 900 skille	n, ON	P Yoor I I I	Room #: Last Re-/ AINT Unit SF Building Room #: Last Re-/ RCURY Quant 36 Building Room #: Last Re-/	1 Assessme V0004 V9500 Name: En 1 Assessme ity Name: En 1	nt: 2024-12 Blue White plaste niskillen nt: 2024-12	s wooden win r asbestos	ndow frame and containing wal	ption d wood wall covering l, presumed with lead paint. Area (sqft): 900 Jnit	Pb: (	).12 % I Pri	Lead (High esumed Le Hazard
ient: Kaw ocation: # irvey Date ient: Kaw ocation: # ient: Kaw ocation: #	rartha Pine Rid 10 : CLASSR( e: 2024-12-12 System Other Other artha Pine Rid 10 : CLASSR( e: 2024-12-12 CASSR( e: 2024-12-12	DOM Floor:	1 Item Vood laster 145 Old Scug 1 145 Old Scug 1	og Road, Enni og Road, Enni	Good 220 900 skiller	n, ON	P 'oor	Room #: Last Re-/ AINT Unit SF Building Room #: Last Re-/ RCURY Quant 36 Building Room #: Last Re-/ PCB	1 Assessme V0004 V9500 Name: En 1 Assessme ity Name: En 1	nt: 2024-12 Blue White plaste niskillen nt: 2024-12 niskillen	s wooden win r asbestos -13 -13	ndow frame and containing wal	ption d wood wall covering l, presumed with lead paint. Area (sqft): 900 Jnit EA Area (sqft): 900	Pb: C	0.12 % I Pro	Lead (High esumed Le Hazard Yes
ient: Kaw irvey Date ient: Kaw ient: Kaw ient: Kaw ient: Kaw	rartha Pine Rid 10 : CLASSRO e: 2024-12-12 System Other Other artha Pine Rid 10 : CLASSRO e: 2024-12-12 rartha Pine Rid 10 : CLASSRO e: 2024-12-12	DOM Floor:	1 Item Vood laster 145 Old Scug 145 Old Scug	og Road, Enni	Good 220 900 skille	n, ON	P 'oor	Room #: Last Re-/ AINT Unit SF Building Room #: Last Re-/ RCURY Quant 36 Building Room #: Last Re-/	1 Assessme V0004 V9500 Name: En 1 Assessme ity Name: En 1	nt: 2024-12 Blue White plaste niskillen nt: 2024-12 niskillen	s wooden win r asbestos -13 -13	ndow frame and containing wal	ption d wood wall covering l, presumed with lead paint. Area (sqft): 900 Jnit EA Area (sqft): 900	Pb: C	).12 % I Pri	Lead (High esumed Le Hazard





urvey Date	e: 2024-12-12							Last Re-	Assessmei	nt: 2024-12	-13		Area (sqft): 800			
							AS	BESTOS								
System	Component	Material	Item	Covering	A*	۷*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 24 x 48 white raised bumps	Surface		С	Y		800			SF	V0007	[None]	0.5-5%	[Abated]	
Duct		Fibreglass		Foil Face												
Floor		Concrete (poured), Concrete slab			D	Ν		800			SF	S0042ABC	None Detected	N.D.	None	
Floor		Vinyl Floor Tile and Mastic	Surface		Α	Y		800			SF	V0006	None Detected	N.D.	None	
Mechanical Equipment		None Found														
Other <sup>1</sup>	Blackboard	Wood			Α	Ν		5			EA	V0000	Non-Asbestos		None	
Other	Blackboard	Adhesive/mastic			Α	Ν		5			EA	V9500	[None]		[Abated]	
Other	Bulletin Board	Adhesive/mastic, Brown mastic adhesive on wall for tackboards			А	N		6			EA	S0038AB	[None]	<0.5%	[Abated]	
Other	Sink	Mastic, Grey, Grey sink mastic			Α	Ν		1			EA	S0022A	[None]	N.D.	[Abated]	
Piping	Hot Water Heating	Fibreglass	Straight													
Piping	Hot Water Heating	Parging Cement, Located in exterior wall corner by drywall wall cover	Fitting	Canvas	С	N		2			EA	V0003	[None]	10-25%	[Abated]	
Structure		Not Insulated														
Wall		Masonry														
Wall <sup>2</sup>		Cement Product			Α	Y		50			SF	V9000	[None]		[Abated]	
Wall		Paint, Beige painted exterior masonry block wall 1968 yoc	Base		A	Y		800			SF	S0021AB	None Detected	N.D.	None	
Wall		Adhesive/mastic, Black vinyl trim adhesive			Α	Ν		80			LF	V0023	None Detected	N.D.	None	
Wall		Caulking, Black caulking around windows frames			В	Y		40			LF	S0035ABC	None Detected	N.D.	None	
Wall	Expansion Joint	Caulking, Grey			Α	Y		10			LF	S0041AB	[None]	0.5-5%	[Abated]	

1 - Green chalkboards are mechanically fastened

2 - Transite board

Client: Kawartha Pine Ridge District Scl Location: #13 : CLASSROOM	hool Board Site: 8145 Old Scu Floor: 1	ugog Road, Enniskillen,	, ON	Buildiı Room	•	Enniskillen Area (sqft): 800		
Survey Date: 2024-12-12				Last R	e-Assessn	nent: 2024-12-13		
				PAINT				
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard
Structure	Steel	800		SF	V9500	Red primer paint joists and beams		Presumed Lead
Structure	Masonry	800		SF	L0005	Beige masonry block paint	Pb: 0.052 %	Lead (Low)
Mechanical Equipment	Metal	240		SF	V9500	Blue metal radiator covers		Presumed Lead

Client: Kawartha Pine Ridge District School Board Site: 8145 Old Scugog Road, Enniskillen, ON Location: #13 : CLASSROOM Survey Date: 2024-12-12

Floor: 1

**Building Name: Enniskillen** Room #: 06 Last Re-Assessment: 2024-12-13

Area (sqft): 800





	MERCURY									
Component	Quantity	Unit	Sample	Hazard						
Light Fixture <sup>1</sup>	36	EA	V9000	Yes						
- 2x 4 fixtures 3 T8 hulls										

1 - 2x 4 fixtures 3 T8 bulbs

Client: Kawartha Pine Ridge District School Board	Site: 8145 Old So	ugog Road, I	Enniskillen, ON	Building	Name: Enniskillen		
Location: #13 : CLASSROOM	Floor: 1			Room #:	06 Area (sqft): 800		
Survey Date: 2024-12-12				Last Re-A	Assessment: 2024-12-13		
				PCB			
Component	Good	Poor	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts	18		EA	V9500			Presumed
Caulking <sup>1</sup>	30		LF	V0000	Black Window Caulking		No
1 - Installed 2002							



- -- --

...

- . . ...

. . . . . . .

-



		-	45 Old Scugo	g Road, Enni	skille	n, ON		•	Name: En	niskillen			A			
	18 : CLASSRO e: 2024-12-12	DOM Floor: 1						Room #: Last Re-/		nt: 2024-12	2-13		Area (sqft): 800			
							AS	BESTOS								
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in)	Surface		С	Y		800			SF	V0007	[None]	0.5-5%	[Abated]	
Duct		None Found														
Floor		Vinyl Floor Tile and Mastic	Surface		Α	Y		800			SF	S0006	None Detected	N.D.	None	
Mechanical Equipment		None Found														
Other	Bulletin Board	Adhesive/mastic, Brown mastic adhesive on wall for tackboards			А	Ν		8			EA	S0038C	Chrysotile	<0.5%	None	
Other	Sink	Adhesive/mastic			Α	Ν		1			EA	V0022	None Detected	N.D.	None	
Other	Window	Caulking, Brown window frame caulking exterior windows			А	Y		40			LF	S0025C	None Detected	N.D.	None	
Piping <sup>1</sup>		Parging Cement	Fitting	Canvas	С	Ν		3			EA	V0003	[None]	10-25%	[Abated]	
Piping	Hot Water Heating	Fibreglass	Straight		С	N										
Piping	Rain Water Leader	Not Insulated			С	N										
Structure		Not Insulated														
Wall <sup>2</sup>		Drywall and joint compound			А	Y		52			SF	V0004	Chrysotile	0.5-5%	Confirmed Asbestos	NF
Wall		Masonry														
Wall		Paint, Exterior beige paint block walls			А	Y		800			SF	S0021G	None Detected	N.D.	None	
Wall		Paint, Beige interior block wall paint			Α	Y		400			SF	V0024	None Detected	N.D.	None	
Wall		Mastic		Rubber	Α	Ν		20			SF	V0044	None Detected	N.D.	None	
Wall	Base	Adhesive/mastic, Vinyl trim adhesive			Α	Ν		60			LF	V0023	None Detected	N.D.	None	

1 - Fittings near sink

2 - ~10 SF removed in 2024, Pinchin File 335495.000 from the vertical pipe enclosure in northeast corner.

. ....

## Client: Kawartha Pine Ridge District School Board Site: 8145 Old Scugog Road, Enniskillen, ON Buildi

Building Name: Enniskillen

Area (caft): 800

Location: #18 : CLASSROOM Floor: 1				RUUIII	#: 144	Area (sqft): 800		
urvey Date: 2024-12-12				Last R	nent: 2024-12-13			
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard
Wall	Masonry	1200		SF	V0005	Beige interior and exterior painted block walls.	Pb: 0.052 %	Lead (Low)
Structure	Steel	800		SF	V9500	Red primer paint joists and beams		Presumed Lead
Other			34 SF V0006			Blue wooden doors	Pb: 0.045 %	Lead (Low)
Other	Other Metal		3 EA V9500			Blue metal door frames		Presumed Lead
Mechanical Equipment	300		Blue metal radiator covers		Presumed Lead			
	System Wall Structure Other Other	System     Item       Wall     Masonry       Structure     Steel       Other     Wood       Other     Metal	SystemItemGoodWallMasonry1200StructureSteel800OtherWood34OtherMetal3	SystemItemGoodPoorWallMasonry1200StructureSteel800OtherWood34OtherMetal3	SystemItemGoodPoorUnitWallMasonry1200SFStructureSteel800SFOtherWood34SFOtherMetal3EA	SystemItemGoodPoorUnitSampleWallMasonry1200SFV0005StructureSteel800SFV9500OtherWood34SFV0006OtherMetal3EAV9500	SystemItemGoodPoorUnitSampleSample DescriptionWallMasonry1200SFV0005Beige interior and exterior painted block walls.StructureSteel800SFV9500Red primer paint joists and beamsOtherWood34SFV0006Blue wooden doorsOtherMetal3EAV9500Blue metal door frames	System       Item       Good       Poor       Unit       Sample       Sample Description       Amount         Wall       Masonry       1200       SF       V0005       Beige interior and exterior painted block walls.       Pb: 0.052 %         Structure       Steel       800       SF       V9500       Red primer paint joists and beams       Pb: 0.055 %         Other       Wood       34       SF       V0006       Blue wooden doors       Pb: 0.045 %         Other       Metal       3       EA       V9500       Blue metal door frames       Pb: 0.045 %

Client: Kawartha Pine Ridge District School BoardSite: 8145 Old Scugog Road, Enniskillen, ONLocation: #18 : CLASSROOMFloor: 1Survey Date: 2024-12-12Survey Date: 2024-12-12

Building Name: Enniskillen Room #: 144 Last Re-Assessment: 2024-12-13

Area (sqft): 800





		MERCURY				
Component		Quantity	Unit	Sample	Hazard	
Light Fixture <sup>1</sup>		24	EA	V9000	Yes	
1 - 12 ,2x 4 fixtures T8 bulbs						
Client: Kawartha Pine Ridge District School Board	Site: 8145 Old Scugog Road, Enniskill	en, ON Building Name: Enniskillen				
Location: #18 : CLASSROOM	Floor: 1	Room #: 144	Area (sqft): 800			

Su	rvey Date: 2024-12-12	ssessment: 2024-12-13						
					PCB			
	Component	Good	Poor	Unit	Sample	Sample Description	Amount	PCB
	Caulking <sup>1</sup>	30		LF	V0000	Black Window Caulking		No

1 - Installed 2002

2025-02-11





Client: Kawartha Pine Ridge District School Board Site: 8145 Old Scugog Road, Enni .ocation: #19 : VESTIBULE Floor: 1 Survey Date: 2024-12-12													Area (sqft): 200			
							AS	BESTOS								
System	Component	Material	Item	Covering	A*	۷*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in)	Surface		С	Y		200			SF	V0007	[None]	0.5-5%	[Abated]	
Duct		None Found														
Floor		Vinyl Floor Tile and Mastic	Surface		Α	Y		200			SF	V0006	None Detected	N.D.	None	
Mechanical Equipment	ment None Found															
Piping	All	Fibreglass														
Structure		Not Insulated														
14/-11	Paint, Beige paint on block wall Ma				В	Y		500			SF	V0024	None Detected	N.D.	None	
Wall	; <b>5</b> 1															
Wall	artha Pine Rid	Mastic	8145 Old Scugo	Rubber	A skiller	N n, ON		20 Building	y Name: Er	niskillen	SF	S0044A	None Detected	N.D.	None	
Wall Client: Kawa ocation: #1	19 : VESTIBUL	Mastic ge District School Board Site:	•					Building Room #	: 151	niskillen ent: 2024-12		S0044A	None Detected Area (sqft): 200	N.D.	None	
Wall Client: Kawa Ocation: #1		Mastic ge District School Board Site:	•					Building Room #	: 151			S0044A		N.D.	None	
Wall lient: Kawa ocation: #1	19 : VESTIBUL	Mastic ge District School Board Site:	•	g Road, Enni		n, ON		Building Room # Last Re- AINT	: 151		2-13	S0044A	Area (sqft): 200		None	Hazard
Wall lient: Kawa ocation: #1	19 : VESTIBUL 2: 2024-12-12	Mastic ge District School Board Site: E Floo	r: 1	g Road, Enni	skille	n, ON	Р	Building Room # Last Re- AINT	: 151 -Assessme		-13 S		Area (sqft): 200 tion	Am		Hazard Lead (Low)
Wall lient: Kawa ocation: #1	19 : VESTIBUL e: 2024-12-12 System	Mastic ge District School Board Site: E Floo	r: 1	g Road, Enni	skiller Good	n, ON	Р	Building Room # Last Re- AINT Unit	: 151 -Assessme Sample		2-13 S	ample Descrip	Area (sqft): 200 tion prick	Am	ount .052 %	Lead (Low)
Wall Client: Kawa Survey Date Client: Kawa Location: #1	19 : VESTIBUL e: 2024-12-12 System Wall Structure	Mastic ge District School Board Site: E Floo ge District School Board Site:	r: 1 Item Masonry Steel : 8145 Old Scugo	ng Road, Enni	skiller Good 500 200	n, ON	P oor	Building Room #: Last Re- AINT Unit SF SF Building Room #:	: 151 -Assessme V0005 V9500 J Name: Er : 151	ent: 2024-12	2-13 S E r	i <b>ample Descrip</b> Beige masonry b	Area (sqft): 200 tion prick	Am	ount .052 %	Lead (Low)
Wall ilient: Kawa ocation: #1 urvey Date lient: Kawa ocation: #1	19 : VESTIBUL e: 2024-12-12 System Wall Structure artha Pine Rid 19 : VESTIBUL	Mastic ge District School Board Site: E Floo ge District School Board Site:	r: 1 Item Masonry Steel : 8145 Old Scugo	ng Road, Enni	skiller Good 500 200	n, ON	P oor	Building Room #: Last Re- AINT Unit SF SF Building Room #:	: 151 -Assessme V0005 V9500 J Name: Er : 151	ent: 2024-12 niskillen	2-13 S E r	i <b>ample Descrip</b> Beige masonry b	Area (sqft): 200 tion prick joist	Am	ount .052 %	Lead (Low)
Wall Client: Kawa ocation: #1 Survey Date Survey Date Client: Kawa ocation: #1	19 : VESTIBUL e: 2024-12-12 System Wall Structure artha Pine Rid 19 : VESTIBUL	Mastic ge District School Board Site: E Floo ge District School Board Site:	r: 1 Item Masonry Steel : 8145 Old Scugo	ng Road, Enni	skiller Good 500 200	n, ON	P oor	Building Room #: Last Re- AINT Unit SF SF Building Room #: Last Re-	: 151 -Assessme V0005 V9500 2 Name: Er : 151 -Assessme	ent: 2024-12 niskillen	2-13 S E r	a <b>mple Descrip</b> Beige masonry b ed primer steel	Area (sqft): 200 tion prick joist	Am	iount 0.052 % F	





Client: Kaw	artha Pine Ric	dge District Sch	ool Board Site	: 8145 Old So	ugog Road, Er	nniskille	en, Of	N	Building	J Name: Er	nniskillen						
Location: #	20 : COAT RO	OM	Flo	or: 1					Room #	: 147				Area (sqft): 275			
Survey Date	e: 2024-12-12								Last Re	Assessme	ent: 2024-12	2-13					
								AS	BESTOS								
System	Component	Μ	laterial	ltem	Covering	g A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazar	d Friable
Ceiling		Ceiling	Tiles (lay-in)	Surface	e	С	Y		275			SF	V0007	[None]	0.5-5%	[Abated	[[
Duct		Nor	ne Found														
Floor		Vinyl Floor	Tile and Mastic	Surface	e	А	Y		275			SF	V0006	None Detected	N.D.	None	
Mechanical Equipment			ne Found														
Other	Window		brown window frame aulking			А	Y		200			LF	S0025B	None Detected	N.D.	None	
Piping	All	Fit	oreglass														
Structure		Not	Insulated														
Wall		Painted blo	ock walls exterior			А	Y		200			SF	V0021	None Detected	N.D.	None	
Wall		Painted blo	ock walls interior			A	Y		200			SF	V0024	None Detected	N.D.	None	
Wall			asonry														
Wall		١	Vastic		Rubber	A	Ν		20			SF	S0044B	None Detected	N.D.	None	
	e: 2024-12-12							F	AINT		ent: 2024-12						
	System			ltem		Good	F	Poor	Unit	Sample		:	Sample Descrip	otion		nount	Hazard
	Wall			Masonry		400			SF	V0005		B	eige paint on ma	· ·	Pb: 0	.052 %	Lead (Low)
	Structure			Steel		275			SF	V9500			Primer on jois	sts			Presumed Lead
Location: #	20 : COAT RO	dge District Sch OM		e: 8145 Old So or: 1	ugog Road, Er	nniskille	en, Of	N	Room #					Area (sqft): 275			
Survey Date	e: 2024-12-12									Assessme	ent: 2024-12	2-13					
								ME	RCURY								
			Component						Quar	-				Jnit		nple	Hazard
			Light Fixture						4					EA	V90	000	Yes
Location: #	artha Pine Ric 20 : COAT RO e: 2024-12-12	dge District Sch OM		e: 8145 Old So or: 1	cugog Road, Er	nniskille	en, Of	N	Room #		nniskillen ent: 2024-12	2-13		Area (sqft): 275			
-									PCB								
	C	omponent		Good	Poor	Unit		9	Sample			Sa	mple Description	on	A	mount	PCB
	(	Caulking <sup>1</sup>		30		LF			V0000			Blac	k Window Caul	king			No

1 - Installed 2002





Client: Kaw	artha Pine Ri	dge District	School Board Site: 8	145 Old Scugo	g Road, Enn	iskille	n, ON	I	Buildin	g Name: En	niskillen						
Location: #2	21 : WASHRO	ОМ	Floor:	1					Room a	<b>#: 152</b>				Area (sqft): 50			
Survey Date	e: 2024-12-12								Last Re	e-Assessme	ent: 2024-12	2-13					
								A	SBESTOS								
System	Component		Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	l Friable
Ceiling		Ce	iling Tiles (lay-in)	Surface		С	Y		50			SF	V0007	[None]	0.5-5%	[Abated	1]
Duct			None Found														
Floor			loor Tile and Mastic	Surface		Α	Y		50			SF	S0006	None Detected	N.D.	None	
Floor	fechanical None Found											S0010	[None]	N.D.	[Abated	1]	
Mechanical Equipment			None Found														
Piping	All		Fibreglass														
Structure			Not Insulated														
Wall			Masonry														
Wall		Paint, Inte	erior masonry wall paint		Masonry	A	Y		100			SF	S0024D	None Detected	N.D.	None	
Wall			Mastic		Rubber	A	Ν		20			SF	S0044C	None Detected	N.D.	None	
	artha Pine Ri 21 : WASHRO	•	School Board Site: 8 Floor:	145 Old Scugo	g Road, Enn	iskille	n, ON	I	Buildin Room a	g Name: En #• 152	niskillen			Area (sqft): 50			
	e: 2024-12-12		110011	-						-Assessme	nt. 2024-12	2.13		Alea (Sqli): So			
Survey Date									PAINT	-433033110		L-13					
	System			Item		Good	Р	oor	Unit	Sample			Sample Descrip	tion	Amo	ount	Hazard
	Wall			asonry		100	-		SF	V0005			ge masonry bloc			052 %	Lead (Low)
	Structure			Steel		50			SF	V9500			primer paint on				Presumed Lead
	Other		!	Vetal		1			EA	V9500			· · · ·	·			Presumed Lead
	artha Pine Ric 21 : WASHRO	•	School Board Site: 8 Floor:	145 Old Scugo 1	g Road, Enn	iskille	n, ON	I	Buildin Room a	g Name: Er #: 152	iniskillen			Area (sqft): 50			
Survey Date	e: 2024-12-12								Last Re	e-Assessme	ent: 2024-12	2-13					
								ME	RCURY								
			Component						Qua	ntity			U	nit	Sam	•	Hazard
			Light Fixture							3			E	EA	V90	00	Yes



- -- --

...

- . . ...



Client: Kawa	t: Kawartha Pine Ridge District School Board Site: 8145 Old Scugog Road, Enniskillen, ON								Building Name: Enniskillen									
Location: #2	25 : CORRIDO	DR Floor: 1	L					Room #:	150				Area (sqft): 5165					
Survey Date	: 2024-12-12							Last Re-	Assessmer	nt: 2024-12	-13							
							AS	BESTOS										
System	Component	Material	Item	Covering	A*	۷*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable		
Ceiling		Ceiling Tiles (lay-in), 24 x 48 white raised bumps	Surface		С	Y		1200			SF	V0007	[None]	0.5-5%	[Abated]			
Ceiling <sup>1</sup>	lissuie				С	Y		300			SF	V0000	Non-Asbestos		None			
Duct		None Found																
Floor		Vinyl Floor Tile and Mastic	Surface		А	Y		765			SF	V0008	[None]	0.5-5%	[Abated]			
Floor	Vinul Eloor Tile and Mastic 12 x 12 off-white			Y		765			SF	V0006	None Detected	N.D.	None					
Floor		Carpet			Α	Y		3300			SF	V0000	Non-Asbestos		None			
Floor		Terrazzo			Α	Y		1100			SF	V0039	None Detected	N.D.	None			
Floor		Mastic, Carpet mastic		Carpet	D	Ν		3000			SF	V0027	Chrysotile	<0.5%	None			
Mechanical Equipment		None Found																
Other		Paint, Interior beige block wall paint.			Α	Y		2000			SF	V0024	None Detected	N.D.	None			
Piping																		
Piping	Hot Water				2			EA	V0003	Chrysotile	10-25%	Confirmed Asbestos	F					
Structure Not Insulated																		
Wall <sup>2</sup>								200			SF	V0004	Chrysotile	0.5-5%	Confirmed Asbestos	NF		

HMIS sticker at location 43 door

1 - Date code 03/01/04

2 - South corridor: DJC remains in north half of the corridor as bulkhead outside Mechanical Room 157 (Loc 24) - approximately 5 linear feet North Corridor: DJC remains as bulkhead in full

. . ...

. .

Client: Kawartha Pine Ridge District School Board		Site: 8145 Old Scugog Road, Enniskillen, ON			Buildir	ng Name: E	Enniskillen		
Location: #25 : CORRIDOR		Floor: 1			Room	#: 150	Area (sqft): 5165		
urvey Date: 2024-12-12					Last R	e-Assessn	nent: 2024-12-13		
				PAINT					
System		Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard
Wall	Dr	ywall and joint compound	150		SF	V0007	beige paint on drywall	Pb: 0.0057 %	No
Wall		Masonry	2000		SF	V0005	Beige paint on block walls	Pb: 0.052 %	Lead (Low)
Structure		Steel	5165		SF	V9500	red primer paint on structural steel joists.		Presumed Lead
Other		Metal	6		EA	V9500	blue painted metal door frames		Presumed Lead

HMIS sticker at location 43 door

Client: Kawartha Pine Ridge District School BoardSite: 8145 Old Scugog Road, Enniskillen, ONLocation: #25 : CORRIDORFloor: 1Survey Date: 2024-12-12Survey Date: 2024-12-12

. ....

. .

Building Name: Enniskillen Room #: 150 Last Re-Assessment: 2024-12-13

Area (sqft): 5165





MERCURY											
Component Quantity Unit Sample Haza											
Light Fixture	82	EA	V9000	Yes							

HMIS sticker at location 43 door

Client: Kawartha Pine Ridge District School Board Location: #25 : CORRIDOR Survey Date: 2024-12-12	Site: 8145 Old Sc Floor: 1	ugog Road, E	Enniskillen, ON	Room #: 1	ame: Enniskillen 50 Area (sqft): 5165 ssessment: 2024-12-13		
				PCB			
Component	Good Poor Unit		Sample	Sample Description	Amount	PCB	
Light Ballasts	41 EA EA			V9500			Presumed

HMIS sticker at location 43 door



- · ·

**B**<sup>1</sup> · · · **A** 

. .

. ....

- - -

. . ...

~ • •

### ALL DATA REPORT

- -- --

•••

- . . ...



urvey Date	e: 2024-12-12							Last Re-/	Assessmer	nt: 2024-12	-13					
							AS	BESTOS								
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 24 x 48 white raised bumps	Surface		С	Y		788			SF	V0007	[None]	0.5-5%	[Abated]	
Ceiling <sup>1</sup>	(fibreglass)	Ceiling Tiles (lay-in)	Surface		С	Y		12			SF	V0000	Non-Asbestos		None	
Ceiling	Bulkhead	Drywall and joint compound	Surface		D	Ν		160			SF	V0004	[None]	0.5-5%	[Abated]	
Duct	All	Fibreglass		Foil Face	С	Ν										
Floor		Vinyl Floor Tile and Mastic, 12 x 12 white tan specks by sink			А	Y		35			SF	V0006	None Detected	N.D.	None	
Floor		Adhesive/mastic, Carpet adhesive Burgundy brown streak carpet adhesive		Carpet	А	Ν		775			SF	S0027ABC	Chrysotile	<0.5%	None	
Mechanical Equipment		None Found														
Other <sup>2</sup>	Blackboard	Wood			А	Ν		5			EA	V0000	Non-Asbestos		None	
Other	Bulletin Board	Adhesive/mastic, Brown mastic on tack boards			Α	N		8			EA	V0038	Chrysotile	<0.5%	None	
Other	Sink	Adhesive/mastic, Gold sink mastic in closet			Α	Ν		3			EA	S0028ABC	[None]	0.5-5%	[Abated]	
Other	Sink	Mastic, Grey, Grey sink mastic			Α	Ν		1			EA	S0022B	None Detected	N.D.	None	
Piping <sup>3</sup>		Parging Cement	Fitting	Canvas	С	Ν		10			EA	V0003	[None]	10-25%	[Abated]	
Piping	Hot Water Heating	Fibreglass	Straight													
Structure		Not Insulated														
Wall <sup>4</sup>		Drywall and joint compound	Surface		Α	Y		100			SF	V0004	[None]	0.5-5%	[Abated]	
Wall		Masonry														
Wall <sup>5</sup>		Cement Product			А	Y		50			SF	V9000	[None]		[Abated]	
Wall Paint, Masonry block wall paint exterior wall Masonry								500			SF	S0021CD	None Detected	N.D.	None	1
Wall Caulking						Y		15			SF	V0036	[None]	N.D.	[Abated]	
Wall	Base	Adhesive/mastic, Black Vinyl trim adhesive			А	Ν		80			LF	S0023A	None Detected	N.D.	None	
Wall <sup>6</sup>	Expansion Joint	Caulking, Grey			С	Ν		10			LF	S0041C	Chrysotile	0.5-5%	Confirmed Asbestos	NF

1 - Date code present

2 - Green chalkboards are mechanically fastened

3 - Above ceiling near interior walls

4 - Transite panel

5 - Transite board

6 - On exterior wall above ceiling grid

Client: Kawartha Pine Ridge District School Location: #27 : CLASSROOM Survey Date: 2024-12-12	Board Site: 8145 Old Scugog Road, E Floor: 1	Site: 8145 Old Scugog Road, Enniskillen, ON Floor: 1				Enniskillen Area (sqft): 800 nent: 2024-12-13		
			PAINT					
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard
Wall	Masonry	500		SF	V0005	Beige paint on masonry block	Pb: 0.052 %	Lead (Low)
0005 00 11			and a second		is at the consisting - Operandial to Binaching Ltd. 2025	Bassa	10 - 1 00	

Quantities shown above are based on visual approximations only and may be subject to variation. Copyright Pinchin Ltd. 2025





Structure		Steel		800		SF	V9500		red primer on joists		Presumed Lead
Structure	Drywall a	and joint compour	nd	100		SF	V0007		Beige paint on drywall wall.	Pb: 0.0057 %	No
Other		Metal		1		EA	V9500		blue metal door frame.		Presumed Lead
Mechanical Equipment		Metal		100		SF	V9500		Blue rad enclosures		Presumed Lead
Client: Kawartha Pine Ridge District	School Board Site	: 8145 Old Sc	ugog Road, Er	nniskillen	, ON	Buildin	ng Name: E	Inniskillen			
Location: #27 : CLASSROOM	Floo	or: 1				Room	#: 7		Area (sqft): 800		
Survey Date: 2024-12-12						Last R	e-Assessm	nent: 2024-12	2-13		
MERCURY											
	Component					Qua	antity		Unit	Sample	Hazard
	Light Fixture <sup>1</sup>					۷	48		EA	V9000	Yes
1 - 12, 2 x 4 fixtures											
Client: Kawartha Pine Ridge District Location: #27 : CLASSROOM		e: 8145 Old Sc or: 1	ugog Road, Er	nniskillen	, ON	Room	#: 7	Enniskillen	Area (sqft): 800		
Survey Date: 2024-12-12							e-Assessm	nent: 2024-12	2-13		
						PCB			Sample Description		
Component		Good	Poor	Unit		Sample			Amount	PCB	
1		30		LF		V0000				No	
1 - Installed 2002			·								

1 - Installed 2002





Client: Kawa	artha Pine Ri	dge District School Board Site: 81	45 Old Scugo	g Road, Enni	skille	n, ON	l	Building	Name: En	niskillen						
	28 : CLASSR		L					Room #:					Area (sqft): 800			
Survey Date	: 2024-12-12							Last Re-	Assessme	nt: 2024-12	-13					
								BESTOS								
System	Component	Material	Item	Covering	A*	۷*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling <sup>1</sup>		Ceiling Tiles (lay-in), 24 x 48 white raised bumps	Surface									V0007	[None]	0.5-5%	[Abated]	
Ceiling <sup>2</sup>		Ceiling Tiles (lay-in)			С	Y		800			SF	V0000	Non-Asbestos		None	
Ceiling <sup>3</sup>	Bulkhead	Drywall and joint compound	Surface		С	Y		140			SF	V0004	Chrysotile	0.5-5%	Confirmed Asbestos	NF
Duct	All	Fibreglass		Foil Face												
Floor		Carpet														
Mechanical Equipment		None Found														
Other		Adhesive/mastic, Gold sink mastic in closet			Α	Ν		1			EA	V0028	[None]	0.5-5%	[Abated]	
Other	Sink	Mastic, Grey, Grey sink mastic			Α	Y		1			EA	S0022C	None Detected	N.D.	None	
Piping	Hot Water Heating	Fibreglass	Straight													
Piping <sup>4</sup>	Hot Water Heating	Fibreglass	Fitting	Canvas	С	Ν						V0000	Non-Asbestos		None	
Structure		Not Insulated														
Wall <sup>5</sup>		Drywall and joint compound	Surface		А	Y		60			SF	V0004	Chrysotile	0.5-5%	Confirmed Asbestos	NF
Wall		Masonry														
Wall <sup>6</sup>		Cement Product			А	Y		10			SF	V9000	Confirmed Asbestos		Confirmed Asbestos	NF
Wall		Paint, Exterior block wall paint			Α	Y		420			SF	S0021EF	None Detected	N.D.	None	
Wall		Adhesive/mastic, Vinyl trim adhesive on block wall			А	Ν		70			LF	S0023C	None Detected	N.D.	None	
Wall <sup>7</sup>		Vermiculite Investigation			D	Ν		2			EA	V0000	Non-Asbestos		None	

1 - Abated 2024 335495.018.

2 - Date Stamped 2024

3 - Approx. 50 SF removed in 2024, Pinchin File 335495.018 from northwest corner of the classroom (vertical riser full removed and approximately 5 linear feet of bulkhead removed from north end)

4 - ACM Pipe insulation removed December 2014

5 - Approx. 40 SF removed in 2024, Pinchin File 335495.018

6 - Transite board on northeast corner of room

7 - None Found

Client: Kawartha Pine Ridge District Schoo Location: #28 : CLASSROOM Survey Date: 2024-12-12	l Board Site: 8145 Old Scugog Road, E Floor: 1	Last Re-Assessme			#: 143	Area (sqft): 800				
	PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard		
Wall	Masonry	420		SF	V0005	Beige painted block walls	Pb: 0.052 %	Lead (Low)		
Structure	Steel	800		SF	V9500	Red primer joists and beams		Presumed Lead		
Other	Wood	34		SF	V0006	Blue wooden closet doors	Pb: 0.045 %	Lead (Low)		
Mechanical Equipment	Metal	120		SF	V9500	Blue radiator enclosures	Presume			
2025-02-11	Quantities shown above are based on v	ject to variation. Copyright Pinchin Ltd. 2025	Page	15 of 29.						





Ceiling	Drywal	l and joint compou	nd	260	SF	V0007	Beige drywall bulkhead	Pb: 0.0057 %	No		
Client: Kawartha Pine Ridge Dis Location: #28 : CLASSROOM Survey Date: 2024-12-12		te: 8145 Old Sc por: 1	ugog Road, Ei	nniskillen, O	Room #:	Name: Enniskillen 143 Assessment: 2024-1	Area (sqft): 800 2-13				
					MERCURY						
	Component				Quant	ty	Unit	Sample	Hazard		
	Light Fixture <sup>1</sup>				48	V9000	Yes				
1 - 12 2 x 4 fixtures											
Client: Kawartha Pine Ridge District School Board Site: 8145 Old Scugog Road, Enniskillen, ON Building Name: Enniskillen Location: #28 : CLASSROOM Floor: 1 Room #: 143 Area (sqft): 800 Survey Date: 2024-12-12 Last Re-Assessment: 2024-12-13											
Componer	:	Good	Poor	Unit	Sample		Sample Description	Amount	PCB		
Caulking <sup>1</sup>		30		LF	V0000		Black Window Caulking		No		
Caulking <sup>1</sup> 30     LF     V0000     Black Window Caulking     NO       1 - Installed 2002           NO											
Client: Kawartha Pine Ridge Dis	rict School Board Sit	te: 8145 Old Sc	ugog Road, Ei	nniskillen, O	N Building	Name: Enniskillen					
•		te: 8145 Old So por: 1	ugog Road, Ei	nniskillen, O	N Building Room #:		Area (sqft): 800				
Client: Kawartha Pine Ridge Dis Location: #28 : CLASSROOM Survey Date: 2024-12-12			cugog Road, Ei	nniskillen, O	Room #:						
Location: #28 : CLASSROOM	Fic		ugog Road, Ei	nniskillen, O	Room #:	143					
Location: #28 : CLASSROOM			cugog Road, Ei		Room #: Last Re-/ MOULD	143	2-13		Mould		

1 - Water damaged tiles





	30 : CLASSRO e: 2024-12-12	DOM Floor: 2	•					Room #: Last Re-/		nt: 2024-12	-13		Area (sqft): 800			
							AS	BESTOS								
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling <sup>1</sup>		Ceiling Tiles (lay-in)			С	Y		800			SF	V0000	Non-Asbestos		None	
Duct	All	Not Insulated														
Floor		Vinyl Floor Tile and Mastic, 12 x 12 white with tan speck floor tile by sink		Carpet	Α	Y		35				V0006	None Detected	N.D.	None	
Floor		Carpet			Α	Y		800			SF					
Floor		Adhesive/mastic, Burgundy brown streak carpet adhesive		Carpet	А	Ν		800			SF	V0027	Chrysotile	<0.5%	None	
Mechanical Equipment		None Found														
Other <sup>2</sup>	Blackboard	Wood			Α	Y		3			EA	V0000	Non-Asbestos		None	
Other <sup>3</sup>	Bulletin Board	Particle Board			Α	Y		6			EA	V0000	Non-Asbestos		None	
Other <sup>4</sup>	Window	Caulking, Brown window frame caulking			Α	Y		20			LF	V0025	None Detected	N.D.	None	
Piping <sup>5</sup>		Cement Product			D	N		100			%	V9000	Confirmed Asbestos		Confirmed Asbestos	NF
Piping	All	Fibreglass														
Structure		Not Insulated														
Wall		Drywall and joint compound			С	Y		100			SF	V0001	[None]	0.5-5%	[Abated]	
Wall		Masonry														
Wall <sup>6</sup>		Paint, Exterior masonry brick paint on masonry		Masonry	А	Y		390			SF	S0029A	Chrysotile	0.5-5%	Confirmed Asbestos	NF
Wall <sup>7</sup>	Door Frame	Caulking			Α	Y		100			LF	V0000	Non-Asbestos		None	
Wall <sup>8</sup>	Expansion Joint	Caulking, Grey			С	N		10			LF	V0041	Chrysotile	0.5-5%	Confirmed Asbestos	NF

1 - Date code present

2 - Chalkboards are mechanically fastened

3 - Tackboards are mechanically fastened

4 - 2002 date stamp on window

5 - Transite pipe below concrete slab

6 - Removed 50 SF on exterior wall in 2024, Pinchin File 335495.018

7 - Installed 2024 - Around Window and Door Frame at Classroom Entrance

8 - On exterior wall above ceiling grid

Client: Kawartha Pine Ridge District S Location: #30 : CLASSROOM Survey Date: 2024-12-12	Site: 8145 Old Scugo Floor: 1	g Road, Ennis	skillen,	ON	Room	#: 114D	inniskillen Area (sqft): 800 nent: 2024-12-13		
System	Item		PAINT Good Poor Unit			Sample	Sample Description	Amount	Hazard
Wall	Masonry		440		SF	V0005	Beige block walls	Pb: 0.052 %	Lead (Low)
Structure	Steel 800			SF	V9500	Primer paint on beams and joists		Presumed Lead	
Mechanical Equipment	Metal 100			SF	V9500	Blue radiator enclosures		Presumed Lead	





Ceiling	Drywall	and joint compoun	nd	200	SF	SF V0007 Beige DJC				No	
Client: Kawartha Pine Ridge District	School Board Sit	e: 8145 Old Sc	ugog Road, Ennis	killen,	ON Building	g Name:	Enniskillen				
Location: #30 : CLASSROOM	Flo	or: 1			Room #	#: 114D		Area (sqft): 800			
Survey Date: 2024-12-12					Last Re	e-Assessi	nent: 2024-12	-13			
					MERCURY						
	Component				Quai	ntity		Unit	Sample	Hazard	
	Light Fixture <sup>1</sup>				4	8		EA	V9000	Yes	
1 - 12 2x 4 fixtures											
Client: Kawartha Pine Ridge District	School Board Sit	e: 8145 Old Sc	ugog Road, Ennis	killen,	ON Building	g Name:	Enniskillen				
Location: #30 : CLASSROOM	Flo	or: 1			Room #	#: 114D		Area (sqft): 800			
Survey Date: 2024-12-12				Last Re-Assessment: 2024-12-13							
					PCB						
Component		Good	Poor	Unit	Sample		Amount	PCB			
Caulking <sup>1</sup>		30		LF	V0000				No		

1 - Installed 2002



...

. ...

- -

**...** 

### ALL DATA REPORT

- -- --

...

- . . ...

. . ...

~ • •



Client: Kaw	artha Pine Rie	dge District School Board Site: 81	45 Old Scugog	Road, Enni	skille	n, ON		Building	Name: Enr	niskillen						
Location: #3	31 : CLASSRO	DOM Floor: 1	L					Room #:	114C				Area (sqft): 800			
Survey Date	e: 2024-12-12							Last Re-	Assessmer	nt: 2024-12	-13					
							AS	BESTOS								
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling <sup>1</sup>		Ceiling Tiles (lay-in)			С	Y		800			SF	V0000	Non-Asbestos		None	
Duct	All	Not Insulated														
Floor		Vinyl Floor Tile and Mastic, 12 x 12 white w tan speck floor tiles		Carpet	А	Y		35			SF	V0006	None Detected	N.D.	None	
Floor		Carpet			Α	Y		800			SF					
Floor		Adhesive/mastic		Carpet	Α	Ν		800			SF	V0027	Chrysotile	<0.5%	None	
Mechanical Equipment		None Found														
Other <sup>2</sup>	Blackboard	Wood			А	Y		3			EA	V0000	Non-Asbestos		None	
Other <sup>3</sup>	Bulletin Board	Particle Board			Α	Y		6			EA	V0000	Non-Asbestos		None	
Other	Sink	Adhesive/mastic, Grey sink mastic			Α	Ν		1			EA	V0022	None Detected	N.D.	None	
Other <sup>4</sup>	Window	Caulking, Brown window caulking			Α	Y		20			LF	V0025	None Detected	N.D.	None	
Piping	All	Fibreglass														
Structure		Not Insulated														
Wall		Masonry														
Wall <sup>5</sup>		Paint, Beige exterior block wall paint			A	Y		390			SF	S0029B	Chrysotile	0.5-5%	Confirmed Asbestos	NF
Wall <sup>6</sup>	Door Frame	Caulking			Α	Y		100			LF	V0000	Non-Asbestos		None	
Wall <sup>7</sup>	Expansion Joint	Caulking, Grey			С	N		10			LF	V0041	Chrysotile	0.5-5%	Confirmed Asbestos	NF

1 - Date code present

2 - Chalkboards are mechanically fastened

3 - Tackboards are mechanically fastened

4 - 2002 date stamp on window

5 - Removed 50 SF on exterior wall in 2024, Pinchin File 335495.018

6 - Installed 2024 - Around Window and Door Frame at Classroom Entrance

7 - On exterior wall above ceiling grid

Client: Kawartha Pine Ridge District Location: #31 : CLASSROOM Survey Date: 2024-12-12	School Board	Site: 8145 Old Scugog Road, Floor: 1	Enniskillen	, ON	Room	#: 114C	Enniskillen Area (sqft): 800 nent: 2024-12-13		
					PAINT				
System		Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard
Wall		Masonry	440		SF	V0005	Beige block	Pb: 0.052 %	Lead (Low)
Structure		Steel	800		SF	V9500	Primer paint on joists and beam		Presumed Lead
Mechanical Equipment		Metal	110		SF	V9500	Blue metal radiator covers		Presumed Lead
Client: Kawartha Pine Ridge District Location: #31 : CLASSROOM	lient: Kawartha Pine Ridge District School Board			, ON		ng Name: I #: 114C	Enniskillen Area (sqft): 800		

Survey Date: 2024-12-12 2025-02-11

Last Re-Assessment: 2024-12-13 Quantities shown above are based on visual approximations only and may be subject to variation. Copyright Pinchin Ltd. 2025

Area (sqft): 800





				MERCONT				
Component				Quantity	/	Unit	Sample	Hazard
Light Fixture <sup>1</sup>				48		EA	V9000	Yes
1 - 12 2 x 4 fixtures								
Client: Kawartha Pine Ridge District School Board Location: #31 : CLASSROOM	Site: 8145 Old So Floor: 1	cugog Road, Er	nniskillen, O	Room #: 1		Area (sqft): 800		
Survey Date: 2024-12-12					ssessment: 2024-12	2-13		
				PCB				
Component	Good	Poor	Unit	Sample		Sample Description	Amount	PCB
Caulking <sup>1</sup>	30		LF	V0000 Black Window Caulking				No

MERCURY

1 - Installed 2002

2025-02-11



#### ALL DATA REPORT



	artha Pine Ri 32 : CLASSR	•	L45 Old Scugog	ı Road, Enni	skille	n, ON		Building Room #:	Name: Enr	niskillen			Area (sqft): 800			
	e: 2024-12-12		-						Assessmer	nt· 2024-12	-13		Alea (3411). 000			
							۵۵	BESTOS			10					
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling <sup>1</sup>		Ceiling Tiles (lay-in)		<b>J</b>	С	Y		800	-		SF	V0000	Non-Asbestos		None	
Ceiling		Drywall and joint compound, Drywall bulkhead			С	Y		100			SF	V0004	Chrysotile	0.5-5%	Confirmed Asbestos	NF
Duct	All	Not Insulated														
Floor		Mastic, Original Mastic			D	N		800			SF	V9500	Presumed Asbestos		Presumed Asbestos	NF
Floor		Vinyl Floor Tile, 12 x 12 white with tan speck vft			Α	Y		800			SF	V0006	None Detected	N.D.	None	
Mechanical Equipment		None Found														
Other	Sink	Adhesive/mastic, Grey sink mastic			Α	Ν		1			EA	V0022	None Detected	N.D.	None	
Other <sup>2</sup>	Window	Caulking, Brown window caulking			Α	Y		20			LF	V0025	None Detected	N.D.	None	
Piping	All	Fibreglass														
Structure		Not Insulated														
Wall		Masonry														
Wall		Paint, Exterior block wall paint		Masonry	А	Y		400			SF	S0029E	Chrysotile	0.5-5%	Confirmed Asbestos	NF

1 - Date code present

2 - 2002 date stamp on windows

Client: Kawartha Pine Ridge District School Board		Site: 8145 Old Scugog Road, Er	nniskiller	n, ON	Buildi	ng Name: E	Enniskillen		
Location: #32 : CLASSROOM		Floor: 1			Room	#: 114B	Area (sqft): 800		
Survey Date: 2024-12-12					Last R	e-Assessn	nent: 2024-12-13		
					PAINT				
System		Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard
Wall		Masonry	400		SF	V0005	Beige block wall paint	Pb: 0.052 %	Lead (Low)
Structure		Steel	800		SF	V9500	red primer paint on steel joist.		Presumed Lead
Mechanical Equipment						V9500	Blue metal radiator covers		Presumed Lead
Ceiling	ywall and joint compound	100		SF	V0007	Beige djc bulkhead	Pb: 0.0057 %	No	
Client: Kawartha Pine Ridge District S Location: #32 : CLASSROOM	School Board	Site: 8145 Old Scugog Road, Er Floor: 1	nniskiller	n, ON		ng Name: E #: 114B	Enniskillen Area (sqft): 800		
Survey Date: 2024-12-12					Last R	e-Assessn	nent: 2024-12-13		
				Ν	ERCURY				
	Component				Qu	antity	Unit	Sample	Hazard
					24	EA	V9000	Yes	
Client: Kawartha Pine Ridge District S Location: #32 : CLASSROOM	Site: 8145 Old Scugog Road, Er Floor: 1	nniskiller	n, ON		ng Name: E #: 114B	Enniskillen Area (sqft): 800			

2025-02-11

Survey Date: 2024-12-12

Last Re-Assessment: 2024-12-13





				PCB			
Component	Good	Poor	Unit	Sample	Sample Description	Amount	PCB
Caulking <sup>1</sup>	30		LF	V0000	Black Window Caulking		No

1 - Installed 2002



.. ..



Client: Kaw	artha Pine Ri	dge District School Board Site: 81	L45 Old Scugog	ı Road, Enni	skille	n, ON	l	Building	Name: Enr	niskillen						
Location: #	33 : CLASSRO	DOM Floor: 1	1					Room #:	114A				Area (sqft): 800			
Survey Date	: 2024-12-12							Last Re-	Assessmer	nt: 2024-12	-13					
							AS	BESTOS								
System	Component	Material	Item	Covering	A*	۷*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling <sup>1</sup>		Ceiling Tiles (lay-in)			С	Y		800			SF	V0000	Non-Asbestos		None	1
Duct	All	Not Insulated														1
Floor		Carpet			Α	Y		775			SF					
Floor		Mastic, Original Mastic			D	Ν		800			SF	V9500	Presumed Asbestos		Presumed Asbestos	NF
Floor		Vinyl Floor Tile, 12 x 12 white with tan specked vft by sink			А	Y		25			SF	V0006	None Detected	N.D.	None	
Mechanical Equipment		None Found														
Other	Bulletin Board	Adhesive/mastic, Presumed mastic for bulletin tack boards			С	Ν		9			EA	V0038	Chrysotile	<0.5%	None	
Other	Sink	Adhesive/mastic, Grey sink mastic			Α	Ν		1			EA	V0022	None Detected	N.D.	None	
Other <sup>2</sup>	Window	Caulking, Brown exterior caulking windows			Α	Y		20			LF	V0025	None Detected	N.D.	None	
Piping	All	Fibreglass										V0000	Non-Asbestos		None	
Structure		Not Insulated														1
Wall		Masonry														
Wall		Paint, Exterior beige block walls		Masonry	A	Y		440			SF	S0029F	Chrysotile	0.5-5%	Confirmed Asbestos	NF
Wall <sup>3</sup>		Vermiculite Investigation			D	Ν		2			EA	V0000	Non-Asbestos		None	
1 Data cod																

1 - Date code present

2 - 2002 date stamp on windows

3 - None Found

Client: Kawartha Pine Ridge District : Location: #33 : CLASSROOM Survey Date: 2024-12-12	School Board	Site: 8145 Old Scugog Road, E Floor: 1	Enniskillen	, ON	Room	#: 114A	Enniskillen Area (sqft): 800 nent: 2024-12-13		
					PAINT				
System		Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard
Wall		Masonry	440		SF	V0005	Beige block wall exterior	Pb: 0.052 %	Lead (Low)
Structure		Steel	800		SF	V9500	red primer steel		Presumed Lead
Mechanical Equipment		Metal	100		SF	V9500	Blue metal radiator covers		Presumed Lead

Client: Kawartha Pine Ridge District School Board	Site: 8145 Old Scugog Road, Enniskill	en, ON Building Name: Enniskillen			
Location: #33 : CLASSROOM	Floor: 1	Room #: 114A	Area (sqft): 800		
Survey Date: 2024-12-12		Last Re-Assessment: 2024-1	2-13		
		MERCURY			
Component		Quantity	Unit	Sample	Hazard
Light Fixture		24	EA	V9000	Yes

Client: Kawartha Pine Ridge District School Board Site: 8145 Old Scugog Road, Enniskillen, ON

**Building Name: Enniskillen** 





Location: #33 : CLASSROOM Flow Survey Date: 2024-12-12	or: 1			Room #: 1 Last Re-As	14A Area (sqft): 800 ssessment: 2024-12-13		
				PCB			
Component	Good	Poor	Unit	Sample	Sample Description	Amount	PCB
Caulking <sup>1</sup>	30		LF	V0000	Black Window Caulking		No

1 - Installed 2002





urvey Date	: 2024-12-12								Assessmer	11: 2024-12	-13					
								BESTOS								
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friabl
Ceiling <sup>1</sup>		Ceiling Tiles (lay-in)			С	Y		200			SF	V0000	Non-Asbestos		None	
Duct		None Found														
Floor		Vinyl Floor Tile and Mastic	Surface		А	Y		200			SF	V0006	[None]	N.D.	[Abated]	
Floor		Ceramic Tiles			А	Y		200			SF					
Floor <sup>2</sup>		Thin-set		Ceramic Tiles	А	Ν		200			SF	V0000	Non-Asbestos		None	
Mechanical Equipment		Metal			А	Y										
Other	Door	Caulking, White caulking on door frame			А	Y		17			LF	S0036C	None Detected	N.D.	None	
Piping	All	Fibreglass		Canvas	С	Y										
Structure		Not Insulated														
Wall		Masonry														
Wall		Paint, Interior block wall paint		Masonry	А	Y		280			SF	S0031BC	Chrysotile	0.5-5%	Confirmed Asbestos	NF
Wall		Adhesive/mastic, Brown adhesive black vinyl trim	Base		А	Ν		40			LF	S0032A	[None]	0.5-5%	[Abated]	
Wall		Adhesive/mastic, Brown adhesive black vinyl trim by toilet			А	N					LF	S0032B	[None]	0.5-5%	[Abated]	

ent: Kawartha Pine Ridge District S cation: #53 : GIRLS WASHROOM	School Board Site: 8145 Old Scugog Road Floor: 1	,		Room	•	Enniskillen Area (sqft): 200		
rvey Date: 2024-12-12				Last R	e-Assessn	nent: 2024-12-13		
				PAINT				
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard
Wall	Masonry	280		SF	V0005	Beige block walls	Pb: 0.052 %	Lead (Low)
Structure	Steel	200		SF	V9500	red primer steel joists		Presumed Lead
Mechanical Equipment	Metal	20		SF	V9500	Blue metal radiator covers		Presumed Lead
ent: Kawartha Pine Ridge District S cation: #53 : GIRLS WASHROOM	School Board Site: 8145 Old Scugog Road Floor: 1	d, Enniskillen	, ON	Buildiı Room	•	Enniskillen Area (sqft): 200		

	MERCURY			
Component	Quantity	Unit	Sample	Hazard
Light Fixture	3	EA	V9000	Yes





rvev Date	e: 2024-12-12							Last Re-	Assessmer	nt: 2024-12	-13					
.,							AS	BESTOS								
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		None Found														
Duct		None Found														
Floor <sup>1</sup>		Vinyl Floor Tile and Mastic, 12 x 12 blue splotches			А	Y		10			SF	V0000	[None]		[Abated]	
Floor		Vinyl Floor Tile and Mastic, 12x12 off white with brown striations	Surface		А	Y		10			SF	V0009	[None]	0.5-5%	[Abated]	
Floor		Ceramic Tiles			Α	Y		20			SF					
Floor <sup>2</sup>		Thin-set		Ceramic Tiles	А	Ν		20			SF	V0000	Non-Asbestos		None	
Mechanical Equipment		None Found														
Piping		Fibreglass			С	Y						V0000	Non-Asbestos		None	
Piping		Parging Cement	Fitting	Canvas	С	Y		15			EA	V0003	Chrysotile	10-25%	Confirmed Asbestos	F
Structure		Metal			С	Y		20			SF					
Wall		Masonry			Α	Y		50			SF					
Wall		Paint		Masonry	А	Y		50			SF	S0043A	Chrysotile	0.5-5%	Confirmed Asbestos	NF

1 - Installed post 2005

2 - Installed post 2023

Client: Kawartha Pine Ridge District School B Location: #54 : CUSTODIAN CLOSET Survey Date: 2024-12-12	oard Site: 8145 Old Scugog Road, E Floor: 1	nniskillen	, ON	Room	#:	nniskillen Area (sqft): 20 lent: 2024-12-13		
				PAINT				
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard
Wall	Masonry	50		SF	L0009	White paint	Pb: 0.083 %	Lead (Low)



## ALL DATA REPORT



irvey Date	: 2024-12-12							Last Re-	Assessmer	nt: 2024-12	-13					
							AS	BESTOS								
System	Component	Material	Item	Covering	A*	۷*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friabl
Ceiling <sup>1</sup>		Ceiling Tiles (lay-in)			С	Y		150			SF	V0000	Non-Asbestos		None	
Duct		None Found														
Floor		Vinyl Floor Tile and Mastic	Surface		А	Y		150			SF	V0006	None Detected	N.D.	None	
Floor		Ceramic Tiles			Α	Y		150			SF					
Floor <sup>2</sup>		Thin-set		Ceramic Tiles	А	Ν		150			SF	V0000	Non-Asbestos		None	
Mechanical Equipment		Metal			Α	Y										
Other	Door	Caulking, White caulking on door frame			А	Y		17			LF	V0036	None Detected	N.D.	None	
Piping	All	Fibreglass		Canvas	С	Y										
Structure		Not Insulated														
Wall		Masonry														
Wall		Paint, Interior block wall paint		Masonry	А	Y		280			SF	S0031E	Chrysotile	0.5-5%	Confirmed Asbestos	NF
Wall		Paint, Interior block wall paint		Masonry	А	Y					SF	V0031	Chrysotile	0.5-5%	Confirmed Asbestos	NF
Wall		Adhesive/mastic, Brown adhesive black vinyl trim	Base		А	N		40			LF	V0032	Chrysotile	0.5-5%	Confirmed Asbestos	NF

2 - Installed post 2023

Client: Kawartha Pine Ridge District Location: #64 : BOYS WASHROOM	School Board	Site: 8145 Old Scugog Road, E Floor: 1	nniskiller	, ON	Room	#: 105	Enniskillen	Area (sqft): 150		
Survey Date: 2024-12-12					Last R	Re-Assessn	nent: 2024-12	2-13		
					PAINT					
System		ltem	Good	Poor	Unit	Sample		Sample Description	Amount	Hazard
Wall		Masonry	280		SF	V0005		Beige block walls	Pb: 0.052 %	Lead (Low)
Structure		Steel	150		SF	V9500		red primer steel joists		Presumed Lead
Mechanical Equipment		Metal	20		SF	V9500		Blue metal radiator covers		Presumed Lead
Client: Kawartha Pine Ridge District	School Board	Site: 8145 Old Scugog Road, E	nniskiller	, ON		0	Enniskillen			
Location: #64 : BOYS WASHROOM		Floor: 1			Room	#: 105		Area (sqft): 150		
Survey Date: 2024-12-12					Last R	Re-Assessn	nent: 2024-12	2-13		
				N	ERCURY					
	Component				Qu	antity		Unit	Sample	Hazard
	Light Fixture					3		EA	V9000	Yes





rvey Date	e: 2024-12-12							Last Re-	Assessmer	nt: 2024-12	-13					
,							AS	BESTOS								
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friabl
Ceiling		None Found														
Duct		None Found														
Floor <sup>1</sup>		Vinyl Floor Tile and Mastic, 12 x 12 blue splotches			А	Y		10			SF	V0000	[None]		[Abated]	
Floor		Vinyl Floor Tile and Mastic, 12x12 off white with brown striations	Surface		А	Y		10			SF	V0009	[None]	0.5-5%	[Abated]	
Floor		Ceramic Tiles			А	Y		40			SF					
Floor <sup>2</sup>		Thin-set		Ceramic Tiles	А	Ν		40			SF	V0000	Non-Asbestos		None	
Mechanical Equipment		None Found														
Piping		Fibreglass			С	Y						V0000	Non-Asbestos		None	
Piping		Parging Cement	Fitting	Canvas	С	Y		4			EA	V0003	Chrysotile	10-25%	Confirmed Asbestos	F
Structure		Metal			С	Y		40			SF					
Wall		Masonry			Α	Y		50			SF					
Wall		Paint		Masonry	А	Y		50			SF	S0043BC	Chrysotile	0.5-5%	Confirmed Asbestos	NF

1 - Installed post 2005

2 - Installed post 2023

Client: Kawartha Pine Ridge District School B Location: #65 : CUSTODIAN CLOSET Survey Date: 2024-12-12	Board Site: 8145 Old Scugog Road, E Floor: 1	nniskillen	, ON	Room	#:	inniskillen Area (sqft): 40 ient: 2024-12-13		
				PAINT				
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard
Wall	Masonry	50		SF	V0009	White paint	Pb: 0.083 %	Lead (Low)



Legend:

#### ALL DATA REPORT



Sample	number	Units				Other				
S####	Asbestos sample collected	SF	Square feet			Α	Access			
L####	Paint sample collected	LF	Linear feet			v	Visible			
P####	PCB sample collected	EA	Each			AP	Air Plenum			
M####	Mould sample collected	%	Percentage			F	Friable material			
V####	Material is visually identified to be identical to S####	LF	Linear feet			NF	Non Friable material			
V0000	Known non hazardous material					PF	Potentially Friable material			
V9000	Material visually identified as a Hazardous Material					Pb	Lead			
V9500	Material is presumed to be a hazardous material					Hg	Mercury			
						As	Arsenic			
						Cr	Chromium			
Access				Conditi						
Α	Accessible to all building occupants				No visible damage or deterioration					
в	Accessible to maintenance and operations staff without a ladder			Fair	Minor, repairable damage, cracking, delamination or deterioration					
С	Accessible to maintenance and operations staff with a ladde areas	y entered, locked	Poor	Irreparable damage or deteriora	ioration with exposed and missing material					
D	Not normally accessible									

#### Visible

Ν

Y The material is visible when standing on the floor of the room, without the removal or opening of other building components (e.g. ceiling tiles or access panels).

The material is not visible to view when standing on the floor of the room and requires the removal of a building component (e.g. ceilings tiles or access panels) to view and access. Includes rarely entered crawlspaces, attic spaces, etc. Observations will be limited to the extent visible from the access points.

The material is partially visible to view when standing on the floor of the room and requires the removal of a building component (e.g. ceiling system or access panels) to

L view completely and access. Includes partially viewed access points to crawlspaces, attic spaces, etc. without entering. Observations are limited to the extent visible from the access points.

#### Colour Coding

The material is a hazardous material, either by analytical results or by visible identification.

The material is presumed to be a hazardous material, based on visual appearance, and was not sampled due to limited access or the non-destructive nature of sampling.

#### Air Plenum


Yes or No No The material is in a return air plenum or in a direct airstream or there is evidence of air erosion (e.g. duct for heating or cooling blowing directly on or across an ACM). This field is only completed where Air Plenum consideration is required by regulation.

APPENDIX VII Photographs






V0003 (Confirmed Asbestos), Parging Cement on Pipe Fittings, CUSTODIAN CLOSET (Location #: 54)



S0043A (Confirmed Asbestos), Wall, Paint, CUSTODIAN CLOSET (Location #: 54)





V0000 (None), Ceiling, Ceiling Tiles (lay-in), GIRLS WASHROOM (Location #: 53) Date code present



L0009(Lead, Low), White paint, Wall, CUSTODIAN CLOSET (Location #: 54)





S0020A (None), Soft brown vertical and upper window caulking, Other, Window, Caulking, EXTERIOR (Location #: 71)



S0022A (None), Grey sink mastic, Other, Sink, Mastic, Grey, CLASSROOM (Location #: 13)





S0023B (None), Black vinyl trim adhesive, Wall, Adhesive/mastic, CUSTODIAN ROOM (Location #: 14)



S0025A (None), Brown window frame caulking 2002 date stamp, Other, Window, Caulking, CUSTODIAN ROOM (Location #: 14)





S0027A (None), Carpet adhesive Burgundy brown streak carpet adhesive, Floor, Adhesive/mastic, CLASSROOM (Location #: 27)



S0029A (Confirmed Asbestos), Exterior masonry brick paint on masonry, Wall, Paint, CLASSROOM (Location #: 30)





S0032A (Confirmed Asbestos on wall paint phase C ), Brown adhesive black vinyl trim on asbestos-containing promer paint, Wall, Adhesive/mastic, GIRLS WASHROOM (Location #: 53)