



Issued February 25, 2025

The following information changes the competitive process documents issued on February 18, 2025.

CLARIFICATIONS

Item 1: Refer to appended contractor laydown area plan (1 page) dated February 25, 2025.

Item 2: Refer to appended environmental addendum 1 (1 page) issued by Pinchin Ltd., dated February 25, 2025.

QUESTIONS AND RESPONSES

- Q1 Please confirm the presence of asbestos transite ceiling tiles in the boys' washroom 114
- R1 Refer to Item 2 above.
- Q2 Please can you provide base building Electrical and Mechanical trades?
- R2 There are no requirements for pre-qualified Electrical and Mechanical sub-contractors.
- Q3 Please can you provide the contact details of fire alarm vendor?
- R3 Refer to Appendix A Construction School Specific Information Sheet Example in the Specifications and below contact information for HWDSB pre-approved fire alarm Control and Testing Service Provider required for Fire Alarm verification.

Hamilton Fire Control is Contact: Michael Fleet - Hamilton Fire Control Phone: (905) 527-7042 Email: <u>michael@hamiltonfirecontrol.ca</u>

- Q4 Please confirm if the Winning bid to be considered will be based on total price including seperate price or just the base bid?
- R4 The contract award will be dependent on the base bid and separate prices.
- Q5 Will we be able to access the builling from the nearest exit doors?
- R5 The successful contractor will have full access to the area of Work excluding the daycare and daycare parking lot, please also refer to Item 1 above.
- Q6 Are we allowed to work after hours or extended hours? if yes then will there be any additional permission required for the sam





R6 Refer to section 1.4 Working Hours of the RFT document.

- Q7 Please confirm if there is any union requirement
- **R7** There are no requirements for union labour.

End of Addendum #1





PART 1 ADDENDUM 1

1.1 Intent

- .1 This addendum is issued to clarify the specifications and answer questions during tender, and shall form part of the contract documents for the project.
- .2 Except as otherwise specified herein, work required by this Addendum shall be in accordance with specifications dated January 7, 2025.

1.2 Question

- Q. Please confirm the presence of asbestos transite ceiling tiles in the boys' washroom 114.
- A. Transite ceiling tiles are present in the Boy's Washroom 114 (HMIS Location 8183) per the HMIS data in the Hazardous Building Materials Report.

END OF ADDENDUM 1